

Rootes Archive Centre Trust

## **The Avenger Collection**

Archive Centre Trustees and Friends

Contact e-Mail: Bob: [spares@theimpclub.co.uk](mailto:spares@theimpclub.co.uk)

October 20, 2013

### **Abstract**

[TBA]

This document is available from the Rootes Archive Centre Web site at [http://tardis.dl.ac.uk/ARCC/Avenger/avenger\\_drawings/index.html](http://tardis.dl.ac.uk/ARCC/Avenger/avenger_drawings/index.html). A PDF format copy of this document can be obtained from [http://tardis.dl.ac.uk/ARCC/Avenger/avenger\\_drawings.pdf](http://tardis.dl.ac.uk/ARCC/Avenger/avenger_drawings.pdf). You probably won't want to print it as there are over 100 pages, but it is searchable with a suitable PDF reader.

© **Rootes Archive Centre 2012-13**. The Rootes Archive Centre does not accept any responsibility for loss or damage arising either directly or indirectly from the use of information contained in any of their reports or in any communication about their tests or investigations. Whilst we have tried to be as accurate as possible, some errors may have occurred in the cataloguing process or interpretation.

## **Contents**

<b>1</b>	<b>Introduction</b>	<b>1</b>
<b>2</b>	<b>Avenger Tube Section</b>	<b>1</b>
<b>3</b>	<b>Negatives Drawer 1.</b>	<b>34</b>
<b>4</b>	<b>Acknowledgements</b>	<b>137</b>

## 1 Introduction

## 2 Avenger Tube Section

Some highlights of this set include:

:

Drwg	Title	Date	Model	Notes
72263862	Tread Strip and Seat Pan Finisher RH	July 10 1968	B Car - Avenger	
72288428	Panel Trunk Lid Outer	14/01/1974	Avenger VI Series	
72290709	Grille Radiator	18/01/1974	Avenger VI	
72290710	Grille Radiator		Avenger VI	
72261058	Homologation Drg - Avenger DL	15/08/1969	Avenger DL	
72261059	Homologation Drg - Avenger Super	15/08/1969	Avenger Super	
72287696	Glass Backlight Hotline	18/02/1974	Avenger 6	
X2260732	Draught Ventilator - B Body	26/09/1969	Avenger	
72257162	Cutting Forme (High Back Seat)	31/03/1969	B Car - Avenger	
72264882	Cutting Forme (Seats)	24/07/1970	B Car - Avenger	
S2267705	Scheme Side Impact Beam Front Door	22/10/1970	Avenger	Sheet 1 of 2
S2267705	Scheme Side Impact Beam Front Door		Avenger	Sheet 2 of 2
S2267706	Scheme Side Impact Beams, 'B' Car Rear Door	07/01/1971	Avenger	Sheet 1 of 2
71261907	Arrangement drawing Exhaust System Heavy Duty 1500cc Single Carb Estate	19/01/1971	B 1500cc Estate - Avenger	
71263210	Arrangement drawing rear axle	09/03/1972	B Vehicle Estate - Avenger	
S2257992	'No Draught' Ventilator	09/07/1969	B Body - Avenger	superceded by S2260732
X2267747	Panel Rear Panhard Rod Bracket (Saloon)	22/01/1970	B Saloon - Avenger	
72254104	Cross Member Rear	15/10/1969	Avenger?	
72254105	Panel Load Floor	11/09/1969	Avenger Estate	
72254118	Cross Member Shock Absorber	01/10/1969	Avenger Estate	
72263966	Trimmed Assy Rear Squab Complete	17/02/1970	Avenger Lo Line	
72263981	Trimmed Assy Rear Seat Squab Complete	11/02/1970	Avenger	
72263949	Trimmed Assy Individual Font Seat Complete	16/02/1970	Avenger Lowline	

72263954	Panel Assy Front Squab Cover Face	19/02/1970	Avenger Lowline	
72263956	Trimmed Assy Individual Front Seat Complete RH	26/02/1970	Avenger Lowline (Option)	All Assy Patrs Listed Simca
S2257698	Layout Bumper Locations to Comply with J681a Recommendations		B Model - Avenger	
S2259575	Installation Drawing Tailgate Hinge		Avenger Estate	
72250340	Panel Inner Rear Wheelarch RH	02/03/1967	Avenger All Models and Estate	
72263960	Panel Assy Front Squab Cover Face	24/02/1970	Avenger Low Line	
72263964	Panel Assy Rear Cushion Cover Top Fluted	23/02/1970	B Body Low Line - Avenger	
72263968	Panel Assy Rear Squab Cover Face	24/02/1970	B Body Lowline - Avenger	
XSK154735A	Layout Rear Quarter Air Extraction	10/01/1968	B Body -Avenger	
72255420	Mat Trunk Floor	11/12/1968	Avenger	
72264824	Trimmed Assy Individual Front Seat Complete RH Reclining	15/07/1970	Avenger	Medium Line
72264899	Cutting Forme (Panel Cover Rear, Upper Front Squab)	30/07/1970	Avenger	72264693
S2264783	Layout Rear Cushion Springcase	08/05/1969	Avenger Estate, High, Lo and Med	
S2291321	Layout Surface Rear Wing End Cap Upper	11/12/1973	Avenger 2 Door	Sheet 1 of 2
S2291321	Scheme Rear Wing End Caps Upper	06/03/1974	Avenger 2 Door	Sheet 2 of 2
72288478	Assy Front Wing RH	11/03/1974	Avenger	
72288484	Assy Trunk Lid Complete	23/11/1974	Avenger Saloon	
72264774	Frame Assy Front Seat High Back	26/06/1970	B Car High Line - Avenger	
72264796	Tread Strip and Scuttle Side Finisher	09/07/1970	B Mailing - Avenger	
72264826	Assy Trimmed Complete Front Seat Right Hand	15/02/1972	Avenger	
72264892	Panel Assy Front Squab Cover Face Centre (Periphery and Pattern Weld Tool)	17/07/1970	B - Avenger	
72288462	RH - Panel Rear Quarter Inner	22/02/1974	B Saloon - Avenger	
72275319	Trimmed Assy Rear Cushion Complete	28/09/1971	B Model - Avenger	
S2258542	General Assy Complete Rear Squab/Cushion	17/01/1970	Avenger Estate	4 sheets
S2258542	Layout Rear Cushion and Squab	14/05/1969	Avenger Estate	sheet 1
72257152	Trimmed Assy Individual Front Seats Complete (Reclining) RH	25/03/1969	Avenger Lo Line	
72257166	Trimmed Assy Individual Front Seat Complete (Reclining) RH	21/03/1969	Avenger Medium Line	

72256281	Border Front Cushion Cover Main	23/12/1968	B Medium Line - Avenger	
72292420	Assy Panel Facia Lower RHD	01/05/1968	Avenger Estate	Also Drawn 10/4/74 J A Wallen
72292421	Assy Panel Facia Lower LHD	01/05/1968	Avenger Estate	
72296645	Spray Pattern - Avenger Estate	21/11/1974	Avenger Estate	
71240905	Cylinder Head Machining Drawing	23/09/1971	1250/1500 Avenger	
S2295356	Avenger Backlight Full Width Plenum -Dry Glazing)	04/02/1975		
72296643	Spray Pattern Avenger 4 Door	17/02/1975	Avenger 4 Door	
72296644	Spray Pattern Avenger 2 Door	25/11/1974	Avenger 2 Door	
72291547	Plates Labels and Stamped Num- bers Required to meet world Wide Legal Requirements (6 Model Year Avenger)	01/08/1975	Avenger (6 Year)	
72297005	Sunbeam 1300 R4BCE - Estate Car Austra	11/02/1976	Avenger	
72297009	Sunbeam 1300 R4BCA 4Tand 2T Saloon		Avenger	
72297010	Sunbeam 1300 R4BCL 4T and 2T Saloon		Avenger	
72297012	Sunbeam 1600 R4BCD - Saloon		Avenger	
72297030	Windshield Wiped and Defog Areas to Proposed ECE Reg	15/04/1976	Avenger 8 and Sunbeam	
2287597	Plates Labels and Stamped Num- bers Required to meet world Wide Legal Requirements 5 Model Year Avenger)	12/08/1974	Avenger	Plan of Body
S1244640	B Twin Carb Throttle Controls	22/11/1968	Avenger	
XSK104811	B' Exhaust and Fuel Tank	16/11/1966	Avenger	Not up to date
XSK156079	Accelerator Controls for Prototypes 9 to 13 inc	28/11/1967	Avenger	
71260574	Assy Instrument Unit	09/06/1970	Avenger	
71275133	Instruction Drawing Assy Vacuum Pipe Dist to Carb	18/04/1975	Avenger Sweden	
S2287901	Layout 2 Door Avenger F/Seat with Regline and Fold Squab With Cen- tre Lock	31/08/1973	Avenger 2 Door	
71272880	Welding Inter Pipe Assy and Si- lencer (Silencer Details)	20/12/1974	Avenger Saloon	Sheet 2 of 2
71272880	Welding Assy Inter Pipe and Main Silencer	11/07/1974	Avenger Saloon	Sheet 1 of 2
72294300	Cutting Instruction	09/06/1975	Avenger?	
72294361	Cutting Instruction Drawing	08/10/1974	U W A2 (Avenger?)	

72294449	Cutting Instruction Drawing	08/10/1974	Avenger?
72294795	Cutting Instruction Drawing	18/10/1974	U W A2 (Avenger?)
72295578	Cutting Instruction Drawing	13/11/1974	Avenger 7/R4 Medium Line
X1275219	Induction Manifold	28/07/1975	Avenger
X1981655	Induction Manifold Casting	28/07/1975	Avenger
20003400	Assy Trimmed Complete Front Seat RH	13/08/1975	Avenger 2 Door Hi-Line
20003500	Assy Trimmed Complete Front Seat LH	13/08/1975	Avenger 2 Door Hi-Line
20006100	Assy Cushion Frame Fold Forward Front Seat	01/09/1975	Avenger
20006200	Assy Frame Front Seat (Recline) RH	20/08/1976	Avenger 4 Door 7 Series
20006300	Assy Frame Front Seat (Recline) LH	20/08/1976	Avenger 4 Door 7 Series
20007200	Assy Frame Fold Forward Front Seat RH	21/08/1975	Avenger 2 Door 7 Series
20007300	Assy Frame Fold Forward Front Seat LH	21/08/1975	Avenger 2 Door 7 Series
20033400	Assy Frame Complete (Recline and Fold Forward with Centre Lock) RH	01/09/1975	Avenger 2 Door 7 Series
20033500	Assy Frame Complete (Recline and Fold Forward with Centre Lock) LH	01/09/1975	Avenger 2 Door 7 Series
20033600	Assy Squab Frame Fold Forward Recline Centre Lock F/Seat RH	02/09/1975	424, Avenger 7 and 8 Year
20033700	Assy Squab Frame Fold Forward Recline Centre Lock F/Seat LH	02/09/1975	424, Avenger 7 and 8 Year
20034200	Assy Frame Front Seat	03/09/1975	Avenger Medium Line 4 Door 7 Year
20034400	Assy Frame Front Seat	03/09/1975	Avenger 4 Door Lo-Line 7 Year
20823600	Assy Trimmed Complete Front Seat RH	17/01/1977	Avenger 2 Door Hi Line 8 Year H7
20823700	Assy Trimmed Complete Front Seat LH	17/01/1977	Avenger 2 Door Hi Line 8 Year H7
21024000	Assy Trimmed Complete Front Seat RH	18/03/1977	Avenger 2 Door Hi-Line 8 Year H7
21024100	Assy Trimmed Complete Front Seat LH	18/03/1977	Avenger 2 Door Hi-Line 8 Year H7
23032000	Pad Front Seat Cushion	24/01/1975	Avenger Med and Prem Line 7 Year
72296706	Facia Impact Areas	21/03/1975	Avenger (7 Year Facelift)
71274199	Cylinder Head Machining Drawing 1295cc	23/12/1974	Avenger 1294cc

71274200	Cylinder Head Machining Drawing 1598cc	23/12/1974	Avenger 1598cc
S2296635	Front Seat Frame Fixed Head Impact Squab	13/03/1975	Avenger Lo-Line
S2297163	Front Seat Frame Fixed and reclining Head Impact Squab	30/04/1975	Avenger 2 Door
S2297197	Modification to Avenger Front Seat Pedestal to Facilitate Fitting to Arrow	Apr-75	Arrow
20036000	Assy Trimmed Complete Front Seat Recline Squab RH	12/09/1975	Avenger 4 Door Series 7 GLS
20036100	Assy Trimmed Complete Front Seat Recline Squab LH	12/09/1975	Avenger 4 Door Series 7 GLS
23028700	Border Cover Main Front Cushion	05/06/1975	7/R4M (Avenger?)
23035700	Assy Panel Front Squab	23/09/1974	7/R4M (Avenger?)
23036600	Assy Panel Front Cushion	12/02/1975	Avenger F/L 7 Medium Line
23044900	Panel Face Rear Squab	12/11/1974	Avenger 7 Saloon Medium Line
23084400	Assy Trimmed Complete Front Seat Recline Squab RH	15/07/1974	Avenger 4 Door Series 7 GL
23084500	Assy Trimmed Complete Front Seat Recline Squab LH	15/07/1974	Avenger 4 Door Series 7 GL
72295376	Panel Rear Header	21/04/1975	Avenger Estate
72295378	Extension Roof to Rear Header	30/04/1975	Avenger
71804677	Torsion Bar	10/02/1975	Avenger 4 Door (Year 6)
72264029	Mat Trunk Floor 'B' Vehicle	11/12/1968	Avenger
72264068	Trimmed Assy Individual Front Seat Complete	05/03/1970	Avenger Medium Line
72264071	Panel Assy Front Squab Cover Face Fluted	03/03/1970	Avenger Medium Line
72264080	Cutting Forme (Seats)	13/03/1970	Avenger Estate Medium Line
72264106	Panel Assy Rear Squab Cover Face Centre	11/03/1970	Avenger Medium Line
72264108	Gearbox Insulation	17/03/1970	Avenger
72264110	Panel Assy Rear Squab Fluted Centre Panel RH	09/03/1970	Avenger Medium Line
72264111	Panel Assy Rear Squab Fluted Centre Panel LH	09/03/1970	Avenger Medium Line
72264114	Trimmed Assy Individual Front Seat Complete RH	11/08/1970	Avenger Medium Line
72264115	Trimmed Assy Individual Front Seat Complete LH	11/08/1970	Avenger Medium Line

S2264083	Scheme Showing Fixings Spring Case Rear Cushion to Panel	24/02/1970	Avenger Estate	
S1264939	Outling of Avenger 1250cc, 1500cc and 1800cc Low Block Single Carb Engines		Avenger Single Carb	
S1264940	Outline of Avenger Twin Carb OHV Engine		Avenger Twin Carb	
S1264941	Outline of Avenger 1875cc Twin Carb High Block OHV Engine		Avenger 1875cc	
S1264942	Outline of Avenger 1875cc Twin Carb High Block OHC Engine		Avenger 1875cc OHC	
72291525	Engine Number Stamping - Avenger	28/01/1975	Avenger 6 Year	
72296529	Assy Panel Rear Seat	21/10/1975	Avenger Estate	
72297203	Panel rear Seat Cushion	28/11/1969	Avenger	
X1269908	Induction Manifold	20/07/1973	Avenger 1300 5 Series	
X1981577	Induction Manifold Casting	20/07/1973	Avenger 1300 5 Series	
S2297100	Layout Front Seat Frame Assy (Recline)		Avenger GL and GLS 6-7 Year	
23029800	Assembly Face Panels Front Squab	18/06/1975	Avenger Low Line	
71274237	Welding Assy Exhaust Downpipes and 'Y' Piece	22/01/1975	Avenger Saloon and Estate	
72294877	Cutting Instruction Drawing (Front Seats)	10/12/1974	Avenger H4	
72295693	Cutting Instruction Drawing (Rear Seat)	06/02/1974	Avenger K4	
72257177	Panel Assy Front Squab Cover Face, Reclining Squab	28/03/1969	Avenger Lo Line	Sheet 1 of 2
72257177	Panel Assy Front Squab Cover Face, Reclining Squab	29/03/1969	Avenger Lo Line	Sheet 2 of 2
72257196	Assy Trim Pad Tailgate	03/11/1969	Avenger Estate High Line	
72257197	Trim Board Tailgate	09/10/1969	Avenger Estate High Line	
72257199	Cover Trim Pad Tailgate	11/08/1970	Avenger	
72257230	Trim Board Rear Quarter Lower RH	07/10/1970	Avenger Estate High Line	
72257274	Main Border Rear Cushion RH	20/07/1970	Avenger Estate Lo, Med, High Line	
72257275	Main Border Rear Cushion LH		Avenger Estate Lo, Med, High Line	
72263988	Panel Assy Rear Squab Cover Face End RH	09/03/1970	Avenger Medium Line	
72263989	Panel Assy Rear Squab Cover Face End LH	09/03/1970	Avenger Medium Line	



72294851	Assy Trim Board Parcel Shelf Rear	13/02/1975	Avenger 2 Door	
72295354	Cross Member Shock Absorber	04/02/1975	Avenger Estate	
72295355	Panel Load Floor	04/02/1975	Avenger Estate	
72296626	Trim Board Parcel Shelf Rear	06/02/1975	Avenger 2 Door	
72296652	Assy Trim Board Parcel Shelf Rear	20/02/1975	Avenger 4 Door	
72296653	Trim Board Parcel Shelf Rear	20/02/1975	Avenger 4 Door	
72296456	Mat Floor Front Auto RHD	14/01/1975	Avenger	
72296457	Mat Floor Front Auto LHD		Avenger	
72296511	Rubber Mat Floor Rear	22/01/1975	Avenger Estate	Sheet 2 of 2
72296511	Rubber Mat Floor Rear	22/01/1975	Avenger Estate	Sheet 1 of 2
72296512	Rubber Mat Floor Rear	22/01/1975	Avenger Saloon	Sheet 2 of 2
72296512	Rubber Mat Floor Rear	22/01/1975	Avenger Saloon	Sheet 1 of 2
S2296530	Layout Front Seat Frame-Avenger Type Modified for Arrow RH	Jan-75	Arrow 4 Door (Not Sceptre)	Superceded S2297139
S2296531	Layout Front Seat Frame-Avenger Type Modified for Arrow LH	Jan-75	Arrow 4 Door (Not Sceptre)	Superceded S2297139
S2297139	Layout Front Seat (Recline)- Avenger 6/7 Type-in Arrow Saloon	19/03/1975	Arrow Saloon	
S2297143	Front Seat Frame (Recline)Head Impact Squab	30/04/1975	Avenger 4 Door	
S2284975	Proposed Safety Belt Slide Scheme	13/03/1973	Avenger	
S2286066	Proposed Safety Belt Slide Scheme	04/05/1973	Avenger 4 door	
X1275177	Welding Assy Exhaust Downpipes and Intermed Pipe Front	16/06/1975	C8 Avenger En- gine	
XSK 158348	Brake and Clutch Pedal Arrange- ment RHD	20/02/1968	Avenger	
71273878	Assy Front Suspension RH	25/03/1975	Avenger Iran	
71273879	Assy Front Suspension LH	25/03/1975	Avenger Iran	
71291879	Panel 'A' Post Lower LH	14/09/1971	Avenger VI	Also B Taylor 02/09/1974
72291878	Panel 'A' Post Lower RH	14/09/1971	Avenger VI	Also B Taylor 02/09/1974
72295368	Assy Housing Torsion Bar Tailgate Counterbalance RH	12/03/1975	Avenger Estate	
72295369	Assy Housing Torsion Bar Tailgate Counterbalance LH	12/03/1975	Avenger Estate	
X1275179	Welding Assy Exhaust Inner Pipe RR, Main Silencer Tailpipe and RR Silencer	19/06/1975	C8 Avenger En- gine	Sheet 1 of 3
X1275179	Welding Assy Exhaust Inner Pipe RR, Main Silencer Tailpipe and RR Silencer (Main Silencer Details)	20/06/1975	C8 Avenger En- gine	Sheet 2 of 3
72276853	Revised Fixings Cushion Rear Seat (Intalastic Springcase 72275290)	22/11/1971	Avenger 2 and 4 Door	
72295290	Instruction Drawing Facia Assy (Hardware) RHD	23/01/1975	Avenger 2 and 4 Door	

72295291	Instruction Drawing Facia Assy (Hardware) LHD	23/01/1975	Avenger 2 and 4 Door	
S2276854	Revised Fixings Cushion rear Seat (Formed Wire Springcase 722275291)	22/11/1971	Avenger 2 and 4 Door	
S2276855	Layout Squab Spring Case	23/11/1971	Avenger	
S2275203	Front Seat Cushion and Squab Pad Layout and Front Seat Valance		Avenger GLS	
23041400	Assy Panels Face Front Squab	27/09/1974	Avenger?	
23044300	Assy Panel Cover Top Rear Cushion	23/09/1974	7/R4M (Avenger?)	
23044400	Panel Top Rear Cushion	16/09/1974	7/R4M (Avenger?)	
23044500	Assembly Panel Top Rear Cushion	25/09/1974	7/R4M (Avenger?)	
23044800	Assy Panel Cover Top Rear Squab	12/11/1974	Avenger 7 Saloon Medium Line	
23046700	Panel Face Rear Squab	30/06/1975	Avenger?	
72297236	Trim Board BC Post	20/06/1975	Avenger all Models	
71245380	Case Gear Box	29/05/1969	Avenger	Sheet 1 of 2
71245380	Case Gear Box	06/06/1969	Avenger	
20130500	Assembly Cover Panel Face Front Seat Squab	17/12/1975	Avenger GL	
20130600	Panel Face Front Seat Squab	12/12/1975	Avenger GL	
71276363	Welding Assembly Inner Pipe and Main Silencer	09/12/1975	Avenger	
71276363	Welding Assembly Inner Pipe and Main Silencer	03/12/1975	Avenger	
71276368	Welding Assembly Exhaust Inner Pipe and Main Silencer	09/12/1975	Avenger	
71276368	Welding Assembly Exhaust Inner Pipe and Main Silencer	03/12/1975	Avenger	
S1277301	Track Control Arm Replacable Ball Joint	23/03/1976	Avenger	
71269876	Instruction Drawing Induction and Exhaust Manifolds SC	21/06/1973	Avenger	
S1265986	Proposed Oil Cooler Pipes BW45 Auto Transmission	22/06/1972	Avenger	
X1266258	Instruction Drawing Induction and Exhaust Manifolds SC	14/04/1972	Avenger (30 AO 10)	
S1276560	Scheme Avenger Gear Shipt Lever in 829 (C8 Tunnel)	Jun-75	Model 829	
S2264923	General Arrangement Individual Front Seat Complete Sheet 1	27/08/1970	Avenger NAS 4 Door	
S2264923	General Arrangement Individual Front Seat Complete Sheet 2	03/09/1970	Avenger NAS 4 Door	

S2276117	Scheme Front Seat Frame (Hi Back Folding Squab)	04/10/1971	Avenger NAS
S2292118	Scheme Moulded Pad Rear Seat Cushion	10/07/1974	Avenger 7
S2292123	Scheme Rear seat Squab Pad	17/07/1974	Avenger 7
23033400	Assembly Panel Face Rear Squab Sheet 1	09/06/1975	Avenger Lowline
23033400	Assembly Panel Face Rear Squab Sheet 2	09/08/1974	Avenger Lowline
23033600	Assembly Trimmed Complete Front Seat RH	16/07/1974	Avenger 2 Door Lowline
23033700	Assembly Trimmed Complete Front Seat LH	16/07/1974	Avenger 2 Door Lowline
23040700	General Arrangement Front Seat Fixed	17/06/1975	Avenger 4 Door (Modle A1)
S23033500	General Arrangement Fold Forward Front Seat	05/05/1975	Avenger 2 Door Lowline (B1)
71269970	High Performance Cam Profile	09/10/1973	Avenger Tiger
72296980	Inst Drg Stamping Vehicle Identification Engine Holologation Plate Numbering	29/01/1976	Avenger 7
S2291224	Scheme Rear Seat Form Wire (Improved Leg Room)	31/01/1974	Avenger
S2292374	Scheme Parcel Tray	30/10/1974	Avenger 6
71276284	Welding Assembly Exhaust Interpipe and Main Silencer, sheet 1	11/11/1975	Avenger
71276284	Welding Assembly Exhaust Interpipe and Main Silencer, sheet 2	07/11/1975	Avenger
71276367	Welding Assembly Exhaust Interpipe and Main Silencer, sheet 1	05/12/1975	Avenger
71276367	Welding Assembly Exhaust Interpipe and Main Silencer, sheet 2	05/12/1975	Avenger
20130900	Panel Top Rear Cushion	03/12/1975	Avenger
20131100	Assembly Cover Panel Face Rear Squab	13/12/1975	Avenger GL
20131200	Panel face Rear Squab	19/09/1975	Avenger GL
20170600	Assembly Cover Panel Top Rear Cushion	10/12/1975	Avenger GL Estate
20170700	Assembly Cover Face Panel Rear Squab	06/12/1975	Avenger Hi-Line Estate
20170800	Panel Top Rear Cushion	09/12/1975	Avenger GL Estate
20170900	Panel Face Rear Squab	08/12/1975	Avenger
20178900	Cutting Instruction Drawing Handbrake Gaiter	23/01/1976	Avenger
20692300	Panel Top Rear Cushion	03/01/1977	Avenger
20692900	Assembly Cover Panel Face Rear Squab	13/01/1977	Avenger

20693000	Panel Face Rear Squab	13/01/1977	Avenger A7
20001200	Assembly Panel Rear Cushion	16/09/1975	Avenger
20004100	Assembly Top Panels Front Cushion	27/11/1975	Avenger
20036300	Assembly Panel Front Cushion	16/09/1975	Avenger
20080500	Cutting Instruction Drawing Rear Seat	02/12/1975	Avenger
20080600	Cutting Instruction Drawing Rear Seat	02/12/1975	Avenger
20131000	Assembly Panel Rear Cushion	16/09/1975	Avenger
20822410	Assembly Top Panels Front Cushion	17/07/1977	Avenger H7
20824500	Assembly Face Panels Front Squab	17/07/1977	Avenger 8 Year Hi-Line
71275283	Arrangement Drawing Exhaust System	06/02/1973	Avenger Estate
71275284	Arrangement Drawing Exhaust System	19/09/1972	Avenger Saloon
71275285	Arrangement Drawing Exhaust System	24/03/1975	Avenger Saloon 6 Year non E C E
71275286	Arrangement Drawing Exhaust System	19/03/1975	Avenger Estate
71276488	Assembly Fuel Tank, Side Filler	01/12/1975	Avenger
71276489	Upper Pressing Fuel Tank	01/12/1975	Avenger
71276490	Bottom Pressing Fuel Tank	01/12/1975	Avenger
71981656	Cover Timing (Die Casting)	21/08/1975	Avenger
72291974	Assembly Body Less Doors RHD	20/02/1975	Avenger 4 Door Saloon
72291975	Assembly Body Less Doors LHD see 72291974	20/02/1975	Avenger 4 Door Saloon
S2277434	Scheme Folding Front Seat Squab Pad Sheet 1	Nov-71	Avenger NAS
S2277434	Scheme Folding Front Seat Squab Pad Sheet 2	05/01/1972	Avenger NAS
S2277434	Layout Protection Pad Lower NAS Fold Fwd Squab Front Seat Sh3	18/01/1972	Avenger NAS 2 Door
20032200	Assembly Trim Pad B. C. Post RH	20/06/1975	Avenger
20032300	Assembly Trim Pad B. C. Post LH	20/06/1975	Avenger
71274953	Instruction Drawing Headlamp Wash/Wipe	22/08/1975	Avenger
72296513	Cutting Instruction Drawing Rear Seat	21/01/1975	Avenger
20003900	Assembly Cover Top Panel Front Cushion	26/11/1975	Avenger
71275968	Headlamp / Front Flasher Assembly Italy Only RH	02/10/1975	Avenger (Italy Only)
71275969	Headlamp / Front Flasher Assembly Italy Only LH	02/10/1975	Avenger (Italy Only)
71275970	Headlamp / Front Flasher Assembly LHD Except France RH	02/10/1975	Avenger (LHD Except France)

71275971	Headlamp / Front Flasher Assembly LHD Except France LH	02/10/1975	Avenger (LHD Except France)
71276004	Radiator	22/10/1975	Avenger
71276005	Radiator See 71276004	22/10/1975	Avenger
71276006	Radiator	21/10/1975	Avenger
71276125	Assembly Tail Lamp	18/09/1975	Avenger 7
71276129	Headlamp / Front Flasher Assembly France Only RH	02/10/1975	Avenger (France Only)
71276130	Headlamp / Front Flasher Assembly France Only LH	02/10/1975	Avenger (France Only)
72295395	Panel Windscreen Aperture RHD	14/08/1975	Avenger Saloon and Estate
72295396	Panel Windscreen Aperture LHD See 72295395	14/08/1975	Avenger Saloon and Estate
72295397	Panel Plenum Chamber See 72295395	14/08/1975	Avenger Saloon and Estate
72292642	Rear Bumper with End Piercings	06/10/1975	Avenger 6 Saloon
72292644	Assembly Rear Bumper Welded	08/10/1975	Avenger
72292645	Assembly Rear Bumper and Rub- bing Strip	08/10/1975	Avenger
20001100	Assembly Panel Rear Squab	16/09/1975	Avenger GLS
20130400	Assembly Panel Front Cushion	16/09/1975	Avenger
20131300	Assembly Panel Rear Squab	16/09/1975	Avenger GL
20693100	Assembly Panel Rear Squab	13/01/1977	Avenger (A7)
72281256	Assembly Trimmed Complete Front Seat	03/11/1972	Avenger
72283056	Assembly Trimmed Complete Front Seat RH	09/11/1974	Avenger
72283057	Assembly Trimmed Complete Front Seat LH See 72283057	09/11/1974	Avenger
72296360	Cutting Instruction Drawing Front Seat	16/12/1974	Avenger H4 - H5
72296400	Cutting Instruction Drawing Front Seat Squab	07/01/1975	Avenger
20004000	Panel Top Front Cushion	28/11/1975	Avenger
20004300	Assembly Cover Face Panel Front Squab	25/11/1975	Avenger 7 Year GT and GL
20004400	Panel Face Front Squab	26/11/1975	Avenger 7 Year GT and GL
20014100	Assembly Cover Rear Cushion	19/12/1975	Avenger
20014300	Assembly Cover Rear Squab	17/12/1975	Avenger
20130200	Assembly Cover Panel Top Front Cushion	10/12/1975	Avenger GL
20130300	Panel Top Front Cushion	19/09/1975	Avenger GL
20130800	Assembly Cover Panel Top Rear Cushion	19/09/1975	Avenger GL
20824000	Panel Top Front Cushion	17/01/1977	Avenger H7
20824400	Panel Face Front Squab	17/07/1977	Avenger

71273660	Type 38 Supervac and 0.812" Dia AS/AS Master Cylinder RHD	03/09/1975	Avenger
71275281	Arrangement Drawing Exhaust System	09/09/1972	Avenger Saloon
71275293	Welding Assembly Exhaust Tailpipe Sheet 1	12/09/1975	Avenger
71275293	Welding Assembly Exhaust Tailpipe Sheet 2	12/09/1975	Avenger
71275641	Type 38 Supervac and 19.05 Dia AS/AS Master Cylinder LHD	12/07/1979	Avenger
71275642	Type 38 Supervac and 0.75 Dia AS/AS Master Cylinder RHD	03/09/1975	Avenger
71275672	Assembly Rear Brake 8 x 1.50 RH	25/09/1975	Avenger
71275673	Assembly Rear Brake 8 x 1.50 LH	25/09/1975	Avenger
71276406	Assembly Rear Brake 8 x 1.50 RH	22/08/1969	Avenger
71276407	Assembly Rear Brake 8 x 1.50 LH	22/08/1969	Avenger
S2295436	Layout of Modified Floor A904 Gearbox in Avenger (Not Complete)	08/01/1976	Avenger
71275265	Air Cleaner Air Temperature Control (SC 1300 and 1600)		Avenger SC (1.75)
71275266	Air Cleaner Air Temperature Control (SC 1300 and 1600)	13/03/1974	Avenger SC (CD150, CD3, CD3W, SU HS4C)
71275267	Air Cleaner Air Temperature Control (SC 1300 and 1600)	23/11/1976	Avenger SC 1300 and 1600
S1273988	Rear Engine Mounting, Avenger Casing Manual Box	05/05/1975	M' Car
S1273989	Rear Engine Mounting, Avenger Casing BW 45 Auto in C7	06/05/1975	C7 'M' Car
S1275504	Sketch of Driveline for Avenger Transmission in C8, Based on 180 Rear Axle	12/05/1975	C8
S1275512	Sketch of A904 Auto and Avenger Borg Warner45 in C7	20/05/1975	C7
20039300	Assembly Cover Panel Top Cushion	10/12/1975	Avenger GLS
20039400	Assembly Cover Panel Face Front Seat Squab	10/12/1975	Avenger GLS
20039500	Assembly Cover Top Panel Rear Cushion	19/09/1975	Avenger GLS
20039600	Assembly Cover Face Panel Rear Squab	03/12/1975	Avenger GLS
20099200	Panel Top Rear Cushion	03/12/1975	Avenger GLS
20099300	Panel Face Front Seat Squab	19/09/1975	Avenger GLS
20099400	Panel Top Front Cushion	19/09/1975	Avenger GLS
20099500	Panel face Rear Squab	19/09/1975	Avenger GLS

71271770	Induction Manifold	09/05/1974	Avenger 1295 and 1598cc
71271916	Headlamp Front Flasher Assembly RH	Feb-75	Avenger 7
71271917	Headlamp Front Flasher Assembly LH	Feb-75	Avenger 7
71981621	Induction Manifold Casting	08/05/1974	Avenger 1295 and 1598cc
S2275791	Catch Rear Quarter Vent	07/02/1972	Avenger 2 Door
2292601	Spoiler Trunk Lid	01/08/1975	Avenger
71271257	Headlamp and Front Flasher Assembly RH	Feb-75	Avenger 7 LHD Except France
71271258	Headlamp and Front Flasher Assembly LH	Feb-75	Avenger 7 LHD Except France
71271918	Headlamp and Front Flasher Assembly RH	02/10/1975	Avenger 7 LHD Except France
71271919	Headlamp and Front Flasher Assembly LH	02/10/1975	Avenger 7 LHD Except France
71272639	Headlamp and Front Flasher Assembly	Feb-75	Avenger 7 LHD France Only
71272640	Headlamp and Front Flasher Assembly	Feb-75	Avenger 7 LHD France Only
71272641	Headlamp and Front Flasher Assembly	27/10/1975	Avenger 7 LHD France Only
71272642	Headlamp and Front Flasher Assembly	27/10/1975	Avenger 7 LHD France Only
71271265	Cable Harness Main See 71272600		Avenger L
X1272813	Welding Assembly Exhaust Manifold	10/05/1974	K3 in Avenger
71272851	Welding Assembly Exhaust Inter Pipe Main Silencer and Exhaust Tailpipe		Avenger Estate all Models
71272851	Main Silencer Assembly		Avenger Estate all Models
71272852	Main Silencer Assembly		Avenger Saloon
71272852	Welding Assembly Exhaust Inter Pipe Main Silencer and Exhaust Tailpipe		Avenger Saloon
71272984	Welding Assembly Exhaust Inter Pipe Main Silencer and Exhaust Tailpipe	19/09/1974	Avenger Saloon
71272984	Welding Assembly Inter Pipe and Silencer (Main Silencer Details)	12/09/1974	Avenger Saloon
71272985	Welding Assembly Exhaust Inter Pipe Main Silencer and Exhaust Tailpipe	26/09/1974	Avenger Estate
71272985	Welding Assembly Inter Pipe and Silencer (Main Silencer Details)	26/09/1974	Avenger Estate

71269477	Gearbox Casing	28/01/1974	Avenger
X1981634	Cylinder Bolck Sand Casting 1735cc	01/11/1974	Avenger 1735cc
X1272384	Modified Arrow Steering Unit to Suit Avenger GT Steering Wheel RHD	14/04/1974	Arrow
X1272385	Modified Arrow Steering Unit to Suit Avenger GT Steering Wheel LHD	14/04/1974	Arrow
71272788	Chart Instrument Unit Assembly	04/10/1976	Avenger
71270398	Roplas Roadwheel 5J x 13 Sheet 1	03/01/1974	Avenger and Arrow
71270398	Roplas Roadwheel 5J x 13 Sheet 2	28/12/1973	Avenger and Arrow
71272832	Instruction Drawing Air Cleaner with Hot Air Pick Up	29/07/1974	Avenger (CD 150)
71803322	Assembly Rack and Pinion Steering Unit RHD	Jun-73	Avenger
71803323	Assembly Rack and Pinion Steering Unit LHD	Jun-73	Avenger
71268632	Engine Cross Section Arrangement and Homologation Drg	19/01/1973	Avenger 1600 Single Carb
71248146	Gearbox Arrangement RHD	03/05/1969	Avenger
71250625	Gearbox Arrangement LHD see 71248146	03/05/1969	Avenger
71271992	Installation Drawing Horn Mounting	18/04/1974	Avenger
71271398	Induction Manifold Casting SC	21/05/1974	Avenger
71272850	Induction Mainfold Machining	23/05/1974	Avenger
71804597	Air Cleaner Air Temp Control S/C CD150	13/03/1974	Avenger S/C CD150
71804598	Air Cleaner Air Temp Control S/C CD175	07/10/1974	Avenger SC CD 175
72291842	Body Less Doors 4 Door Saloon Sheet 1	26/08/1974	Avenger VII 4 Door Saloon
72291842	Body Less Doors 4 Door Saloon Sheet 2	26/08/1974	Avenger VII 4 Door Saloon
72291843	Body Less Doors 2 Door Saloon Sheet 1	12/09/1974	Avenger VII 2 Door Saloon
72291843	Body Less Doors 2 Door Saloon Sheet 2	12/09/1974	Avenger VII 2 Door Saloon
72291844	Instruction Drawing Welding Body Less Doors Sheet 1	25/10/1974	Avenger VII Estate
72291844	Instruction Drawing Welding Body Less Doors Sheet 2	25/10/1974	Avenger VII Estate
72291940	Welding Body Side	11/10/1974	Avenger Estate
71272686	Assembly Tail Lamp RH	18/09/1975	Avenger VII
71272687	Assembly Tail Lamp LH	18/09/1975	Avenger VII
72288356	Panel Headlamp Pocket RH	23/01/1974	Avenger



72288357	Panel Headlamp Pocket LH	23/01/1974	Avenger
72288395	Panel Rear Inner	24/01/1974	Avenger VI
72288398	Panel Tail Lamp and End Cap 4 Door RH	19/02/1974	Avenger
72288399	Panel Tail Lamp and End Cap 4 Door LH	19/02/1974	Avenger
72288400	Panel Tail Lamp and End Cap 2 Door RH	19/02/1974	Avenger
72288401	Panel Tail Lamp and End Cap 2 Door LH	19/02/1974	Avenger
71272833	Instruction Drawing Air Cleaner with HAPU	29/07/1974	Avenger LHD
71273661	Type 38 Supervac and 0.812" Dia AS/AS M/Cyl LHD	24/09/1974	Avenger LHD
24448900	Arrangement Drawing Rear Axle	11/07/1974	Avenger Estate R4-00-0-45
25548800	Arrangement Drawing Rear Axle	13/02/1978	Avenger Iran (Salisbury)
71247732	Assembly Drawing Rear Axle	11/07/1974	Avenger and Avenger Iran
71266618	Assembly Rear Axle	11/07/1974	Avenger
71266619	Assembly Drawing Rear Axle	11/07/1974	Avenger Estate R4-00-0-45
S1262955	Collapsible Convolute Steering Colum (AP) RH	23/02/1971	Avenger
S1262956	Collapsible Convolute Steering Colum (AP) LH	23/02/1971	Avenger
S1263419	Saninaw Steering Colum	01/07/1971	Avenger NAS
S1268187	Steering Column with Lucas Switch 163A Avenger Sht 1	22/02/1973	Avenger
S1268187	Steering Column with Lucas Switch 163A Avenger Sht 2	Dec-72	Avenger
S1268187	Steering Column with Lucas Switch 163A Avenger Sht 3	04/12/1972	Avenger
S1273709	Reart Suspension Geomerty 'B' Es- tate		Avenger Estate
X1262956	Assembly Steering Column RH	09/04/1971	Avenger
X1262957	Assembly Steering Column LH	09/04/1971	Avenger
X1264000	Assembly Steering Column RH	13/08/1971	Avenger
X1264001	Assembly Steering Coulumn LH	13/08/1971	Avenger
X1273145	Instruction Drawing Fixings	13/09/1974	Avenger
71271356	Cable Harness Main RHD	18/12/1973	Avenger R4 M5
71271357	Cable Harness Main LHD	19/12/1974	Avenger R4 HP
71271358	Cable Harness Main RHD	19/12/1974	Avenger R4 HP
S1261751	D. I. Clearance Cowl Seering Col- umn	10/12/1970	Avenger
S1264109	Energy Absorbing Steering Column in 'B' Vehicle	19/10/1971	Avenger

S1273707	Check on Rack and Pinion Gaiter Clearance from Crossmember	12/11/1969	Avenger
S1273707	Check on Rack and Pinion Gaiter Clearance from Crossmember		Avenger
S1273710	Eaton Livia Steering Column with Air Bag Restraint	30/06/1970	Avenger
72273164	Panel Side Impact Beam Outer Front Door RH	15/04/1971	Avenger Saloon and Estate NAS
72273165	Panel Side Impact Beam Outer Front Door LH	15/04/1971	Avenger Saloon and Estate NAS
72273166	Panel Side Impact Beam Outer Rear Door RH	02/04/1971	Avenger Saloon and Estate NAS
72273167	Panel Side Impact Beam Outer Rear Door LH	02/04/1971	Avenger Saloon and Estate NAS
72274344	Filler Panel Rear Wing and Quarter RH	31/08/1971	Avenger Estate
72274345	Filler Panel Rear Wing and Quarter LH	31/08/1971	Avenger Estate
X1272806	Induction Manifold 1800 K3	02/05/1974	Avenger 1800 K3
X2275198	Vehicle Shipping Arrangement Drawing	30/09/1971	Avenger
72291835	Assembly Body Less Doors	15/08/1974	Avenger All Models
26362000	Assembly Tail Lamp	12/11/1979	Avenger 7 Saloon
26410200	Assembly Windscreen and Plenum Chamber Complete RHD	26/11/1979	Avenger
26410200	Assembly Engine Compartment and Main Floor RHD	13/11/1979	Avenger Estate
26410300	Assembly Windscreen and Plenum Chamber Complete LHD	26/11/1979	Avenger
26410300	Assembly Engine Compartment and Main Floor LHD	13/11/1979	Avenger Estate
26411200	Assembly Body Side RH	15/03/1977	Avenger 8 Four Door
26411300	Assembly Body Side LH	15/03/1977	Avenger 8 Four Door
72254105	Panel Load Floor	11/09/1969	Avenger Estate
72254238	Panel Drain Channel Tail Lamp RH	20/11/1969	Avenger
72254239	Panel Drain Channel Tail Lamp LH	20/11/1969	Avenger
72254160	Panel 'E' Post Inner RH	07/11/1969	Avenger Estate
72254161	Panel 'E' Post Inner LH	07/11/1969	Avenger Estate
72254186	Panel Roof Sheet 2	11/06/1969	Avenger Estate
72254262	Panel Front Panhard Rod Bracket	03/09/1970	Avenger Estate
72254275	Panel Rear Seat	25/08/1969	Avenger Estate
72250036	Panel Front Door Outer RH	21/03/1967	Avenger
72250037	Panel Front Door Outer LH	21/03/1967	Avenger
72250324	Panel Sill Inner RH	23/01/1967	Avenger Saloon and Estate

72250325	Panel Sill Inner LH	23/01/1967	Avenger Saloon and Estate
72273602	Reinforcement Front Door Hinges RH	03/05/1971	Avenger
72273603	Reinforcement Front Door Hinges LH	03/05/1971	Avenger
72274270	Panel Rear Sidemember RH	29/08/1969	Avenger Estate
72274271	Panel Rear Sidemember LH	29/08/1969	Avenger Estate
72275452	Panel Cantrail Closing RH	12/11/1971	Avenger 2 Door
72275453	Panel Cantrail Closing LH	12/11/1971	Avenger 2 Door
72275548	Panel Striker Face Rear Quarter RH	26/11/1971	Avenger 2 Door
72275549	Panel Striker Face Rear Quarter LH	26/11/1971	Avenger 2 Door
72250084	Panel Trunk Lid Inner	21/03/1967	Avenger Saloon
XSK159791	Proposed Door Lock 'B' Body Front Door	22/07/1968	Avenger
72250026	Panel Dash RHD	26/01/1967	Avenger
72250027	Panel Dash LHD	26/01/1967	Avenger
72250052	Panel Main Floor	20/12/1967	Avenger Saloon
72250378	Reinforcing Windscreen Lower Panel	21/03/1967	Avenger
72252101	Panel Assembly Front Squab Cover Face (Welded)	13/01/1969	Avenger Medium Line
72276788	Panel Inner Tailgate Sheet 2	11/05/1972	Avenger Estate
71267714	Arrangement of Oil Cooler Pipes BW45 Auto Transmission	27/06/1973	Avenger
71263690	Welding Assembly Exhaust Pipe	28/02/1973	Avenger
71268689	Welding Assembly Exhaust Inter Pipe and Main Silencer	06/03/1973	Avenger
71268689	Welding Assembly Inter Pipe and Silencer (Silencer Details)	02/03/1973	Avenger
71269334	Fuel Tank Assembly	04/03/1969	Avenger
71269306	5J x 13 Styled Disc Wheel (Rostyle)	05/04/1973	Avenger and Arrow
X1269418	Mainshaft	16/03/1973	Avenger
72291352	Bumper Rear	13/02/1974	Avenger Estate
71268360	Cable Harness Main RHD	21/02/1973	Avenger R4 K L
71268361	Cable Harness main LHD	21/02/1973	Avenger R4 L
71268362	Cable Harness Main RHD	21/02/1973	Avenger R4 M S
71268363	Cable Harness Main LHD	21/02/1973	Avenger R4 M S
71268364	Cable Harness Main RHD	21/02/1973	Avenger R4 H P
71268365	Cable Harness Main LHD	21/02/1973	Avenger R4 H P
71269307	Brake Drum	15/04/1970	Avenger
71266989	Rear Cover Gearbox	14/03/1973	Avenger
71269401	Mainshaft	16/03/1973	Avenger
71981539	Rear Cover Gearbox H P Die Casting	02/03/1973	Avenger
71981539	Rear Cover Gearbox H P Die Casting	07/03/1973	Avenger

71267202	Assembly Heater Case	23/06/1972	Avenger
71267234	Assembly Case Ventilation Unit	23/06/1972	Avenger
71267235	Assembly Case Ventilation Unit	23/06/1972	Avenger
71267396	Headlamp	30/01/1973	Arrow and Avenger
71268387	Assembly Heater Case	23/06/1972	Avenger
71803961	Air Cleaner	24/05/1971	Avenger Single Carb 1300
S2295342	Headlamp Fitting Clearances	03/12/1974	Avenger VI
71271259	Tail Lamp RH Sheet 1	24/01/1974	Avenger Series 6
71271259	Tail Lamp RH Sheet 2	26/11/1973	Avenger Series 6
71271260	Tail Lamp LH Sheet 1	24/01/1974	Avenger Series 6
71271260	Tail Lamp LH Sheet 2	26/11/1973	Avenger Series 6
71266370	Installation Drg Exhaust and Evap- orative Emission Control System	22/09/1972	Avenger
S2291944	Scheme Bonnet Inner Overslam Stop	09/01/1975	Avenger
71269419	Mainshaft	01/06/1973	Avenger
71270808	Assembly Fuel Tank Side Filler	22/05/1971	Avenger Side Filler
71270808	Assembly Fuel Tank Side Filler	22/05/1974	Avenger - Side Filler
X1271504	Adaptor Engine Gearbox - 'K' En- gine in Avenger	05/03/1974	K' Engine in Avenger
X1271504	Adaptor - Engine - Gearbox	05/03/1974	K Engine in Avenger
X1271505	Gearbox Casing	05/03/1974	Avenger
X1271505	Gearbox Casing	05/03/1974	Avenger
71268961	Assembly Horn Mounting Double Headlamp	27/11/1972	Avenger
71268962	Assembly Horn Mounting Single Headlamp	27/11/1972	Avenger
71269446	Assembly Automatic Transmission BW45 Twin Carb	11/11/1971	Avenger (BW45 Twin Carb)
71269446	Assembly Automatic Transmission BW45 Twin Carb	11/11/1971	Avenger (BW45 Twin Carb)
71269959	Welding Assembly Exhaust Inter Pipe and Main Silencer	15/02/1972	Avenger R4 - H3 - 41 - L (SPN97)
71270254	General Arrangement Accelerator Controls RHD Single Carb	06/06/1973	Avenger Single Carb
71270255	General Arrangement Accelerator Controls RHD Twin Carb	18/07/1973	Avenger Twin Carb RHD
71263067	Assembly Heater Complete with Controls and Cables	17/10/1972	Avenger
71266056	Assembly BW45 Automatic Trans- mission Twin Carb Sheet 2	11/11/1971	Avenger
71266139	Assembly Heater Complete with Controls and Cables	21/07/1972	Avenger

71266955	Assembly BW45 Automatic Transmission Single Carb Sheet 1	11/11/1971	Avenger
71266955	Assembly BW45 Automatic Transmission Single Carb Sheet 2	11/11/1971	Avenger
71266956	Assembly BW45 Automatic Transmission Twin Carb Sheet 1	11/11/1971	Avenger
71267200	Side Panel RH Sheet 1	29/06/1972	Avenger
71267201	Side Panel LH Sheet 2	29/06/1972	Avenger
71267236	Side Panel RH Ventilator Unit	29/06/1972	Avenger
71269519	Radiator Including Oil Cooler	25/05/1975	Avenger
71271455	Mainshaft for A304 Speedo	22/01/1974	Avenger and Sunbeam
S1260176	Handbrake Scheme Whippetree Type	22/04/1970	Avenger Estate
X1271644	Exhaust Manifold to suit installation in Avenger and Engine Test	18/01/1974	K3 1600cc / 1800cc
71268691	Welding Assembly Tail Pipe Exhaust	28/02/1973	Avenger
72295586	Assembly Cover Rear Squab	26/11/1974	Avenger
X1271192	Adaptor Plate	18/12/1973	K3 with Avenger Gearbox
70271407	Radiator Including Oil Cooler	25/05/1975	Avenger
S1263343	Collapsible Steering Column	18/05/1971	Avenger
S1263386	Bracket 7deg Collapsible Steering Column	21/06/1971	Avenger
S1263387	Bracket (7deg) Collapsible Steering Column (AP)	21/06/1971	Avenger
S1263387	Bracket (7deg) Collapsible Steering Column (AP)	Jul-71	Avenger
S1263647	E A Column Support	08/02/1971	Avenger
S1268184	Collapsible Convolute (A and P) Steering Column	24/02/1971	Avenger
S1268185	A C Delco Collapsible Convolute Steering Column with Redesigned Switch	15/12/1970	Avenger
XSK160635	Energy Absorbing Steering Column (Saginaw) Fitted with Sunbeam Arrow Handwheel (Modified Cowl)	28/05/1968	Avenger
71265501	General Arrangement Front Suspension	09/02/1972	Avenger
71803242	Lamp Direction Indicator Italy RH	21/03/1972	Avenger
71803243	Lamp Direction Indicator Italy LH	21/03/1972	Avenger
71267030	Induction Manifold Single Carb	30/06/1972	Avenger 1295cc - 1598cc
71267114	Cam Profile	12/09/1972	Avenger
71267138	Cylinder Block 1600cc Sheet 1	06/09/1972	Avenger 1600cc
71267138	Cylinder Block 1600cc Sheet 2	06/09/1972	Avenger 1600cc
71267138	Cylinder Block 1600cc Sheet 3	06/09/1972	Avenger 1600cc

71267143	Inlet Manifold Twin Carb	07/09/1972	Avenger 1295cc - 1598cc
71302001	Propeller Shaft	05/11/1970	Avenger Argentina
71803658	Air Cleaner Twin Carb	07/06/1972	Avenger Twin Carb Domestic
71981481	Inlet Manifold Twin Carb	22/05/1972	Avenger 1250cc - 1295cc - 1598cc
71981500	Induction Manifold Single Carb	14/07/1972	Avenger 1295cc - 1598cc
71267204	Assembly Instrument Unit	Jun-72	Avenger
71267205	Assembly Instrument Unit	Jun-72	Avenger
71267206	Assembly Instrument Unit	Jun-72	Avenger
71267207	Assembly Instrument Unit	Jun-72	Avenger
71267208	Assembly Instrument Unit	Jun-72	Avenger
71267209	Assembly Instrument Unit	Jun-72	Avenger
71267210	Assembly Instrument Unit	Jun-72	Avenger
71267211	Assembly Instrument Unit	Jun-72	Avenger
72250412	Panel Crossmember Front	02/05/1967	Avenger Saloon and Estate
71261844	Silencer Exhaust	21/12/1970	Avenger
71261997	Arrangement Drawing Exhaust System	09/03/1971	Avenger 1250/1500cc Saloon
71264973	Arrangement Drawing Exhaust System Heavy Duty Saloon	21/10/1971	Avenger 1250/1500cc Heavy Duty Saloon
71264974	Arrangement Drawing Exhaust System Estate	22/10/1971	Avenger 1250/1500cc Estate
71264975	Arrangement Drawing Exhaust System Heavy Duty Estate	21/10/1971	Avenger 1250/1500cc Heavy Duty Estate
71264979	Welding Assembly Exhaust Pipe Front	27/10/1971	Avenger
71266329	Air Cleaner	07/06/1972	B' (Avenger) NAS T/C
71803954	Air Cleaner	07/06/1972	Avenger T/C
71265796	Arrangement Drawing Exhaust System (Italy)	19/06/1972	Avenger Saloon (Italy)
71266280	Arrangement Drawing Exhaust System (Italy)	19/06/1972	Avenger Estate (Italy)
71266657	Assembly Rack and Pinion Steering Unit LHD	18/05/1972	B' Model LHD (Avenger)
X1267082	Inlet Manifold Twin Carb	12/06/1972	Avenger 1500TC

71266243	Assembly and Instruction Drawing Engine Dress-up T/C Air Conditioning Unit	17/04/1972	Avenger
71266331	Assembly Cover Airbox	26/03/1975	Avenger
71267212	Assembly Instrument Unit	06/07/1972	Avenger
71266740	Assembly Rack and Pinion Steering Unit RHD	11/10/1972	Avenger
71266741	Assembly Rack and Pinion Steering Unit LHD	11/10/1972	Avenger
71803809	Control Box	01/12/1972	Imp, Arrow and Avenger
71266383	Assembly Drawing Alternator Installation	18/04/1972	Avenger Cricket only
71267909	Instruction Drawing Pipe Petrol Pump to Carb	17/11/1972	Avenger
71268020	Assembly Stub Axle and Strut RH Front Suspension	10/11/1972	Avenger
71268021	Assembly Stub Axle and Strut LH Front Suspension	10/11/1972	Avenger
71268022	Assembly Stub Axle and Strut RH Front Suspension	10/11/1972	Avenger
71268023	Assembly Stub Axle and Strut LH Front Suspension	10/11/1972	Avenger
71268024	Assembly Stub Axle and Strut RH	10/11/1972	Avenger
71268025	Assembly Stub Axle and Strut LH	10/11/1972	Avenger
71268026	Assembly Stub Axle and Strut RH	10/11/1972	Avenger
71268027	Assembly Stub Axle and Strut LH	10/11/1972	Avenger
71268028	Assembly Stub Axle and Strut RH	10/11/1972	Avenger
71268029	Assembly Stub Axle and Strut LH	10/11/1972	Avenger
71268030	Assembly Stub Axle and Strut RH	10/11/1972	Avenger
71268031	Assembly Stub Axle and Strut LH	10/11/1972	Avenger
71266476	Handwheel and Pad Steering	20/06/1972	Avenger 2 Door GT
71266562	Assembly Rack and Pinion Steering Unit RHD	17/05/1972	Avenger
71266563	Assembly Rack and Pinion Steering Unit LHD	17/05/1972	Avenger
71266742	Assembly Rack and Pinion Steering Unit RHD	14/06/1972	Avenger
71266743	Assembly Rack and Pinion Steering Unit LHD	14/06/1972	Avenger
71803230	Assembly Rack and Pinion Steering Unit RHD	01/06/1972	Avenger
71803230	Assembly Rack and Pinion Steering Unit LHD	01/06/1972	Avenger
72250380	Panel 'A' Post Closing Upper RH	12/04/1967	Avenger Saloon and Estate

72250381	Panel 'A' Post Closing Upper LH	12/04/1967	Avenger Saloon and Esate
X1275242	Assembly Radiator	19/08/1975	C8 Avenger Engine Std Trans Fixed Fan
71265626	Arragement Drawing Exhaust System	19/06/1972	Avenger Twin Carb Saloon (Italy)
71265844	Gearbox Casting	05/08/1971	Avenger
71265871	Extension Housing Borg Warner 35	02/06/1972	Avenger
71265872	Installation Drawing Auto Transmission Borg Warner 35	05/06/1972	Avenger
71265873	Borg Warner Type 35 Assembly	05/06/1972	Avenger
71266392	Arragement Drawing Exhaust System	26/06/1972	Avenger
71981510	Gearbox Castting Sheet 1	19/04/1972	Avenger
71981510	Gearbox Castting Sheet 2	19/04/1972	Avenger
71981516	Extension Housing Casting Borg Warner 35	02/06/1972	Avenger
712666393	Arrangement Drawing Exhaust System (T/C Estate)	27/06/1972	Avenger Twin Carb Estate R4-J3-C-45-L
71263638	Welding Assembly Front and Inner Pipes and Expanxion Box	26/01/1972	Avenger
71267063	Arrangement Drawing Exhaust System	24/03/1977	Avenger Saloon 5
71267065	Arrangement Drawing Exhaust System	19/03/1975	Avenger Estate 5
71267310	Cable Harness Main RHD		Avenger R4 - M5
71267316	Cable Harness Main RHD		Avenger R4 - KL
71267317	Cable Harness Main LHD		Avenger R4 - L
71267319	Cable Harness Main LHD		Avenger R4 - M5
71267320	Cable Harness Main RHD		Avenger R4 - HP
71267321	Cable Harness Main LHD		Avenger R4 - HP
71272878	Arrangement Drawing Exhaust System	06/02/1973	Avenger Estate 5
71275282	Arrangement Drawing Exhaust System	06/02/1973	Avenger Estate 5
71261841	Assembly Exhaust Front and Intermediate Pipes and Expansion Box	09/03/1971	Avenger
71263018	Cable Harness RHD	14/04/1971	Avenger R4-00-L-45-R
71263019	Cable Harness LHD	14/04/1971	Avenger R4-00-L-45-L
71263020	Cable Harness RHD	14/04/1971	Avenger R4-00-M-45-R
71263022	Cable Harness RHD	15/04/1971	Avenger R4-00-H-45-R



71263023	Cable Harness LHD	15/04/1971	Avenger R4-00-H-45-L
71265648	Long and Cross Section Arrangement 1250cc T/C 'B' Engine	03/07/1969	Avenger 1250cc T/C
71265648	Long and Cross Section Arrangement 1250cc T/C 'B' Engine	02/09/1971	Avenger 1250cc T/C
71265757	Long and Cross Section Arrangement 1250cc 'B' Engine	15/05/1969	Avenger 1250cc S/C
71265757	Long and Cross Section Arrangement 1250cc 'B' Engine	15/05/1969	Avenger 1250cc S/C
71265758	Long and Cross Section Arrangement 1500cc 'B' Engine	09/05/1969	Avenger 1500cc S/C
71265758	Long and Cross Section Arrangement 1500cc 'B' Engine	09/05/1969	Avenger 1500cc S/C
71265759	Long and Cross Section Arrangement 1500cc T/C 'B' Engine	03/07/1969	Avenger 1500cc T/C
71265759	Long and Cross Section Arrangement 1500cc T/C 'B' Engine	03/07/1969	Avenger 1500cc T/C
71241114	Carrier Machining Rear Axle Sheet 1	23/04/1970	Avenger
71241114	Carrier Casting Rear Axle Sheet 2	02/04/1970	Avenger
71241114	Carrier Casting Rear Axle Sheet 3	05/07/1971	Avenger
71241114	Carrier Casting Rear Axle Sheet 4	15/04/1980	Avenger and Talbot Sunbeam (424)
71263010	Cable Harness RHD	07/04/1971	Avenger R4-00-HP-4-HR
71263011	Cable Harness LHD	07/04/1971	Avenger R4-00-L-41-L
71263012	Cable Harness RHD	09/04/1971	Avenger R4-00-M-41-R
71263013	Cable Harness LHD	09/04/1971	Avenger R4-00-M-41-L
71263014	Cable Harness RHD	14/04/1971	Avenger R4-00-HP-41-R, R4-J3-H-41-R
71263015	Cable Harness LHD	14/04/1971	Avenger R4-00-HR-41-L, R4-J3-H-41-L
71263016	Cable Harness RHD	14/04/1971	Avenger R4-J3-LM-41-R, R4-00-K-41-R
71263017	Cable Harness LHD	14/04/1971	Avenger R4-J3-LM-41-L
71803272	Assembly Front Brake 8 x 13/4 RH	23/03/1972	Avenger
71803273	Assembly Front Brake 8 x 13/4 LH	23/03/1972	Avenger
71803276	Assembly Rear Brake 8 x 11/2 RH	30/03/1972	Avenger
71803277	Assembly Rear Brake 8 x 11/2 LH	30/03/1972	Avenger

71803278	Backplate Rear Brake 8 x 11/2 RH	30/03/1972	Avenger
71803279	Backplate Raer Brake 8 x 11/2 LH	30/03/1972	Avenger
X1981520	Induction Manifold Casting	13/07/1972	Avenger 1250cc and 1627cc S/C
71265107	Extension Housing Borg Warner 45	13/10/1971	Arrow and Avenger Borg Warner 45
71265847	Borg Warner Type 35 Assembly	08/05/1972	Avenger
71981470	Extension Housing (Casting) BW 45	28/09/1971	Avenger Borg Warner 45
71981513	Converter Housing (L. P. Die Cast- ing) BW 45	05/05/1972	Avenger Borg Warner 45
X1267022	Induction Manifold Machining	30/06/1972	Avenger 1250cc and 1627cc S/C
72250340	Panel Inner Rear Wheel Arch RH	09/02/1967	Avenger Saloon and Estate all Models
72250341	Panel Inner Rear Wheel Arch LH	09/02/1967	Avenger Saloon and Estate all Models
X1265502	Assembly Stub Axle and Strut RH	21/01/1972	Avenger
X1265503	Assembly Stub Axle and Strut LH	21/01/1972	Avenger
71266206	Crankshaft Machining	26/01/1972	Avenger 1250cc and 1627cc
71981521	Cylinder Block Sand Casting 1627cc (Sheet 1)	10/08/1972	Avenger 1627cc
71981521	Cylinder Block Sand Casting 1627cc (Sheet 2)	10/08/1972	Avenger 1627cc
71981521	Cylinder Block Sand Casting 1627cc (Sheet 3)	10/08/1972	Avenger 1627cc
71268109	Roplas Wheel 5J x 13 Sheet 1	11/01/1973	Avenger GLS
71268109	Roplas Wheel 5J x 13 Sheet 2	17/01/1973	Avenger GLS
71981441	Cylinder Block Sand Casting Sheet 1	11/11/1971	Avenger 1250cc
71981441	Cylinder Block Sand Casting Sheet 1	11/11/1971	Avenger 1250cc
71981441	Cylinder Block Sand Casting Sheet 1	11/11/1971	Avenger 1250cc
71981442	Cylinder Block Sand Casting Sheet 1	04/11/1971	Avenger 1500cc
71981442	Cylinder Block Sand Casting Sheet 1	04/11/1971	Avenger 1500cc
71981442	Cylinder Block Sand Casting Sheet 1	04/11/1971	Avenger 1500cc
71981526	Cylinder Block Sand Casting Sheet 1	10/08/1972	Avenger 1600cc
71981526	Cylinder Block Sand Casting Sheet 1	06/09/1972	Avenger 1600cc

71981526	Cylinder Block Sand Casting Sheet 1	06/09/1972	Avenger 1600cc	
20466000	Panel Closing 'A' Post Lower RH	06/10/1976	Avenger	
20466100	Panel Closing 'A' Post Lower LH	06/10/1976	Avenger	
71128000	Panel Closing 'A' Post Lower RH	16/10/1976	Avenger	
71128100	Panel Closing 'A' Post Lower LH	16/10/1976	Avenger	
72292002	Assy Panel Top Rear Cushion	17/07/1974	Avenger	Sheet 1 of 2
72292002	Assy Panel Top Rear Cushion	17/07/1974	Avenger	Sheet 2 of 2
23082000	Assy Trimmed Complete Front Seat RH	05/12/1973	Avenger	
23082100	Assy Trimmed Complete Front Seat LH	05/12/1973	Avenger	
72278410	Plate Inner Mechanism Assy RH	09/01/1974	Avenger 2 Door	
72278411	Plate Inner Mechanism Assy LH	09/01/1974	Avenger 2 Door	
72288724	Assy Trimmed Complete Individual Front Seat RH	16/11/1973	Avenger 2 Door 5 Series	Option for Sport, Lo/Med Line
72288725	Assy Trimmed Complete Individual Front Seat LH	16/11/1973	Avenger 2 Door 5 Series	Option for Sport, Lo/Med Line
72290192	Assy Frame Fold Forward Front Seat RH	07/01/1974	Avenger 2 Door	
72290193	Assy Frame Fold Forward Front Seat LH	07/01/1974	Avenger 2 Door	
72290350	Assy Trimmed Complete Individual Front Seat RH	26/02/1974	Avenger 2 Door Medium Line	
72290351	Assy Trimmed Complete Individual Front Seat LH	26/02/1974	Avenger 2 Door Medium Line	
72290352	Assy Trimmed Complete Individual Front Seat RH	27/02/1974	Avenger 2 Door Lo-Line (Option)	
72290353	Assy Trimmed Complete Individual Front Seat LH	27/02/1974	Avenger 2 Door Lo-Line (Option)	
23035800	Assy Trimmed Complete Front Seat RH	08/10/1974	Avenger 2 Door Year 7 Medium Line	
23035900	Assy Trimmed Complete Front Seat LH	08/10/1974	Avenger 2 Door Year 7 Medium Line	
72292116	Assy Trimmed Complete Front Seat Squab RH	15/05/1974	Avenger 4 Door Series VI GLS	
72292117	Assy Trimmed Complete Front Seat Squab LH	15/05/1974	Avenger 4 Door Series VI GLS	
72295633	Assembly Panel Insert Front Seat Squab	26/11/1974	Avenger	
S2255177	Layout Windshield and Backlight Apertures	15/11/1968	Avenger	Sheet 1 of 2

72291862	Instruction Drawing Front Door Welding	16/07/1974	Avenger
72291863	Instruction Drawing Rear Door Welding	08/08/1974	Avenger
72291952	Panel Rear Seat	07/05/1971	Avenger Saloon
S2294022	General Arrangement Rear Seat Complete	01/11/1974	Avenger 7 High-line
S2294301	General Arrangement Rear Seat Complete	25/10/1974	Avenger Premium Line
72287656	Proposal Rear Bumper	06/11/1973	Avenger
72295692	Cutting Instruction Drawing	03/12/1974	Avenger UW H-O
S2286081	Scheme Comparison AMA Dimensions Avenger Series 4 and 6 and Competitors		Avenger
72291804	Panel Rear	11/04/1974	Avenger Estate
S2291223	Scheme Rear Seat (Improved Leg Room)	30/01/1974	Avenger Hi Line and Premium
S2292003	Layout Rear Seat Form Wire (Improved Leg Room)	23/04/1974	Avenger
X2292004	Layout Rear Seat (Improved Legroom)	08/05/1974	Avenger Hi Line and Premium
X2292020	Assy Complete Rear Seat	09/05/1974	RL4 Avenger Low Line
23045700	Panel Top Rear Cushion	25/06/1975	Avenger
72291734	Assy Front Seat (Recline) RH	11/06/1974	Avenger 4 Door Series VI
72291735	Assy Front Seat (Recline) LH	11/06/1974	Avenger 4 Door Series VI
72291874	Instruction Drawing Welding Rear Floor	02/08/1974	Avenger 2 and 4 Door Saloon
72291874	Instruction Drawing Welding Rear Floor	02/08/1974	Avenger 2 and 4 Door Saloon
72291875	Assy Rear Floor (Spot Weld List)	15/08/1974	Avenger 2 and 4 Door Saloon
72292052	Assy Frame Front Seat	14/05/1974	Avenger VI Medium Line
72294450	Assy Frame Complete Front Seat (Fixed) RH	09/10/1974	Avenger
72294451	Assy Frame Complete Front Seat (Fixed) LH	09/10/1974	Avenger
72290154	Assy Frame Complete Front Seat RH	05/12/1973	Avenger 2 Door 5 Series
72290155	Assy Frame Complete Front Seat LH	05/12/1973	Avenger 2 Door 5 Series
S2283760	Scheme Pad Support Frame Front Seat Squab	12/12/1972	928 / Avenger

S2285055	Proposed Modification to Extension Roof to rear Header and Roof Flange	19/03/1973	Avenger Estate	Sheet 1 of 2
S2285055	Proposed Modification to Extension Roof to rear Header and Roof Flange	19/03/1973	Avenger Estate	Sheet 2 of 2
S2286074	G A Front Seat RH GLS and GL Option Head Restraint	10/05/1973	Avenger Saloon	
S2286075	G A Front Seat LH GLS and GL Option Head Restraint	10/05/1973	Avenger Saloon	
72287717	Assy Bonnet	25/03/1974	Avenger	
72281422	Assy Trimmed Complete Rear Squab	26/02/1974	Avenger 4 Door	
72281455	Assy Trimmed Complete Rear Squab	06/03/1974	Avenger 4 Door	
S2285261	Safety Belt Front Upper Mounting Exercise		Avenger 2 Door	
S2295308	Scheme Tunnel Reinforcing Suspension Refinement	27/09/1974	Avenger VII	
72288499	Instruction Drawing Understructure Rear	25/03/1974	Avenger Estate	Sheets 1 and 2
72291810	Instruction Drawing Welding Body Side	26/03/1974	Avenger 2 and 4 Door	
72294302	Assy Trimmed Complete Rear Squab	26/11/1974	Avenger 6 Premium Line	
72294303	Assy Trimmed Complete RR Cushion	24/10/1974	Avenger 6 Premium Line	
72295310	Panel Dash RHD	02/10/1974	Avenger	
72295311	Panel Dash LHD	02/10/1974	Avenger	
S2295335	Scheme Avenger Estate Fuel Filler	13/01/1975	Avenger Estate	
S2295346	Scheme Avenger Estate Fuel Filler	20/12/1974	Avenger Estate	
72295579	Assy Trimmed Complete Rear Cushion	26/11/1974	Avenger	
72295585	Assy Trimmed Complete Rear Squab	26/11/1974	Avenger	
72282711	Assy Trimmed Complete Rear Squab	26/02/1974	Avenger 2 Door	
72294019	Assy Trimmed Complete Front Seat (Fixed)	22/05/1974	Avenger Series VI Medium Line	
72294198	Assy Trimmed Complete Front Seat RH (Option)	24/08/1974	Avenger Series VI Medium Line	
72294199	Assy Trimmed Complete Front Seat LH (Option)	24/08/1974	Avenger Series VI Medium Line	
72291124	End Cap lower Rear Wing RH	04/06/1974	Avenger	Sheets 1 and 2
72291125	End Cap lower Rear Wing LH	04/06/1974	Avenger	Sheets 1 and 2
72291300	End Cap Upper Rear Wing RH	07/05/1974	Avenger 4 Door	

72291301	End Cap Upper Rear Wing LH	07/05/1974	Avenger 4 Door	
72288701	Section Drawing Seal	28/06/1974	Avenger	
72291942	Assy Body Side RH (Spot Welding list)	11/10/1974	Avenger Estate	72293448 Sweden only
72291943	Assy Body Side LH (Spot Welding List)	11/10/1974	Avenger Estate	72293449 Sweden only
72293098	Pad Front Seat Squab	23/08/1974	Avenger (6/R4-00-MHP-41,45-LR)	
72287694	Glass Backlight	12/02/1974	Avenger VI	
72287695	Glass Backlight Tinted	12/02/1974	Avenger VI	
72264822	Trimmed Assy Individual Front Seat Complete RH	14/07/1970	Avenger Lo-Line	
72264823	Trimmed Assy Individual Front Seat Complete LH	14/07/1970	Avenger Lo-Line	
72276788	Panel Inner Tailgate	11/05/1972	Avenger Estate	Sheet 2 of 2
72288426	Panel Radiator and Horn Mounting LH	09/01/1974	Avenger Series 7	
72288427	Panel Radiator Mounting LH	14/01/1974	Avenger Series 7	
72288494	Assy Body Side RH	26/03/1974	Avenger 4 Door Saloon	
72288495	Assy Body Side LH	26/03/1974	Avenger 4 Door Saloon	
72288498	Assy Understructure Rear (Spot Weld List)	25/03/1974	Avenger Estate	
72291362	Assy Rear Bumper Bolted	26/04/1974	Avenger 6 (Mk 2)	
72291363	Assy Rear Bumper Bolted	26/04/1974	Avenger 6	
72291364	Assy Rear Bumper Bolted	26/04/1974	Avenger 6 (Mk 2)	
72291365	Assy Rear Bumper Bolted	26/04/1974	Avenger 6 (Mk 2)	
S2287659	Scheme Di Cast Filler Pieces Rear Wing	20/11/1973	Avenger 6	
S2283321	Scheme Moulded Pad Front Seat Cushion	23/11/1972	Avenger (928)	
S2283970	Scheme Seat Belt Anchorage Rear Quarter Inner	18/01/1973	Avenger 2 Door	
X2283674	Pad Squab Front Seat	27/09/1973	Avenger (928)	
72291870	Drilling Instruction Drg Body Complete, Grille and Lamp Surround	02/08/1974	Avenger	
S72288375	Heaslamp Assy Avenger 6		Avenger 6	
71260528	Cable Harness RHD	27/05/1970	Avenger	
71260529	Cable Harness LHD	19/05/1970	Avenger (B Model)	
71260531	Cable Harness LHD	22/05/1970	Avenger (B Model)	
71260541	Housing Face Vent RH	21/05/1970	Avenger	
71260542	Housing Face Vent LH	21/05/1970	Avenger	

72291826	Instruction Drawing Assy Engine Compartment and Main Floor RHD	05/06/1974	Avenger VI	Sheets and 2	1
72291827	Instruction Drawing Assy Engine Compartment and Main Floor LHD	05/06/1974	Avenger VI	Sheets and 2	1
2274195	Layout Front Seats		Avenger Lo-Line		
S2291719	Scheme Pad Cushion Front Seat	10/09/1974	Avenger Series VI High and Med Line		
S2294017	Sub Scheme Rear Seat Cushion Springcase	14/08/1974	Avenger 4 Door Series VI		
23034300	Panel Cover Back Front Squab	09/03/1974	Avenger		
23034600	Border Cover Main Front Cushion	19/06/1974	Avenger 2 Door		
23038200	Panel Back Cover Front Squab (Fold Forward and Recline)	18/03/1974	Avenger 2 Door		
72288706	Assy Squab Frame Fold Forward Recline Centre Lock Front Seat RH	12/11/1973	Avenger 2 Door		
72288707	Assy Squab Frame Fold Forward Recline Centre Lock Front Seat LH	12/11/1973	Avenger 2 Door		
72288708	Assy Mechanisum Fold Forward Recline Centre lock Front Seat RH	27/11/1973	Avenger 2 Door		
72288709	Assy Mechanisum Fold Forward Recline Centre lock Front Seat LH	27/11/1973	Avenger 2 Door		
72290202	Assy Trimmed Complete Individual Front Seat RH	09/01/1974	Avenger 2 Door Lo-Line		
72290203	Assy Trimmed Complete Individual Front Seat LH	09/01/1974	Avenger 2 Door Lo-Line		
72291238	Cutting instruction Drawing	17/04/1974	Avenger 2 Door Lo and Med Line		
72291651	Cutting Instruction Drawing	28/03/1974	Avenger 2 Door (Recline)		
72254198	Panel Outer Tailgate	25/07/1969	Avenger Estate	Sheet 2 of 2	
72291832	Instruction Drawing Welding Body Side	18/06/1974	Avenger 2 Door		
20021400	Assy Complete Parcel Tray RHD	13/06/1974	Avenger VI		
20021500	Assy Complete Parcel Tray LHD	13/06/1974	Avenger VI		
72288490	Panel Front Wing RH	08/04/1974	Avenger Saloon and Estate	Sheets and 2	1
72288491	Panel Front Wing LH	08/04/1974	Avenger Saloon and Estate	Sheets and 2	1
72291830	Assy Body Side (Spot Weld List) RH	19/06/1974	Avenger 2 Door		
72291831	Assy Body Side (Spot Weld List) LH	19/06/1974	Avenger 2 Door		
S2283075	Scheme Pads and Wire Pad Support Front Seat Squab	23/11/1972	928/Avenger		
S2284436	Scheme Assy of Squab Pad, Support Frame to Squab Tube	29/01/1973	Avenger	Sheet 1 of 2	

S2284436	Scheme Assy of Squab Pad, Support Frame to Squab Tube	29/01/1973	Avenger	Sheet 2 of 2
S2284444	Scheme Rationalised Front Seat Frame (Fixed Squab)	26/01/1973	Avenger Lo-Line	
S2291217	Layout Front Seat Frame Assy (Adj) LH Seat Frame	19/03/1974	Avenger Hi-Line	
S2294783	General Arrangement Rear Seat Complete	30/12/1974	Avenger Series 7 DL Estate	
72291788	Assy Springcase Rear Cushion (Instalastic)	17/11/1975	Avenger Series 6	
S2288471	Scheme Mod Rear Panel 'B' Car Estate 6 Series	03/04/1974	Avenger Estate 6 Series	
X2266008	Proposed Trunk floor Changes Ect. 'B' Body	15/01/1970	Avenger	Sheet 1 of 3
X2266008	Proposed Petrol Filler Pipe Cover		Avenger	Sheet 2 of 3
X2266008	Support Strut Boot Lid Lock Striker		Avenger	Sheet 3 of 3
72291796	Border Cover Main Rear Cushion RH	22/08/1974	Avenger	
72291797	Border Cover Main Rear Cushion LH	22/08/1974	Avenger	
72292091	Panel Insulation Rear Squab	19/12/1975	Avenger	
72293142	Assy Cover Complete Rear Cushion	19/07/1974	Avenger Estate	
72288360	Panel 'B C' Post Closing RH	02/01/1974	Avenger Saloon and Estate	
72288361	Panel 'B C' Post Closing LH	02/01/1974	Avenger Saloon and Estate	
72290990	Cover Trim Pad Rear Quarter Lower RH	31/12/1973	Avenger	
72290991	Cover Trim Pad Raer Quarter Lower LH	31/12/1973	Avenger	
72291322	End Cap Upper Rear Wing RH	06/05/1974	Avenger 2 Door	
72291322	Layout Surface Rear Wing End Cap Upper RH	11/12/1973	Avenger	Sheet 1 of 2
72291323	End Cap Upper Rear Wing LH	06/05/1974	Avenger 2 Door	
72291323	Layout Surface Rear Wing End Cap Upper LH	11/12/1973	Avenger	
S23020000	Scheme Reclining Front Seat with Avenger Pads	17/06/1975	Imp Premium Line	
S23020000	Scheme Reclining Front Seat with Avenger Pads	17/06/1975	Chrysler United Kingdom	
71241179	Borg Warner Type 35 Assembly	28/06/1968	Avenger	
71241180	Converter Housing (Sheet 1)	06/10/1970	Avenger	
71241180	Converter Housing Casting (Sheet 2)	06/10/1970	Avenger	
71241181	Extension Housing Borg Warner (Sheet 1)	07/12/1970	Avenger	
71241181	Extension Housing Borg Warner (Sheet 2)	07/12/1970	Avenger	



71241306	Upper Pressing Fuel Tank	25/02/1969	Avenger
71241307	Bottom pressing Fuel Tank	19/02/1969	Avenger
71241308	Fuel Tank Assembly	04/03/1969	Avenger
S1241356	Proposed Installation of 11.00 Dia Brake Drum in 'B' Venicle Front Suspension Unit	05/09/1968	Avenger
71240907	Front Main Bearing Cap	10/10/1972	Avenger
71240908	Inner Main Bearing Cap (See 71240907)	10/10/1972	Avenger
71240909	Centre Main Bearting Cap (See 71240907)	10/10/1972	Avenger
71240910	Inner Main Bearing Cap (See 71240907)	10/10/1972	Avenger
71240911	Rear Main Bearing Cap (See 71240907)	10/10/1972	Avenger
71240920	Exhaust Manifold	18/02/1967	Avenger
X1259838	Windscreen Wiped Areas, Federal		Avenger
71248553	Cover Timing (sheet 1)	10/06/1969	Avenger (B Vehicle)
71248553	Cover Timing (sheet 2)	11/06/1969	Avenger (B Vehicle)
71245521	Camshaft	28/02/1969	B Vehicle Avenger
71241005	Air Filter Assembly	05/08/1968	Avenger
71241053	Long and Cross Sectional Arrangement 'B' Engine 1500cc	09/05/1969	Avenger
71241053	Long and Cross Sectional Arrangement 'B' Engine 1500cc	09/05/1969	Avenger
71241054	Long and Cross Sectional Arrangement 'B' Engine 1250cc	15/05/1969	Avenger
71241054	Long and Cross Sectional Arrangement 'B' Engine 1250cc	15/05/1969	Avenger
71241055	Installation Drawing Engine Complete	25/07/1973	Avenger 1300cc and 1600cc
71241100	Gearbox Casting	06/04/1970	Avenger
71241100	Gearbox Casting	06/04/1970	Avenger
71241100	Gearbox Casting	13/04/1970	Avenger
71241152	Differential Box Rear Axle	12/03/1970	Avenger
X1241021	Crankshaft (1800cc)	20/03/1969	Avenger 1800cc?
X1241068	Assembly Sump (1800cc)	09/09/1968	Avenger 1800cc?
71241968	Rear Panel	16/03/1968	Avenger
71241970	Case assembly	25/01/1969	Avenger
71241981	Side Panel RH	25/01/1969	Avenger
71241982	Side Panel LH	25/01/1969	Avenger
71241986	Heater Assembly	16/08/1968	Avenger
72253430	Valance Front Seat RH	09/07/1969	Avenger
72253431	Valance Front Seat LH	09/07/1969	Avenger

72252101	Panel Assy Front Squab Cover Face (Welded)	13/01/1969	Avenger (B)	Sheet 1 of 2
72252101	Panel Assembly Front Squab Cover Face (Welded)	13/01/1969	Avenger (B)	Sheet 2 of 2
72253767	Drip Molding Finisher Front Right Hand	04/10/1968	Avenger DL	
72253862	Cover Crash Roll RHD	30/04/1970	Avenger ?	
72253866	Reinforcing Panel Support - Crash Roll	12/09/1968	Avenger	
S2253819	Rear Door Assy	17/05/1968	Avenger	
S2294780	Proposed Installation of Modified Avenger 6 Series Front Seat In Arrow Saloon	11/10/1974	Arrow	
72295628	General Arrangement Front Seat (Fold and Recline) RHD	21/11/1974	Avenger 2 Door Hi-Line	
S2278477	Avenger Front Seat Frame with Modified Pedastal	03/03/1972	Avenger	
S2284911	Scheme Layout-Pad Overlay-Front Seat Squab		Avenger	
S2285006	Scheme Rationalised Door Handles		Avenger 5	
S2292092	Fixed Front Seat Medium Line (4 Door)	02/04/1974	Avenger Series 6	
S22A64858	Layout Front Seat B Hi Line Saloon 4 Door	26/02/1973	Avenger	
X2283654	Right Hand Frame Pad Support Front Seat Squab	29/11/1972	Avenger	
X2284445A	Frame Pad Support Front Seat Squab		Avenger	
72251349	Pad Front Seat Cushion	10/11/1968	Avenger	
72251775	Panel Assy Rear Cushion Cover Top	21/12/1968	Avenger	
72251776	Panel Assy Rear Squab cushion Face	01/01/1969	Avenger	
72251800	Border Front Cushion Cover Main	18/01/1968	Avenger High Line	
72251848	Pad Front Seat Cushion	07/11/1968	Avenger	
72251874	Border Front Cushion Cover Main	14/01/1969	Avenger	
72251876	Panel Front Squab Cover Face Side RH	13/01/1969	Avenger	
72251900	Assy Body Less Doors RHD	06/09/1967	Avenger	
72250395	Panel Gearbox Cover	19/04/1967	Avenger Auto	
72250408	Panel Bonet Locking Platform	08/01/1974	Avenger/Sunbeam	
72250410	Panel Mounting Headlamp and Radiator RH	12/05/1967	Avenger	
72250416	Lower D Post RH	03/05/1967	Avenger 4 Door	
72250446	Reinforcement Trunk Floor RH	16/06/1967	Avenger Saloon	
72250486	Headlamp Mounting Panel (Twin) RH	30/10/1967	Avenger GL/GT	

72250492	Panel Facia - Form and Common Piercings	11/01/1968	Avenger	
72250493	Facia Panel Pressing	07/02/1968	Avenger	
71260575	Assy Instument Unit	09/06/1970	Avenger	
23045000	Assemby Panel Rear Squab	12/11/1974	Avenger ?	
71262443	Heater Ventilator Unit	05/03/1971	Avenger	
72250096	Windscreen Aperture and Plenum Panel	14/12/1966	Avenger Saloon and Estate	
72251704	Panel Assy Front Squab Cover Face Sheet 1	10/01/1969	Avenger DL	
72251715	Panel Assy Front Cushion Cover Top Sheet1	07/01/1969	Avenger DL	
72251728	Rear Sear Cushion Cover Sheet 1	09/12/1968	Avenger DL	
72251745	Pad Rear Squab	22/10/1968	Avenger	
72251749	Rear Squab Seat Cover Sheet 1	04/12/1968	Avenger DL	
72251753	Rear Seat Squab Cover Sheet 1	22/01/1968	Avenger GL and GT	
72251774	Panel Assy Front Cushion Top Sheet 1	10/01/1969	Avenger Super	
206722-00	Homologation Drawing Fuel Tank	04/10/1976	Avenger Mk2	
72520369	Insulation Wheel Arch Rear	23/04/1974	Avenger	
72251612	Trimmed Assy Individual Front Seat Complete RH	09/10/1968	Avenger G L and G T	
72251614	Rear Squab Complete D L	14/06/1967	Avenger	Superceded 72264618-9
72251615	Rear Squab Complete Super	14/06/1967	Avenger	
72251616	Spring Case Assy Rear Seat Squab	21/11/1968	Avenger	
72251672	Trimmed Assy Individual Front Seat Complete	12/01/1968	Avenger D L	
72251676	Front Seat Frame	24/10/1968	Avenger	
72251677	Front Seat Frame	29/10/1968	Avenger	
72251680	Front Seat Frame - Reclining RH	08/11/1968	Avenger G L and G T	
72253283	Front Seat Cushion Cover	15/07/1968	Avenger Super	
72250901	Underbody, Master Gig Locations and Tolerances	15/08/1967	Avenger	
72250902	Body Less Doors - Master Gig Location	11/07/1967	Avenger	
72250903	Paint Process, Arrangement (Drainage)	02/08/1967	Avenger	
72251008	Assembly Body Side RH	24/07/1967	Avenger	
72251605	Spring Case Assy Rear Seat Cushion	22/11/1968	Avenger	High, Medium and Low Line
72251606	Trimmed Assy Rear Cushion Complete Low Line	12/11/1968	Avenger	

72251610	Trimmed Assy Individual Front Seat Complete Medium Line	Nov 01 1968	Avenger	Up To and 3rd Year
----------	---	-------------	---------	--------------------

### 3 Negatives Drawer 1.

Some highlights of this set include:

:

Negative No	Description	Date	Model	Notes
	Following have AF Prefix			
19	Neg-Strip 19 to 30 Car Lights in the Dark?	07/12/1970		Cassette Pot
20	Neg-Strip1A to 33A Mainly Car Lights in the Dark?	07/12/1970		Cassette Pot
21	1of3 Kodak Frames Car lights on dark open road Early Morning	08/12/1970		Cassette Pot
21	2of3 Kodak Car running/Parked on open road early morning	08/12/1970		Cassette Pot
21	3of3 Unkown Film 3 Photos thro Windscreen	08/12/1970		Cassette Pot
22	Neg-Strip of Ilford Film Car lights on dark conditions open road	08/12/1970		Cassette Pot
23	1of 2 Neg-Strip of Ilford Film Car on/parked road Scenery	08/12/1970		Cassette Pot
23	2of2 Kodak Frames Car with lights on Dark Early Morning	08/12/1970		Cassette Pot
	Following have B prefix			
218	B Car Timing Summary			
	Following have C prefix			
2	Arrow Hunter Crash Test G12		Arrow	
4	Arrow Hunter Crash Test Doors Open		Arrow	
5	Arrow Hunter Crash After Test G12		Arrow	
6	Arrow Hunter Crash Test G12		Arrow	
7	Arrow Hunter Crash Test G12 Driver Position		Arrow	
8	Arrow Hunter Crash Test G12 Rear View		Arrow	
9	Arrow Hunter Crash Test G12 Rear View		Arrow	
10	Arrow Hunter Crash Test G12 Under Drivers Position		Arrow	
11	Arrow Hunter Crash After Test G12 Front Wheel		Arrow	

12	Arrow Hunter Crash After Test G12 Front SideFront Wheel	Arrow
13	Arrow Fastback Crash Test G18	Fastback
14	Arrow Fastback Crash After Test G18	Fastback
15	Arrow Fastback Crash After Test G18	Fastback
16	Arrow Fastback Crash Test Rear View	Fastback
17	ARROW Fastback Crash After Test Driver Position	Fastback
18	ARROW Fastback Crash After Test Passenger Position	Fastback
19	Arrow Fastback Crash After Test Above Bonnet	Fastback
20	Arrow Fastback Crash After Test G18 Front Wheel	Fastback
21	Arrow Fastback Crash After Test G18 Front Wheel	Fastback
22	Arrow Fastback Crash Test G18	Fastback
23	Arrow Fastback Crash Test G18	Fastback
24	Arrow Fastback Crash Test G18 Door Open	Fastback
25	Arrow Fastback Crash Test G18 Door Open	Fastback
26	Arrow Fastback Crash Test Rear	Sunbeam
27	Arrow Fastback Crash Test Passen- ger Position	Fastback
28	Arrow Fastback Crash Test Front View	Fastback
29	Arrow Fastback Crash Test Rear View	Sunbeam
30	Arrow Fastback Crash Test Driver Position	Fastback
31	Arrow Fastback Crash Test Front Near Side	Fastback
32	Arrow Fastback Crash Test Rear Near Side	Fastback
33	Arrow Fastback Crash Test Mirror Driver Position	Fastback
34	Arrow Fastback Crash After Test G19 Near Side View	Fastback
36	Arrow Fastback Crash After Test G19 Side View	Fastback
37	Arrow Fastback Crash After Test Front near view	Fastback
38	Arrow Fastback Crash After Test G19 Off side view	Fastback

39	Arrow Fastback Crash After Test Near side front	Fastback	
40	ARROW Fastback Crash After Test Driver Position	Fastback	
41	ARROW Fastback Crash After Test Passenger Position	Fastback	
42	Arrow Fastback Crash After Test G19 Driver Position	Fastback	
43	Arrow Fastback Crash Test Rear View	Sunbeam	
44	After Crash Test		
45	After Crash Test		
46	After Crash Test Windscreen		
47	Crash Test Trackway to rear		
48	Gearbox		
49	Vehicle Underside		
50	Arrow Fastback Crash Test Near- side and Tripod	Fastback	Ektacolour
51	3D View of Striker Bolt Plate As- sembly		
52	3D View of Door Panel Assembly		
53	3D View of Door Panel Assembly		
54	3D View of striker Bolt Assembly		
55	Lock Cylinder and Latch Proposal Glove Box Sketch		No
56	Arrow Fuel Tank	Fastback	
57	Arrow Crash After Test Underneath Front		
58	Arrow Crash After Test Underneath Front		
59	Arrow Crash After Test Underneath Steering Rods		
60	Arrow Crash After Test General un- derneath view		
61	Arrow Crash After Test G28 Near- side Front		
62	Arrow Crash Test Dash and below		
63	Arrow Fastback Crash Test G28 General Offside View	Fastback	
64	Arrow Fastback Crash Test G28 Boot Open	Sunbeam	
65	Arrow Crash After Test Bonnet		
66	Arrow Crash After Test Forward Front Seating		
67	Arrow Crach Test G28 Front near- side wheel area		
68	Arrow Crash After Test Windscreen on Bonnet		

69	Arrow Crash After Test Dash Wind-screen on Bonnet		
70	Arrow Fastback After Test G2? View Nearside rear	Fastback	
71	Arrow Crash Test Driver Position		
73	Arrow Fastback Crash Test G28 View nearside	Fastback	
74	Arrow Fastback Crash After Test G28 View nearside	Fastback	
75	Arrow Crash After Test Driver Position	Fastback	
76	Arrow Fastback Crash After Test G28 View offside	Fastback	
77	Crash Test G33 View underneath Exhaust Box		
78	Crash Test View Engine compartment		
79	Sketch Proposal GandF Series Glove Box Doors		374-F-309
80	Arrow Fastback Crash G32 View nearside	Fastback	
81	Arrow Fastback Crash After Test G3? View Nearside	Fastback	
82	Arrow Fastback Crash Test G32 View offside	Fastback	
83	Arrow Fastback Crash G32 View Offside	Fastback	
84	Arrow Fastback Crash After Test G32 View Offside wing	Fastback	
85	Arrow Fastback Crash After Test G32 View Nearside wing	Fastback	
86	Arrow Fastback Crash After Test View of rear	Sunbeam	
87	Arrow Fastback Crash Test Driver Position		
88	Arrow Fastback Crash After Test under Steering Position		
89	Arrow Fastback Crash After Test Rear Seating		
90	ARROW Fastback Crash After Test Driver Position		
91	ARROW Fastback Crash After Test Driver Position		
92	ARROW Fastback Crash After Test Driver Position		
93	Arrow Fastback Crash After View above Bonnet		

94	Californian G37 Crash Test (JHP 492E)	Imp Californian	
94	Californian G37 Crash Test (JHP 492E)	Imp Californian	
95	Californian G37 Crash Test (JHP 492E)	Imp Californian	
95	Californian G37 Crash Test (JHP 492E)	Imp Californian	
96	Californian G37 Crash Test (JHP 492E)	Imp Californian	
97	Californian G37 Crash Test (JHP 492E)	Imp Californian	
98	Californian G37 Crash Test (JHP 492E)	Imp Californian	
99	Californian G37 Crash Test (JHP 492E)	Imp Californian	
100	Imp Coupe Crash Test G37 View nearside	Imp Coupe	
101	Californian G37 Crash Test (JHP 492E)	Imp Californian	
102	Californian G37 Crash Test (JHP 492E)	Imp Californian	
103	Californian G37 Crash Test (JHP 492E)	Imp Californian	
104	Californian G37 Crash Test (JHP 492E)	Imp Californian	
105	Californian G37 Crash Test (JHP 492E)	Imp Californian	
106	Californian G37 Crash Test (JHP 492E)	Imp Californian	
107	Californian G37 Crash Test (JHP 492E)	Imp Californian	
108	Photo small ? Detail		
109	Photo small ? Detail		
110	Photo small ? Detail		
111	Arrow Fastback Crash After Test G32 View nearside corner		Color Photo
112	Photo outside Damaged car on side		
113	Photo outside Damaged car on side View under engine		
114	Photo outside Damaged car on side View under engine		
115	Photo outside Damaged car F?? View on nearside wing		
116	Arrow Fastback Damaged Car F17 View Offside	Fastback	
117	Arrow Fastback Damaged Cars F7 and F14 nearside	Sunbeam	



118	Photo outside crash car View on front wing		
119	Photo outside crash car View of front		
120	Photo outside crash car View of front		LHP 680F
121	Arrow Fastback Damaged Cars F14 and F17 Offsides	Fastback	
122	Arrow Fastback Damaged Car F?4 View Offside wing		
123	Arrow Fastback Damaged Car F?? View nearside wing		
124	Arrow Fastback Damaged Car F14 View nearside	Fastback	
125	Note 10 color transparencies Imp G44 with dummy @MIRA 30/1/69	Imp	
126	Photo crashed car View under engine		
127	Crashed Car G32 View underside Engine/Gearbox		
128	Crashed Car G32 View inside of Front WheelEngine/Gearbox		
129	Crashed Car G32 View on underside		
130	Crashed Car View inside of Wheel		
131	Crashed Car G28 View on underside		
132	Crashed Car G28 View on underside of engine		
133	Crashed Car G28 View on underside of engine		
134	Crashed Car G28 View on underside of engine		
135	Imp 44 Crash Test	Imp	
136	Imp 44 Crash Test	Imp	
137	Imp 44 Crash Test	Imp	
138	Imp 44 Crash Test	Imp	
139	Imp 44 Crash Test	Imp	
140	Imp Crash Test G4 Driver Position	Imp	2 same Number
140	Imp After Crash Test G44 Driver Position	Imp	
141	Imp 44 Crash Test	Imp	
142	Imp 44 Crash Test	Imp	
143	Imp 44 Crash Test	Imp	
144	Imp 44 Crash Test	Imp	
145	Imp 44 Crash Test	Imp	
146	Imp 44 Crash Test	Imp	
147	Imp 44 Crash Test	Imp	
148	Imp 44 Crash Test	Imp	

149	Imp 44 Crash Test	Imp	
150	Imp Husky G48 Crash Test	Imp Husky	
151	Imp Husky G48 Crash Test	Imp Husky	
152	Imp Husky G48 Crash Test	Imp Husky	
153	Imp Husky G48 Crash Test	Imp Husky	
154	Imp Husky G48 Crash Test	Imp Husky	
155	Imp Husky G48 Crash Test	Imp Husky	
156	Imp Husky G48 Crash Test	Imp Husky	
157	Imp Husky G48 Crash Test	Imp Husky	
158	Imp Husky G48 Crash Test	Imp Husky	
159	Imp Husky G48 Crash Test	Imp Husky	
160	Imp Husky G48 Crash Test	Imp Husky	
161	Imp Husky G48 Crash Test	Imp Husky	
162	Imp Husky G48 Crash Test	Imp Husky	
163	Imp Husky G48 Crash Test	Imp Husky	
164	Imp Husky G48 Crash Test	Imp Husky	
165	Imp Husky G48 Crash Test	Imp Husky	
166	Imp Husky G48 Crash Test	Imp Husky	
167	Imp Husky G48 Crash Test	Imp Husky	
168	Imp Husky G48 Crash Test	Imp Husky	
169	Imp Husky G48 Crash Test	Imp Husky	
170	Imp Husky G48 Crash Test	Imp Husky	
171	Imp Husky G48 Crash Test	Imp Husky	
172	Arrow Fastback Crash Test G53 View before of nearside	Fastback	
173	Arrow Fastback Crash G53 View nearside	Fastback	
174	Arrow Fastback Crash After Test G53 nearside	Fastback	
219	Photo of Car Interior		
220	Photo of Engine Bay Battery		
221	Photo of Fuel Tank		JKV 670E
222	Photo of Fork End		
223	Arrow Fastback Crash GR83 View of rear	Sunbeam	JKV 670E
224	Arrow Fastback LHD Crash G86 Driver Position		
225	Arrow Fastback LHD After Crash Test Driver Position		
226	Photo of Fuel Tank		
227	Arrow Fastback LHD Crash G86 Driver Position		
228	Arrow LHD After test G86 View front offside		
229	Arrow LHD After test G86 View of windscreen area		
230	Arrow LHD After test G86 View front seating area		

231	Arrow LHD Fastback Crash After Test G86 Nearside	Sunbeam
232	Arrow LHD Fastback Crash Before Test G86 Nearside	
233	Arrow LHD Fastback Crash After G86 Offside	
234	Arrow LHD Fastback Before Crash G86 nearside	
235	Arrow LHD Fastback After Crash G86 Driver Position	
236	Arrow LHD After test G86 View front	
237	Arrow LHD After test G86 View over bonnet	
238	Arrow LHD Fastback After Crash G86 View nearside	
239	Arrow Fastback Before Crash 86 View nearside	
240	Arrow LHD Fastback After Crash G86 Driver Position	
241	Engine Compartment	
242	Avenger Rear View	Avenger
243	Avenger Side View	Avenger
244	Avenger Rear View	Avenger
245	Avenger Side View	Avenger
246	View under Gearbox	
247	Avenger Before Test G92 nearside	Avenger
248	Avenger Before Test G92 offside	Avenger
249	Avenger Before Test G92 Wind-screen area	Avenger
250	Avenger LHD Before Test G92 above bonnet	Avenger
251	Avenger LHD Test G92 Windscreen area	Avenger
252	Avenger LHD Test G92 Driver position	Avenger
253	Avenger LHD Test G92 Driver position	Avenger
254	Avenger LHD Test G92 Front seating area	Avenger
255	Avenger LHD Test G92 Rear seating area Camera	Avenger
256	Avenger LHD After Test G92 Nearside	Avenger
257	Avenger LHD After Test G92 Above Windscreen	Avenger
258	Avenger LHD After Test G92 View from Offside/Windscreen	Avenger

259	Avenger LHD After Test G92 Off-side	Avenger
260	Avenger LHD After Test G92 Off-side wing	Avenger
261	Avenger LHD After Test G92 Near-side wing	Avenger
262	Avenger LHD After Test G92 Near-side	Avenger
263	Avenger LHD After Test G92 Driver position	Avenger
264	Avenger LHD After Test G92 Driver Position	Avenger
265	Avenger LHD After Test G92 View from Front	Avenger
266	Avenger LHD After Test G92 View under engine bay	Avenger
267	View under Gearbox Prop shaft	
268	Avenger LHD After Test G92 View under sump	Avenger
269	View on inside of front wheel After Test	
270	View under gearbox and Silencer	
271	Avenger LHD After test G92 View above engine bay	Avenger
273	Damage detail	
274	Several Damage cars outside	
275	Avenger LHD After Test G92 View of Battery Engine Bay	Avenger
276	Avenger LHD After Test G92 View of Battery Engine Bay	Avenger
277	View of Pedals	
278	View in front of seats	
279	Damage detail	
280	Damage detail	
281	Avenger LHD After Test G92 View of Steering Rack	Avenger
282	Avenger LHD After Test G92 Damage Detail	Avenger
283	Avenger LHD After Test G92 Damage inside front wheel	Avenger
284	View of Damage Gearbox Prop shaft	
285	View of Damage Steering rack and trackrod	
286	View of Damage under diff	
287	View of Damage Steering rack and trackrod	

288	Avenger LHD After Test G92 View on underside	Avenger	
289	Avenger LHD After Test G92 View on front underside	Avenger	
290	2 views of Lorry cab and drivers position		Water damaged neg
291	2 views of Lorry cab and drivers position		Water damaged neg
292	View of loory cab for near side		Water damaged neg
293	2 views of Damaged lorry cab		Water damaged neg
294	3 views of Lorry cab		Water damaged neg
295	2 Vews of vehicles and people		Water damaged neg
296	2 Views of Vechicles "Frank Grounds"		Water damaged neg
297	Commer Lorry? 9937 E Front Damaged	Commer	Water damaged neg
298	Bond? Minicar Under Artic Trailer damaged	Bond?	Water damaged neg
299	3 Photos Artic Lorry inc Road Scene		Water damaged neg
300	2 Photos of Lorry Cab		Water damaged neg
301	Damage Detail		
302	Damage detail Engine bay or boot		
303	Damage detail Engine bay or boot		
304	Detail damage Car		
305	Grills G9 Multi 2/3 photo exposure sequence		
306	Grills G9 Multi 2/3 photo exposure sequence		
307	Grills G9 Multi 2/3 photo exposure sequence		
308	Grills G9 Multi 2/3 photo exposure sequence		
309	Grills G9 Multi 2/3 photo exposure sequence		
310	Grills G9 Multi 2/3 photo exposure sequence		
311	Grills G9 Multi 2/3 photo exposure sequence		
312	Grills G9 Multi 2/3 photo exposure sequence		53737
313	Arrow Fastback After Crash Test H7 Offside	Fastback	

314	Arrow Fastback Before Crash H7 Offside	Fastback
315	Arrow Fastback Before Crash H7 Nearside	Fastback
316	Arrow Fastback After Crash Test H7 Nearside	Fastback
317	Close up of steering wheel and roof above	
318	Arrow Fastback LHD After Test H7 Drivers position and bonnet	Fastback
319	Arrow Fastback LHD After Test H7 Over windscreen	Fastback
320	Arrow Fastback After Test H7 Boot	Fastback
321	Arrow Fastback After test H7 Rear Seating	Fastback
322	View of Driving Position	
323	Arrow Fastback LHD Test H7 Passenger side	Fastback
324	Arrow Fastback LHD After Test H7 Passenger side	Fastback
325	Arrow Fastback LHD Test H7 Over windscreen	Fastback
326	Arrow Fastback LHD After Test H7 Through windscreen	Fastback
327	Arrow Fastback LHD After Test H7 nearside front	Fastback
328	Arrow Fastback LHD After Test H7 All car from nearside	Fastback
329	Arrow Fastback Engine compartment	
330	Arrow Fastback LHD Windscreen	
331	Arrow Fastback LHD After Test H7 Offside Front	Fastback
332	Arrow Fastback LHD After Test H7 Underside	Fastback
333	Arrow Fastback LHD After Test H7 Underside front	Fastback
334	Avenger Before Crash Test H18 Offside	Avenger
335	Avenger Crash Test H18 Offside	Avenger
336	Avenger Crash Test H18 Offside front	Avenger
337	Avenger Crash Test H18 nearside	Avenger
338	Avenger Drivers position	Avenger
339	Avenger before test H18 near side	Avenger
340	Avenger After Test H18 nearside view	Avenger
341	Underside view of steering	

342	Avenger Test H18 Engine Bay	Avenger
343	Avenger After Test H18 nearside front view	Avenger
344	Avenger Test H18 View above Roof	Avenger
345	Avenger Test H18 Front	Avenger
346	Avenger After Test H18 View above roof	Avenger
347	Avenger Test H18 Drivers Position	Avenger
348	Avenger Test H18 Drivers Position	Avenger
349	Avenger Test H18 Rear View Towing Strop	Avenger
350	Under side of Engine	
351	Under side of Gearbox	
352	Wheel to Body	
354	Under side of Gearbox	
355	Avenger Test H18 Engine Bay	Avenger
356	Wheel to Body	
357	Avenger Test H18 Fuel Filler	Avenger
358	Detail	
359	Detail Spring and Exhaust	
360	Avenger After Test H18 Front	Avenger
361	Avenger After Test H18 Front	Avenger
363	View of Rear suspension	
364	Avenger After Test H18 Underside	Avenger
365	Avenger After Test H18 Underside Front	Avenger
366	Detail underside Silencer	
367	View of underside Engine and Gearbox	
368	Detail	
369	Detail Spring	
370	Detail Track Rod and Gaiter	
371	Detail underside Exhaust Box	
372	Avenger After Test H18 Engine Bay	Avenger
373	Detail Underside Front to Rear	
376	Detail Underside Differential	
377	Detail Underside Differential Prop Shaft	
378	Detail Tyre to Wheel Arch Gap	
379	Detail Underside Forward to Engine Bay	
380	Detail Underside Silencer forward	
382	Note 382 -399 Colour Slides	
383	Note 382 -399 Colour Slides	
384	Note 382 -399 Colour Slides	
385	Note 382 -399 Colour Slides	
386	Note 382 -399 Colour Slides	
387	Note 382 -399 Colour Slides	

388	Note 382 -399 Colour Slides		
389	Note 382 -399 Colour Slides		
390	Note 382 -399 Colour Slides		
391	Note 382 -399 Colour Slides		
392	Note 382 -399 Colour Slides		
393	Note 382 -399 Colour Slides		
394	Note 382 -399 Colour Slides		
395	Note 382 -399 Colour Slides		
396	Note 382 -399 Colour Slides		
397	Note 382 -399 Colour Slides		
398	Note 382 -399 Colour Slides		
399	Note 382 -399 Colour Slides		
400	Steering System Impact		Vehicle Pre- sentation
401	Barrier Impact Test H18 Results?	Avenger	Vehicle Pre- sentation
402	Barrier Impact Test Results?		
403	Note 403 to 407 Colour Slides		
404	Note 403 to 407 Colour Slides		
405	Note 403 to 407 Colour Slides		
406	Note 403 to 407 Colour Slides		
407	Note 403 to 407 Colour Slides		
408	Avenger Test H33 Offside		Neg 12A
409	Color Neg H33 Front Compartment		Neg 11A
410	Colour Neg People around Yellow Avenger H33		33794
411	Colour Neg Test H33 Drivers Posi- tion		Neg 9A
412	Colour Neg Avenger Test H33 Peo- ple around	Avenger	Neg 7A
413	Avenger Before Test H33 Nearside	Avenger	Neg 15A
414	Avenger Test H33 Lights and Film- ing	Avenger	Neg 6A
415	Avenger Test H33 Lights and Film- ing	Avenger	Neg 5A
416	Empty		
417	Avenger Before Test H33 Offside	Avenger	Neg 1A
418	Avenger Before Test H33 Rear	Avenger	Neg 2A
419	Avenger Before Test H33 Rear	Avenger	Neg 1
420	Avenger Test HR28 Rear Outside	Avenger	
421	Avenger Test HR26 Rear Damage	Avenger	
422	Detail underside Tailpipe area		
423	Avenger Test HR28 Inside Boot	Avenger	
424	Avenger Test HR28 Inside Boot	Avenger	
425	Avenger Test HR28 Fuel Tank	Avenger	
426	Avenger Test HR 28 Fuel Tank Rear wheel	Avenger	



427	Avenger Test HR28 Inside Boot Offside	Avenger
428	Detail underside Fuel Tank and Filler	Avenger
429	Avenger Test HR28 rear view	Avenger
430	Avenger Test HR28 Offside	Avenger
431	Avenger HR28 Damaged and Collision TRAILER Rig in Field	Avenger
432	Avenger HR28 Damaged and Collision TRAILER Rig H3?	Avenger
433	Avenger HR28 Damaged and Another H3 ?	Avenger
434	Avenger HR28 Damaged and Another H3?	Avenger
435	Avenger H33 LHD 2 Photos of Engine Bay	
436	Detail Underside View Rear forward	
437	Detail Underside View Differential	
438	Detail Underside back of rear wheel	
439	Detail Underside Gearbox and Silencer	
440	Detail Underside Prop Shaft and Silencer	
441	Detail Underside Behind Front Wheel	
442	Detail Underside Front suspension	
443	Detail Underneath	
444	Detail Underneath Front Suspension	
445	Detail of Damage Windscreen Pillar Test ?83	
446	Detail of Damage Windscreen Pillar	
447	Avenger Test H33 Front Damage Offside view	Avenger
448	Avenger Test H33 Front Damage Nearside view	Avenger
449	Avenger Test H33 Front Damage View Front	Avenger
450	Avenger Test H33 View around Fuel Filler	Avenger
451	Detail Around Brake Disc	
452	Detail Underneath Prop Shaft and Silencer	
453	Detail Around Brake Disc	
454	Damage detail onlift Front Underside	
455	View underneath Engine Bay	
456	View underneath Engine Bay	

457	Avenger Test H33 Nearside	Avenger	
458	Avenger LHD H33 Drivers position	Avenger	
459	Avenger LHD H33 Drivers Seat	Avenger	
460	Avenger LHD H33 Drivers position	Avenger	
461	Avenger H33 LHD of Engine Bay	Avenger	
462	Avenger H33 LHD Above Wind- screen and Bonnet	Avenger	
463	Avenger After Test H33 Offside View	Avenger	
464	Avenger After Test H33 Offside Wing View	Avenger	
465	Avenger LHD Test H33 Drivers Po- sition	Avenger	
466	Avenger After Test H33 Offside View	Avenger	
467	Avenger After test H33 Nearside View	Avenger	Print also
468	Avenger Test H33 Offside View	Avenger	
469	Avenger Test H33 Front View	Avenger	
470	Avenger Test H33 Drivers Position	Avenger	
471	Avenger Test H33 Drivers Position	Avenger	
472	Avenger Test H33 Rear View	Avenger	
473	Detail around Wheel Hub		
474	Detail around Wheel Hub		
475	Detail around spare Wheel in Boot		
476	View Underneath Fuel Tank and Diff		
477	Detail ?		
478	Detail Underneath Fuel Tank and Rear Wheel		
479	Detail Underneath		
480	Detail Underneath Fuel Tank and Diff		
481	Detail Underneath Fuel Tank		
482	Detail ?		
483	Detail Windscreen Pillar		
484	Detail Windscreen Pillar		
485	Detail ?		
486	Test HR2? View of Offside Doors		
487	Detail View of Nearside Doors and Windows		
488	Test HR28 View into Boot		
489	Damage view into Boot Offside		
490	View rear of Offside Rear Door and Handle		
491	Detail Shaft Splines		
492	View underneath Gearbox Prop Shaft Silencer		

493	Avenger Test H33 View Underside	Avenger
494	Detail View Under Engine Bay and Front Wheels	
495	Detail Underneath Forward of Prop Shaft	
496	Detail Underneath Springs?	
497	Detail Servo?	
498	Detail Underneath Damper ?	
499	Detail Underneath Damper ?	
500	Detail Chassis ?	
501	Detail Body Joint?	
502	Detail around wheel	
503	Detail Damage Chassis	
504	Avenger LHD Test H33 View of Windscreen Bonnet	Avenger
505	Avenger Test H37 View Offside	Avenger
506	Avenger Test H37 View NearSIDE	Avenger
507	Avenger Test H37 View of Rear	Avenger
508	Avenger Test H37 Drivers position	Avenger
509	Avenger Test H37 Drivers position	Avenger
510	Detail Above Engine Bay	
511	Avenger Test H37 View of Windscreen and Bonnet	Avenger
512	Detail Track Rod and Gaiter Double Image	
513	Detail Underside Gearbox rearward	
514	Avenger Test H37 Front View	Avenger
515	Avenger Test H37 Underside from Front	Avenger
516	Detail inside of Front Wheel	
517	Detail under Engine Bay and inside Front Wheel	
518	Detail Underneath of Diff and Fuel Tank	
519	Detail Underside	
520	Avenger After Test H37 View Near-side	Avenger
521	Avenger After Test H37 View Off-side	Avenger
522	Avenger LHD After Test H37 Drivers Position	Avenger
523	Avenger After Test H37 Offside Front	Avenger
524	Avenger After Test H37 Nearside	Avenger
525	Avenger After Test H37 Windscreen Area	Avenger
526	Avenger After Test H37 View Thro Back to Front	Avenger

527	Avenger After Test H37 Nearside Front	Avenger
528	Avenger After Test H37 View of Bonnet and Windscreen	Avenger
529	Avenger After Test H37 Drivers Position	Avenger
530	Detail Thro Quarter Light	
531	Detail of inside of Nearside Front Wheel	
532	Avenger After Test H37 Front	Avenger
533	Detail of inside of Offside Front Wheel	
534	Detail from above Engine Bay	
535	Detail of Front Seat Backs missing	
536	Avenger Test H37 Drivers position	Avenger
537	Detail Damage nearside Suspension	
538	Detail Damage Bulkhead Area	
539	Detail Rods or Tubes?	
540	Detail ? Underneath	
541	Detail Underneath Rear Spring	
542	Detail Underneath Gearbox	
543	Detail Underneath Gearbox	
544	Detail Underneath Gearbox Support	
545	Detail Underneath Prop Shaft and Silencer	
546	Detail Underneath Prop Shaft and Silencer	
547	Detail Underneath Gearbox and Prop Shaft	
548	Detail Underneath Diff and Drive Shafts	
549	Detail Wheelarch and Door Latch	
550	Door Latch Detail Offside	
551	Door Latch Detail Nearside	
552	Door Hinge Detail Nearside	
553	Door Hinge Detail Nearside Rear	
554	Door post Detail	
555	Avenger Test H58 View of Front	Avenger
556	Avenger Test H58 View of Rear	Avenger
557	Avenger Test H58 View of Nearside	Avenger
558	Avenger Test H58 View Offside	Avenger
559	Avenger LHD H58 View Of Windscreen	Avenger
560	Avenger View of Engine Bay	Avenger
561	Avenger Test Drivers Position	
562	Avenger Test Steering Wheel	

563	Avenger LHD Test H58 View of Dash	
564	Avenger LHD Test H58 Steering Wheel	
565	Detail of Interior	
566	Detail of Interior	
567	Detail of Underside of Engine Bay	
568	Detail Airfilter?	
569	Detail Underside Steering Rack	
570	Detail Underside Steering Rack	
571	Detail Underside Steering Rack	
572	Detail Underside Steering Rack	
574	Avenger After Test H58 Front View	
575	Avenger After Test H58 View Near-side	
576	Avenger After Test H58 View Off-side	
577	Avenger After Test H58 View Off-side Wing	
578	Avenger After Test H58 View Off-side Wing	
579	Detail of Driver Position	
580	Detail Damage Underside Steering Rack	
581	Detail Damage Underside Front Wheel	
582	Detail Damage Underside Front Wheel	
583	Detail Damage Underside Front Wheel	
584	Detail Underside Steering Rack	
585	Detail Underside Steering Rack	
586	Test Damage of Dash	
587	Avenger Test H57 Nearside	Avenger
587	"A" Avenger Damaged Test H57 All Underside	
588	Avenger Damaged Test H57 Near-side	
588	"A" Damage Detail H57 Steering	
589	Detail Drivers Position	
589	"A" Detail of Interior n	
590	Avenger Damaged Test H57 Offside	
590	"A" Damage Detail Engine Bay	
591	Detail of Drivers Position	
591	"A" Detail Underside Gearbox	
592	Test Detail of Drivers Position	
593	Avenger Test H57 Offside Damaged Rear	

594	Avenger Test H57 Offside Damaged Front and Rear	
595	Avenger Test H57 Nearside Damaged Front and Rear	
596	Avenger After Test H57 Nearside Wing	
597	Avenger After Test H57 Offside Wing	
598	Damage Detail Engine Bay	
599	Damage Detail Front Suspension	
600	Damage Detail Engine Bay	
601	Damage Detail Underside Fuel Tank and Diff	
602	Test H57 Damage Detail Underside Engine Bay	
603	Test H57 Damage Detail Underside from Front	
604	Damage Detail Underside Prop Shaft	
605	Detail Dash Area	
606	Detail Drivers Position	
607	Detail Driver and Passenger Seats	
608	Damage Detail Test H58 Gearbox and Prop Shaft	
609	Avenger Damaged Test H58 Underside View	
610	Avenger Damaged Test H58 Front Underside View	
611	Detail Underside of Boot and Diff	
612	Test H58 Graph	
613	Detail Engine Bay	
614	Avenger Before Test H72 Offside View	Avenger
615	Avenger After Test H72 Offside Wing	
616	Avenger After Test H72 Nearside Wing	
617	Test H72 Front Passenger Knees	
618	Avenger After Test H72 Nearside	
619	Avenger After Test H72 Offside	
620	Avenger Test H72 Nearside	Avenger
621	Avenger LHD Test 72 Rear Offide	
622	Avenger LHD Test Dummy Driver	
623	Avenger LHD Test H72 Passengers Knees	
624	Avenger LHD Test H72 Dummy Passenger	

625	Avenger LHD Test H72 Dummy Passenger		
626	Avenger LHD Test H72 Windscreen and Bonnet		
627	Avenger LHD After Test H72 Near-side		
628	Detail Underside of Rear		
629	Detail Underside of Front		
630	Detail of Underside		
682	Lorry under Tower Rig Hanger outside		Envelope
683	Lorry Test C14 Hanging Plate Cab		Envelope
684	Chart of Technical Safety Organisation		Safety
685	Avenger Estate Test H98 Offside	Avenger Estate	
686	Avenger Estate Test H98 Nearside	Avenger Estate	
687	Avenger Estate Test H98 Front	Avenger Estate	
688	Avenger Estate Test H98 Rear	Avenger Estate	
689	Avenger Estate Test H98 Tailgate open		
690	Avenger Estate Test H98 Windscreen and Bonnet		
691	Avenger Estate Test H98 Engine Bay		
692	Avenger Estate Test H98 Drivers Position		
693	Avenger Estate Test H98 Interior		
694	Avenger Estate Test H98 Interior		
695	Avenger Estate Test H98 Front Seating		
696	Avenger Estate After Test H98 Nearside Rear Quarter		
697	Avenger Estate After Test H98 Nearside		
698	Avenger Estate After Test H98 Offside		
699	Detail Damage Drivers Position		
700	Detail Damage After Test H98 Front Seating		
701	Detail Damage Offside Front Wing		
702	Detail Damage Nearside Front Wing		
703	Detail Test H98 Roof and Interior		
704	Detail Test H98 Roof and Interior		
705	Detail Damage Test H98 Engine Bay		
706	Detail Damage Test H98 Front Seating		

707	Detail Damage Test H98 Driver Position	
708	Detail Damage Test H98 Underside Steering and Wheel	
709	Detail Damage Test H98 Underside Steering and Wheel	
710	Detail Damage Test H98 Underside Gearbox Support	
711	Detail Damage Test H98 Underside Front	
712	Detail Damage Test H98 Underside	
713	Detail Damage Underside Rear	
714	Detail Damage Underside Prop Shaft	
715	Detail Damage Test H98 Underside Prop Shaft	
716	Lorry Damage After Test C14 Offside Cab	Lorry
717	Lorry Cab in Compression Rig	
718	Lorry Cab in Compression Rig	
719	Lorry Cab in Compression Rig	
720	Lorry Cab Test C14 FrontQuarter	
721	Lorry Cab Test C14 FrontQuarter	
722	Lorry Cab Test C14 Compression Offside	
723	Lorry Cab Test C14 Compression Offside Quarter	
724	Lorry Cab Compression Test Front	
725	Lorry Cab Compression Test Rear	
726	Lorry Cab Compression Test Rear	
727	Lorry and Outside Tower Test Rig	
728	Lorry Test C12 Tower Test Rig	
729	Lorry Test C12 Tower Test Rig	
730	Lorry Test C12 Tower Test Rig	
731	Damaged Lorry Test C15	Ford
732	Damaged Lorry Test C15	Ford
733	Damaged Lorry Drivers Position	
734	Damaged Lorry Test C1 Front with Collision Plate	Ford
735	Damaged Lorry Test C15 Front Nearside Quarter	Ford
736	Damaged Lorry Cab Rear Offside Quarter	Ford
737	Damaged Lorry Test C1 Font Offside Quarter and Plate	Ford
738	Damaged Lorry Cab Nearside Rear Quarter	Ford
739	Damaged Lorry Cab C15 Nearside	Ford



740	Damaged Lorry Cab C15 Front Nearside	Ford
741	Avenger Body Test J23 Offside	
742	Detail Drivers Seat Airbag	
743	Detail Test J23 Drivers Area and Airbag	
744	Detail Front Seating Airbag	
745	Detail Test J23 Offside Rear Door and Wheel Arch	
746	Avenger Body Test J23 Offside 3 Dummies	
747	Detail Dummy in Drivers Position	
748	Detail Dummies in Rear Seats	
749	Detail Dummies in Rear Seats	
750	Detail Dummies in Front Seats	
751	Detail Dummies in Front Seats	
752	Detail Dummies in Car View from Rear	
753	Detail Dummies in Front Seats	
754	Detail After Test J24 Dummies in Front Seats	
755	Detail Instrumentatio and Rear of Car Test JS??	
756	Detail Avenger Body Offside no Doors	
757	Detail Avenger Body Offside no Door View front Seating	
758	Detail Avenger Body Offside no Door Dummy Driver	
759	Avenger Body Test J24 Nearside Dummies	
760	Detail After Test J24 Dummies in Front Seats	
761	Detail After Test J24 Dummies in Front Seats Offside	
762	Detail After Test J24 Dummies in Front Seats Nearside	
763	Detail Damage Test J24	
764	Detail Damage Test J24	
765	Detail Damage Engine Bay Offside Rear Corner	
766	Detail Damage	
767	Detail Damage	
768	Vehicle After Test View Dummy in Drivers Position	
769	Avenger After Test J37 Offside	
770	Detail After Test Front Seating	
771	Detail After Test Roof	

772	Avenger After Test J37 Windscreen		
773	Avenger After Test J37 Nearside		
774	Avenger LHD After Test J37n Thro Driver Window		
775	Avenger LHD Test J37 Offside		
776	Avenger LHD Test J37 thro Drivers Window		
777	Avenger LHD Test J37 Thro Rear Window		
778	Avenger LHD Test J37 Offside		
779	Avenger LHD Test j37 Nearside Quarter		
780	Avenger LHD Test J37 thro Passenger Window		
781	Avenger LHD Test J37 Thro Drivers Door		
782	Detail H72 LHD Thro nearside Windscreen		
783	Detail Inside of Front Wheel		
784	Detail Strut Mounting		
785	Detail J37 Thro nearside Windscreen		
786	Avenger After Test J37 View of Front		
787	Detail of Seat mounting		
788	Late Model Imp J80 Crash Test (TDU 626J)	Imp	2 Photos
788	Detail of Steering Position		
789	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
790	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
790	Detail After Test J80 Steering Wheel	Imp	
791	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
791	Imp After Test J80 Front Damage Offside View	Imp	
792	Late Model Imp J80 Crash Test (TDU 626J)	iImp	
792	Imp After Test J80 Damage Dash Area	Imp	
793	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
793	Imp After Test J80 Thro Rear Window	Imp	
794	Late Model Imp J80 Crash Test (TDU 626J)	Imp	

794	Imp After Test J80 View on Front	Imp	TDU 626J
795	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
795	Imp Test J80 Nearside View	Imp	
796	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
796	Imp Test J80 Rear View	Imp	
797	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
797	Imp After Test J80 Nearside Quar- ter View	Imp	
798	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
798	Imp Test J80 Offside	Imp	
799	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
800	Stiletto J86 Crash Test	Stiletto	
800	Coupe Imp Test J86 Nearside	Imp Coupe	
801	Stiletto J86 Crash Test	Stiletto	
801	Coupe Imp Test J86 Offside	Imp Coupe	
802	Stiletto J86 Crash Test	Stiletto	
802	Coupe Imp After Test J86 Thro Rear Window		
803	Stiletto J86 Crash Test	Stiletto	
803	Coupe Imp After Test J86 Offside		
804	Stiletto J86 Crash Test	Stiletto	
804	Coupe Imp After Test J86 Nearside		
805	Stiletto J86 Crash Test	Stiletto	
805	After Test J86 Detail Thro Passen- ger Window		
806	Stiletto J86 Crash Test	Stiletto	
806	Detail Test J86 Thro Passenger Window		
807	Stiletto J86 Crash Test	Stiletto	TDU 631J
807	Coupe Imp Test J86 Rear View	Imp Coupe	
808	Detail of Damaged Drivers Position		
809	Detail of Damaged Pedal Area		
810	Avenger After Test J58 offside Doors	Avenger	
811	Avenger Test J58 Rear View		
812	Avenger After Test J58 View on Front Offide Quarter		
813	Deatil of Dummy in Drivers Seat		
814	Avenger After Test J58 Dummy Driver Offside		
815	Avenger After Test J58 Dummies in Offside Seats		

816	Test J58 Dummies in Office Seats Thro Rear Window			
817	Avenger Outside Front View	Avenger	RKV 344H	
818	Avenger Front View People Around			
819	Detail String/Wiring			
820	Detail Front Seating Dummy			
821	Detail Rear Seating Dummy			
822	Detail View thro Rear Window			
823	Avenger Dummy Driver thro Doorway			
824	Space Frame Rig			
825	Space Frame Rig		Water Damage	
826	Space Frame Rig		Water Damage	
828	Arrow Fastback Test J99 View of Rear	Sunbeam		
829	Arrow Fastback Test J99 View of Nearside			
830	Detail of Engine Bay Test J99			
831	Arrow Fastback Test J99 Offside View			
832	Detail of Drivers Position Test J99			
833	Detail of Drivers Position Test J99			
834	Arrow Fastback After Test J99 Nearside View			
835	Arrow Fastback After Test J99 Offside View			
836	Detail Test J99 View of Steering Position			
837	Arrow Fastback After Test J99 Nearside View			
838	Detail of Drivers Position from Nearside			
839	Arrow Saloon Test J98 Rear View		Humber	
840	Arrow Saloon Test J98 View Front Seating Area			
841	Arrow Saloon Test J98 View Drivers Position			
842	Arrow Saloon Test J98 Nearside View			
843	Arrow Saloon Test J98 Nearside View			
844	Detail View of Engine Bay Test J98			
845	Detail of Steering Wheel			
846	Detail of Front Seating			

847	Arrow Saloon After Test J98 Offside View		
847	(A) Block Chrysler Dummy		2 Negs
848	Arrow Saloon After Test J98 Rear Nearside		
849	Arrow Saloon After Test J98 Rear Nearside Quarter		
850	Arrow Estate Test 119 View of Dash and Steering Wheel	Arrow Estate	
851	Arrow Estate Test 119 View of Dash and Steering Wheel	Arrow Estate	
852	Arrow Estate After Test 119 View from Offside Front	Arrow Estate	
853	Arrow Estate After Test 119 Offside	Arrow Estate	
854	Detail Thro Drivers Quarter Light		
855	Arrow Estate After Test 119 Nearside Front	Arrow Estate	
856	Arrow Estate After Test 119 Offside		
857	Detail Of Steering Wheel and Dash		
858	"5and6" Detail Damage Avenger Test J98	Avenger	
859	Avenger Body Test JS130 Offside no doorOff		
860	Avenger Body Test JS130 Close up Offside		
861	Avenger Body Test JS130 Nearside Dummies		
862	Avenger Body Test JS130 Nearside Dummies		
863	Avenger Body After Test JS130 Offside		
864	Avenger Body After Test JS130 Padded Dash		
865	Avenger Body After Test JS130 Padded Dash		
866	Avenger Body High Front Seats and Dummies		
867	Avenger Body High Front Seats and Dummies thro Pass.Door		
868	Detail After Test JS130 View thro Drivers Door Dummies		
869	Detail After Test JS130 View of Windscreen Area Dummies		
870	Detail After Test JS130 View thro Passenger Door Dummies		
871	Detail After Test JS130 View thro Passenger Door Dummies		
872	Detail Test J132 Engine Bay		

873	Detail Test J132 Intrumented Steering Wheel	
874	Arrow Fastback Test J132 Rear	Sunbeam
875	Arrow Fastback Test J132 Offside View	
876	Arrow Fastback Test J132 Drivers Position thro Pass.Door	
877	Arrow Fastback Test J132 Nearside	
878	Arrow Fastback Test J132 Drivers Position thro Pass.Door	
879	Arrow Fastback After Test J132 Nearside	
880	Arrow Fastback After Test J132 Offside Wing	
881	Arrow Fastback After Test J132 Drivers Position	
882	Arrow Fastback After Test J132 Offside	
883	Arrow Fastback After Test J132 Nearside	
884	Arrow Fast Back After Test J132 Nearside Wing	
885	Avenger 2 Door Test J114 Offside	Avenger
886	Avenger 2 Door Test J114 Rear	Avenger
887	Avenger 2 Door Test J114Nearside	Avenger
888	Detail Boot Spare Wheel	
889	Detail ?	
890	AvengerTest J114R Rear	Avenger
891	Avenger Test J114R View LH Rear Quarter	Avenger
892	Avenger 2 Door After J114R Nearside View Dustbin	
893	Avenger 2 Door After J114R Offside View Dustbin	
894	Avenger 2 Door After J114R Nearside View	
895	Avenger 4 Door After J150 Nearside View	
896	Avenger 4 Door Test J150 Nearside View	
897	Avenger 4 Door After J150 Offside View	
898	Detail Drivers Position Test J150	
899	Detail After Test J150 View thro Rear Window	
900	Detail After Test J150 View thro Passenger Door	
901	Detail Test J150 Drivers Position	

902	Detail Test J150 Drivers Position thro Passenger Door		
903	Avenger Test 150 View thro Rear Window		
904	Avenger Test J150 Engine Bay		
905	Avenger Test J150 View down Near-side		
906	Avenger Test J150 View down Off-side Rear Wing		
907	Avenger Test J150 Rear		
908	Avenger After Test J150 Offside		
909	Avenger After Test J150 Nearside		
910	Block Dummy		
911	Block Dummy		
912	Block Dummy		
913	Block Dummy		
914	Block Dummy		
915	Block Dummy		
916	Block Dummy		R/388
917	Block Dummy		
918	Outline of Concept Car Advanced Engineering		
919	Diagram Vehicle Handling Parameters Tyres		
920	Detail Test K45 Engine Bay		
921	Detail After Test Steering Wheel		
922	Detail After Test K45 Dummy Driver		
923	Detail After Test K45 Dummy Driver		
924	Detail After Dummies thro Passenger Window		
925	Detail After Test K45 Thro Offside Door Dummy		
926	Detail LHD After Test K45 Nearside Door Dummy		
927	Detail LHD After Test K45 Nearside Door Dummy		
928	Avenger LHD After Test K45 Off-side		
929	Avenger LHD After Test K45 Near-side		
930	Avenger LHD Test K45 Nearside	Avenger	
931	Avenger 4 Door Test K45 Offside		
932	Avenger 4 Door Test K45 Nearside People		
933	Avenger 4 Door After Test K45 Nearside Rear Quarter		

934	Avenger Test K45 View thro Rear Window		
935	Typed Text "Rigid Foam Anthropometric Test Device"		Neg Damaged
936	Block Dummy		
937	Block Dummy		
938	Line up of Various Damaged Test Cars K7 plus		
939	Front Damage Test K45 Avenger 4 Door		
940	Text Document Vehicle Primary Control and Stability		
941	Graph		
942	Graphs Examples of Known Car Layout Constant 40mph		
943	Graph/Diagram Test Method		
944	23 Detail Seatbelt Anchor		
944	24 Deatil Seatbelt at Side of Driver Seat		
948	Instrumented Seat and Dummy on Trolley		Run Number 1
949	Instrumented Seat and Dummy on Trolley	01/02/1972	Run Number 2
950	Instrumented Seat and Dummy on Trolley	01/02/1972	Run Number 3
951	Detail of Diff and Spring		
952	Block Dummy in Front Passenger Seat		
953	Detail of Seatbelt Anchor		
954	Detail of Seatbelt across Block Dummy		
955	Block Dummy in Drivers Seat		
956	Block Dummy in Drivers Seat		
957	Seatbelt across Block Dummy in Passengers Seat		
958	Block Dummy		
959	Block Dummy		
960	Avenger 4 Door LHD Test K99		
961	Avenger 4 Door LHD Test K99 Damaged		
962	Avenger 4 Door LHD Test K99 Drivers Position		
963	Avenger Estate Test K99 View of Rear	Avenger Estate	
964	Avenger Estate Test K99 View thro Rear Offside Window		
965	Avenger Estate Test K99 Engine Bay		



966	Avenger Estate Test K99 Nearside	
967	Avenger Estate Test K99 Offside	
968	Avenger Estate Test K99 Offside Front Damage	
969	Avenger Estate Test K99 Nearside Front Damage	
970	Avenger Estate Test K99 Nearside Front Damage	
971	1 Dummy in Seat	
971	2 Close up of Dummy in Seat	
971	3 Dummy out of Seat	
971	4 Close up of Dummy out of Seat	
971	5 Test Wiring to Test Seat	
971	6 Detail of Seatbelt	
972	7 Negatives of Seatbelt/Dummy Test	
973	8 Negatives of Seatbelt/Dummy Test	
974	6 Negatives of Seatbelt/Dummy Test	
975	Dummy and Seat on Trolley	22/02/1972
976	6 Negatives of Seatbelt/Dummy Test	
977	Dummy and Seat on Trolley	22/02/1972
978	6 Negatives of Seatbelt/Dummy Test	
979	Dummy and Seat on Trolley	22/02/1972
980	9 Negatives of Seatbelt/Dummy Test	
981	Dummy and Seat on Trolley	22/02/1972
982	6 Negatives of Seatbelt/Dummy Test	
983	Dummy and Seat on Trolley	22/02/1972
984	6 Negatives of Seatbelt/Dummy Test	
985	Dummy and Seat on Trolley Test KS184	07/03/1972
986	6 Negatives of Seatbelt/Dummy Test	
987	Dummy and Seat on Trolley	07/03/1972
988	6 Negatives of Seatbelt/Dummy Test	
989	Dummy and Seat on Trolley	07/03/1972
990	Dummy and Seat on Trolley	07/03/1972
991	6 Negatives of Seatbelt/Dummy Test	
992	6 Negatives of Seatbelt/Dummy Test	

993	Dummy and Seat on Trolley	07/03/1972		
994	6 Negatives of Dummy/Seat Test K202			
995	Avenger 4 Door After Test K202 Nearside Quarter			
996	Avenger 4 Door After Test K202 Nearside Quarter			
997	Damage After Test K202			
998	2 Negatives of Test K109			
999	Avenger Estate After Test K109 Nearside View			
1000	Block Dummy			
1001	Block Dummy			
1002	11 Negated of Avenger Test K241		Avenger	RKV 345H
1003	4 Negatives Details of Test K241			
1004	Bump Trolley For Rear Shunt Test			
1005	8 Negatives of Avenger Test K229			
1006	10 Negatives of Dummy/Seat Test KS325			
1007	3 Negatives of Dummy/Seat Test Ks325			
1008	15 Negatives of Avenger Test K263			
1009	Avenger LHD Test K263 Nearside			
1010	6 35mm Negatives around Steering Wheel			
1011	Avenger 4 Door Test K319 Nearside			
1012	8 Negatives Of Avenger Test K319			
1013	A-6 35mm Negatives around Car Test G69			
1013	B-12 35mm Negatives around Car Test G69			
1013	C-10 35mm Negatives around Car Test G69			
1014	7A-4 35mm Negatives of Steering Wheel			
1015	8 Negatives of Avenger Test L48			
1016	2 Negatives Details of Test L48			
1017	Avenger 4 Door L48 Nearside			
1018	6 35mm Negatives around Steering Wheel			
1019	7 35mm Negatives around Steering Wheel			
1021	10 Negated Avenger Test L153			
1023	4 35mm Negatives Car Interior /Person			
1025	Detail of Steering Rack Suspension			
1026	Detail of Car Front Underside			
1027	Detail of Car Front Underside			

1028	Detail of Car Rear Underside		
1029	Detail of Car Rear Underside		
1030	All Underside of Car Test K319		
1031	All Underside of Car Test K319		
1032	Detail of Car Front Underside		
1033	Car Interior Desired Location Area		
1034	Avenger 4 Door Rear Nearside View	Avenger	REG 725
1035	Avenger 4 Door Nearside View	Avenger	
1036	Avenger 4 Door Front Nearside View	Avenger	REG 725
1037	2 35mm Negatives of Engine Bay		
1038	12 35mm Negatives of Body Details		
1039	Lots of 35mm Negatives of Body Details		
1040	7 35mm Negatives of Seat/Belt Details		
1041	10 35mm Negatives of Test Damage Detail		
1051	Imp 468 After Crash Test	Imp	
1051	Imp Nearside Front Damage	Imp	VJU68?
1052	Imp 486 After Crash Test	Imp	
1052	Imp Nearside Front Damage Number Plates	Imp	
1053	Imp 486 After Crash Test	Imp	
1053	Imp Nearside Front Damage Number Plates	Imp	
1054	Imp 486 After Crash Test	Imp	
1054	Imp Nearside Front Damage Number Plates	Imp	
1055	Imp 792 After Crash Test	Imp	
1055	Close up of Damage		
1056	Imp 792 After Crash Test	Imp	
1056	Close up of Damage		
1057	Imp 792 After Crash Test	Imp	
1057	Close up of Damage		
1058	Imp 792 After Crash Test	Imp	
1058	Totally Wrecked Imp amid other Cars		
1059	Imp 792 After Crash Test	Imp	
1059	Totally Wrecked Imp amid other Cars		
1060	Imp 792 After Crash Test	Imp	
1060	Close up of Damage		
1061	Imp 542 After Crash Test	Imp	
1061	Close up of Damage		
1062	Imp 542 After Crash Test	Imp	
1062	Close up of Damage		
1063	Imp 542 After Crash Test	Imp	

1063	Wrecked Imp/Chamois Front Damage		
1064	Imp 542 After Crash Test	Imp	
1064	Wrecked Sunbeam/Chamois Twin Headlights Front Damage		
1065	Imp 542 After Crash Test	Imp	
1065	Detail Of Front Damage		
1066	Imp 542 After Crash Test	Imp	
1066	Close up of Damage		
1067	Imp 542 After Crash Test	Imp	
1067	Detail Damage		
1068	Imp 542 After Crash Test	Imp	
1068	Imp Extensive Front Damage	Imp	
1069	Imp 542 After Crash Test	Imp	
1069	Imp Extensive Front Damage along side of Minx	Imp Minx	
1070	Imp 542 After Crash Test	Imp	
1070	Imp Extensive Front Damage Person	Imp Minx	
1071	12 35mm 4A-15A Negatives of Avenger	Avenger	
1071	12 35mm 16A-28A Negatives of Details		
1071	12 35mm 29A-37A Negatives of Details		
1072	8 35mm Negatives of Details mainly Interior		
1073	5 35mm Negatives of Detail		
1074	81-12 35mm Negatives of Details		
1081	86-6 35mm Negatives of "M" Registered Car		GRW 6?7M
1087	5/6/7 6 35mm Negatives of Details		
1088	2 Negatives of Dash/Steering Wheel		
1089	Outline of Wheel and Exhaust Boot Layout?		
1090	Ouline of Wheel and Exhaust Boot Layout		
1091	8 35mm Negatives of Details mainly Seat		
1091	6 35mm Negatives of Details		3/4 Front
1091	8 35mm Negatives of Details mainly Seat		
1092	6 35mm Negatives of Details including Seat		
1093	12 35mm Negatives of Details including Interior and Wheels		
1094	2 35mm Negatives of Seat Frame		
1095	Dash		

1096	Detail of Dash End		
1097	6 35mm Negatives Dash/Steering Wheel thro windscreen		
1100	2x Diagramatic of Body and Doors		
1101	2x Consept? Car and Person		
1102	Drg 73166246 Assembly of 6 Speed Gearbox		73166246
1103	Drg 73166247 Assembly of 5 Speed Gearbox		73166247
1104	Drg 73166245 Assembly of 5 Speed Gearbox		73166245
1105	Drg 73166243 Assembly of 5 Speed Gearbox		73166243
1106	Drg 73166240 Assembly of 4 Speed Gearbox		73166240
1107	Drg 73166249 Assembly of 5 Speed Gearbox		73166249
1108	Drg 73166250 Assembly of 6 Speed Gearbox		73166250
1109	Drg 73166248 Assembly of 6 Speed Gearbox		73166248
1110	Drg 73166242 Assembly of 4 Speed Gearbox		73166242
1111	Avenger Estate in Test Chamber	Avenger	
1112	Avenger Estate in Test Chamber	Avenger	
1113	Drivers Seat with Skelton Dummy		
1114	Diagram Avenger Estate LHD Int Mirror 10m		
1115	Diagram Avenger Estate LHD Pass Ext Mirror 4m		
1116	2x Diagram Avenger Estate LHD Drivers Pass Ext Mirror 4m		
1117	C6 Diagram RHD Passenger Ext Mirror 6m		
1118	C6 RHD Diagram Passenger Ext Mirror 4m		
1119	C6 RHD Diagram Passenger Ext Mirror 4m		
1120	C6 RHD Diagram Passenger Ext Mirror 10m		
1121	C6 RHD Diagram Drivers Ext Mir- rir 10m		
1122	Mirror Diagram		
1123	Mirror Diagram		
1124	Mirror Diagram		
1125	Mirror Diagram		
1126	Mirror Diagram		
1127	Mirror Diagram		

1128	Mirror Diagram		
1129	Mirror Diagram		
1130	Mirror Diagram		
1131	Mirror Diagram		
1132	Lorry Plate in front Test	Lorry	
1134	Mirror Diagram		
1135	Mirror Diagram		
1136	Mirror Diagram		
1137	Mirror Diagram		
1138	Mirror Diagram		
1139	Mirror Diagram		
1140	Mirror Diagram		
1141	Mirror Diagram		
1142	Mirror Diagram		
1143	Mirror Diagram		
1144	Mirror Diagram		
1145	Mirror Diagram		
1146	Mirror Diagram		
1147	Mirror Diagram		
1148	Mirror Diagram		
1149	Car Interior Drivers Position		
1150	Car Body in Test Chamber		
1151	Car Body in Test Chamber		
1152	Mirror Diagram		
1153	Mirror Diagram		
1154	Mirror Diagram		
1155	Mirror Diagram		
1156	Mirror Diagram		
1157	Mirror Diagram		
1158	Mirror Diagram		
1159	Mirror Diagram		
1160	Mirror Diagram		
1161	Mirror Diagram		
1162	Mirror Diagram		
1163	Mirror Diagram		
1164	Damage Empty Package		
1165	Graph Pass Side 7m		
1166	Graph Driver Side 10m		
1167	Graph Driver Side 10m		
1168	4 35mm Negatives of Robin Eyre Maunsell Imp	Imp Comp.	LWK 700F
1169	Graph Pass. Side Ext Mirror 4m		27/02/1979
1170	Graph Pass. Side Ext Mirror 6m		27/02/1979
1171	Graph Driver Side Ext Mirror 7m		27/02/1979
1172	Graph Drivers Side Ext Mirror 6m		27/02/1979
1173	Graph Int Mirror LHD 4m		
1174	Graph Int Mirror LHD 6m		
1175	Graph Int Mirror LHD 4m		

1176	Graph Int Mirror LHD 6m			
1177	Mirror Diagram			
1178	Mirror Diagram			
1179	Mirror Diagram			
1180	8 35mm Negatives Mainly Car Interiors			
1181	/1Mirror Diagram			
1181	/2 Mirror Diagram			
1181	/3 Mirror Diagram			
1181	/4/Mirror Diagram			
1182	7 35mm Negatives Peugeot 309 Saloon			
1183	10 35mm Negatives Peugeot 309 Saloon			
1184	7 35mm Negatives Peugeot 309 Saloon			
100	Californian G37 Crash Test (JHP 492E)		Imp Californian	
	Following have D prefix			
1	6 Arrow Type Cars inside Building		Arrow	
2	Car Dash and Steering Position			
3	Chart "E - Car Master Timing Schedule"			
4	Chart "B - Estate Car Timing"			
5	Diagrams "'B' Load Floor Lengths"			
6	"B Estate Car and Competitors-Tailgate Opening Width"			
7	"B Estate Car and Competitors-Rear Aperature Height"			
8	"B E/C Styling Programme"			
9	"Estate Car Comparative Load Floor Lengths"			
10	Chart "E - Car Master Timing Schedule"			2 Negatives
11	Family Tree Type Diagram			
12	"1800cc Engine Master Timing Schedule" H series			
13	"'B' Estate Car and Competitors Prices			2 Negatives
14	"Rapid TransitExperimental (RTX) Coach"		Coach	
15	Futuristic Lorry		Lorry	
16	List/Table			
17	"'C' Premium Features Over Highline"			
18	"'C' Highline V6 Features Over Medium"			

19	”’C’ Medium Versus Victor 2000 Features”	
20	”’C’ Medium Features Over Lowline”	
21	”Premium Additional Specification-Alternatives”	
22	”’C’ Lowline Versus Victor 1600 Features”	
23	”’C’ Versud Rover 2000 Features”	
24	”’C” Range Kerb Weights and Drag Factor”	
25	”’C’ Car Volume Forecasts”	
26	35mm Slide of ”’C’ Car Options Domestic”	
27	”Large Car Market Prices”	
28	”C Car Master Timing Plan”	
29	”’C’ Derivatives Cost Status”	
30	”’C’ Highline V6 Versus Corsair 2000E Features”	
31	’C’ Lowline Prime Cost Status	
32	”E Car Volumes Domestic”	
33	”E Car Investment”	
34	”E Car Volumes Domestic”	
35	”Recent Decesions Incurring costs”	
36	”C Car Range Name Alternatives”	
37	”Prime Costs to US Eastern Seaboard”	
38	”E Car (Small) v ’B”	
39	”E Car Prime Cost v B Car”	
40	””E Car Volumes Export”	
41	”E Car (Large) Price v ’B’ and ’C’ Cars”	
42	E Car Volumes Export”	
43	”C Car Project Summary”	
44	”E Powertrain Interchangeability attern”	
45	”E Car Long Range Plan Asumptions”	
46	”E Car Decisions Required”	
47	”E Car Body Panel Alternatives”	
48	”E Car Parameters v ’B’ and ’C””	
49	”E Car Volumes”	
50	”E Car Cost and Price”	
51	Schematic Car E3	
52	Schematic Car E4	
53	Schematic Car E4a	
54	Schematic Car E4b	
55	Schematic Car E5	



56	Schematic Car Ea and b		
57	"E Car Investment Long Range"		
58	"C CarMaster Timing Plan"		
59	"C Car Project Summary"		
60	"C Highline V6 v Corsair 2000E Features"		
61	C Premium v Rover 2000 Features		
62	Large Car Market Prices		
63	C Medium Features over Lowline		
64	C Highline V6 Features Over-Medium		
65	C Medium v Victor 2000 Features		
66	C Premium Features Over Highline		
67	Decisions and Investigations Adversely Affecting Programme		
68	C Car Options Domestic		
69	C Car Options Export Built-up		
70	C Range Kerb Weights		
71	C Outstanding Styling Programme		2 Negatives
72	C Lowline Car Prime Costs		
73	Press Cutting Renault 12/16 Photo		
74	Press Cutting Renault 12/16 Photo		
75	Press Cutting Renault 12/16 Dash		
76	G Series Model Chart		
77	Press Cutting The Time Share Indices		
78	Press Cutting Market Reports (Rootes)		
79	Rear View Arrow Sunbeam	Arrow	JKV 287E
80	Rear View Arrow Sunbeam	Arrow	JKV 287E
81	Track Photo of Lancia	?	
82	Track Photo of Mini	Mini	
83	Track Photo of Porche	Porche	
84	Track Photo of Mini	Mini	
85	Track Photo of Car	?	
86	Track Photo of Cortina	Cortina	
87	Track Photo of Saab	Saab	
88	Track Photo of Lancia	Lancia	
89	Track Of Lotus Cortina	Cortina	
90	Track Photo of Lancia	Lancia	
91	Track Photo of Car	?	
92	Track Photo of Cortina	Cortina	
93	Track Photo of Lancia	Lancia	
94	Forward Project Plan Summary Trucks	Trucks	
95	Forward Project Plan Summary Car 69 to 79	Car	
96	Rootes Series Model Chart		

97	Arrow Long Range Plan	Arrow
98	Rear Door Dimensions	
99	B Estate Load Floor Length	
100	NAS 1970 Facelift Proposals	
101	NAS 1970 Facelift Proposals	
102	NAS 1970 Facelift Proposals	
103	NAS 1970 Federal Requirements	
104	NAS 1970 Facelift Proposals	
105	NAS 1970 Facelift Proposals	
106	NAS 1970 Facelift Proposals	
107	B E/C Styling Programme	
108	B Estate Car and Competitors Rear Aperature Height	
109	Estate Car Comparitive Load Floor Lengths	
110	B Estate Car and Competitors Tail- gate Opening Width	
111	Total Cost Effect of Facelift Propos- als	
112	Total Cost Effect of Face Proposals	
113	E Car Preprogramme Timing	
114	3D Barchart?	
115	NAS 1970 Proposals	
116	1800cc Engine Master Timing Plan	
117	NAS 1970 Facelift Proposals	
118	B Estate Car and Competitors Prices	
119	B Estate Car Derivative Lineup	
120	Schematic Tailgate Dimensions	
121	Card Marked No Negatives Slides Only	
122	B Estate Car and Competitors Prices	
123	Market Segmentation Chart (Eu- rope)	
124	Forward Product Plan Summary - Car	
125	Forward Product Plan Summary - Car	
126	Major Unit Commonality Chart	
127	Body Unit Commonality Chart	
128	Decision Alternatives	
129	Decision Alternatives	
130	NAS 1970 Facelift Proposals	
131	Total Cost Effect of Facelift Pro- posal	
132	NAS 1970 Facelift Proposals	
133	NAS 1970 Timing	

134	NAS Federal Requirements		
135	Estate Car Comparitive Capacities		
136	B Estate Car and Competitor Prices		
137	B Estate Car and Competitor Prices		
138	B E/C Model Line Differentials		
139	B E/C (Built Up) Model Mix		
140	B eE/C Volumes J Series 1972/73		
141	B E/C Differential Prime Cost Prices		
142	Estate Comparitive Load Volumes		
143	B E/C Styling Programme		
144	Estate Car Comparitive Load Floor Lengths		
145	B Estate Car Master Timing Plan		
146	Photo of Central Console		
147	Labels?		
148	Forward Summary Plan Trucks		
149	Proposed European Truck Ride and Drive in Belgium		Europe Map
150	Proposed European Truck Ride and Drive in Belgium		Europe Map
151	Continuation of Europe Map East- wards		Map
152	Project Plan Summary - Passenger Cars		
153	Project Plan Summary - Trucks		
154	Product Plan Summary - Passenger Cars		
155	Product Plan Summary - Trucks		
156	Advanced Product Influence Dia- gram		
157	Product Plan Summary - Trucks		
158	Rootes and Competition	Feb-69	
159	Forward Product Plan Summary - Car(Alternative)		
160	Product Plan Summary - Truck		
161	Product Plan Summary - Truck		
162	Product Plan Summary - Truck		
163	Product Plan Summary - Truck		
164	Volume and Penetration		
165	Investment Alternative		
166	Market Segmentation Chart (Eu- rope)		
167	Market Segmentation Chart (Eu- rope)		
168	Market Segmentation Chart (Eu- rope)		

169	Market Segmentation Chart (Europe)		
170	Market Segmentation Chart (Europe)		
171	Rootes Long Range Plan Alternatives		
172	Market Segmentation Chart		
173	Rootes Market Coverage		
174	Rootes and Competition E Car		
175	Rootes and Competition 'E' Car	Feb-69	
176	Rootes and Competition 'B' Minus	Feb-69	
177	Rootes and Competition 'B' Car	Feb-69	Avenger
178	Unit Commonality Objectives 'B' Car	Feb-69	Avenger
179	Rootes Competitions 'C' Car	Feb-69	Chrysler 180/2.0Lt
180	Rootes Competitions 'D' Car	Feb-69	
181	Body Unit Commonality	Feb-69	
182	Forward Product Planning	24/01/1969	
183	Volume and Penetration	Feb-69	
184	Forward Product Planning		
185	Volume and Penetration	Feb-69	
186	Forward Product Planning	Feb-69	
187	Volume and Penetration	Feb-69	
188	Forward Product Planning Summary	Feb-69	
189	Volume and Penetration, Domestic and Export	Feb-69	
190	Forward Product Plan	Feb-69	
191	Volume and Penetration	Feb-69	
192	Forward Product Plan	Feb-69	
193	1250cc 'B' Car vs Viva		Avenger
194	B' Range, Mechanical Features up to 1800cc		Salisbury Axle
195	B' car vs Cortina 1600cc		Avenger vs Cortina
197	B' Car Production Objectives	Feb-69	Avenger
198	B' Car and Competitions		
199	B' Car Derivative Line-up		Avenger
200	B Low Line vs Minx Low Line Performance		Avenger (B) 88mph 17 secs
200	B Car Vv Minx/Hunter Performance		Minx 83mph 18.2 secs
201	B Low Line vs Minx Low Line General Data		Avenger vs Minx
202	B Low Line vs Minx Low Line Interior		Avenger vs Minx
203	B Car 1250cc vs 4dr Viva SL		Avenger vs Viva

204	B Car Body and Hardware		Avenger
205	Avenger 1250 Lowline vs Escort 1100		Avenger
206	Forward Product Plan	Up to 1976	
207	Forward Product	Feb-69	
208	Market Generation Chart	1972-1973	
209	Market Segmentation Chart (Europe)		
210	M Series Volume + Market Penetration	April-69 and Feb-69	
211	Schematic Side Elevation of Chassis (Low)		
212	High Volume Saloons. C.C. against year	1969-1972	
213	Literature		
214	Car Tuning Summary		
216	City Centre MP A Car + InterCity Family Car		
217	I.C. Imp. BEA Badge. Drawn by "Steicns", Mini MPV		Imp
218	B Car Timing Summary	Apr-69	Avenger
220	C Car Major Changes in Specifications		Chrysler 180/2.0Lt
221	C Car Range Kerb Weight	Apr-69	Chrysler 180/2.0Lt
222	C Car Timing Summary	Apr-69	Chrysler 180/2.0Lt
223	B Car Prime Cost status	Apr-69	Avenger
224	C Car Volume Forecourt	Apr-69	Chrysler 180/2.0Lt
225	C Car Prime Cost inc. Contingency	1968 and 1969, 2off	Chrysler 180/2.0Lt
226	C Range Kerb	Apr-69	Chrysler 180/2.0Lt
227	B Car Timing Summary Pre Launch	Apr-69	Avenger
228	C Car Timing Summary Pre Launch	Apr-69	Chrysler 180/2.0Lt
229	B Car Prim Cost Status	Apr-69	Avenger
230	B Car Total Volume Charge		Avenger
231	Dodge 500 30 ton Tractor - Volume Forecast Intro	05/01/1970	Dodge 500
232	Dodge 500 30 ton Tractor - Financial Data	Apr-69	Dodge 500
233	Dodge 500 30 ton Tractor - Competitors	Apr-69	Dodge 500
234	Dodge 300 30 ton Tractor	c 1970	Dodge 500
235	C Body in White Critical Items	c 1970	Chrysler 180/2.0Lt

236	C Lowline Prime Cost Status	Apr-69	Chrysler 180/2.0Lt Avenger	
237	B - Car, Volume Change	1969 - 05/69		
238	Barreiros and Rootes Long Range Plan 3	up to 1980		
239	Commercial Sales Record	Early 1970 to 1980		
240	Product Decision Planning	c 1970		
241	Product Asumptions Plan 2			
242	Product Asumptions Plan 3			
243	Product Asumptions Plan 1			
244	B Car Timing Summary			
245	C Car Volume Forecasts			
246	Forward Product Plan Summary - Cars Alternative			
247	Forward Product Plan Summary - Trucks Alternative 2			
248	Forward Product Plan Summary - Trucks Alternative 3			
249	Forward Product Plan Summary - Cars			5 Negatives
250	E Car Forward Timing Draft			
251	Product Planning Open Building			
252	Chrysler Europe Timing Schedule			
253	Chrysler Europe Timing Schedule			
254	Chrysler Europe Timing Schedule			
256	Barreiros and Rootes Long Range Plan Alternative 2	May-69		2 Negatives
257	Option Code Index G Series			
258	Programme Timing			2 Negatives
259	Photo Religious Picture?			
260	Photo Religious Picture?			
261	Drawing of Simca 937 (derived from Simca 1000)		Simca 937	
262	Total Volume and Domenistic Pen- etration Graph			2 Negatives
263	Barreiros and Rootes Long Range Plan Alternative 2			2 Negatives
264	CV Product Decision Pattern			2 Negatives
265	Photo Lorry Cab		Dodge	
266	Forward Project Plan Summary - Truck			2 Negatives
267	Forward Product Plan Summary - Car			2 Negatives
268	Chrysler Europe Car Make and Model List	13-May-69		
269	Ideal World Product Plan			
270	Projection of European Truck Sales Trend			2 Negatives

271	Domestic PenetrationBy Big Ten	2 Negatives
272	Domestic PenetrationBy Big Ten	2 Negatives
273	European Truck Market	2 Negatives
274	European BU and KD Tariff Barriers Map	Map
275	European Source CO Ability Truck Requirements	2 Negatives
276	European Truck Market E Series	
277	Four Major European Truck Source Countries	2 Negatives
278	Chrysler European Trucks Production Requirements	2 Negatives
279	Chrysler Sales Projection in European Truck Market	2 Negatives
280	European Truck Market Chrysler Penetration	2 Negatives
281	Recommendations	2 Negatives
282	Commercial Vehicle Strategy Story	3 Negatives
283	Chart?	2 Negatives
284	Chart?	2 Negatives
285	Chart?	3 Negatives
286	Commercial Vehicle Strategy Story	2 Negatives
287	Rootes Commercial Vehicles	2 Negatives
288	Commercial Vehicle Strategy Story	2 Negatives
289	Commercial Vehicle Strategy Story	2 Negatives
290	Commercial Vehicle strategy Story	2 Negatives
291	Commercial Vehicle strategy Story	2 Negatives
292	Commercial Vehicle strategy Story	2 Negatives
293	Commercial Vehicle strategy Story	2 Negatives
294	Commercial Vehicle strategy Story	2 Negatives
295	Map European Truck Market	
296	Tractor Cross Margin	
297	Heavy ?	
298	Light/Medium Contribution	
299	Heavy Truck Crodd Margin	
300	B Vehicle Saloon Car Range	
301	Price Comparision Hillman Ford Austin	
302	Principle Dimensions Light Van Models	
303	Principle Dimensions ??? Van Models	
304	Forward Product Plan Summary Car	2 Negatives
305	Forward Product Plan Summary Truck	2 Negatives
306	Colour Slides Presentation by G.Kleman	Missing

307	Colour Slides Presentation by G.Kleman		Missing
308	Colour Slides Presentation by G.Kleman		Missing
310	Colour Slides Presentation by G.Kleman		Missing
311	Colour Slides Presentation by G.Kleman		Missing
313	Colour Slides Presentation by G.Kleman		Missing
314	Colour Slides Presentation by G.Kleman		Missing
315	Colour Slides Presentation by G.Kleman		Missing
316	Colour Slides Presentation by G.Kleman		Missing
317	Used for Slide		Missing
318	Used for Slide		Missing
319	Photo Detail Of Engine Area Injectors?		
320	Photo Detail Of Engine Area Pipes?		
321	Chart Working Product Plan Summary Trucks		
322	Forward Product Plan Summary Car		
323	Forward Product Plan Summary Trucks		
324	Marker Segmentation Chart		
325	Price and Var. Profit Comparision		
326	R429 Price Variable Profit and Investment		
327	Implications of V6 Engine in Arrow and Rapier	Arrow/Rapier	
328	Announcement Pattern		
329	R429 Timing	R429	
330	Major Changes to Install 1725cc in JR429	JR429	
331	Key Dates		
332	Price Proposals G Series		
333	Coupe Price Coverage		
334	Major Changes to Install 2500cc in JR429	JR429	
335	Rootes Sales/Target Sheet?		
336	Rootes Sales/Target Sheet?		2 Negatives
337	Rootes Sales/Target Sheet ?		2 Negatives
338	Rootes Sales/Target Sheet ?		2 Negatives
339	??? Link Figures?		3 Negatives
340	Promise and Actual Dates		



341	Ventora Badge Behind Front Wheel Bodywork		Ventora	
342	Detail Bodywork in front of Rear Wheel		?	
343	Detail inc Wheel			Water Damage
344	Ventora Badge Behind Front Wheel Bodywork		Ventora	
345	Sunbeam Alpine Specification Con- tent		Sunbeam Alpine	
346	Hillman Imp Saloon Product Con- cept		Imp Saloon	
347	Sunbeam Alpine Price Compari- sons		Sunbeam Alpine	
348	Hillman Imp Price Comparisions		Imp	
349	Hillman GT Price Comparisions		Hillman GT	
350	Hillman GT Specification Content		Hillman GT	
351	Hillman GT Product Concept		Hillman GT	
352	Hillman GT Performance		Hillman GT	
353	Sunbeam Alpine Performance Com- parision		Sunbeam Alpine	
354	Hillman Imp Saloon Lowest Priced 4 Seater British Family Saloon		Imp Saloon	
355	Hillman Imp Saloon Profitabilty		Imp Saloon	
356	Sunbeam Alpine "GT Style and Concept at Low Price"		Sunbeam Alpine	
357	Hillman GT "High Performance Low Cost 4 Door Saloon"		Hillman GT	
358	Ideal World Product Plan			
359	Analysis of Alternatives			
360	Arrow Rootes		Arrow	
361	R429 Rapier Rootes		Rapier	
362	Vechicle Weight Estimates lbs			
363	Major Savings Under Consideration			
364	Prime Cost Movement Base Model			
365	Major Specification Changes April- August 1969	1969		
366	Anticipated Additional Cost Penal- ties not yet Detailed			
367	Prime Cost Movement Derivatives including Engineering Contigency			
368	Cost Savings Since Last Review			
369	Engine Performance			
370	Vechicle Performance			
371	JR541 Timing Summary		JR 541	
372	Major Changes to Install 1725 TC in R429		R429	

373	Major Changes to Install 1800/1800TC in R429		R429
374	Timing Comparisons		
375	Key Date Timing Rootes C Car Simca 949		Simca 949
376	R541 Rootes		
377	R429 Rapier Rootes		Rapier
378	R429 Rapier Rootes		Rapier
379	Sales Volume Forecasts		
385	Long Range Plans Key Dates		
386	Rootes?		
387	Rootes Arrow		Arrow
388	Rootes C		
389	Straight Line Chart?		
390	R541 Long Range Car v ?????		
391	Feature Comparison ??? V ???		
392	Comparison B and C Gearboxes		
393	Comparison B and C Axles		
394	New Medium Saloon Timing		
395	Arrow 4 Door Saloon Timing		
396	1800 B Derived Engine Timing		
397	1725 in B Unique Coupe Timing	Aug 69-Oct 72	
398	Arrow 2 Door Coupe Timing	Aug 69-Oct 70	
399	B / C riveline Capacity Increase Timing	Aug 69-May72	
400	B543? Long Range Plan v Product Engineering Recommendations		
401	JR541 prices v B and C Cars Timing Summary		
402	Major Changes to Install 1800/1800TC in R429		
403	B541 Product Assumptions		
404	Feature Comparisons 1725AL SC v 1800 SC Engineal sc		
405	Vehicle Weight Comparison LBS		
406	Prime Cost Movement Base Model		
407	Manufacturing Project	Aug-69	
408	Prime Cost Movement Derivatives		
409	Rootes C Car Simca 949 key Date Timing	Dec 69-Mar 71	Simca
410	Timing Comparisons		
411	Anticipated Additional Cost Penalties not yet Detailed		
412	Cost Savings Since Last Review		
413	Long Range Plans Key Dates		
414	Variance Over Strategy Study By Model		

415	Variance Over Strategy Study By Model		
416	How Do We Measure Up?		
417	What Makes a Truck Saleable in this High Volume Market?		
418	What Type of Truck are we Designing?		
419	Who are We Competing with in these Market?		
420	Photo Lorry Cab Tilted	Lorry	2 Negatives
421	Photo Lorry Cab Nearside	Lorry	2 Negatives
422	Photo of Lorry Cab	Lorry	2 Negatives
423	Photo Of Lorry Cab Tilted	Lorry	2 Negatives
424	Photo of Lorry Nearside	Lorry	
424	A Photo of Lorry Nearside	Lorry	
425	Photo of Lorry Cab	Lorry	
426	Photo od Lorry Front	Lorry	
427	Diagramme of Lorry Cab Dimension Codes		VGX 317G
428	Photo Details Panel/Pressing		
429	Photo Details Panel/Pressing		
432	Competitive Wheel Base Lineup		
434	Competitive Action		
435	Competitive Wheel Base Lineup		
436	Major Options		
439	Body Payload Factors as / of GVW		
440	8 HP/Ton Optional Engine (Where Available)		
441	CV Segment Market Size		
443	8HP/Ton Standard Engine		
444	Postioning of Payloads v Competition		
445	Diesel Engine Offered Rootes 100 Series v Competition		
446	G.V.W. Ranges of Rootes v Competition		
447	Timing	Oct 69 - Aug 72	4 Negatives
448	Variable Costs		
449	100 Series Cab v Competition Medium Truck		2 Negatives
450	100 Series Cab v Competition Light Truck		
451	Forward Product Plan Summary		3 Negatives
453	Broad Indication of Rootes Car Sales By Volume		
454	Broad Indication of Rootes Car Sales By Value		

455	Sketch Of 1950s Car Steaming Radiator			
456	Sketch Of 1950s Car Swag in Boot			
457	Outline Sketches of 3 Cars Superimposed			2 Negatives
459	Objectives of AD HOC Group	Sep-69		
460	Presentation of Rootes Models Must Pass	Sep-69		
461	Summary of Product Programme Decision and Development System	Sep-69		
462	Long Range Product Plan Decision	Sep-69		
463	Activity Analysis of Product Alternatives	Sep-69		
464	Product study Decision	Sep-69		
466	Programme Approval Decision	Sep-69		2 Negatives
467	Activity Programme Implementation	Sep-69		
468	Company Timing Plan Index			
469	Recommendation			
470	Photo Lorry Front BMC Cunard Line		BMC Lorry	NVP 462G
471	2 Photos Lorry Front BMC Water Splash		BMC Lorry	
472	Photo Lorry Front Quarter BMC Lorry		BMC Lorry	
473	Photo Lorry BMC "Keep in Low Gear"		BMC Lorry	
474	Photo Lorry BMC		BMC Lorry	SRW 107H
475	Photo BMC Lorry from Front Near-side Quarter		BMC Lorry	SRW 104H
476	Photo BMC Lorry Nearside		BMC Lorry	
477	Photo Lorry Nearside			
478	Photo BMC Lorry Front		BMC Lorry	SRW 104H
479	Photo BMC Lorry Laird		BMC Lorry	SRW 107H
480	Forward Product Plan Summary - Car	1970-1974	Imp and Arrow	
481	B Reskin Model Lineup - Current Prices			
482	R429 Prices versus Competition			
483	Proposed B Reskin Panel Formula Saloons			
484	Key Date Timing B Car Programme			
485	R 429 Programmje Parameters	Oct-69		
486	HR 4 29B Unique Skin Coupe Summary Timing			
487	H 429 Initial Financial Release			
488	Import Registration Growth 62/63 - 68/69			

489	Arrow B and C Dimension and Price H Series			
490	Arrow 2 Door/R429 Prices (US Dollar)	Arrow Alpine	Rapier	
491	J Series Market Segmentation Chart Domestic			
501	Why Cummins			
502	Tractors	Tractors		
503	Power/Weight Requirements			
504	Technical Details	Cummins Perkins	-	
505	Total Range Profitabilty			
506	Technical Details Cummins Engine	Cummins		
507	An Alternative Engine Supply			
511	100 Series Initial Financial Release			
512	C.V.Market Size Total Market			
513	Rootes cv C.V.Total Export Volume			
514	Commercial Vehicle Strategy Study			
515	Capital Requirements			Oct-69
517	Forward Product Plan Summary Trucks			
518	100 Series Cab v Competition Light Truck			
519	100 Series Cab v Competition Medium Truck			
521	Rootes C.V. Market Segment Shares 4-12 12+(Commer)	Commer		
522	Positioning of Payload v Competition			Damp Damage
523	Payload Factors			
524	Truck Ranges			
525	Construction and Use Regulations			
526	Financial Comparisions Rperiod 1970/1975			1970/1975
534	New Model Planning Export Sept 1969			Sep-69
535	100 Series Profitbility			Oct-69
536	100 Series Programme Timing for Medium Duty Truck 103			
537	Arrow B and C Dimension and Price H Series			
538	J Series Market Segmentation Chart Domestic			
542	Photo Peugeot 504 Berline	Peugeot 504		
543	Photo Peugeot 304 Berline	Peugeot 304		
544	Photo Peugeot 304 Berline	Peugeot 304		
545	Photo Fiat 124	Fiat 124		
546	Photo Fiat 124 Sport Coupe	Fiat 124		2 Negatives

547	Photo Peugeot 204 Berline Grand Luxe	1970	Peugeot 204	
548	Photo Fiat 125		Fiat 125	
549	100 Series Profitability			
550	An AD HOC Group of Affected Functional Directors	Sep-69		2 Negatives
551	Recommendations That the Rootes Administrative Committee	Sep-69		2 Negatives
552	Company Timing Plan Index	Sep-69		2 Negatives
553	Objectives of AD HOC Group	Sep-69		2 Negatives
554	List of Essential Stages New Model Panning	Sep-69		2 Negatives
555	Chrysler Europe Timing Schedule			2 Negatives
556	Chrysler Europe Timing Schedule			2 Negatives
558	Import Registration Growth 62/63 - 68/69			2 Negatives
559	Proposed B Reskin Panel Formula Saloons			
562	Capital Requirements			
563	100 Series Profitability			
564	Rootes Commercial Vehicles			
565	Total Volume Profitabilty			
566	Commercial Vehicle Strategy Study			
567	100 Series Programme			
568	100 Series Programme Capital Expenditure			2 Negatives
570	Rootes C.V. Market Share Domestic			2 Negatives
571	R 429 Prices v Competition			
572	B Reskin Variable Cost Relationships to B and C			
576	B Reskin Saloons Size and Specification Lineup			
577	U.K. Van Market Growth			
578	European Compact Van Market - 1967	1967		
579	Compact Van Sales 1967	1967		
580	Br H Series Introduction+ Volume Incremental Substitution			
581	B Car H Series Introduction			
582	B Reskin			
583	Arrow 4 Door MID G - H		Arrow	
584	Delay E car to Job One J			
585	Imp H and J		Imp	
586	Expenditure F thru J Codes 1 and 2			
587	ARROW 2 Door H		Arrow	
588	Base Capital Plan f to J eries			2 Negatives

589	Chrysler Europe Rootes Truck Program		2 Negatives
590	Chrysler Europe Rootes Truck Program		2 Negatives
591	Chrysler Europe Passenger Car Product Proposal	K Series	2 Negatives
592	Chrysler Europe Passenger Car Product Proposal	F and J Series	2 Negatives
593	Chrysler Europe Rootes Truck Program Profit Forecast		2 Negatives
594	Chrysler Europe Barreiros Truck Program		
595	Chrysler Europe Passenger Car Product Proposals	F to J Series	
596	H - Series 910 Extension	H Series	Positive
597	Major Product Developments	G H J K M Series	Positive
598	K Series Investment		Positive
599	Simca Growth Plan		Positive
600	Simca Product Evolution	Oct-69	Positive
601	International Product Planning Committee Proposal	14-Oct-69	Positive
602	K Series Proposals	K - Series	Positive
603	K Series Financial Implications	K - Series	Positive
604	Guidelines and Objectives		Positive
605	Simca Market Growth		Positive
606	Competitive Developments		Positive
607	EEC Market Growth		Positive
608	Simca Product Evolution November 1969	1969-1976	
612	Photo Lorry Offside	Lorry	
613	Car Outline Swag in Boot Universal Outline Specification Losses		2 Negatives
614	Product Specification and Options Volume and Profit 3 Cars Outlines		2 Negatives
615	Rootes Car Sales F thru l by Volume		2 Negatives
616	UK Specification = Export Flop Car Outline		2 Negative
617	Forward Project Plan Summary Car		
618	Forward Project Plan Summary Car		2 Negatives
619	Rootes Car Sales F thru l by Volume	Sep-69	
620	Graph 100 Series Major Sheet Metal		
621	Graph 100 Series Major Sheet Metal		
622	Graph 103 Range		
623	Graph 103 Range		
624	Graph 103 Range		
625	Graph 103 Range		
626	Graph 103 Range		
627	Graph 103 Range		

628	Graph 103 Range			
629	Graph 103 Range			
630	Graph 103 Range			
631	List of Names and Addresses			
632	C Car Prices UK Basic Retail			
633	Additional Specification Item			
634	Large Car Market Prices UK Basic Retail			
635	Arrow 4 Door Models for F and G Series		F and G Series Arrow	
636	Arrow 4 Door Models for F and G Series	Nov-69	F and G Series Arrow	
637	Arrow 4 Door Models and Price Lineup for F and G Series	Nov-69	F and G Series Arrow	
638	Arrow 2 Door Coupe for G Series	Nov-69	Arrow Coupe	
639	Colour Keying Major Items	Nov-69		
640	Exterior Trim Changes Parier Only	Nov-69	Rapier	
641	Holbay Performace Package		Hillman GT Alpine Rapier	
642	N.A.S Requirements			
643	Arrow 2 Door Coupe for G Series Domestic Timing			
644	Arrow 2 Door Coupe for G Series N.A.S. Timing			
645	Recommended Actions	Nov-69		
646	Timing N.A.S. B Car			
647	Forward Product Plan Summary Truck			
648	Forward Product Plan - Truck			
649	Arrow 2 Door Coupe Sales Forecasts	Nov-69		
650	Photo 2 Door Saloon VIVA HC		Viva HC	MLG 401H
651	Grainy Photo of 2 Door Saloon Renault 9?		Renault 9?	
652	Forward Product Plan - Truck			
653	3 Photos Of Pickup, Station Wagon, Forward Control Van			
654	List of Names and Addresses			
655	Slide B Lowline v Minx Lowline General Data		Minx	Negative
655	to 661 Duplicates of D655 to 661 on one sheet			
656	B Car Body and Hardware Features			
657	B 1250cc Medium Line v 4 Door Viva SL 1150 cc Comparision		Viva	
658	B 1250cc Medium Line v Escort 1300 cc Super Comparision		Escort	
659	B Lowline v Minx Lowline Interior Package		Minx	



660	B Lowline v Minx Lowline General Data		Minx	
661	B Car Product Objectives			
662	Anticipated Additional Cost Penalties not yet Detailed			
663	B Car Domestic Costs			
664	B Car Domestic Costs			
665	B Car Vehicles Weight Estimates LBS			
666	B Car Additional Cost Savings under Consideration			
667	B Car Additional Cost Savings under Consideration			
668	Major Cost Changes ( Prime Cost )			
669	Major Cost Changes ( Prime Cost )			
673	Manufactures Participation By Segment	1973/74		
674	B Plus B Reskin Exterior Dimension Comparison			
676	B Reskin Plus Saloon Size and Specification Lineup			
677	B Reskin B Plus Variable Cost Relationship to B and C			
678	B Reskin B Plus Panel Formula Orginal Plan			
679	B Reskin B Plus Panel Formula (Saloons) Current Status			1500-1250 Engines
680	B Reskin B Plus Panel Formula Saloons Current Status			1725 Engine
683	B Plus B Re-Skin Formula Estates Current Status			
684	B Reskin B Plus Model Limeup Prices			
685	B Plus B Reskin Engine Range Comparision			
686	Planned Weekly Capacities J Series			
687	To Small to Read ?			
688	To Small to Read ?			
689	PPC meeting Structure U.K.Market 1 Color Slide J McDonald	06/01/1970		Note
690	Tradesman 108 Wheelbase Van		Dodge A100	
691	Dodge Job Mated Tradesman Vans		Dodge A100	
692	Dodge Tradesman Vision Van		Dodge A100	
693	Rootes B Vehicle Presentation Utilisation Chart B			
694	Section Drawing Thru B Rear Axle			
695	3 Alternative Dashboard Layouts			
696	Photo of Dash in Lorry Cab		Lorry?	

697	Photo of Drivers position in Lorry Cab	Lorry?	
698	Photo of Dash in Lorry Cab	Lorry?	
699	Photo of Lorry Can Nearside Door Open	Lorry?	
700	Photo of Drivers position in Lorry Cab	Lorry?	
701	Photo of Dodge Van Frint	Vision Van?	
702	Photo of Dodge Vision Van Front Offside Quarter	Vision Van?	
703	Photo Of Dodge Vision Drivers Position	Vision Van?	
704	Structure of the UK Market		Water Damage
705	4 Profile Car Shapes-Saloon Coupe Estate		Water Damage
706	Outline 4 Door Passenger Compartment People Outlines		
707	Many Blue Chrysler Pentagons		
708	Press Cutting of Holden Torana Australias	Torana	
709	Profitability Statementon P.B. Minor Facelift		
710	Timing Schedule for Facelift		
711	Investment Costs for P.B. Minor Facelift		
712	Volume Data P.B. Minor Facelift		
713	Option Prices for Deluxe Cabs on Van Ranges		
714	/8A Photo of (Avenger) Car from another	Avenger?	2 Negatives
714	2x35mm Photo of Avenger? From another Car.		Package Damaged
715	Photo Van Cab Drivers Position	Bedford?	
716	Photo Van Cab Drivers Position	Bedford?	
717	Photo Van Cab Drivers Position	Bedford?	
719	Photo Van Cab Drivers Position	Bedford?	
720	Photo of Van Front side nearside Quarter	Bedford?	
721	Comparision of Design Differences		2 Negatives
722	Comparision of Design Differences		2 Negatives
723	1970 U.K.Domestic Market Light Car Segment Sedan Prices		2 Negatives
724	New Product Programme by Major U.K. Manufactures		2 Negatives
725	!970 U.K.Domestic Market Smal Car Segment Sedan Prices		2 Negatives

726	Comparision of Design Differences		Imp-Arrow-Avenger	2 Negatives
727	Structure of uk Market			4 Negatives
728	Rootes Passenger Car Engines			2 Negatives
729	Site Boundary Map (Linwood Plant)			
730	Site Boundary Map (Linwood Plant) with added Buildings?			
731	UK Market by Segment 1965-1975	1965-1975		2 Negatives
732	Side View Outline with Power Chain B Car			
733	100 Series Abridge Profile Issue 10	27/07/1970		
734	Timing Schdule for Minor Facelift	Jan/Feb 1970		
735	P B Van Range Minor Facelift (Title Slide)			
736	Production Releases			
737	100 Series Timing	Mar-70		
738	Option Prices for Deluxe Cabs on Van Ranges			
739	Investment Costs for P.B. Minor Facelift			
740	Walk Thru Programme Review (Title Slide)			
741	Reason for Keeping the Walk Thru			
742	Accounte Loss Walk-Thru Range	1965-1974		
743	Price Increases Effective from 1 Jan 1970 Walk Thru Range		Model K30	
744	Price Increases Effective from 1 Jan 1970 Walk Thru Range		Model KC 40	
745	Financial Effect of Walk-Thru Deletion			
746	Programme Approval Package April 1968 Notes 1 to 6	Apr-68		
747	Programme Approval Package April 1968 Notes 7 to 13	Apr-68		
748	Present Walk-Thru Improvement Package Notes 1 to 6			
749	Proposed New Items			
750	Indicative Volumes for Walk Thru Range			
751	Top Half Photo of 2 Door Saloon Ford Taunus?		Ford Taunus?	
752	Bottom Half Photo of 4 Door Saloon Avenger?		Avenger?	
753	Photo of 2 Door Saloon		?	BE 96096
754	Market Relationship of UK Competitive Entrants			

755	Diagram Avenger Interior and Exterior Width	Avenger	
756	Section Drawing Thro B Rear Axle		
757	B Car Objectives "More Car Than Competition"		
758	Outline Side view Comparision of Arrow and B Car Gearbox		
759	Outline Of B Car Rear suspension		
760	Side Outline with Drive Chain B Car		
761	Diagram of Cross Section of B Engine		
762	Comparision of B Model v Arrow Seating Package		
763	UK Car Market by Segment Early 1960's		
764	UK Car Market by Segment 11 Months 1969		
765	UK Car Market by Segment Mid 1960's		
766	Photo of Nearside of Hunter (Arrow)	Hunter	
767	Photo of 4 Door Saloon Avenger?	Avenger?	PVC 606H
768	Photo of 4 Door Saloon Rear 2 People	?	
769	"Kingfisher Blue" Photo of Series 5 Hillman Minx	Minx	
770	Photo of People around a Fullsize Car Model Design Workshop	?	
771	Photo of People Building above Model Design Workshop	?	
772	Photo of Ford 105E Anglia	Ford Anglia	
773	Photo of Vauxhall Viva	Vauxhall Viva	
774	Photo of 3 Dash layouts		
775	Photo of 4 Door Saloon 2 People	?	
776	Photo of 4 Door Saloon Grill Change	?	
777	Photo of 4 Door Saloon Avenger?	Avenger?	
778	Photo of Avenger production Line	Avenger	
779	Photo of Front Seating in Automatic Car Avenger?	Avenger ?	
780	Side View Diagram of Car W1 with Engine Block	?	
781	Side View Diagram of Car W3 with Engine Block and Drive	?	
782	Variable Costs Detail (Over)		
783	Kety Model Costs Vendor Tooling		
784	Key Model Cost Variable Cost		

785	100 Series Status Review 24-March 1970 (Title Slide)	24/03/1970		
786	100 Series Timing			
787	Barreiros E.H.D. Tractor		Tractor	
788	Investment Costs for P.B. Minor Facelift			
789	Profitability			
790	Capital Expenditure			
791	500 Series Deluxe Car			
792	Weight Variance 11.2 Ton Key Model 103 Range			
793	Items for Discussion			
794	Volume Loss Detail 104 Range			
795	Volume Loss Detail 103 Range			2 Negatives
796	Volume Loss Detail 102 Range			
797	Volumes 100 Series			
798	Timing 100 Series			
799	Photo of Coupe Front Offside View		?	2 Negatives
800	Photo of Coupe Offside View			2 Negatives
801	Photo Fullsize Model of Coupe Style Car Front			2 Negatives
802	Photo Fullsize Model of Coupe Style Car Rear			2 Negatives
803	Photo Fullsize Model of Coupe Style Car Nearside			2 Negatives
804	Photo Fullsize Model of Coupe Style Car Nearside Rear			3 Negatives
805	Photo Coupe Style Car Gallant		Gallant?	4 Negatives
806	Photo Coupe Style Car Gallant			4 Negatives
807	Major Unit Programme Front Axle Variable Costs			
808	Major Unit Programme Front Axle Reasons for Proposal			
809	Major Unit Programme Proposal			
810	Eaton Axles - Gearbox			
811	Major Unit Programme Current Drive Line Components			
812	Major Unit Programme Design and Development Cost			
813	Major Unit Programme Variable Costs Axles			
814	Variable Cost Assumptions			
815	Major Unit Programme Proposed Units G/Box - Axles			
816	Major Unit Programme Commer and Dodge Trucks			
817	Major Unit Programme Graph Indicative Cost Savings			

818	Major Unit Programme Variable Costs Gearboxes	
819	Major Unit Programme Rear Axle and Gearbox Investment	
820	Major Unit Programme Proposed Major Unit Lineup	
821	To small to read Presentation Slide?	
822	To small to read Presentation Slide?	
823	To small to read Presentation Slide?	
824	To small to read Presentation Slide?	
825	To small to read Presentation Slide?	
826	To small to read Presentation Slide?	
827	Rootes Motors Limitede plus Pentagon	1 Pos/1 Neg
828	Major Unit Programme Proposed D/L Units	
829	Major Unit Programme Proposal	
830	Major Unit Programme Current Drive Line Components	
831	Major Unit Programme Indicative Cost Savings	
832	Major Unit Programme Variable Cost	
833	Major Unit Programme Design and Development Cost	
834	Major Unit Programme Return-Rear Axle/Gearbox Return on Investment	
835	Major Unit Programme Return-Rear Axle/Gearbox Payback	
836	Major Unit Programme Volumes Proposed Unit Lineup	
837	Major Uinit Programme Front Axle Return on Investment	
838	Major Unit Programme Front Axle Payback	
839	Major Unit Programme Front Axle Investment	2 Negatives
840	Epicyclic Drive	
841	Range Change 8 Speed Gearbox Straight 8 Speed G/Box	2 Negatives
842	Advantages of Cummins V504 over V8 470	
843	Cummins V8 504 Investment	
844	Cummins V8 504 190 Volumes	
845	Variable Cost (Over)/Under V8 470	2 Negatives
846	Technical Detail Cummins Engines	2 Negatives
847	Product Study April 1970	

848	Cummins V 8 504 Average Annual Financial Effect		
849	List of Names and Addresses		
850	Block Diagram of Departments and Management		Damaged
851	Walk Thru Improvements Profitability Statement		
852	Walk Thru Improvements Investment Costs		
853	Walk Thru Improvements Timing Schedule		
854	Walk Thru Improvements Price Increases		
855	Walk Thru Improvements Programme Approval May 1970	May-70	2 negatives
856	Volumes Walk Thru Range Domestic		
857	Present Walk Thru Improvement Package		
858	Proposed New Items		
859	Sunbeam Arrow Badge"		Sunbeam Arrow
860	Plymouth Avenger Badge		Plymouth Avenger
861	Sunbeam Arrow Badge"		Sunbeam Arrow
862	Plymouth Badge		Plymouth
863	Photo of 6 Cars/Models Own and Competitors		Various
864	Photo of 6 Cars/Models Own and Competitors		Various
865	Cutting Autocar 7-5-1970 Ford Pinto GM XP887		Ford Pinto
866	Photo Toyota Corona Mark 2		Toyota Corona
867	Ford 15M (Foreign Magazine)		Ford 15M
868	Opel Coupe plus 2		Opel Coupe
869	Mercedes 4.5		Mercedes 4.5
870	VW/NSU K70		VW-NSU K70
871	Ford 12m-15M (Foreign Magazine)		Ford 12M-15M
872	Ford 12m-15M (Foreign Magazine)		Ford 12M-15M
873	Photo of Underside Engine Bay Car?		?
874	Photo of Underside Engine Bay Car?		?
875	Photo of Underside of Rear Car?		?
876	Photo of Nearside of Car? Doors Open		?
877	Photo Boot of Renault 12		Renault 12
878	Photo Engine Bay Renault 12?		Renault12?

879	Models for Future Annouement		Various Competi- tiors	
880	36 Own and Competitors Cars/Models Prices	May-70	Various	
881	11 Own and Competitors Cars/Models Specs-Dimensions		Various	Sht 1 of 2
882	11 Own and Competitors Cars/Models Specs-Technical		Various	Sht 2 of 2
883	11 Own and Competitors Cars/Models History Sales	1969	Various	
884	Chrysler B Car v Ford Europe			
885	Photo of Differential Area Lorry?		?	
886	Photo of Engine Rear Area Lorry?		?	
887	Photo of Silencer Underside of Lorry?		?	
888	Photo of Engine/Injectors of Lorry?		?	
889	Photo of Engine Top of Lorry?		?	
890	Photo of Gearbox end of Engine Lorry?		?	
891	Photo of Chassis fixing/Mounting Fitting Lorry?		?	
892	Photo of Rear Spring to Chassis fix- ing		?	
893	Photo of Detail Fitting? Lorry?		?	
894	Photo of Detail Fitting? Lorry?		?	
895	Photo of Hub (Front) Lorry?		?	
896	Photo of Hub (Front) Lorry?		?	
897	Photo of Cable Harness		?	
898	Photo of bare Lorry Chassis		Lorry?	
899	Photo of bare Lorry Chassis with Wheels		Lorry?	
900	Photo of Lorry? Engine			
901	Photo of Lorry Engine and under- slung Radiator		Lorry	
902	Photo Sidelights on Cab/Van			
903	Photo of Van Body Rear			
904	Photo of bare Lorry Chassis		Lorry	
905	Phot Triumph 1300 Saloon		Triumph 1300	GWK 879D
906	South African Spec			
907	Engine Applications			
908	Car Features			
909	Cab Weight and Simplicity 103 and 500 Series			
910	Timing Job No 1			
911	Competitive Weight Summary 100 Series Key Models			
912	Block Diagram of Departments and Management			



913	Action and Risk			
914	Weight Status			
915	Unit Variable Cosr Movement by Key Model			
916	Domestic Retail Price Movement Key Models			
917	Unit Variable Cost Movement Approved Changes			
918	Volume Change Casual Factors 1971	1971		
919	Volume Change by Range 1971	1971		
920	Timing Domestic			
921	Arrow Facelift Key Dates	July 1970- Oct 1971	Arrow	
922	Financial Summary 1971 - 4	1971-1974		
923	100 Series Staus and Finanal Report No 2June 1970	Jun-70		
924	Casual Factors			
925	Cost Variance Causal Factors Summary 1971 - 4	1971-1974		
926	South Africa Spec Commercial Vechicles 10,000-14,000 lb			
927	South Africa Spec Commercial Vechicles 14,000-16,000 lb			
928	South Africa Spec Commercial Vechicles 16,000-19500 lb			
929	South Africa Spec Commercial Vechicles 19,501-26,000 lb			
930	South Africa Spec Commercial Vechicles 26,001-32,500			
931	Chrysler U.K. Proposed Models 26,001-32000lb			
932	Photo of Car Front		?	
933	Photo of Car Rear Houses in Background			
934	Photo thro Edge of Windscreen another Car		?	
935	Photo 2 Cars Parkes Front on Rear		?	
936	Photo on open road Overtaking		?	
937	Photo of Lorry/Car at crossroads		?	
938	Photo of 2 Cars in Driveway		?	BGF 196H
939	Photo of 3 Cars at Roadworks		?	
940	Cutting (Foreign Magazine) 2 Door Saloon Car		?	
941	Cutting (Foreign Magazine) 2 Door Saloon Car		?	
942	Cutting (Foreign Magazine) 2 Door Saloon Car Rear		?	
943	Cutting (Foreign Magazine) 2 Door Saloon Car Side/Rear		?	

944	Cutting (Foreign Magazine) New Fiat 850		Fiat 850	
945	Arrow Facelift 1972 Model Year	1972	Arrow	
946	Iran Arrow Facelift 1971 Model Year	1971		
947	Paint and Trim Colours 1971 Model Year	1971		
948	Ride/Drive Outward Route (A.M.)			
949	Ride/Drive Afternoon Route			
950	Ride/Drive Return Route (A.M.)			
951	Model History Production and Sales 1969 Routes and Competitors	1969		
952	Specifications Sheet 1 of 2 Technical	May-70		
953	Specifications Sheet 2 of 2 Technical	May-70		
954	Motor Road Test or Advertising Material			
955	Pricing Hillman and Competitor Cars			
956	Model for Future Announcement (Competitor Cars)			
957	Destroyed			
958	Triumph 1500	20/08/1970	Triumph 1500	RVC 458H
959	Triumph 1500	20/08/1970	Triumph 1500	RVC 458H
960	Photo of 2 Door Saloon Car		?	RRW 97J
961	Photo of Control Pedals		?	
962	Photo of Car just below Driving Mirror		?	
963	Photo of Car Drivers Position		?	
964	Photo of Car Engine over Wing Bonnet Open		?	
965	Photo of Exhaust under Car?		?	
966	Photo on Underside of Car Towards Front		?	
967	Photo on inside of Wheel		?	
968	Photo on Underside of Car Towards Front		?	
969	Photo showing Sparewheel in Boot		?	
970	Exclusive 2 Photos of Car thro Bars		?	
971	Photo of Small 4 Door Car Rear Nearside Quarter		?	
972	Photo of Perche127?		Perche 127	Damaged
973	Photo of New Citroen GS		Citroen GS	
974	3 Views of Citroen GS		Citroen GS	
975	Tatra "T 613"		Tatra T 613	
975	2nd Cannot get out of Package			Water Damage
976	Exclusive 2 Photos of 2 Door Car		?	
977	5 Photos of Small Cars (2 Models)		?	
978	Photo of Small 2 Door Car		?	

979	2 Photos of Bmw Opel Cars		BMW Opel	
980	3 Photos of Opel and BMW Cars		Opel BMW	
982	Photo of Coupe Style Car behind Barrier		?	
983	Photo of Coupe Style Car behind Barrier mot 8/70	Aug-70	?	
985	Photo of Arrow Car Rear		Arrow	LWK 839F
986	Photo of Arrow Car Fronr		Arrow	LWK 839F
987	Photo of Arrow Car Nearside		Arrow	LWK 839F
988	Photo of Arrow Carb Nearside Rear Quarter		Arrow	
989	Photo of Arrow Car Nearside		Arrow	
990	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
991	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
992	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
993	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
994	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
995	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
996	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
997	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
998	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
999	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
1000	Imp MHP 181F (Has Mk1 Trim)		Imp	
1001	Photo of Imp Offside Front Quarter		Imp	
1002	Imp MHP 181F (Has Mk1 Trim)		Imp	
1003	Imp MHP 181F (Has Mk1 Trim)		Imp	
1004	Imp MHP 181F (Has Mk1 Trim)		Imp	
1005	Photo Nearside of Arrow		Hunter?	
1007	Photo Hillman Hunter Rear Offside Quarter		Hunter	YMV 626H
1008	Photo Hillman Hunter Rear		Hunter	YMV 626H
1009	Photo Hillman Hunter Front		Hunter	YMV 626H
1010	Photo Lorry Short Wheelbase		Lorry	
1011	Photo Lorry Short Wheelbase		Lorry	
1012	Photo of Coach-Barrebos		Coach	
1013	Photo of Rocket Battery Fitted Truck		Military	
1014	Photo of Tilt Covered Lorry		Lorry	

1015	Photo of Tilt Covered Lorry	Military	
1016	Photo of Tilt Covered Lorry Militaires Barreiros	Military	
1017	Articulated Lorry plus Trailer Options	Lorry	
1019	Tractor 7.000	Tractor	
1020	Lorry being loaded bt Forklift	Lorry	
1021	Coach inside plus Engine and Drivers Position	Coach	
1022	Photo of Car 2 Door Saloon	?	1971 AC 78
1023	Photo of Car 4 Door Saloon	?	1971 AS 78
1024	Photo of Yute-Pickup Chrysler Banayi Fargo	Fargo	
1025	Photo of Hillman Hunter DL Rear	Hunter	
1026	Photo of Hillman Hunter DL Offside Front Quarter	Hunter	
1027	Photo of Hillman Hunter DL Offside	Hunter	
1028	Photo of Hillman Hunter DL Rear Offide Quarter	Hunter	
1029	Photo of Hillman Hunter DL Front	Hunter	
1030	Imp MYM 770H Outside Offices	Imp	
1031	Photo Avenger Estate Car People	Avenger	SVC 826J
1032	Photo Avenger Estate Car	Avenger	SVC 826J
1033	Photo Avenger Estate Car Rear	Avenger	SVC 826J
1034	Bar Chart European b Saloon KR 641		
1035	Photo of Car 2 Door Saloon	?	
1036	Photo/Outline Hatchback Saloon Cars	?	MLG 401H
1037	2 Photos of Car 2 Door Saloon thro bars	?	
1038	Magazine Cutting Of Triumph? 2 Door Saloon	Triumph?	RVC 447H
1039	Photo of Car 2 Door Saloon at speed	?	
1040	Photo of Car LHD 4 Door	?	7122 VZ 75
1041	Photo of Commer Van	Commer Van	
1042	Photo of Larger Van	Van	
1043	Photo of SWB Commer Lorry	Commer Lorry	
1044	Date Barchart Chrysler Product Plan - Passenger Car	Various	
1045	Date Barchart - US 2 Door Coupe H/A 429	H/A 429	
1046	Date Barchart - Eupropean B Saloon K/R 641	K/R 641	
1047	Barchart Arrow Facelift H/R 541	Arrow	
1048	Date Line Paint and Trim Colours 1972 Model Year		1972

1049	Barchart Iram Arrow Facelift H/I 541		Arrow	
1050	Date Line B Estate Car H/R 445		H/R 445	
1051	Date Line Chrysler European Product Plan Passenger Car		Various	
1052	Effects of BHP/Ton Legistration on Current Range			
1053	Current Longe Range Plan Strategy			
1054	U.K. Market Size - Volume			
1055	Phase 1 Proposals			
1056	Recommended Guidelines for 500 Series Replacement			
1057	Possible Alternative Regulations			
1058	Construction and Use Regulations			
1059	Expected Regulation			
1060	Why Replace the 500 Series			
1061	Decisions Required			
1062	500 Series Phase 1			
1063	Alternatives Cabs			
1064	Possible Power Trains with 8 BHP/Ton			
1065	Actions Required 500 Series			
1066	Planning Assumptions			
1067	Current Heavy Truck L.R.P.			
1068	Premium Heavy Truck Market (1969)	1969		
1069	15m Length / Front Overhang	Oct-70		
1070	Possible Power Trains with 8 BHP/Ton			
1071	500 Series Phase 1			
1072	Phase 1 Proposals			
1073	Expected Regulation			
1074	Current Heavy Truck L.R.P.			
1075	Premium Heavy Truck Market (1969)	1969		
1076	15m Length / Front Overhang			
1077	1969 European Heavy Truck Market	1969		
1078	Could not Rear Stuck in Package			
1079	Photo Of 2 Door Coupe Rear		?	Stuck
1080	Photo Of 2 Door Coupe Nearside		?	
1081	Photo Of 2 Door Coupe Nearside Front Quarter		?	HVW 834J
1082	Interior Photo of Front Seating of Car		?	Stuck
1083	Photo of Cortina Estate Car Nearside		Cortina	
1084	Barchart Chrysler European Product Plan Passenger Car		Various	

1085	Barchart Chrysler European Product Plan Passenger Car	Various	
1086	Barchart Chrysler European Product Plan Passenger Car	Various	
1087	Barchart Chrysler European Product Plan Commercial Vehicles	Commercial	
1088	Barchart Chrysler European Product Plan Commercial Vehicles	Commercial	
1089	Photo of Simca 1204 Special	Simca1204	
1090	Photo of Simca 1000 Special	Simca1000	
1091	Photo of Simca 1200 S Coupe	Simca 1200S	
1092	Photo of Simca 1501 Special	Simca 1501S	
1094	Photo of Fiat 125 Special	Fiat 125	
1095	Photo of Fiat 124	Fiat 124	
1096	Interior Photo of Front Seating of Car	?	Stuck
1097	Interior Photo of Fiat 124	Fiat 124	
1098	Interior Photo of Fiat 125 Special	Fiat 125	
1099	General Data Engines		
1100	Exterior Dimensions		
1101	Chrysler 100 Standard Features		
1102	General Data Chassis		
1103	Interior Package		
1104	Barchart Chrysler European Product Plan Passenger Car	Various	
1105	Barchart Chrysler European Product Plan Commercial Vehicles		
1106	Photo in Showroom a line of 9 Cars	Various	
1107	Imp SDU 626 Show Stand Pictures	Imp	
1107	Photo in Showroom a line of 8 Small Cars	Various inc Imp	
1108	Imp SDU 626 Show Stand Pictures	Imp	
1108	Photo in Showroom 2 lines of Cars as 1106-1107a	Various inc Imp	
1109	Photo of Car Wheel Firestone Wide Oval Tyre		
1110	Long Range Plans Key Date Timing Chrysler Europe Cars		
1111	Long Range Plans Key Date Timing Chrysler Europe Cars		
1112	Long Range Plans Key Date Timing Chrysler Europe Cars		
1113	Photo of 4 Door Saloon Car	?	DYF 334
1114	Photo of LHD Fastback Car Audi?	Audi?	
1116	Photo of 4 Door Saloon Car Audi	Audi	
1118	2 Photos of 2 Door Coupe Style Car	?	
1119	Photo of 4 Door Coupe Style Car People Relaxing	?	

1120	Photo of 4 Door Saloon Car		HVW 823J
1121	Photo of 2 Door Car Capri	Capri	KEV 915L
1122	2 Photo of 1971 Vega 2300 Coupe	Vega 2300	
1123	Hillman Hunter Chrysler UK	Hunter	
1124	UK-Simca 3303? Chrysler France	Simca 3303?	
1125	100 Series Truck	Truck	
1126	Renault 12	Renault	
1127	Fiat 126?	Fiat	
1128	Colt Gallant	Colt	
1129	Simca 3300	Simca 3300	
1130	Simca 3301	Simca 3301	
1131	Hillman Avenger	Avenger	
1132	Ford Escort	Ford Escort	2 Negatives
1133	Alpine/Rapier Chrysler U.K.	Alpine/Rapier	
1134	Austin/Morris 1100/1300	BMC 1100/1300	
1135	Vauxhall Viva GM UK	Viva	
1136	Chrysler 160/180 (Chrysler France)	Chrysler 160/180	
1137	Cortina Mk III	Cortina	Stuck
1138	Toledo	Toledo	Stuck
1139	Foreign Magazine Article Test VW 1302/1302S	VW 1302	
1140	Foreign Magazine Article Test VW K70	VW K70	
1141	Foreign Magazine Article Mercedes 250/250CE	Mercedes 250	
1142	Foreign Magazine Article Opel Model?	Opel?	
1143	Cartoon City Fire Tender		
1144	Barchart Chrysler European Prod- uct Plan Passenger Car	Various	
1145	Magazine Article VW Small Car	VW?	Stuck
1146	Outline BMW Coupe	BMW	Stuck
1147	2 Photos of Renault 12	Renault 12	Stuck
1148	Mini Volkswagen	VW	Stuck
1150	Mini Audi	Audi	Stuck
1151	BMW 2000	BMW 2000	Stuck
1152	Mercedes 350SL	Mercedes 350SL	Stuck
1153	Outline of 2 Door Coupe Style Car	?	Stuck
1154	Foreign Magazine Article of Small 2 Door Car	?	Stuck
1155	Photo of 2 Door Car	?	Stuck
1156	Photo of 2 Door Small Car	?	Stuck
1157	Photo of 4 Door Car Volvo?	Volvo?	Stuck
1158	Photo of 4 Door Large Car?	?	Stuck
1160	Automotive Product Group Lorry		HUE 997D
1161	Karrier Bantam Tractor Units 1M Order from British Rail	Karrier Bantam	

1163	7 Photos of Imp and 6 Other makes of small Car	Imp +	KYM 770H
1164	5 Photos of Cars Chrysler European Products	Arrow inc	
1165	6 Photos of Vans-Lorries Chrysler European Products		
1166	3 Photos of Lorries Chrysler European Products		
1167	1A Photo of Car thro Window of another	?	
1167	2A Photo of Car thro Window of another		
1167	3A Photo of Car thro Window of another		
1168	4A Photos including Filling Car ar Fuel Pump		
1169	Magazine Article "Rovers Shape of Things to Come"	Rover V	
1170	Car Outline Drawing Iran B Near-side	Iran B	
1171	2 Outline View Drawings of Iran B	Iran B	
1172	Photo of 4 Door Saloon Car	?	
1173	Car Outline Drawing Iran B Rear	Iran B	
1174	18 Negs of Car Details	?	
1175	Photo of 2 Door Coupe Style Car	?	Stuck
1177	Photo of Ford Capri	Ford Capri	
1178	4 Photo of Exterior/Interior of Coupe Style Car	?	Stuck
1179	Photo of 2 Door Coupe Style Car-VW?	VW?	Stuck
1180	Photo of 2 Door Saloon Car	?	Stuck
1181	Chrysler European Product Plan - Commercial Vehicles		
1182	Chrysler Far East and Africa Product Plan Passenger Car		
1183	Chrysler European Product Plan - Passenger Car		
1184	Chrysler European Product Plan - Passenger Car		
1185	Chrysler European Product Plan - Passenger Car		
1186	Chrysler European Product Plan - Commercial Vehicles		
1187	Chrysler European Product Plan - Commercial Vehicles		
1188	Chrysler European Product Plan - Passenger Car		



1189	Chrysler Latin America Product Plan - Passenger Car		
1190	Photo of 2 Door Coupe Style Car?	?	DXE 143J
1191	Chrysler European Product Plan - Passenger Car		
1192	Chrysler European Product Plan - Passenger Car		
1193	Chrysler European Product Plan - Commercial Vehicles		
1281	Photo of Hillman Hunter Front Off-side Quarter	Hillman Hunter	WRW 259J
1282	Photo of Hillman Hunter Front Off-side Quarter	Hillman Hunter	WRW 259J
1283	Photo of Hillman Hunter Rear Off-side Quarter	Hillman Hunter	WRW 259J
1284	Photo of Hillman Hunter Rear Off-side Quarter	Hillman Hunter	WRW 259J
1285	Chrysler European Product Plan - Passenger Car		
1286	Chrysler European Product Plan - Commercial Vehicles		
1287	Chrysler European Product Plan - Passenger Car		
1288	Chrysler European Product Plan - Passenger Car		
1289	Chrysler European Product Plan - Commercial Vehicles		
1290	Chrysler European Product Plan - Commercial Vehicles		
1291	2-2 Colour Negatives of Lorry? Front	Lorry?	
1291	4-2 Colour Negatives of Lorry? Front Offside Quarter	Lorry?	
1291	6-2 Colour Negatives of Lorry? Side	Lorry?	
1291	7-1 Colour Negatives of Lorry? Inside Cab	Lorry?	
1291	8-1 Colour Negatives of Lorry? Inside Cab	Lorry?	
1291	10-2 Colour Negatives of Lorry? Rear of Tractor Unit	Lorry?	
1292	10 Sheets Expressed Demand for European Size Engines etc		
1293	Engine Cost Penalty U.K. Manufacture	Avenger/Arrow	
1294	Engine Cost Penalty France Manufacture		
1295	15 Color Negs of Lorry? Detail	Lorry?	

1296	Photo of Lorry? Front Nearside Quarter	Lorry?	
1297	Photo of Lorry? Cab Nearside-Dodge?	Dodge?	
1298	Photo of Lorry? Cab Nearside Front Quarter Berliet TR 300	Berliet TR 300	
1299	Photo of Lorry? and Trailer	?	M 887645
1300	Photo of Scania Lorry Tractor Unit Dick Hamptons	Scania	UOT 174H
1301	Photo of Fiat Lorry Cab	Fiat	
1302	Photo of Styer Lorry Cab	Styer	L90 390
1303	Photo of Volvo Lorry Front	Volvo	N5327
1304	Photo of Car Transporter Cab AEC James Car Deliveries	AEC	KPW 425E
1305	Photo of Car Transporter Cab AEC James Car Deliveries	AEC	KPW 425E
1306	Photo of Car Transporter Cab Guy Richmond Rd Garage	Guy	
1307	Photo of Car Transporter Cab Guy Richmond Rd Garage	Guy	
1308	Photo of Henschel Lorry Front Nearside Quarter	Henschel	
1309	Photo of Man Lorry and Trailer	Man	
1310	Photo of Mercedes Lorry and Trailer	Mercedes	
1311	Photo of Daf Articulated Lorry Front	Daf	
1312	Photo of Lorry? Front Nearside Quarter	?	
1313	6 Negatives Roadscene Cars Van	?	
1314	Product Comparision Commercial Vehicles		
1315	A lot of Product Comparision Commercial Vehicles Sheets		
1316	Photo Of Car Rallye 1 Front	Rallye 1	
1317	Photo Of Car Rallye 1 Rear	Rallye 1	
1318	Photo Of Car Rallye 2 Rear	Rallye 2	
1319	Photo Of Car Rallye 2 Front	Rallye 2	
1320	Photo of 4 Door Saloon Car		
1320	Photo of Small Van	Van?	YWK 889K
1321	Photo of Small Van Rear Door Open	Van?	
1351	Photo of the Consul GT	Consul GT	MNO 253K
1352	Photo of the Consul GT? Nearside	Consul GT?	
1353	Photo of a German 4 Door Car Rear Offside Quarter	?	GG-DM 329
1354	Photo of 4 Door Hatchback Car?	?	
1355	Photo of 2 Door LHD Small Car?	?	2807 CB 92
1356	Photo of Opel Ascona SR	Opel Ascona	
1356	2 Photo of 2 Door Small Car	?	

1356	3 Photo of 2 Door Small Car	?	
1356	4 Photo of 2 Door Small Car	?	
1357	Small 2 Door Car	Simca?	
1357	5 Photo of 4 Door Saloon Car	?	
1357	6 Photo of 4 Door Saloon Car	?	
1357	7 Photo of 4 Door Saloon Car	?	
1358	Photo of Consul Fastback Style	Consul	
1358	10 Photo of 4 Door Small Car	?	LGO 961K
1358	11 Photo of 4 Door Small Car	?	
1358	12 Photo of 4 Door Small Car	?	
1359	4 Photo of 4 Door Small Car	?	
1359	5 Photo of 4 Door Small Car	?	
1359	6 Photo of 4 Door Small Car	?	
1359	Photo of Car BMCL 15	BMCL 15	
1360	Photo of Small 4 Door Hatchback Car	?	
1360	1 Photo of 4 Door Saloon Car	?	
1360	2 Photo of 4 Door Saloon Car	?	
1360	3 Photo of 4 Door Saloon Car	?	
1361	5 Photo Of Citroen 4 Door Car	Citroen	
1361	6 Photo Of Citroen 4 Door Car	Citroen	
1361	7 Photo Of Citroen 4 Door Car	Citroen	
1361	11 Photo of 2 Door Small Car	?	
1362	Photo of Saloon Car Auto Union/Audi	Auto Union/Audi	
1362	12-/1/H 3 Photos of Raised Back Van?	Van?	
1363	Photo of Car BMW?	BMW	M-YE 1450
1363	6 Photo of Car Peugeot?	Peugeot	
1363	7 Photo of Car Peugeot?	Peugeot	
1363	8 Photo of Car Peugeot?	Peugeot	
1364	6-Photo of Small 4 Door Car?	?	
1364	11-Photo of Small 4 Door Car?	?	
1364	12-Photo of Small 4 Door Car?	?	
1365	7-Photo of Small 2 Door Car?	?	
1365	8-Photo of Small 2 Door Car?	?	
1365	9-Photo of Small 2 Door Car?	?	
1366	2- Photo of 4 Door Hatchback Type Car Renault?	Renault?	
1366	3- Photo of 4 Door Hatchback Type Car Renault?	Renault?	
1366	4- Photo of 4 Door Hatchback Type Car Renault?	Renault?	
1367	Photo of Wheel/Tyre		
1368	3 Colour Negs Rallye 2 Simca 1100. French Reg	Simca Rallye	
1369	Chrysler 180 BKV 303K	Chrysler 180	
1369	6-Photo of 4 Door Saloon Car?	?	

1369	11-Photo of 4 Door Saloon Car?	?
1369	12-Photo of 4 Door Saloon Car?	?
1370	Fiat 127, K Reg	Fiat 127
1370	4-Photo of Small 2 Door Hatchback Car	?
1370	5-Photo of Small 2 Door Hatchback Car	?
1370	6-Photo of Small 2 Door Hatchback Car	?
1371	Mk1 Simca 1100 Van	Simca 100 Van
1371	1- Photo of Small Van?	?
1371	2- Photo of Small Van?	?
1371	3- Photo of Small Van?	?
1372	Avenger Super Estate	z
1372	1-Photo of Estate Car?	?
1372	2-Photo of Estate Car?	?
1372	3-Photo of Estate Car?	?
1372	4-Photo of Estate Car?	?
1373	5-Photo of 2 Door Fastback Car?	?
1373	6-Photo of 2 Door Fastback Car?	?
1373	7-Photo of 2 Door Fastback Car?	?
1374	Ford Granada Mk1	Granada
1374	8- Photo of 4 Door Saloon Car Ford?	Ford?
1374	9- Photo of 4 Door Saloon Car Ford?	Ford?
1374	10- Photo of 4 Door Saloon Car Ford?	Ford?
1375	Ford Granada Mk1 Estate	Granada
1375	H/12-2 Views of of a Car? Interior	?
1376	Maxi	Maxi
1376	6-Photo of 4 Door Car Maxi?	Maxi?
1376	8-Photo of 4 Door Car Maxi?	Maxi?
1377	Capri	Capri
1377	6-Photo of 2 Door Fastback Car Capri?	Capri?
1377	7-Photo of 2 Door Fastback Car Capri?	Capri?
1377	8-Photo of 2 Door Fastback Car Capri?	Capri?
1378	Taunus Coupe	Taunus Coupe
1378	9-Photo of 2 Door Fastback Car?	?
1378	10-Photo of 2 Door Fastback Car?	?
1378	11-Photo of 2 Door Fastback Car?	?
1944	BMC 1100/1300	1100/1300
1945	Maxi	Maxi
1946	NSU RO80	RO80
1947	BMC 1800	1800
1948	Mini	Mini
1949	Datsun Cherry 100A	Datsun Cherry

1950	Alfasud		Alfasud
1951	Ford Taunus Estate		Ford taunus Estate
1952	Fiat 132		Fiat 132
1953	Opel Kadett Estate		Opel Kadett Estate
1954	German Group Test		
1955	Chrysler Euro Product Plan		
1979	K Reg Audi 100 Coupe		Audi 100
1980	Product Development Competition, with Photos		
1981	Product Development Competition, with Photos		
1982	Toyota		Toyota
1983	Datsun? Vertical Light over Wing Toyota?		Datsun 180B
1985	Datsun 180B		Datsun 180B
1986	Opel Kadett 2 Door		Opel Kadett
1987	Opel Kadett 2 Door		Opel Kadett
1988	Early VW Golf		VW Golf
1989	Opel Kadett	Oct-72	Opel Kadett
1990	Allegro, K Reg Princess (Wedge) with Boot Spoiler		Allegro and Princess
1991	Opel Kadett Impression		Opel Kadett
1992	VW Passat		VW Passat
1993	VW Passat	1973	VW Passat
1994	Renault R23	1973	Renault R23
1995	Sherpa Van, Distant Shots		Sherpa Van
1996	Mk2 Capri GT		Capri
1997	Mk2 Capri GT		Capri
1998	Mk2 Capri GT		Capri
1999	Mk2 Capri GT		Capri
2000	Mk2 Capri GT		Capri
2002	VW Golf Mk1		Golf
2003	Renault 5		Renault 5
2004	Opel like a Metro		Opel
2005	Opel/Innocenti cross?		Opel
2006	VW Polo Mk1		VW Polo
2007	Opel Kadett Impression		Opel Cadet
2008	104/LNA Impression		
2009	Mk1 Fiesta, Artists Impression		Fiest
2010	VW Golf, German Specification		VW Golf
2011	VW Golf Mk1 4 Door		VW Golf
2012	Golf, Fiat 128		Golf / Fiat 128
2013	Escort, Opel		Escort / Opel
2014	Simca, Renault 6, Golf		Simca
2015	VW Golf Mk1 Advert		VW Golf
2016	K M Bedford		Bedford

2017	K M Cab Interior Bedford	Bedford
2018	Simca 1100 Van	Simca 1100 Van
2021	Early Sherpa Van	Sherpa
2022	Chrysler 180 After Crash Test Rear View	Chrysler 180
2023	Chrysler 180 After Crash Test Rear View	Chrysler 180
2024	Chrysler 180 After Crash Test	Chrysler 180
2024	Chrysler 180 After Crash Test	Chrysler 180
2025	No62 Smashed Front 4 Door	Humber?
2026	Chrysler 180 Interior	Chrysler 180
2027	Chrysler 180 Before Crash Test	Chrysler 180
2028	Chrysler 180 Before Crash Test	Chrysler 180
2029	Chrysler 180 Before Crash Test	Chrysler 180
2030	Chrysler 180 Before Crash Test	Chrysler 180
2031	Chrysler 180 Before Crash Test	Chrysler 180
2032	Chrysler 180 RH Side Before	Chrysler 180
2033	Chrysler 180 RH Side Before	Chrysler 180
2034	Chrysler 180 LH Side Before	Chrysler 180
2035	Chrysler 180 Front View (Crashed)	Chrysler 180
2036	Chrysler 180 Rear View - French No plates	Chrysler 180
2037	Chrysler 180 Crash Test Interior	Chrysler 180
2038	Chrysler 180 Crash Test LH Side View	Chrysler 180
2039	Chrysler 180 Crash Test Underside	Chrysler 180
2040	Peugeot/Citroen Product Development	
2041	Ford Product Development	
2042	Fiat Product Development	
2043	Renault Product Development	
2044	VW/Audi Product Development	
2045	BLMC Product Development	
2046	Europe Product Development	
2047	Fuel Consumption vs Competition 840-1100cc	
2048	Fuel Consumption Avenger vs Competition 1100-1600cc	
2049	Fuel Consumption Hunter vs Competition 1600-2000cc	
2050	Chrysler European Trucks Projection	
2051	Dodge Pick Up Interior	Dodge Pick Up
2052	Dodge Pick Up	Dodge Pick Up
2053	Dodge Pick Up	Dodge Pick Up
2054	Dodge Pick Up	Dodge Pick Up
2055	Dodge (D50) Pick Up	Dodge Pick Up
2056	Magirus Deutz Lorry	

2057	Opel Ascona		Opel Ascona	
2058	2 door Coupe (Opel Manta Influenced)			
2059	Alpine Prototype and V W Passat		Alpine Prototype	
2060	Ford Escort 4 Door		Escort	
2061	Solar Prototype and Audi		Solra Prototype	
2062	Commer Road Sweeper, Norwich. Commando Type		Commer	
2063	Dodge Commando Tipper		Dodge Commando	
2064	Dodge Commando		Dodge Commando	
2065	PVC 153 N Commer PB Ambulance (Works)		Commer PB	
2066	Lorry Chassis			
2067	M Reg Dodge Commando		Dodge Commando	
2068	Dodge Barreiros Tractor Unit		Dodge	
2069	Dodge Cab Interior	Late 1970's	Dodge	
2070	Three Dashboard Commercial			
2071	Consept 4 Door GT Car		?	
2072	Consept Utility Badged Commer		Commer	
2073	Consept Pickup		?	
2074	Renault 14, Peugeot 205 Photo		Peugeot 205	
2118	Photo of 4 Door Saloon Car Avenger?		Avenger?	
2119	Photo of 4 Door Saloon Car Avenger?		Avenger?	LRW 163P
2120	Photo of 4 Door Saloon Car Avenger?		Avenger?	LRW 163P
2121	Photo of 4 Door Saloon Car Avenger?		Avenger?	LRW 163P
2122	Photo of 4 Door Saloon Car Avenger?		Avenger?	LRW 163P
2123	Photo of 4 Door Saloon Car Avenger?		Avenger?	LRW 163P
2124	Photo of 4 Door Saloon Car Avenger?		Avenger?	LRW 163P
2125	Photo of 4 Door Saloon Car Avenger?		Avenger?	LRW 163P
2126	9 Photo Of Details of Car Interior			
2127	Photo of 2 Door Car Ascona		Ascona	
2128	Photo of 4 Door Car Ascona		Ascona	
2129	Photo of 2 Door Car Manta		Manta	
2130	Photo of 2 Door Car Manta		Manta	
2131	Photo of 4 Door Car Manta		Manta	
2132	Photo of German 2 Door Small Car		?	K-UT 202
2133	Photo of German 2 Door Small Car		?	K-UT 202

2134	Photo of 4 Door Car Renault	Renault	5228 EK 92
2135	Photo of Fiat 128-3P	Fiat	
2136	Photo of 2 Door Hatchback Car?	?	
2137	Photo of 2 Ford?Door Saloon Car	Ford?	K-AP 996
2138	Photo of 4 Door Estate Car?	Estate?	
2139	Photo of 2 Door Fastback Car?	?	LMJ 243P
2140	Photo of 4 Door Saloon Car?	?	LMJ 242P
2141	Photo of 4 Door Hatchback Car?	?	5232 EK 92
2142	Photo of a Number Plate just		
2143	Photo of 2 Door Hatchback Car?	?	
2144	Photo of 4 Door Renault 20 TL	Renault 20 TL	
2145	Photo of 2 Door LHD Small Car? Tradeplates	?	
2146	Photo Of 4 Door Saloon Car Ford?	Ford	K-LV 526
2147	Photo Of 4 Door Saloon Car Ford?	Ford	K-LV 526
2148	Photo of 2 Door Hatchback Car?	?	
2149	Photo of 2 Door German Hatchback Car?	?	K-UK 993
2150	Magazine Article Tipo 124	Tipo 124	
2151	Magazine Article Coupe Seat 143	Seat 143	
2152	Photo of 2 Door Small Car?	?	
2153	Photo of Hatchback Rear Door	?	
2154	Grainy Photo of Car	?	
2155	Grainy Photo of 4 Door Saloon	?	
2156	Specifications, Timing, Emissions Literature		
2156	Grainy Photo of Audi 120	Audi 120	
2157	Photo of 2 Door Car?	?	
2158	Photo of 2 Door Car?	?	
2159	5 Photos of Car?	?	
2160	12 Photos of Detail of Inte- rior/Exterior Car	?	
2160	15 Photos of Detail of Small Lorry Interior/Exterior	Lorry	
2161	11 Photos of Detail of Interior of Car?		
2161	14 Photos of Detail of People Car- rier Interior/Exterior	People Carrier	
2161	12 Photos of Detail of People Car- rier Interior/Exterior	People Carrier	
2161	Photo of 4 Door Saloon Car Avenger?	Avenger	GVC 185N
2162	Photo of 4 Door Saloon Car Avenger? Offside	Avenger	
2163	Photo of 4 Door Saloon Car Avenger? Nearside	Avenger	GVC 185N
2164	Photo of 2 Door Saloon Hillman	Hillman	OAC 361P
2165	Photo of 2 Door Saloon Hillman	Hillman	OAC 361P



2166	Photo of 2 Door Saloon Hillman	Hillman	OAC 361P
2167	Photo of 4 Door Estate Car Hillman Avenger	Avenger	OAC 362P
2168	Photo of 4 Door Estate Car Hillman Avenger	Avenger	OAC 362P
2169	Photo of 4 Door Estate Car Hillman Avenger	Avenger	OAC 362P
2170	17-Photo of Door Interior		
2170	19-Photo of Front Seats		
2171	20-Photo of Door Interior		
2171	21-Photo of Front Seats		
2172	15-Photo of Door Interior		
2172	16-Photo of Front Seats		
2173	Photo of Front of Car?		
2174	Photo of 4 Door Saloon Car OFF- SIDE Front Quarter		
2175	Photo Of 4 Door Saloon Car?	?	
2176	Photo of the Front of a Small Car Fiat	Fiat	
2177	Photo Of a 2 Door Small Car Fiat	Fiat	
2178	Photo of a 2 Door Fiat Rear	Fiat	
2179	Photo of the Front of Car?	?	
2180	Photo of a Small Hatchback Car?	?	
2181	Photo of an Opel Small Car?	Opel?	
2182	Photo of a Small Fiat Car	Fiat	ORW 976P
2183	Photo of a Small Fiat Car	Fiat	ORW 976P
2184	Photo of a Small Fiat Car Rear	Fiat	ORW 976P
2185	Photo of Front of Car?	?	
2186	Photo of Offside Front of Small Car?	?	
2187	Photo of Nearside Rear of Small Car?	?	
2188	Photo of Front of Car?	?	OHP 488P
2189	Photo of Same Car as 2188	?	OHP 488P
2190	Photo of Same Car as 2188	?	OHP 488P
2191	Photo of Front of VW Small Car?	VW	
2192	Photo of same Car as 2191	VW	
2193	Photo of same Car as 2191	VW	
2194	Photo of Front of VW Small Car	VW	
2195	Photo of same Car as 2194	VW	
2196	Photo of same Car as 2194	VW	
2197	Photo of Front of Vauxhall Car	Vauxhall	MVC 41P
2198	Photo of same Car as 2197	Vauxhall	MVC 41P
2199	Photo of same Car as 2197	Vauxhall	MVC 41P
2200	Photo of Rear of a small Car?	?	
2201	Photo of the same Car as 2200	?	
2202	Photo of same Car as 2200	?	
2203	Photo of an Audi Car Front	Audi	JVB 331P
2204	Photo of same Car as 2203	Audi	JVB 331P

2205	Photo Of same Car as 2203	Audi	JVB 331P
2207	Photo of a Cars Drivers Console		
2208	Photo of a NCL Electric Powered Van	Electric Van	
2209	Photo of Toothed/Vee Belt Drive Engine		
2210	Photo of 3 Round Details?		
2211	7 Photos of Interior/Exterior View of Car?	?	OAC 145P
2211	7 Photos of Detail View of Car?		
2212	4 Photos of 4 Door Saloon Car	?	NMJ 292P
2213	8 Photos of 2 Doror Small Hatchback	?	PLH 665R
2214	11 Photos of Interior/Exterior of 4 Door Car?	?	NOF 700R
2215	5 Photos of Interior/Exterior of 4 Door Car?	?	PKV 472R
2216	9 Photos of Detail View of Car?		
2217	5 Photos of Detail View of Car?		
2218	11 Photos of Interior/Exterior View of 4 Door Car?	?	
2219	3 Photos(same side view) of a 4 Door Saloon Car	?	
2220	2 Side Photos of 4 Door Saloon Car (same as 2219?)		
2221	2 Photos of 4 Door Fastback Car?	?	
2222	Photo of 4 Door Hatchback Type Car?		
2223	Photo of Vauxhall Commodore	Vauxhall	
2224	Photo of Side of Car Vauxhall Commodore?		
2225	Photo of side view of Car with Air-flow Lines		
2226	Photo of Renault 30TS	Renault 30TS	
2227	Photo of Car possibly Ford?	Ford?	PUK 197R
2228	Photo of same car as 2227		PUK 197R
2229	Photo of Front of same Car as 2227		PUK 197R
2230	Photo of same Car as 2227 with Door/Hatch open		
2231	1-2 Photos (same) of a Wheel/Tyre		
2231	2-2 Photos (same) of a Wheel		
2232	Photo part Nearside View of 4 Door Car	?	
2233	Photo part Nearside View of 4 Door Car as 2232	?	RRW 395N?
2234	Photo of Rear Nearide Corner of Car as 2232	?	
2235	Photo of Nearside of Car as 2232	?	

2236	Photo of Offside of Car as 2232		?	
2237	Photo of Simca Car Rear		Simca	237BNZ 75
2238	1-11 Photos of Detail ViewS of Car?			
2238	2-4 Photos of Detail ViewS of Car?			
2239	1-Photo of Prototype Mini?		Mini	ADO 88
2239	2- 2 Photos(same) of Prototype Mini?		Mini	ADO 88
2240	Photo of Side view of Car? Singer?		Singer?	
2241	Photo of Nearside Front Quarter of Car? as 2240			
2242	Photo of Offside Rear Quarter of Car? as 2240			
2243	Photo of Control Console Possibly Car as 2240			
2244	Photo of Control Console			
2245	Outline of Vans 50 Series HCV WheelBases and Volumes		50 Series Vans	
2246	Outline of Trucks 50 Series HCV WheelBases and Bodylengths		50 Series Trucks	
2247	Outline of Walk Thru Van		Walk Thru Van	
2248	50 Series Job 1 Introduction Dates	Oct 78 - Jan 80	50 Series	
2249	Outline of Bantam Truck		Bantam Truck	
2250	Outline of 50 Series Cab Variations		50 Series	
2251	50 Series Models and Weights Chassis/Cab		50 Series	
2252	7 Photos of Interior of Cabs possibly Vans/Trucks			
2253	15 Photos of Detail of Interiors of ?/Exterior			
2254	2 Photos (same) of Display on Wall			
2255	Outline of 10-40 Series Van - Beam Axle 127" WB		10-40 Seies Van	
2256	Outline of Euro Van - RWD 128" WB		Euro Van	
2257	Outline of Euro Van - FWD 128" WB		Euro Van	
2258	Outline of 10-40 Series Van - IFS 127" WB		10-40 Seies Van	
2259	Outline of 45 Series Van 127" WB		45 Series Van	
2260	1-5 Photos of Exterior View of Vans and Lorries		Van/Lorry	
2260	2-12 Photos of Exterior View of Vans and Lorries		Van/Lorry	
2260	3-11 Photos of Exterior View of Vans and Lorries		Van/Lorry	
2260	4-11 Photos of Exterior View of Vans and Lorries		Van/Lorry	

2260	5-15 Photos of Exterior View of Vans and Lorries		Van/Lorry	
2260	6-15 Photos of Exterior View of Vans and Lorries		Van/Lorry	
2261	11 Photos of a Medium Van and Lorry		Van/Lorry	
2262	12 Photo of a Lorry and a Van		Van/Lorry	
2262	11 Photos of Exterior/Interior View of a Pickup		Pickup	
2262	12 Photo of Detail of Pickup		Pickup	
2263	2 Slides of Van-Future Legislation/Compliance			
2264	29 Photos of Interior Detail of Cabs Van/Lorry?		Van/Lorry	
1984	Datsun 180B		Datsun 180B	
	Following have E prefix			
1	Photo of Fiat 125 Car Seat Frame and Springs		Fiat 125	
2	Photo of Fiat 125 Car Seat Covers		Fiat 125	
3	Photo of Rusty Body Work?			
4	Photo Of Ford Escort Radiator Parts		Ford Escort	
5	Photo Closeup of Radiator Detail			
6	Photo of Inside of Luggage Compartment			
7	Photo of empty Engine Compartment			
8	Photo of Driving Position			
9	Photo of Inside of Luggage Compartment			
10	Photo of Bodywork Construction Detail			
11	Photo of Bosch and Lucas Alternator Parts			
12	Photo of Bodywork Construction Detail?			
13	Photo of Bodywork Construction Detail?			
14	Photo of Ford Escort 1100 Silencer Box Detail		Ford Escort	
15	Photo of Ford Escort Pedal Arms-Fulcrum Brkt-Accelerator Arm		Ford Escort	
16	Photo of Steering Rack-Wheel-Shaft Detail			
17	Chart to small to see			
18	Competitive Vehicle Analysis and Cost Reduction Dept.Major Function			

19	Vendor Costs		
20	C Car Priliminary Category Cost Breakdown		
21	Lines of Communication		
22	Chart to small to see		
23	Facelift/New Model Programmes and Control Report 1968/75	1968-75	
24	Organisation and Headcount		
25	Workload and Allocation (Estimating and Clerical)		
26	C Car Comparitor Vechicle		
27	C Car Triangulation Sheet		
28	Corporate Prime Cost		
29	Photo of incomplete Car Body on Jig		
30	Photo of Half a Floor Pan on Jig		
31	Photo of incomplete Car Body Boot		
32	Photo of incomplete Car Body Bulkhead Forward		
33	Photo of incomplete Car Body Rear Passing Area		
34	Photo of incomplete Car Body Front Offside Wing		
35	Photo of Nearside of Ford Crapri		Ford Capri
36	Photo of Rear of Ford Crapri		Ford Capri
37	Photo of Front of Ford Crapri		Ford Capri
38	Photo of Front Offside Quarter of Ford Capri		Ford Capri
39	Photo of Rear Nearside Quarter of Ford Capri		Ford Capri
40	Photo of Drivers Position of Ford Capri?		
41	Photo of View inside of Boot of Ford Capri		Ford Capri
42	Photo of View inside of Engine Bay of Ford Capri		Ford Capri
43	Photo on Underside Rear of Ford Capri?		
44	Photo on Underside of Ford Capri?		
45	Photo on Underside of Engine Ford Capri		
46	Photo of 3 ??? off Cortina-Escort C Model		
47	Photo of Bodywork Construction Car		
48	Photo of One Side of Body Structure Front		

49	Photo of One Side of Body Structure Rear		
50	Photo of One Side of Body Structure		
51	Photo of Body Construction Rear Bulkhead		
52	Photo of Body Construction Front Bulkhead		
53	1-Photo of 2 Body Part Pressing		
53	2-Photo thro Door of Lorry Cab		
54	Photo of Body Construction Upside Down on Jig		
55	1-Photo of Twin Rear Wheel Flatbed Lorry NearSide View	Lorry	
55	2-Photo of 2 Body Part Pressing		
56	Photo of Twin Rear Wheel Flatbed Lorry Rear View	Lorry	
57	Photo of Twin Rear Wheel Flatbed Lorry Front View	Lorry	
58	Photo of Twin Rear Wheel Flatbed Lorry Front Offside View	Lorry	
59	Photo Of Detail Parts?		
60	Photo of Inside Door Structure for Lorry		
61	Photo of Door Mechanism for Lorry		
62	Photo of Front of a Van or Pickup		
63	Photo on Underside of a Chassis		
64	Photo of Driving Position of Van or Pickup		
65	Photo showing Sideview of Pickup		
66	Photo of Driving Position of Van or Pickup		
67	Photo showing a Side view on a People Carrier possibly VW	VW?	
68	Photo Showing Nearside Quarter View Vehicle as 67	VW	UXD 631G
69	Photo Showing Offside Quarter View Vehicle as 67	VW	UXD 631G
70	Photo Showing Front View Vehicle as 67	VW	UXD 631G
71	Photo Showing Rear View Vehicle as 67	VW	UXD 631G
72	Photo Showing Inside Rear of Vehicle as 67	VW	UXD 631G
73	Photo on Underside of a Chassis		
74	Photo on Underside of a Chassis		
75	Photo on Underside of a Chassis		

76	Data Sheet Friden Decimel Equivalents		
77	Photo of Detail possibly Engine Bay		
78	Photo from Front Quarter of Car across Engine Bay?		
79	Photo from Front Quarter of Car across Engine Bay?		
80	Photo Inside a Car? Boot		XWD 766H
81	Photo of Car? Spare Wheel and Cover		
82	Photo of Car? Spare Wheel in Storage		
83	Photo of Car? Spare Storage from Underneath		
84	Photo of Car? Oneside Drive Shaft from Underneath		
85	Photo of Car? Underneath showing Suspension?		
86	Photo of Car? Underneath showing Steering-Drive-Suspension?		
87	Photo of Car? Underneath showing Diff?		
88	Photo of Car? Underneath showing Exhaust-Silencer		
89	Photo of Car? General Underneath View		
90	Photo of Honda 77 Rear View	Honda 77	
91	Photo of Honda 77 View Underneath Rear	Honda 77	
92	Photo of Honda 77 View of Front Bonnet Open	Honda 77	
93	Photo of Honda 77 View Underneath Front	Honda 77	
94	Photo of Honda 77 View Front of Front Wing	Honda 77	
95	Photo of Honda 77 View Rear of Rear Wing	Honda 77	
96	Photo of Honda 77 View of Driving Position Closeup	Honda 77	
97	Photo of Honda 77 View of Driving Position	Honda 77	
98	Photo of Honda 77 View of Driving Position Closeup	Honda 77	
99	Photo of Honda 77 Rear Light Cluster	Honda 77	
100	Photo of Honda 77 Engine Bay	Honda 77	
101	Photo of Honda 77 Boot	Honda 77	
102	Photo of Honda 77 Engine Bay	Honda 77	

103	Photo of Honda 77 Front Bonnet OpenEngine Bay		Honda 77	
104	Photo Underneath Car En- gine/Exhaust			
105	Photo Underneath Car En- gine/Exhaust			
106	Photo Underneath Car Silencer			
107	Photo of Car Details?			
108	Photo of De Dion and Elbow Assem- bly			X1251539
109	Photo of De Dion and Elbow Assem- bly			X1251539
110	2 (same) Photo of Final Drive and Torque Tube Assembly			
111	Photo of Brake Drum			X1239804
112	Photo of Top Link			X1251552?
113	Photo of Bottom Link			X1243541
114	Photo of Panhard Rod			X156610A?
115	Photo of Bottom Link			X1251541
116	Photo of Brake Assembly			X1251528?
117	Photo of Mounting Rubber			X1251553?
118	Photo of Drive Shaft			X1251558?
119	Photo of Mounting Bracket			X1251533
120	Photo of Drive Flange			X1251524
121	Photo of Hub			X1251569
122	Photo of Drive Shaft			X1251512
123	Photo of Lots of Car Parts			
124	Photo of 3 Hill Start Test Clutches Test 1,2,and New DSW8			
	Following have F prefix			
1	Defrosting Test-4 Door Arrow Sedan		Sunbeam	
2	Plots from an Overdrive Test			
3	Defrost Test-Sunbeam Alpine GT (Prototype)		Sunbeam Alpine	
4	Defrosting Test-Sunbeam Alpine Coupe Production Vehicle		Sunbeam Alpine	
5	Defrost Test-Sunbeam Alpine GT (Production)			
6	Defrost Test-Commer VanPB Range LHD (Production)		Commer Van	
7	Demisting Test-Hillman Hunter Sa- loon (Production Vehicle)		Hillman Hunter	Report10691
8	Demisting Test-B Model Saloon (Prototype Vehicle) Fig1			Report10691
9	Demisting Test-B Model Saloon (Prototype Vehicle) Fig2			Report10961



10	Defrost Test B Model Vehicle B12 LHD Saloon		Report10961
11	Defog Test B Model Vehicle B12 LHD Saloon	29/11/1968	TR No21498
12	Plots from an Overdrive Test		
13	Defog Test Front WindShield C Model	03/12/1968	Report10739
14	Defrost Test C Model		Report10739
15	Photo of Inner Workings of Diff 125lb/Ft Drive		
16	Photo of Inner Workings of Diff 125lb/Ft Drive		
17	Photo of Inner Workings of Diff 250lb/Ft Drive		
18	Photo of Inner Workings of Diff 250lb/Ft Drive		
19	Photo of Inner Workings of Diff 375lb/Ft Drive		
20	Photo of Inner Workings of Diff 375lb/Ft Drive		
21	Photo of Inner Workings of Diff 500lb/Ft Drive		
22	Photo of Inner Workings of Diff 500lb/Ft Drive		
23	3 Photos of person working on ???		
24	2 Photo Underneath Car?		
25	Photo of Inner Workings of Diff 375lb/Ft Drive		
26	Photo of Inner Workings of Diff 250lb/Ft Drive		
27	Photo of Inner Workings of Diff 500lb/Ft Drive		
28	Photo of Inner Workings of Diff 125lb/Ft Drive Overrun		
29	Photo of Inner Workings of Diff 250lb/Ft Drive Overrun		
30	Photo of Inner Workings of Diff 375lb/Ft Drive Overrun		
31	Photo of Inner Workings of Diff 500lb/Ft Drive Overrun		
32	Photo of Inner Workings of Diff 125lb/Ft Drive		
33	Defog Test Front WindShield C Model	0/12/1968	Report10739
34	Defrost Test C Model		
35	Some Rig		
36	As 35		
37	Test Rig around Wheel Disc		

38	Test Rig around Steering/Front Suspension
39	Compression Test Machine
40	Defog or Defrost? Test/ Area Plot to small to read
41	Defog or Defrost? Test/ Area Plot to small to read
42	Detail Photo of showing Straps above Diff?
43	Detail Photo of showing Seats Back?
44	Detail Photo of showing Straps above Diff?
45	Detail Photo of showing Straps above Diff?
46	Detail Photo of showing Seats Back?
47	Photo of showing Floor Pan Damage/Straps above Diff?
48	Detail Photo of showing Seats Back?
49	Photo showing extensive inside of Car Passenger Area
50	Photo showing Front Edge of Rear seat
51	Detail Photo showing bolts on Strips?
52	Detail Photo showing bolts on Strips?
53	Photo of 4 Door Saloon Car? Fan across Windscreen?
54	Photo of 4 Door Saloon Car? By brick wall
55	Photo of Car (same as 53) Front Unfinished
56	Photo of Car (same as 53) Rear Unfinished
57	Photo of Engine in Car C92
58	Photo of underside Front detail Steering/Suspension
59	Photo showing Steering/Bellhousing/Wiring(Test)
60	Photo showing Steering Components in Test Machine
61	Photo showing Detail-Hinge-Bolts-Tube?
62	Photo of Steering Items in Compression/Vibration Tester
63	Photo of Imp/Chamois Outside of Building
64	Photo of 2 Assemblies?

65	Photo of 2 Assemblies?		
66	Photo of Hexagon Detail?		
67	Photo of Hexagon Detail?		
68	3 View Drawing of Diff.-Deflection Test Fig 1 C Model.		Report12214
69	C Model Defog Performance Wind-screen Diagram		
70	C Model Defrost Performance Windscreen Diagram		
71	Defrost Test Dodge Light Bus RHD PB Range Diesel		Report12417
72	Defrost Test Dodge Light Bus RHD PB Range Diesel		
73	Defrost Test Dodge Light Bus RHD PB Range Diesel		
74	B Propshaft Plunge Fig1-2-3-4 Traces		Report8868
75	2 Photos (same) too small to read		
76	2 Photos (same) of Testing Machine?		
77	Photo of Specimen under Tensile Testing		
78	2 Photo of Hinge Component Parts		
79	Outline Drg.- Mode Shape at 12.5c/s Resonance	05/03/1968	H.J.Wyman
80	Three D.O.F.Ride and Shudder Model Diagram		
81	Diagrammatic Representation of Car Degrees of Freedom		
82	Outline Drg.- Mode Shape at 8.8c/s Resonance		
83	Photo of Specimen after Tensile Testing		
84	Photo of Jig/Fixture in Testing Machine Test Area		
85	Photo of Jig/Fixture in Testing Machine Overall View		
86	Photo of Jig/Fixture out of Testing Machine		
87	Photo of Jig/Fixture out of Testing Machine		
88	Photo of Jig/Fixture out of Testing Machine		
89	Photo of Jig/Fixture out of Testing Machine		
90	Photo of Door Latch Items readied fro Testing?		

91	Defrost Test Dodge Light Bus RHD PB Range Diesel	Report12137
92	Defrost Test C Model Prototype (C11) Lo-Line 1724cc	Report12684
93	Defrost Test Hillman Avenger GL (Pre-Production) Cond.2	Report12750
94	Defrost Test Hillman Avenger GL (Pre-Production) Cond.3	Report12750
95	Defrost Test Hillman Avenger GL (Pre-Production) Cond.1	Report12750
96	Defrost Test Hillman Avenger GL (Pre-Production) Cond.4	Report12750
97	Defrost Test N.A.S.B Model (Pre- Production) Cond.1	Report12912
98	Defrost Test N.A.S. B Model (Pre- Production) Condition 2	Report 12912
99	Defrost Test N.A.S. B Model (Pre- Production) Condition 3	Report 12912
100	Defrost Test N.A.S. B Model (Pre- Production) Condition 4	Report 12912
101	Defrost Test N.A.S. B Model (Pre- Production) Condition 11	Report 12912
102	Defrost Test N.A.S. B Model (Pre- Production) Condition 10	Report 12912
103	Defrost Test N.A.S. B Model (Pre- Production) Condition 12	Report 12912
104	Defrost Test N.A.S. B Model (Pre- Production) Condition 9	Report 12912
105	Defrost Test N.A.S. B Model (Pre- Production) Condition 8	Report 12912
106	Defrost Test N.A.S. B Model (Pre- Production) Condition 7	Report 12912
107	Defrost Test N.A.S. B Model (Pre- Production) Condition 6	Report 12912
108	Defrost Test N.A.S.B Model (Pre- Production) Cond.5	Report12912
109	Defrost Test Commer 103 Phase 1 Prototype Test No 1	Report1292
110	Defrost Test Commer 103 Phase 1 Prototype Test No 2	Report1292
111	Defrost Test Commer 103 Phase 1 Prototype Test No 3	Report1292
112	Defrost Test Commer 103 Phase 1 Prototype Test No 4	Report1292
113	Traces Dynamic Pushrod Loads Figures 1,2,3,4.5.6 and 7	Report1277
114	Defrost Test N.A.S. Avenger (L.C.Engine LHD)	Report12943

115	Detail Photo of Hoses and Frame-trap?
116	Photo of Jig/Fixture in of Testing Machine
117	Photo of Jig/Fixture in of Testing Machine
118	Photo of looks like a Vibration Test Rig
119	Photo of a Complicated Test Rig
120	Photo of 2 Fans/Impellers
121	Photo of Control Console of Test Apparatus?
122	Photo of a Filtered Test Apparatus?
123	Photo of a Test Table?
124	Photo of a Test Frame?
125	Photo of a Pipe Connection on Test Apparatus?
131	Photo of a Rotating Joint/Bellows?
132	Photo with Label "Cross Member Fatigue Test"
133	Photo of Spined End of Shaft "Alternating Torque Test"
134	Photo of Results of a Rotating Bending Test
135	Photo of Results of a Rotating Bending Test
136	Photo of Labelled Shaft/Coupling?
137	Photo of Results of a Rotating Bending Test
138	Photo of Results of a Rotating Bending Test
139	Photo of Results of a Rotating Bending Test
140	Photo of Results of a Rotating Bending Test
141	Photo of Body Sheet Metal Work Front Grill Area
142	Photo of Body Sheet Metal Work Front Radiator Area
143	Photo of Underneath of Floor Pan?
144	Photo of Assembly on Test Table Floor Pan?
145	Photo of Assembly on Test Table Floor Pan?
146	Photo of Assembly on Test Table Floor Pan?
147	Photo of Assembly on Test Table Floor Pan?

148	Photo of Broken Strut Test Result?		
149	Photo of Broken Strut Test Result?		
150	Photo of Assembly on Test Table Floor Pan?		
151	Photo of Assembly on Test Table Floor Pan/Chassis Member?		
152	Photo of Assembly on Test Table Floor Pan/Chassis Member?		
153	Photo of Assembly on Test Table Cross Member?		
154	Photo of Car Body Assembly on Test Table Door Upright Joint		
155	Photo of Car Body Assembly on Test Table Door Upright Joint		
156	Photo of Car Body Assembly on Test Table Door Upright Joint		
157	Photo of Car Body Assembly on Test Table Door Upright Joint		
158	2 Photos of Diff. Internals		
159	Defrost Test 1500cc Avenger LHD Toughened Screen Test 1		Report12987
160	Defrost Test 1500cc Avenger LHD Toughened Screen Test 2		
161	Defrost Test N.A.S. Avenger LHD B238 L.C.Engine		
162	Defrost Test N.A.S. Avenger LHD B238 L.C.Engine		Report 13312/C
163	Defrost Test N.A.S. Avenger LHD B238 L.C.Engine		Report 13312/D
164	Windscreen Defrost Test NAS Avenger LHD	Avenger	
164	Defrost Test N.A.S. Avenger LHD B238 L.C.Engine		Report 13312/B
165	12 Windscreen Plots-Defrost Test NAS Twin Carb B Estate		Peport 13751
166	Defrosting Test NAS Twin Carb. B Estate Test No 9		Report 13751
167	Defrosting Test - Plymouth Cricket (Face Vents Closed)Test 1		Report 13758
168	Defrosting Test - Plymouth Cricket RH239185838 Test 1		Report 13747
169	Defrosting Test - Plymouth Cricket (Face Vents Open)Test 3		Report 13758
170	Defrosting Test - Plymouth Cricket RH239185838 Test 2		Report 13747
171	Defrosting Test - Plymouth Cricket (Face Vents 1/2Open)Test 2		Report 13758

172	Photo ofd Car Items in Test Machine		
173	Angle	Avenger?	
174	Imp Sport Cold Weather Equipment	Imp Sport	
174	Photo of Laidout Car Parts Panels-Silencer-Fan and Cowl		
175	Imp Sport Cold Weather Equipment	Imp Sport	
175	Photo of Sport Apex Engine Bay	Sunbeam Stiletto	
176	Defrost Test - Plymouth Cricket Chassis No23920462		Report 14021
177	Defrost Test - Plymouth Cricket Chassis No23920462		Report 14021
178	Defrosting Test - Plymouth Cricket 12 Module 12 GP Heater 71263066		Report14084
179	Defrosting Test - Plymouth Cricket 13 Module 12 GP Heater 71263067		Report 14034
180	Photo of 2 Triangulated Items		
181	Photo of 2 Triangulated Items		
182	Defrost Test Cricket B278 Chassis No238205383		
183	Defrost Test Cricket B278 Chassis No238205383 Delanair Heater		
184	Unrecognizable Photo Strip		
185	Photo of Cylinder Head Casting?		
186	5 Photos of Detail Views of Car?		
187	Photo of Windscreen with Pads		
188	Photo of Test Console/Aparatus alongside 4Door Saloon		
189	Photo of Test Aparatus with Pads		
190	Photo of Aparatus in 189 fitted to Windscreen		
191	Photo of Driving Position Simulator?		
192	Photo of Driving Position Simulator?		
193	2-2 Circuit Diagrams D3112-Yaw Rate Channel 3		D 3112
193	3-Circuit Diagram D3113-Roll Rate Channel 5		D 3113
193	4-Circuit Diagram D3114-Lateral Accel. Channel 7		D 3114
193	5-Circuit Diagram D3115-Handwheel Angle9 Channel 7		D 3115
193	6 Circuit Diagram D3116-5th Wheel Road Speed Channel 11		D 3116
193	7 Circuit Diagram D3117-Clock Generator - Channel 13		D 3117

193	8 Circuit Diagram D3118-????— Channel 15 and 16		D 3118
193	9 Circuit Diagram D3119 Gyro Unit Gyro Block		D 3119
193	10 Circuit Diagram D3120 Gyro Unit Gyro Power Supply		D 3120
193	11 Circuit Diagram D3121 DC-DC Power Unit Handling Equip		D 3121
193	12 2 Circuit Diagrams D3122 5 Volt Regulator Board P/S		D 3122
193	13 Circuit Diagrams D3123 10 Volt Regulator Board P/S		D 3123
193	14 Circuit Diagrams D3124 -??- Power Unit		D 3124
193	15 Circuit Diagrams D3125 -No Ti- tle		D 3125
193	16 Circuit Diagrams D3126		D 3126
193	1-Circuit Diagrams D3111-Pitch Rate Channel 1		D 3111
194	Photo of Test Car? M119 Front Damaged		
195	35mm-8A-Test Car M119 Front Damage Nearside		
196	35mm-9A-Test Car M119 Front Damage Offside	Saloon	
197	35mm-5A-Test Car M119 Driving Position		
198	35mm-6A-Test Car M119 Engine Compartment		
199	35mm-7A-Test Car M119 Wind- screen Area		
200	35mm-1A-Test Car M119 Nearside	Saloon	
201	35mm-2A-Test Car M119 Offside		
202	35mm-3A-Test Car M119 Driving Position		
203	35mm-4A-Test Car M119 Door Opening		
204	35mm-14A-Test Car M119 Corner of Winscreen		
205	35mm-15A-Test Car M119 Roof		
206	35mm-11A-Test Car M119 Across Front		
207	35mm-12A-Test Car M119 Wind- screen Corner		
208	35mm-13A-Test Car M119 Wind- screen Edge		
209	35mm-25A-Test Car M119 Con- sole/Dash		



210	35mm-26A-Test Car M119 Wind-screen	
211	35mm-27A-Test Car M119 Wind-screen	
212	35mm-21A-Test Car M119 Door Corner?	
213	35mm-22A-Test Car M119 Door Opening	
214	35mm-23A-Test Car M119 Driving Position	
215	35mm-24A-Test Car M119 Console/Dash	
216	35mm-17A-Test Car M119 Body Joint Detail	
217	35mm-18A-Test Car M119 Body Joint Detail	
218	35mm-19A-Test Car M119 Roof Corner	
219	35mm-20A-Test Car M119 Roof Corner Inside	
220	Photo Test Car M106 Front Damage	Estate
221	Photo Car Test Area	
222	Photo Test Car M106 Before Damage Nearside	Estate
223	Photo Test Car M106 Before Damage Offside	Estate
224	Photo Test Car M106 After Damage Offside	
225	Photo Test Car M106 After Damage Nearside	
226	Photo Test Car M106 After Damage Nearside	
227	35mm-4A-Test Car M109 Drivers Seat Area	
228	35mm-5A-Test Car M109 Drivers Seat Area	
229	35mm-1A-Test Car M109 Detail?	
230	35mm-2A-Test Car M109 Front Corner	
231	35mm-3A-Test Car M109 Drivers Position	
232	Photo Test Car M91 After Damage Offside	Saloon
233	Photo Test Car M91 After Damage Offside	Saloon
234	Photo Test Car M91 After Damage Offside	Saloon

235	Photo Test Car M91 After Damage Nearside	Saloon	
236	Photo of Car? Test M91 Front Damaged		
237	35mm-35 Photo of Car Seat Details		
238	1-35mm-36 Photo of Car Seat Details		
238	2-4X35mm-3,4,5and6 Damage to Car after Test 2		
239	35mm-37 Photo of Car Seat Details		
239	6X35mm-19,21,22,23,24and25 Car Body Damage		
240	35mm-32 Photo of Car Drivers Position		
240	35mm 14 Photo of Car Damage		
240	35mm 15 Photo of Car Damage		
240	35mm 16 Photo of Lorry Damage	Lorry	
240	35mm 17 Photo of Lorry Damage	Lorry	
240	35mm 11 Photo of Lorry Damage	Lorry	
240	35mm 12 Photo of Lorry Damage	Lorry	
240	35mm 13 Photo of Lorry Damage	Lorry	
241	35mm-33 Photo of Car Seat Details		
241	11X35mm 31A to 42A+Photos of Test Car N75	Saloon	
242	35mm-34 Photo of Car Drivers Position		
242	2X35mm 11 and 12 Photo of Damage		
243	35mm-28-Test Car M9 Drivers Position		
243	Photo of Test Machine?		
244	35mm-29-Test Car M9 Drivers Position		
244	Photo of Test Machine?		
245	35mm-30-Test Car Engine Bay		
245	9X35mm Various Photos of Test Car P19?H	Saloon	
245	Another 11x35mm Photo of After Test P13? Damage	Saloon	
246	35mm-31-Test Car Engine Bay		
246	12x35mm Photo of After Test Damage		
246	Another 11x35mm Photo of After Test Damage		
247	11x35mm Photo of Car Test P35? Damage	Saloon	
247	Another 5x35mm Photos OF AFTER Test Car		FHP 507L

248	12x35mm Photos of Details of Car				FDU 147L
248	Another 6x35mm Photos of Detail of Car				FDU 147L
249	8x35mm Photos Test? Damage				
249	Another 12x35mm Photos of Van Test P36			Van	
250	11x35mm Photos of Vehicles Details				
250	Another 3x35mm Photos of Vehicles Details				
251	12x35mm Photos of Test HS 9 Mainly Seats and Bodywork				
252	3x35mm Photos of Damage Vehicle Cab?				
253	10x35mm Photos of Damaged Test Vehicle				
253	Another 12x35mm Photos of Damaged on Test Vehicle				
254	12x35mm Photos of Damaged Vehicle Test P36				
254	Another 8x35mm Photos of Damaged Vehicle Underneath				
255	3x35mm Photos of Behind Rear Seating?				
256	6x35mm Photos of Test Frame or Tower				
257	6x35mm Photos of Vehicle-Battery-Suspension-Steering				
258	3 x35mm Photos Front Seat Frame in Position				
259	11x35mm Photos of Alternators and Test Equipment				
259	Another 11x35mm Photos of Alternator Parts				
260	Windshield Defront Test	05/02/1976		Avenger/Imp	
	Avenger/Imp Engine				
261	Windshield Defront Test	17/02/1976		Avenger/Imp	
	Avenger/Imp Engine				
262	Windshield Defront Test	20/02/1976		Avenger/Imp	
	Avenger/Imp Engine				
263	Windshield Defront Test	24/02/1976		Avenger/Imp	
	Avenger/Imp Engine				
264	Windshield Defront Test	12/02/1976		Avenger/Imp	
	Avenger/Imp Engine				
265	Windshield Defront Test	19/02/1976		Avenger/Imp	
	Avenger/Imp Engine				
266	Windshield Defront Test	13/02/1976		Avenger/Imp	
	Avenger/Imp Engine				

267	Windshield Defront Test Avenger/Imp Engine	27/02/1976	Avenger/Imp
268	Windshield Defront Test Avenger/Imp Engine	25/02/1976	Avenger/Imp
269	Photo under Rear of Car? Showing Fuel Tank		RDU 51M
270	10x35mm Photos of Damaged Test Vehicle-Drivers Position		
270	1 Photo of Car PR 37 Underneath Rear Showing Fuel Tank		RDU 51M
271	Photo of Underneath- Fuel Tank Datum Marks		
272	Photo of 2 Door Hatchback PR 37 Rear RH Quarter		RDU 51M
273	Photo of 2 Door Hatchback PR 37 Rear LH Quarter		RDU 51M
274	Photo of 2 Door Hatchback PR 37 Above Front RH Quarter		
275	Photo of 2 Door Hatchback PR 37 Front LH Quarter		RDU 51M
276	Photo of 2 Door Hatchback PR 37 Offside		
277	Photo of 2 Door Hatchback PR 37 Underneath Tank Hanging		RDU 51M
278	Photo of 2 Door Hatchback PR 37 Underneath Tank Hanging		RDU 51M
279	Photo of 2 Door Hatchback PR 37 Underneath Tank Hanging		RDU 51M
280	Photo of Underneath Fuel Tank Dented Datum Marks		
281	Photo of 2 Door Hatchback PR 37 Dent in RH Rear Panel		RDU 51M
282	Photo of 2 Door Hatchback PR 37 Dent in RH Rear Panel		RDU 51M
283	Photo of 2 Door Hatchback PR 37 Dent in RH Rear Panel		
284	Photo of 2 Door Hatchback PR37 Damaged Rear End		RDU 51M
285	Photo of 2 Door Hatchback PR37 Damaged Rear End Nearside View		
286	Photo of 2 Door Hatchback PR37 Damaged Rear End Nearside View		RDU 51M
288	12x35mm Photos of Car Damaged from Rear		
289	16x35mm Photos of Car Features Dash-Console-Doorhandle		
289	Another 9x35mm Photos of Dash Parts-Test Equipment		

290	12x35mm Photos Silencer- and Test Equipment			
291	3X35MM Photos of Rear/Boot Floor Area			
292	14x35mm Closeup Photos of PR37 Detail-Springs-Wheel			RDU 51M
292	Another 11x35mm Photos Underneath Car-Body Panel			
293	12x35mm Photo of after Test PR 37 Damage			RDU 51M
293	Another 4x35mm Photos PR37 Rear Inside-Nearside Rear			RDU 51M
294	7x35mm Photo Inside and Out Test Car PR37			RDU 51M
294	Another 12x35mm Photos PR37 Mainly Outside Views			RDU 51M
295	Defrost Test? Avenger SC1 (Ex B301) RHD 930 Engine	04/05/1976	Avenger	
296	Repeat Test 16 Avenger SC1 (Ex B301) RHD 930 Engine	27/04/1976	Avenger	
297	Repeat Test 18A Avenger SC1 (Ex B301) RHD 930 Engine	05/05/1976	Avenger	
298	Repeat Test 14 Avenger SC1 (Ex B301)	13/04/1976	Avenger	
299	Test as 13 Avenger SC1 (Ex B301) RHD 930cc Engine	12/04/1976	Avenger	
300	Test Avenger SC1 (Ex B301) RHD 930cc Engine	15/04/1976	Avenger	
301	Test Avenger SC1 (Ex B301) RHD 930cc Engine	09/04/1976	Avenger	
302	As Test 19 Avenger SC1 (Ex B301) RHD 930cc Engine	06/05/1976	Avenger	
303	Defrost Test Volkswagen Polo LHD Engine 2950 RPM	25/03/1976	Volkswagen Polo	
304	6x Photos Views of 2 Door Hatchback			
305	2x35mm Photos of Cars Details? with Datum Marks			
306	11x35mm Photos Mainly Fueltanks Plus Diff			
306	Another 12x35mm Photos of Details Diff-Underneath-Fuel Filler			
307	11x35mm Photos of Test PR37 Underneath-Outside-Interior			RDU 51m
307	Another 8x35mm Photos of Underneath Mainly Sparewheel Area			
308	4x35mm Photo of Test Car R18			

308	Another 4x35mm Photo of Test Car R18		
309	8x35mm Detail views of Test Car R18		
310	14x35mm Detail Steering-Underneath-Details Test Car		
310	Another 11x35mm Photos of Test Car R19 Underneath		
311	14x35mm Photos of Test Car R19		
312	5x35mm Photos of Test Car R19		MRV 709M
313	10x35mm Photos of Test Van RR35	Van	
313	Another 3x35mm Photos of Test Van RR35	Van	
314	6x35mm Photo of Test Van RR35 Underneath		
315	9x35mm Detail Damage on Test Vehicle		
316	Photo of Car Body on Test Rig		
317	Photo of Car Body on Test Rig		
318	Photo of Car Body on Test Rig		
319	Photo of Small 2 Door Hatchback-Side		
320	Photo of Small 2 Door Hatchback-Rear Nearside		RKV 411R
321	Photo of Small 2 Door Hatchback-Rear		RKV 411R
322	Photo of Small 2 Door Hatchback-Rear		RKV 411R
323	Photo of Small 2 Door Hatchback-Front Offside		RKV 411R
324	9x35mm Photo Mainly Door Details		
325	5x35mm Photo Mainly Door Details		
326	6x35mm Photo Mainly Door Details		
327	12X35mm Photos Details of Test Car R60		
327	Another 10x35mm Photo of Detail of Tested Car		
327	Another 8x35mm Photos of Test Car Suspension-Door		
328	11X35mm Photos Details of Test Car R60		
328	Another 6X35mm Photos Details of Test Car R60 Steering Column		RRR 354R
329	11X35mm Photos Details of Test Car		
330	11X35mm Photos Details of Test Car Drivers Position Pedals		

331	12X35mm Photos Details of Test Car Underneath-Suspension	
331	Another 11x35mm Details of Test Car Underneath-Suspension	
332	9x35mm Photos Mainly Body Details	
333	Outline of 2 Door Hatch showing Airflow over Rear	
334	Outline of 2 Door Hatch showing Airflow over Rear	
335	12x35mm Photos Details of Test Car R88 Inside-Underneath	
335	Another 14x35mm Photos of Test Car R88	
335	Another 11x35mm Photos of Test Car R88 General Views	
336	12x35mm Photos of Test Car R88 Damage	
336	Another 10x35mm Photos of Damage mainly underneath	
336	/14 Another 35mm Photo of ??? (Rayner/Reid/Barley)	
337	12x35mm Photos of Test Car R88 Inside-Outside-Engine Bay	
338	9x35mm Photos of Test Car R88 Outside-Pedals-Body Details	
339	12x35mm Photos mainly of Window Framing	
339	Another 10x35mm Photos mainly Window Framing	
339	Another 9x35mm Photos-Car Person with Dog	RKV 411R
340	12x35mm Photos of Car Mainly Body Details	RKV 411R
340	Another 6x35mm Photos-Seating Details	
340	Another 12x35mm Photos mainly of Window Framing	
341	12x35mm Photos of Building Details?	
341	Another 8x35mm Photos of Building Details?	
341	Another 8x35mm Photos of Building Details?	
342	8x35mm Photos of Tested Car R124	
342	Another 9x35mm of Tested Car R124	

343	12x35mm Detail photo of Test Car R124 Damage		
343	Another 12x35mm Detail photo of Test Car R124 Damage		
343	Another 5x35mm Photos of Test Car Damage		
344	8x35mm Photos of Tested Car R124 Damage		
344	Another 12x35mm Photos of Test Car Damage		
344	Another 8x35mm Photos of Test Car R88 Damage		
345	12x35mm Photos of Test Car R124 Damage		
345	Another 13x35mm Photos of Test Car R124 Damage-Labels		
346	8x35mm Photos of Test Car Damage		
346	Another 12x35mm Detail Damage - Internal		
346	Another 12x 35mm Photos of Test Car R88		
347	8x35mm Photos of Damaged Test Car Mainly Engine Bay		
348	7x35mm Photos of Damaged Test Car Mainly Engine		
349	9x35mm Photos of Damaged Test Car-Body-Underneath		
350	15x35mm Photos of Test Car R141	Estate	
351	12x35mm Photos of Damaged Detail Framing-Some Labeled		
351	Another 3x35mm Photos of Damaged Detail some Labelled		
352	13x35mm Photos of Car Detail some Labelled		
352	Another 12x35mm Photo Of Damaged Labelled P76/152		
353	4x35mm Photos of Edge of Broken Glass		
354	3x35mm Photos of Broken Glass		
355	Photo of Rear of Small Hatchback		
356	Photo of Front of Small Hatchback Chrysler	Chrysler	UHP 238R
357	2 Photos (same) of Small Hatchback as 355 Rear Offside		
358	Photo of Front of Small Hatchback Offside		



359	Photo View of Front Offside Quarter Chrysler	Chrysler	UHP 238R
360	Photo of Test Rig		
361	Photo of Test Rig		
362	Photo of Control Console of Test Rig		
363	Photo of Control Console of Test Rig		
364	12x35mm Photos of Test Car SR13 Boot Floor-Wheels		
365	Photo of Small Hatchback Side House in Background		
366	Photo of Chrysler Hatchback Front Quarter Tree Background	Chrysler	RRW 430R
367	Photo of Chrysler Hatchback Front Tree Background	Chrysler	RRW 430R
368	Photo of Chrysler Hatchback Rear Quarter Tree Background	Chrysler	RRW 430R
369	Photo of Chrysler Hatchback Rear Tree Background	Chrysler	RRW 430R
371	7x35mm Photos of Damaged Test Car Fueltank Area		
371	Another 12x35mm Photos of Test Car 204R Damage		
372	9x35mm Photos of Test Car 202		
373	12x35mm Photos of Test Car 202 Damage		
373	Another 14x35mm Photos of Test Car Damage-Underneath		
373	Another 4x35mm Photos of Test Car Damage-Engine		
374	8X35Cmm Photos of Detail Damage mainly Underneath		
375	10x35Cmm Photos of Detail Damage		
376	9x35mm Photos of Test Car TR2		
376	Another 12x35mm Photos Wheels-Boot-Driveshaft		
377	12x35mm Photos of Test Car TR2 Damage		
377	Another 12x35mm Photo of Test Car TR2		
378	9x35mm Photos of Car Damage		
379	10x35mm Photos of Car Damage Underneath		
380	19x35mm Photos of Test Car SR105		
381	8 Plots Of Defrost/Demist Tests 50 Series EV 298		

382	6x35mm Photos of 2 Vans Outside		
383	6x35mm Photos of Test Car T103?- Engine-Underneath		
384	21x35mm Photos of Test Car T103		
385	10x35mm Photos of Test Car T103		
386	9x35mm Photo of Electric Motor Powered Test Rig		
387	12x35mm Photos of Seat Test Rig?		
387	Another 5x35mm Photos of Seat Test Rig		
388	8x35mm Photos of "Doorlocks and Hinges"		
389	5x35mm Photos of "Seatbelt An- chorage Points" Pass		
390	9x35mm Photos of "Seatbelt An- chorage Points" Failure		
391	11x35mm Photos of "Seatbelt An- chorage Points"		
392	11x35mm Photos of Dash/Console Mockup?		
393	22x35mm Photos of Test Car TR191 and T102?		
394	7x35mm Photod of Car Body Joints Labelled		
395	3x35mm Photos of Car Body Struc- ture Labelled		
396	5x35mm Photos of Broken Car Structure		
397	10x35mm Photos of Cab of Body Structure?		
398	12x35mm Photos of Damage De- tails?		
399	6x35mm Photos of Seatbelt Anchor- ages		
400	Detail Lights Dodge		Dodge
400	10x35mm Photos of Light Units		
401	2x35mm Photos of Internal Structure-Seatbelt Anchorage?		
402	7x35mm Photos of LorryCab/Van Seating 26Nov1979 RHS	26/11/1979	
403	10x35mm Photos of Seat Setup Sur- face Plate and in Cab		
404	15x35mm Photos of PB Van (Eire)	27/07/1979	
405	7x35mm Photos of PB Van (Eire) Under Test	27/07/1979	
406	7x35mm Photos of Instrument Pan- els		

406	Another 3x35mm Photos of Instrument Panels			
407	21x35mm Detail Photos of Test Vehicle			
408	11x35mm Photos of Test Car VR96			
409	15x35mm Photos of Test Car VR96			
410	14x35mm Photos of Test Car VR96			
411	18x35mm Photos of Test Car VR 96			
412	2x35mm Photos of Test Rig with Dial Gauge			
413	8x35mm Photos of Body Structure/Spotwelds	08/07/1980		
414	7x35mm Photos of Something Coiled-Round Object			
415	15x35mm Photos of Car Body Doors Test.			
418	6x35mm Photos of Body Structure/Spotwelds	27/08/1980		
419	10x35mm Photos of Interior Passenger Compartment Views			
420	3x35mm Photos of Car on open Road			Loose
	Following have Q prefix			
62	Avenger Tiger Prototype WVC 204J		Avenger Tiger	
63	Avenger Tiger Prototype WVC 204J		Avenger tiger	
	No prefix			
718	Photo Van Cab Drivers Position		Bedford?	

## 4 Acknowledgements

[TBA]