

# Rootes Archive Centre Trust

## Photographs and Negatives

Matt Ollman, Bob Allan, Richard Sozanski and Friends

Contact e-Mail: Bob: [spares@theimpclub.co.uk](mailto:spares@theimpclub.co.uk)

September 3, 2017

### Abstract

This is a list of photographs and negatives held at the Rootes Archive Centre in Banbury. We note that there is a much larger collection of Rootes press photographs and related material in the Coventry Herbert Museum.

This document is available from the Rootes Archive Centre Web site at <http://tardis.dl.ac.uk/ARCC/Photos/photos/index.html>. A PDF format copy of this document can be obtained from <http://tardis.dl.ac.uk/ARCC/Photos/photos.pdf>. You probably won't want to print it as there are over 100 pages, but it is searchable with a suitable PDF reader.

© **Rootes Archive Centre 2012-17**. The Rootes Archive Centre does not accept any responsibility for loss or damage arising either directly or indirectly from the use of information contained in any of their reports or in any communication about their tests or investigations. Whilst we have tried to be as accurate as possible, some errors may have occurred in the cataloguing process or interpretation.

**Contents**

**1 Introduction** **1**

**2 Negatives Drawer 1.** **1**

2.1 Imp Related Photographic Negatives . . . . . 104

**3 Negatives Dunstable** **109**

**4 Acknowledgements** **119**

## 1 Introduction

The filing cabinet which contains large photographic negatives has six drawers and is extremely heavy. We recently moved it and had to remove the top three drawers to do so. We need more help to catalogue the full set of negatives, but some have been done already as shown below.

## 2 Negatives Drawer 1.

Some highlights of this set include:

:

Negative No	Description	Date	Model	Notes
	Following have AF Prefix			
19	Neg-Strip 19 to 30 Car Lights in the Dark?	07/12/1970		Cassette Pot
20	Neg-Strip1A to 33A Mainly Car Lights in the Dark?	07/12/1970		Cassette Pot
21	1of3 Kodak Frames Car lights on dark open road Early Morning	08/12/1970		Cassette Pot
21	2of3 Kodak Car running/Parked on open road early morning	08/12/1970		Cassette Pot
21	3of3 Unkown Film 3 Photos thro Windscreen	08/12/1970		Cassette Pot
22	Neg-Strip of Ilford Film Car lights on dark conditions open road	08/12/1970		Cassette Pot
23	1of 2 Neg-Strip of Ilford Film Car on/parked road Scenery	08/12/1970		Cassette Pot
23	2of2 Kodak Frames Car with lights on Dark Early Morning	08/12/1970		Cassette Pot
	Following have B prefix			
218	B Car Timing Summary			
	Following have C prefix			
2	Arrow Hunter Crash Test G12		Arrow	
4	Arrow Hunter Crash Test Doors Open		Arrow	
5	Arrow Hunter Crash After Test G12		Arrow	
6	Arrow Hunter Crash Test G12		Arrow	
7	Arrow Hunter Crash Test G12 Driver Position		Arrow	
8	Arrow Hunter Crash Test G12 Rear View		Arrow	
9	Arrow Hunter Crash Test G12 Rear View		Arrow	

10	Arrow Hunter Crash Test G12 Under Drivers Position	Arrow
11	Arrow Hunter Crash After Test G12 Front Wheel	Arrow
12	Arrow Hunter Crash After Test G12 Front SideFront Wheel	Arrow
13	Arrow Fastback Crash Test G18	Fastback
14	Arrow Fastback Crash After Test G18	Fastback
15	Arrow Fastback Crash After Test G18	Fastback
16	Arrow Fastback Crash Test Rear View	Fastback
17	ARROW Fastback Crash After Test Driver Position	Fastback
18	ARROW Fastback Crash After Test Passenger Position	Fastback
19	Arrow Fastback Crash After Test Above Bonnet	Fastback
20	Arrow Fastback Crash After Test G18 Front Wheel	Fastback
21	Arrow Fastback Crash After Test G18 Front Wheel	Fastback
22	Arrow Fastback Crash Test G18	Fastback
23	Arrow Fastback Crash Test G18	Fastback
24	Arrow Fastback Crash Test G18 Door Open	Fastback
25	Arrow Fastback Crash Test G18 Door Open	Fastback
26	Arrow Fastback Crash Test Rear	Sunbeam
27	Arrow Fastback Crash Test Passenger Position	Fastback
28	Arrow Fastback Crash Test Front View	Fastback
29	Arrow Fastback Crash Test Rear View	Sunbeam
30	Arrow Fastback Crash Test Driver Position	Fastback
31	Arrow Fastback Crash Test Front Near Side	Fastback
32	Arrow Fastback Crash Test Rear Near Side	Fastback
33	Arrow Fastback Crash Test Mirror Driver Position	Fastback
34	Arrow Fastback Crash After Test G19 Near Side View	Fastback
36	Arrow Fastback Crash After Test G19 Side View	Fastback

37	Arrow Fastback Crash After Test Front near view	Fastback	
38	Arrow Fastback Crash After Test G19 Off side view	Fastback	
39	Arrow Fastback Crash After Test Near side front	Fastback	
40	ARROW Fastback Crash After Test Driver Position	Fastback	
41	ARROW Fastback Crash After Test Passenger Position	Fastback	
42	Arrow Fastback Crash After Test G19 Driver Position	Fastback	
43	Arrow Fastback Crash Test Rear View	Sunbeam	
44	After Crash Test		
45	After Crash Test		
46	After Crash Test Windscreen		
47	Crash Test Trackway to rear		
48	Gearbox		
49	Vehicle Underside		
50	Arrow Fastback Crash Test Near- side and Tripod	Fastback	Ektacolour
51	3D View of Striker Bolt Plate As- sembly		
52	3D View of Door Panel Assembly		
53	3D View of Door Panel Assembly		
54	3D View of striker Bolt Assembly		
55	Lock Cylinder and Latch Proposal Glove Box Sketch		No
56	Arrow Fuel Tank	Fastback	
57	Arrow Crash After Test Underneath Front		
58	Arrow Crash After Test Underneath Front		
59	Arrow Crash After Test Underneath Steering Rods		
60	Arrow Crash After Test General un- derneath view		
61	Arrow Crash After Test G28 Near- side Front		
62	Arrow Crash Test Dash and below		
63	Arrow Fastback Crash Test G28 General Offside View	Fastback	
64	Arrow Fastback Crash Test G28 Boot Open	Sunbeam	
65	Arrow Crash After Test Bonnet		
66	Arrow Crash After Test Forward Front Seating		

67	Arrow Crach Test G28 Front near-side wheel area		
68	Arrow Crash After Test Windscreen on Bonnet		
69	Arrow Crash After Test Dash Windscreen on Bonnet		
70	Arrow Fastbast After Test G2? View Nearside rear	Fastback	
71	Arrow Crash Test Driver Position		
73	Arrow Fastback Crash Test G28 View nearside	Fastback	
74	Arrow Fastback Crash After Test G28 View nearside	Fastback	
75	Arrow Crash After Test Driver Position	Fastback	
76	Arrow Fastback Crash After Test G28 View offside	Fastback	
77	Crash Test G33 View underneath Exhaust Box		
78	Crash Test View Engine compartment		
79	Sketch Proposal GandF Series Glove Box Doors		374-F-309
80	Arrow Fastback Crash G32 View nearside	Fastback	
81	Arrow Fastback Crash After Test G3? View Nearside	Fastback	
82	Arrow Fastback Crash Test G32 View offside	Fastback	
83	Arrow Fastback Crash G32 View Offside	Fastback	
84	Arrow Fastback Crash After Test G32 View Offside wing	Fastback	
85	Arrow Fastback Crash After Test G32 View Nearside wing	Fastback	
86	Arrow Fastback Crash After Test View of rear	Sunbeam	
87	Arrow Fastback Crash Test Driver Position		
88	Arrow Fastback Crash After Test under Steering Position		
89	Arrow Fastback Crash After Test Rear Seating		
90	ARROW Fastback Crash After Test Driver Position		
91	ARROW Fastback Crash After Test Driver Position		

92	ARROW Fastback Crash After Test Driver Position		
93	Arrow Fastback Crash After View above Bonnet		
94	Californian G37 Crash Test (JHP 492E)	Imp Californian	
94	Californian G37 Crash Test (JHP 492E)	Imp Californian	
95	Californian G37 Crash Test (JHP 492E)	Imp Californian	
95	Californian G37 Crash Test (JHP 492E)	Imp Californian	
96	Californian G37 Crash Test (JHP 492E)	Imp Californian	
97	Californian G37 Crash Test (JHP 492E)	Imp Californian	
98	Californian G37 Crash Test (JHP 492E)	Imp Californian	
99	Californian G37 Crash Test (JHP 492E)	Imp Californian	
100	Imp Coupe Crash Test G37 View nearside	Imp Coupe	
101	Californian G37 Crash Test (JHP 492E)	Imp Californian	
102	Californian G37 Crash Test (JHP 492E)	Imp Californian	
103	Californian G37 Crash Test (JHP 492E)	Imp Californian	
104	Californian G37 Crash Test (JHP 492E)	Imp Californian	
105	Californian G37 Crash Test (JHP 492E)	Imp Californian	
106	Californian G37 Crash Test (JHP 492E)	Imp Californian	
107	Californian G37 Crash Test (JHP 492E)	Imp Californian	
108	Photo small ? Detail		
109	Photo small ? Detail		
110	Photo small ? Detail		
111	Arrow Fastback Crash After Test G32 View nearside corner		Color Photo
112	Photo outside Damaged car on side		
113	Photo outside Damaged car on side View under engine		
114	Photo outside Damaged car on side View under engine		
115	Photo outside Damaged car F?? View on nearside wing		

116	Arrow Fastback Damaged Car F17 View Offside	Fastback	
117	Arrow Fastback Damaged Cars F7 and F14 nearside	Sunbeam	
118	Photo outside crash car View on front wing		
119	Photo outside crash car View of front		
120	Photo outside crash car View of front		LHP 680F
121	Arrow Fastback Damaged Cars F14 and F17 Offsides	Fastback	
122	Arrow Fastback Damaged Car F?4 View Offside wing		
123	Arrow Fastback Damaged Car F?? View nearside wing		
124	Arrow Fastback Damaged Car F14 View nearside	Fastback	
125	Note 10 color transparencies Imp G44 with dummy @MIRA 30/1/69	Imp	
126	Photo crashed car View under en- gine		
127	Crashed Car G32 View underside Engine/Gearbox		
128	Crashed Car G32 View inside of Front WheelEngine/Gearbox		
129	Crashed Car G32 View on underside		
130	Crashed Car View inside of Wheel		
131	Crashed Car G28 View on underside		
132	Crashed Car G28 View on underside of engine		
133	Crashed Car G28 View on underside of engine		
134	Crashed Car G28 View on underside of engine		
135	Imp 44 Crash Test	Imp	
136	Imp 44 Crash Test	Imp	
137	Imp 44 Crash Test	Imp	
138	Imp 44 Crash Test	Imp	
139	Imp 44 Crash Test	Imp	
140	Imp Crash Test G4 Driver Position	Imp	2 same Number
140	Imp After Crash Test G44 Driver Position	Imp	
141	Imp 44 Crash Test	Imp	
142	Imp 44 Crash Test	Imp	
143	Imp 44 Crash Test	Imp	
144	Imp 44 Crash Test	Imp	

145	Imp 44 Crash Test	Imp	
146	Imp 44 Crash Test	Imp	
147	Imp 44 Crash Test	Imp	
148	Imp 44 Crash Test	Imp	
149	Imp 44 Crash Test	Imp	
150	Imp Husky G48 Crash Test	Imp Husky	
151	Imp Husky G48 Crash Test	Imp Husky	
152	Imp Husky G48 Crash Test	Imp Husky	
153	Imp Husky G48 Crash Test	Imp Husky	
154	Imp Husky G48 Crash Test	Imp Husky	
155	Imp Husky G48 Crash Test	Imp Husky	
156	Imp Husky G48 Crash Test	Imp Husky	
157	Imp Husky G48 Crash Test	Imp Husky	
158	Imp Husky G48 Crash Test	Imp Husky	
159	Imp Husky G48 Crash Test	Imp Husky	
160	Imp Husky G48 Crash Test	Imp Husky	
161	Imp Husky G48 Crash Test	Imp Husky	
162	Imp Husky G48 Crash Test	Imp Husky	
163	Imp Husky G48 Crash Test	Imp Husky	
164	Imp Husky G48 Crash Test	Imp Husky	
165	Imp Husky G48 Crash Test	Imp Husky	
166	Imp Husky G48 Crash Test	Imp Husky	
167	Imp Husky G48 Crash Test	Imp Husky	
168	Imp Husky G48 Crash Test	Imp Husky	
169	Imp Husky G48 Crash Test	Imp Husky	
170	Imp Husky G48 Crash Test	Imp Husky	
171	Imp Husky G48 Crash Test	Imp Husky	
172	Arrow Fastback Crash Test G53 View before of nearside	Fastback	
173	Arrow Fastback Crash G53 View nearside	Fastback	
174	Arrow Fastback Crash After Test G53 nearside	Fastback	
219	Photo of Car Interior		
220	Photo of Engine Bay Battery		
221	Photo of Fuel Tank		JKV 670E
222	Photo of Fork End		
223	Arrow Fastback Crash GR83 View of rear	Sunbeam	JKV 670E
224	Arrow Fastback LHD Crash G86 Driver Position		
225	Arrow Fastback LHD After Crash Test Driver Position		
226	Photo of Fuel Tank		
227	Arrow Fastback LHD Crash G86 Driver Position		
228	Arrow LHD After test G86 View front offside		

229	Arrow LHD After test G86 View of windscreen area	
230	Arrow LHD After test G86 View front seating area	
231	Arrow LHD Fastback Crash After Test G86 Nearside	Sunbeam
232	Arrow LHD Fastback Crash Before Test G86 Nearside	
233	Arrow LHD Fastback Crash After G86 Offside	
234	Arrow LHD Fastback Before Crash G86 nearside	
235	Arrow LHD Fastback After Crash G86 Driver Position	
236	Arrow LHD After test G86 View front	
237	Arrow LHD After test G86 View over bonnet	
238	Arrow LHD Fastback After Crash G86 View nearside	
239	Arrow Fastback Before Crash 86 View nearside	
240	Arrow LHD Fastback After Crash G86 Driver Position	
241	Engine Compartment	
242	Avenger Rear View	Avenger
243	Avenger Side View	Avenger
244	Avenger Rear View	Avenger
245	Avenger Side View	Avenger
246	View under Gearbox	
247	Avenger Before Test G92 nearside	Avenger
248	Avenger Before Test G92 offside	Avenger
249	Avenger Before Test G92 Windscreen area	Avenger
250	Avenger LHD Before Test G92 above bonnet	Avenger
251	Avenger LHD Test G92 Windscreen area	Avenger
252	Avenger LHD Test G92 Driver position	Avenger
253	Avenger LHD Test G92 Driver position	Avenger
254	Avenger LHD Test G92 Front seating area	Avenger
255	Avenger LHD Test G92 Rear seating area Camera	Avenger
256	Avenger LHD After Test G92 Nearside	Avenger

257	Avenger LHD After Test G92 Above Windscreen	Avenger
258	Avenger LHD After Test G92 View from Offside/Windscreen	Avenger
259	Avenger LHD After Test G92 Off-side	Avenger
260	Avenger LHD After Test G92 Off-side wing	Avenger
261	Avenger LHD After Test G92 Near-side wing	Avenger
262	Avenger LHD After Test G92 Near-side	Avenger
263	Avenger LHD After Test G92 Driver position	Avenger
264	Avenger LHD After Test G92 Driver Position	Avenger
265	Avenger LHD After Test G92 View from Front	Avenger
266	Avenger LHD After Test G92 View under engine bay	Avenger
267	View under Gearbox Prop shaft	
268	Avenger LHD After Test G92 View under sump	Avenger
269	View on inside of front wheel After Test	
270	View under gearbox and Silencer	
271	Avenger LHD After test G92 View above engine bay	Avenger
273	Damage detail	
274	Several Damage cars outside	
275	Avenger LHD After Test G92 View of Battery Engine Bay	Avenger
276	Avenger LHD After Test G92 View of Battery Engine Bay	Avenger
277	View of Pedals	
278	View in front of seats	
279	Damage detail	
280	Damage detail	
281	Avenger LHD After Test G92 View of Steering Rack	Avenger
282	Avenger LHD After Test G92 Damage Detail	Avenger
283	Avenger LHD After Test G92 Damage inside front wheel	Avenger
284	View of Damage Gearbox Prop shaft	
285	View of Damage Steering rack and trackrod	

286	View of Damage under diff		
287	View of Damage Steering rack and trackrod		
288	Avenger LHD After Test G92 View on underside	Avenger	
289	Avenger LHD After Test G92 View on front underside	Avenger	
290	2 views of Lorry cab and drivers position		Water damaged neg
291	2 views of Lorry cab and drivers position		Water damaged neg
292	View of loory cab for near side		Water damaged neg
293	2 views of Damaged lorry cab		Water damaged neg
294	3 views of Lorry cab		Water damaged neg
295	2 Vews of vehicles and people		Water damaged neg
296	2 Views of Vechicles "Frank Grounds"		Water damaged neg
297	Commer Lorry? 9937 E Front Damaged	Commer	Water damaged neg
298	Bond? Minicar Under Artic Trailer damaged	Bond?	Water damaged neg
299	3 Photos Artic Lorry inc Road Scene		Water damaged neg
300	2 Photos of Lorry Cab		Water damaged neg
301	Damage Detail		
302	Damage detail Engine bay or boot		
303	Damage detail Engine bay or boot		
304	Detail damage Car		
305	Grills G9 Multi 2/3 photo exposure sequence		
306	Grills G9 Multi 2/3 photo exposure sequence		
307	Grills G9 Multi 2/3 photo exposure sequence		
308	Grills G9 Multi 2/3 photo exposure sequence		
309	Grills G9 Multi 2/3 photo exposure sequence		
310	Grills G9 Multi 2/3 photo exposure sequence		
311	Grills G9 Multi 2/3 photo exposure sequence		

312	Grills G9 Multi 2/3 photo exposure sequence		53737
313	Arrow Fastback After Crash Test H7 Offside	Fastback	
314	Arrow Fastback Before Crash H7 Offside	Fastback	
315	Arrow Fastback Before Crash H7 Nearside	Fastback	
316	Arrow Fastback After Crash Test H7 Nearside	Fastback	
317	Close up of steering wheel and roof above		
318	Arrow Fastback LHD After Test H7 Drivers position and bonnet	Fastback	
319	Arrow Fastback LHD After Test H7 Over windscreen	Fastback	
320	Arrow Fastback After Test H7 Boot	Fastback	
321	Arrow Fastback After test H7 Rear Seating	Fastback	
322	View of Driving Position		
323	Arrow Fastback LHD Test H7 Passenger side	Fastback	
324	Arrow Fastback LHD After Test H7 Passenger side	Fastback	
325	Arrow Fastback LHD Test H7 Over windscreen	Fastback	
326	Arrow Fastback LHD After Test H7 Through windscreen	Fastback	
327	Arrow Fastback LHD After Test H7 nearside front	Fastback	
328	Arrow Fastback LHD After Test H7 All car from nearside	Fastback	
329	Arrow Fastback Engine compartment		
330	Arrow Fastback LHD Windscreen		
331	Arrow Fastback LHD After Test H7 Offside Front	Fastback	
332	Arrow Fastback LHD After Test H7 Underside	Fastback	
333	Arrow Fastback LHD After Test H7 Underside front	Fastback	
334	Avenger Before Crash Test H18 Offside	Avenger	
335	Avenger Crash Test H18 Offside	Avenger	
336	Avenger Crash Test H18 Offside front	Avenger	
337	Avenger Crash Test H18 nearside	Avenger	
338	Avenger Drivers position	Avenger	

339	Avenger befor test H18 near side	Avenger
340	Avenger After Test H18 nearside view	Avenger
341	Underside view of steering	
342	Avenger Test H18 Engine Bay	Avenger
343	Avenger After Test H18 nearside front view	Avenger
344	Avenger Test H18 View above Roof	Avenger
345	Avenger Test H18 Front	Avenger
346	Avenger After Test H18 View above roof	Avenger
347	Avenger Test H18 Drivers Position	Avenger
348	Avenger Test H18 Drivers Position	Avenger
349	Avenger Test H18 Rear View Towing Strop	Avenger
350	Under side of Engine	
351	Under side of Gearbox	
352	Wheel to Body	
354	Under side of Gearbox	
355	Avenger Test H18 Engine Bay	Avenger
356	Wheel to Body	
357	Avenger Test H18 Fuel Filler	Avenger
358	Detail	
359	Detail Spring and Exhaust	
360	Avenger After Test H18 Front	Avenger
361	Avenger After Test H18 Front	Avenger
363	View of Rear suspension	
364	Avenger After Test H18 Underside	Avenger
365	Avenger After Test H18 Underside Front	Avenger
366	Detail underside Silencer	
367	View of underside Engine and Gearbox	
368	Detail	
369	Detail Spring	
370	Detail Track Rod and Gaiter	
371	Detail underside Exhaust Box	
372	Avenger After Test H18 Engine Bay	Avenger
373	Detail Underside Front to Rear	
376	Detail Underside Differential	
377	Detail Underside Differential Prop Shaft	
378	Detail Tyre to Wheel Arch Gap	
379	Detail Underside Forward to Engine Bay	
380	Detail Underside Silencer forward	
382	Note 382 -399 Colour Slides	
383	Note 382 -399 Colour Slides	

384	Note 382 -399 Colour Slides		
385	Note 382 -399 Colour Slides		
386	Note 382 -399 Colour Slides		
387	Note 382 -399 Colour Slides		
388	Note 382 -399 Colour Slides		
389	Note 382 -399 Colour Slides		
390	Note 382 -399 Colour Slides		
391	Note 382 -399 Colour Slides		
392	Note 382 -399 Colour Slides		
393	Note 382 -399 Colour Slides		
394	Note 382 -399 Colour Slides		
395	Note 382 -399 Colour Slides		
396	Note 382 -399 Colour Slides		
397	Note 382 -399 Colour Slides		
398	Note 382 -399 Colour Slides		
399	Note 382 -399 Colour Slides		
400	Steering System Impact		Vehicle Pre- sentation
401	Barrier Impact Test H18 Results?	Avenger	Vehicle Pre- sentation
402	Barrier Impact Test Results?		
403	Note 403 to 407 Colour Slides		
404	Note 403 to 407 Colour Slides		
405	Note 403 to 407 Colour Slides		
406	Note 403 to 407 Colour Slides		
407	Note 403 to 407 Colour Slides		
408	Avenger Test H33 Offside		Neg 12A
409	Color Neg H33 Front Compartment		Neg 11A
410	Colour Neg People around Yellow Avenger H33		33794
411	Colour Neg Test H33 Drivers Posi- tion		Neg 9A
412	Colour Neg Avenger Test H33 Peo- ple around	Avenger	Neg 7A
413	Avenger Before Test H33 Nearside	Avenger	Neg 15A
414	Avenger Test H33 Lights and Film- ing	Avenger	Neg 6A
415	Avenger Test H33 Lights and Film- ing	Avenger	Neg 5A
416	Empty		
417	Avenger Before Test H33 Offside	Avenger	Neg 1A
418	Avenger Before Test H33 Rear	Avenger	Neg 2A
419	Avenger Before Test H33 Rear	Avenger	Neg 1
420	Avenger Test HR28 Rear Outside	Avenger	
421	Avenger Test HR26 Rear Damage	Avenger	
422	Detail underside Tailpipe area		
423	Avenger Test HR28 Inside Boot	Avenger	
424	Avenger Test HR28 Inside Boot	Avenger	

425	Avenger Test HR28 Fuel Tank	Avenger
426	Avenger Test HR 28 Fuel Tank Rear wheel	Avenger
427	Avenger Test HR28 Inside Boot Off-side	Avenger
428	Detail underside Fuel Tank and Filler	Avenger
429	Avenger Test HR28 rear view	Avenger
430	Avenger Test HR28 Offside	Avenger
431	Avenger HR28 Damaged and Collision TRAILER Rig in Field	Avenger
432	Avenger HR28 Damaged and Collision TRAILER Rig H3?	Avenger
433	Avenger HR28 Damaged and Another H3 ?	Avenger
434	Avenger HR28 Damaged and Another H3?	Avenger
435	Avenger H33 LHD 2 Photos of Engine Bay	
436	Detail Underside View Rear forward	
437	Detail Underside View Differential	
438	Detail Underside back of rear wheel	
439	Detail Underside Gearbox and Silencer	
440	Detail Underside Prop Shaft and Silencer	
441	Detail Underside Behind Front Wheel	
442	Detail Underside Front suspension	
443	Detail Underneath	
444	Detail Underneath Front Suspension	
445	Detail of Damage Windscreen Pillar Test ?83	
446	Detail of Damage Windscreen Pillar	
447	Avenger Test H33 Front Damage Offside view	Avenger
448	Avenger Test H33 Front Damage Nearside view	Avenger
449	Avenger Test H33 Front Damage View Front	Avenger
450	Avenger Test H33 View around Fuel Filler	Avenger
451	Detail Around Brake Disc	
452	Detail Underneath Prop Shaft and Silencer	
453	Detail Around Brake Disc	

454	Damage detail onliff Front Under- side		
455	View underneath Engine Bay		
456	View underneath Engine Bay		
457	Avenger Test H33 Nearside	Avenger	
458	Avenger LHD H33 Drivers position	Avenger	
459	Avenger LHD H33 Drivers Seat	Avenger	
460	Avenger LHD H33 Drivers position	Avenger	
461	Avenger H33 LHD of Engine Bay	Avenger	
462	Avenger H33 LHD Above Wind- screen and Bonnet	Avenger	
463	Avenger After Test H33 Offside View	Avenger	
464	Avenger After Test H33 Offside Wing View	Avenger	
465	Avenger LHD Test H33 Drivers Po- sition	Avenger	
466	Avenger After Test H33 Offside View	Avenger	
467	Avenger After test H33 Nearside View	Avenger	Print also
468	Avenger Test H33 Offside View	Avenger	
469	Avenger Test H33 Front View	Avenger	
470	Avenger Test H33 Drivers Position	Avenger	
471	Avenger Test H33 Drivers Position	Avenger	
472	Avenger Test H33 Rear View	Avenger	
473	Detail around Wheel Hub		
474	Detail around Wheel Hub		
475	Detail around spare Wheel in Boot		
476	View Underneath Fuel Tank and Diff		
477	Detail ?		
478	Detail Underneath Fuel Tank and Rear Wheel		
479	Detail Underneath		
480	Detail Underneath Fuel Tank and Diff		
481	Detail Underneath Fuel Tank		
482	Detail ?		
483	Detail Windscreen Pillar		
484	Detail Windscreen Pillar		
485	Detail ?		
486	Test HR2? View of Offside Doors		
487	Detail View of Nearside Doors and Windows		
488	Test HR28 View into Boot		
489	Damage view into Boot Offside		

490	View rear of Offside Rear Door and Handle	
491	Detail Shaft Splines	
492	View underneath Gearbox Prop Shaft Silencer	
493	Avenger Test H33 View Underside	Avenger
494	Detail View Under Engine Bay and Front Wheels	
495	Detail Underneath Forward of Prop Shaft	
496	Detail Underneath Springs?	
497	Detail Servo?	
498	Detail Underneath Damper ?	
499	Detail Underneath Damper ?	
500	Detail Chassis ?	
501	Detail Body Joint?	
502	Detail around wheel	
503	Detail Damage Chassis	
504	Avenger LHD Test H33 View of Windscreen Bonnet	Avenger
505	Avenger Test H37 View Offside	Avenger
506	Avenger Test H37 View NearSIDE	Avenger
507	Avenger Test H37 View of Rear	Avenger
508	Avenger Test H37 Drivers position	Avenger
509	Avenger Test H37 Drivers position	Avenger
510	Detail Above Engine Bay	
511	Avenger Test H37 View of Windscreen and Bonnet	Avenger
512	Detail Track Rod and Gaiter Double Image	
513	Detail Underside Gearbox rearward	
514	Avenger Test H37 Front View	Avenger
515	Avenger Test H37 Underside from Front	Avenger
516	Detail inside of Front Wheel	
517	Detail under Engine Bay and inside Front Wheel	
518	Detail Underneath of Diff and Fuel Tank	
519	Detail Underside	
520	Avenger After Test H37 View Near-side	Avenger
521	Avenger After Test H37 View Off-side	Avenger
522	Avenger LHD After Test H37 Drivers Position	Avenger
523	Avenger After Test H37 Offside Front	Avenger

524	Avenger After Test H37 Nearside	Avenger
525	Avenger After Test H37 Windscreen Area	Avenger
526	Avenger After Test H37 View Thro Back to Front	Avenger
527	Avenger After Test H37 Nearside Front	Avenger
528	Avenger After Test H37 View of Bonnet and Windscreen	Avenger
529	Avenger After Test H37 Drivers Position	Avenger
530	Detail Thro Quarter Light	
531	Detail of inside of Nearside Front Wheel	
532	Avenger After Test H37 Front	Avenger
533	Detail of inside of Offside Front Wheel	
534	Detail from above Engine Bay	
535	Detail of Front Seat Backs missing	
536	Avenger Test H37 Drivers position	Avenger
537	Detail Damage nearside Suspension	
538	Detail Damage Bulkhead Area	
539	Detail Rods or Tubes?	
540	Detail ? Underneath	
541	Detail Underneath Rear Spring	
542	Detail Underneath Gearbox	
543	Detail Underneath Gearbox	
544	Detail Underneath Gearbox Support	
545	Detail Underneath Prop Shaft and Silencer	
546	Detail Underneath Prop Shaft and Silencer	
547	Detail Underneath Gearbox and Prop Shaft	
548	Detail Underneath Diff and Drive Shafts	
549	Detail Wheelarch and Door Latch	
550	Door Latch Detail Offside	
551	Door Latch Detail Nearside	
552	Door Hinge Detail Nearside	
553	Door Hinge Detail Nearside Rear	
554	Door post Detail	
555	Avenger Test H58 View of Front	Avenger
556	Avenger Test H58 View of Rear	Avenger
557	Avenger Test H58 View of Nearside	Avenger
558	Avenger Test H58 View Offside	Avenger

559	Avenger LHD H58 View Of Wind-screen	Avenger
560	Avenger View of Engine Bay	Avenger
561	Avenger Test Drivers Position	
562	Avenger Test Steering Wheel	
563	Avenger LHD Test H58 View of Dash	
564	Avenger LHD Test H58 Steering Wheel	
565	Detail of Interior	
566	Detail of Interior	
567	Detail of Underside of Engine Bay	
568	Detail Airfilter?	
569	Detail Underside Steering Rack	
570	Detail Underside Steering Rack	
571	Detail Underside Steering Rack	
572	Detail Underside Steering Rack	
574	Avenger After Test H58 Front View	
575	Avenger After Test H58 View Near-side	
576	Avenger After Test H58 View Off-side	
577	Avenger After Test H58 View Off-side Wing	
578	Avenger After Test H58 View Off-side Wing	
579	Detail of Driver Position	
580	Detail Damage Underside Steering Rack	
581	Detail Damage Underside Front Wheel	
582	Detail Damage Underside Front Wheel	
583	Detail Damage Underside Front Wheel	
584	Detail Underside Steering Rack	
585	Detail Underside Steering Rack	
586	Test Damage of Dash	
587	Avenger Test H57 Nearside	Avenger
587	"A" Avenger Damaged Test H57 All Underside	
588	Avenger Damaged Test H57 Near-side	
588	"A" Damage Detail H57 Steering	
589	Detail Drivers Position	
589	"A" Detail of Interior n	
590	Avenger Damaged Test H57 Offside	
590	"A" Damage Detail Engine Bay	

591	Detail of Drivers Position	
591	"A" Detail Underside Gearbox	
592	Test Detail of Drivers Position	
593	Avenger Test H57 Offside Damaged Rear	
594	Avenger Test H57 Offside Damaged Front and Rear	
595	Avenger Test H57 Nearside Damaged Front and Rear	
596	Avenger After Test H57 Nearside Wing	
597	Avenger After Test H57 Offside Wing	
598	Damage Detail Engine Bay	
599	Damage Detail Front Suspension	
600	Damage Detail Engine Bay	
601	Damage Detail Underside Fuel Tank and Diff	
602	Test H57 Damage Detail Underside Engine Bay	
603	Test H57 Damage Detail Underside from Front	
604	Damage Detail Underside Prop Shaft	
605	Detail Dash Area	
606	Detail Drivers Position	
607	Detail Driver and Passenger Seats	
608	Damage Detail Test H58 Gearbox and Prop Shaft	
609	Avenger Damaged Test H58 Underside View	
610	Avenger Damaged Test H58 Front Underside View	
611	Detail Underside of Boot and Diff	
612	Test H58 Graph	
613	Detail Engine Bay	
614	Avenger Before Test H72 Offside View	Avenger
615	Avenger After Test H72 Offside Wing	
616	Avenger After Test H72 Nearside Wing	
617	Test H72 Front Passenger Knees	
618	Avenger After Test H72 Nearside	
619	Avenger After Test H72 Offside	
620	Avenger Test H72 Nearside	Avenger
621	Avenger LHD Test 72 Rear Offide	
622	Avenger LHD Test Dummy Driver	

623	Avenger LHD Test H72 Passengers Knees		
624	Avenger LHD Test H72 Dummy Passenger		
625	Avenger LHD Test H72 Dummy Passenger		
626	Avenger LHD Test H72 Windscreen and Bonnet		
627	Avenger LHD After Test H72 Near- side		
628	Detail Underside of Rear		
629	Detail Underside of Front		
630	Detail of Underside		
682	Lorry under Tower Rig Hanger out- side		Envelope
683	Lorry Test C14 Hanging Plate Cab		Envelope
684	Chart of Technical Safety Organisa- tion		Safety
685	Avenger Estate Test H98 Offside	Avenger Estate	
686	Avenger Estate Test H98 Nearside	Avenger Estate	
687	Avenger Estate Test H98 Front	Avenger Estate	
688	Avenger Estate Test H98 Rear	Avenger Estate	
689	Avenger Estate Test H98 Tailgate open		
690	Avenger Estate Test H98 Wind- screen and Bonnet		
691	Avenger Estate Test H98 Engine Bay		
692	Avenger Estate Test H98 Drivers Position		
693	Avenger Estate Test H98 Interior		
694	Avenger Estate Test H98 Interior		
695	Avenger Estate Test H98 Front Seating		
696	Avenger Estate After Test H98 Nearside Rear Quarter		
697	Avenger Estate After Test H98 Nearside		
698	Avenger Estate After Test H98 Off- side		
699	Detail Damage Drivers Position		
700	Detail Damage After Test H98 Front Seating		
701	Detail Damage Offside Front Wing		
702	Detail Damage Nearside Front Wing		
703	Detail Test H98 Roof and Interior		
704	Detail Test H98 Roof and Interior		

705	Detail Damage Test H98 Engine Bay	
706	Detail Damage Test H98 Front Seating	
707	Detail Damage Test H98 Driver Position	
708	Detail Damage Test H98 Underside Steering and Wheel	
709	Detail Damage Test H98 Underside Steering and Wheel	
710	Detail Damage Test H98 Underside Gearbox Support	
711	Detail Damage Test H98 Underside Front	
712	Detail Damage Test H98 Underside	
713	Detail Damage Underside Rear	
714	Detail Damage Underside Prop Shaft	
715	Detail Damage Test H98 Underside Prop Shaft	
716	Lorry Damage After Test C14 Offside Cab	Lorry
717	Lorry Cab in Compression Rig	
718	Lorry Cab in Compression Rig	
719	Lorry Cab in Compression Rig	
720	Lorry Cab Test C14 FrontQuarter	
721	Lorry Cab Test C14 FrontQuarter	
722	Lorry Cab Test C14 Compression Offside	
723	Lorry Cab Test C14 Compression Offside Quarter	
724	Lorry Cab Compression Test Front	
725	Lorry Cab Compression Test Rear	
726	Lorry Cab Compression Test Rear	
727	Lorry and Outside Tower Test Rig	
728	Lorry Test C12 Tower Test Rig	
729	Lorry Test C12 Tower Test Rig	
730	Lorry Test C12 Tower Test Rig	
731	Damaged Lorry Test C15	Ford
732	Damaged Lorry Test C15	Ford
733	Damaged Lorry Drivers Position	
734	Damaged Lorry Test C1 Front with Collision Plate	Ford
735	Damaged Lorry Test C15 Front Nearside Quarter	Ford
736	Damaged Lorry Cab Rear Offside Quarter	Ford

737	Damaged Lorry Test C1 Font Off-side Quarter and Plate	Ford
738	Damaged Lorry Cab Nearside Rear Quarter	Ford
739	Damaged Lorrt Cab C15 Nearside	Ford
740	Damaged Lorry Cab C15 Front Nearside	Ford
741	Avenger Body Test J23 Offside	
742	Detail Drivers Seat Airbag	
743	Detail Test J23 Drivers Area and Airbag	
744	Detail Front Seating Airbag	
745	Detail Test J23 Offside Rear Door and Wheel Arch	
746	Avenger Body Test J23 Offside 3 Dummies	
747	Detail Dummy in Drivers Position	
748	Detail Dummies in Rear Seats	
749	Detail Dummies in Rear Seats	
750	Detail Dummies in Front Seats	
751	Detail Dummies in Front Seats	
752	Detail Dummies in Car View from Rear	
753	Detail Dummies in Front Seats	
754	Detail After Test J24 Dummies in Front Seats	
755	Detail Instrumentatio and Rear of Car Test JS??	
756	Detail Avenger Body Offside no Doors	
757	Detail Avenger Body Offside no Door View front Seating	
758	Detail Avenger Body Offside no Door Dummy Driver	
759	Avenger Body Test J24 Nearside Dummies	
760	Detail After Test J24 Dummies in Front Seats	
761	Detail After Test J24 Dummies in Front Seats Offside	
762	Detail After Test J24 Dummies in Front Seats Nearside	
763	Detail Damage Test J24	
764	Detail Damage Test J24	
765	Detail Damage Engine Bay Offside Rear Corner	
766	Detail Damage	
767	Detail Damage	

768	Vehicle After Test View Dummy in Drivers Position		
769	Avenger After Test J37 Offside		
770	Detail After Test Front Seating		
771	Detail After Test Roof		
772	Avenger After Test J37 Windscreen		
773	Avenger After Test J37 Nearside		
774	Avenger LHD After Test J37n Thro Driver Window		
775	Avenger LHD Test J37 Offside		
776	Avenger LHD Test J37 thro Drivers Window		
777	Avenger LHD Test J37 Thro Rear Window		
778	Avenger LHD Test J37 Offside		
779	Avenger LHD Test j37 Nearside Quarter		
780	Avenger LHD Test J37 thro Passenger Window		
781	Avenger LHD Test J37 Thro Drivers Door		
782	Detail H72 LHD Thro nearside Windscreen		
783	Detail Inside of Front Wheel		
784	Detail Strut Mounting		
785	Detail J37 Thro nearside Windscreen		
786	Avenger After Test J37 View of Front		
787	Detail of Seat mounting		
788	Late Model Imp J80 Crash Test (TDU 626J)	Imp	2 Photos
788	Detail of Steering Position		
789	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
790	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
790	Detail After Test J80 Steering Wheel	Imp	
791	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
791	Imp After Test J80 Front Damage Offside View	Imp	
792	Late Model Imp J80 Crash Test (TDU 626J)	iImp	
792	Imp After Test J80 Damage Dash Area	Imp	

793	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
793	Imp After Test J80 Thro Rear Window	Imp	
794	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
794	Imp After Test J80 View on Front	Imp	TDU 626J
795	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
795	Imp Test J80 Nearside View	Imp	
796	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
796	Imp Test J80 Rear View	Imp	
797	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
797	Imp After Test J80 Nearside Quarter View	Imp	
798	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
798	Imp Test J80 Offside	Imp	
799	Late Model Imp J80 Crash Test (TDU 626J)	Imp	
800	Stiletto J86 Crash Test	Stiletto	
800	Coupe Imp Test J86 Nearside	Imp Coupe	
801	Stiletto J86 Crash Test	Stiletto	
801	Coupe Imp Test J86 Offside	Imp Coupe	
802	Stiletto J86 Crash Test	Stiletto	
802	Coupe Imp After Test J86 Thro Rear Window		
803	Stiletto J86 Crash Test	Stiletto	
803	Coupe Imp After Test J86 Offside		
804	Stiletto J86 Crash Test	Stiletto	
804	Coupe Imp After Test J86 Nearside		
805	Stiletto J86 Crash Test	Stiletto	
805	After Test J86 Detail Thro Passenger Window		
806	Stiletto J86 Crash Test	Stiletto	
806	Detail Test J86 Thro Passenger Window		
807	Stiletto J86 Crash Test	Stiletto	
807	Coupe Imp Test J86 Rear View	Imp Coupe	TDU 631J
808	Detail of Damaged Drivers Position		
809	Detail of Damaged Pedal Area		
810	Avenger After Test J58 offside Doors	Avenger	
811	Avenger Test J58 Rear View		
812	Avenger After Test J58 View on Front Offide Quarter		

813	Detail of Dummy in Drivers Seat		
814	Avenger After Test J58 Dummy Driver Offside		
815	Avenger After Test J58 Dummies in Offside Seats		
816	Test J58 Dummies in Offside Seats Thro Rear Window		
817	Avenger Outside Front View		
818	Avenger Front View People Around	Avenger	RKV 344H
819	Detail String/Wiring		
820	Detail Front Seating Dummy		
821	Detail Rear Seating Dummy		
822	Detail View thro Rear Window		
823	Avenger Dummy Driver thro Doorway		
824	Space Frame Rig		Water Damage
825	Space Frame Rig		Water Damage
826	Space Frame Rig		Water Damage
828	Arrow Fastback Test J99 View of Rear	Sunbeam	
829	Arrow Fastback Test J99 View of Nearside		
830	Detail of Engine Bay Test J99		
831	Arrow Fastback Test J99 Offside View		
832	Detail of Drivers Position Test J99		
833	Detail of Drivers Position Test J99		
834	Arrow Fastback After Test J99 Nearside View		
835	Arrow Fastback After Test J99 Offside View		
836	Detail Test J99 View of Steering Position		
837	Arrow Fastback After Test J99 Nearside View		
838	Detail of Drivers Position from Nearside		
839	Arrow Saloon Test J98 Rear View	Humber	
840	Arrow Saloon Test J98 View Front Seating Area		
841	Arrow Saloon Test J98 View Drivers Position		
842	Arrow Saloon Test J98 Nearside View		

843	Arrow Saloon Test J98 Nearside View		
844	Detail View of Engine Bay Test J98		
845	Detail of Steering Wheel		
846	Detail of Front Seating		
847	Arrow Saloon After Test J98 Offside View		
847	(A) Block Chrysler Dummy		2 Negs
848	Arrow Saloon After Test J98 Rear Nearside		
849	Arrow Saloon After Test J98 Rear Nearside Quarter		
850	Arrow Estate Test 119 View of Dash and Steering Wheel	Arrow Estate	
851	Arrow Estate Test 119 View of Dash and Steering Wheel	Arrow Estate	
852	Arrow Estate After Test 119 View from Offside Front	Arrow Estate	
853	Arrow Estate After Test 119 Offside	Arrow Estate	
854	Detail Thro Drivers Quarter Light		
855	Arrow Estate After Test 119 Near-side Front	Arrow Estate	
856	Arrow Estate After Test 119 Offside		
857	Detail Of Steering Wheel and Dash		
858	"5and6" Detail Damage Avenger Test J98	Avenger	
859	Avenger Body Test JS130 Offside no doorOff		
860	Avenger Body Test JS130 Close up Offside		
861	Avenger Body Test JS130 Nearside Dummies		
862	Avenger Body Test JS130 Nearside Dummies		
863	Avenger Body After Test JS130 Offside		
864	Avenger Body After Test JS130 Padded Dash		
865	Avenger Body After Test JS130 Padded Dash		
866	Avenger Body High Front Seats and Dummies		
867	Avenger Body High Front Seats and Dummies thro Pass.Door		
868	Detail After Test JS130 View thro Drivers Door Dummies		
869	Detail After Test JS130 View of Windscreen Area Dummies		

870	Detail After Test JS130 View thro Passenger Door Dummies	
871	Detail After Test JS130 View thro Passenger Door Dummies	
872	Detail Test J132 Engine Bay	
873	Detail Test J132 Intrumented Steer- ing Wheel	
874	Arrow Fastback Test J132 Rear	Sunbeam
875	Arrow Fastback Test J132 Offside View	
876	Arrow Fastback Test J132 Drivers Position thro Pass.Door	
877	Arrow Fastback Test J132 Nearside	
878	Arrow Fastback Test J132 Drivers Position thro Pass.Door	
879	Arrow Fastback After Test J132 Nearside	
880	Arrow Fastback After Test J132 Off- side Wing	
881	Arrow Fastback After Test J132 Drivers Position	
882	Arrow Fastback After Test J132 Off- side	
883	Arrow Fastback After Test J132 Nearside	
884	Arrow Fast Back After Test J132 Nearside Wing	
885	Avenger 2 Door Test J114 Offside	Avenger
886	Avenger 2 Door Test J114 Rear	Avenger
887	Avenger 2 Door Test J114Nearside	Avenger
888	Detail Boot Spare Wheel	
889	Detail ?	
890	AvengerTest J114R Rear	Avenger
891	Avenger Test J114R View LH Rear Quarter	Avenger
892	Avenger 2 Door After J114R Near- side View Dustbin	
893	Avenger 2 Door After J114R Offside View Dustbin	
894	Avenger 2 Door After J114R Near- side View	
895	Avenger 4 Door After J150 Nearside View	
896	Avenger 4 Door Test J150 Nearside View	
897	Avenger 4 Door After J150 Offside View	
898	Detail Drivers Position Test J150	

899	Detail After Test J150 View thro Rear Window		
900	Detail After Test J150 View thro Passenger Door		
901	Detail Test J150 Drivers Position		
902	Detail Test J150 Drivers Position thro Passenger Door		
903	Avenger Test 150 View thro Rear Window		
904	Avenger Test J150 Engine Bay		
905	Avenger Test J150 View down Near-side		
906	Avenger Test J150 View down Off-side Rear Wing		
907	Avenger Test J150 Rear		
908	Avenger After Test J150 Offside		
909	Avenger After Test J150 Nearside		
910	Block Dummy		
911	Block Dummy		
912	Block Dummy		
913	Block Dummy		
914	Block Dummy		
915	Block Dummy		
916	Block Dummy		R/388
917	Block Dummy		
918	Outline of Concept Car Advanced Engineering		
919	Diagram Vehicle Handling Parameters Tyres		
920	Detail Test K45 Engine Bay		
921	Detail After Test Steering Wheel		
922	Detail After Test K45 Dummy Driver		
923	Detail After Test K45 Dummy Driver		
924	Detail After Dummies thro Passenger Window		
925	Detail After Test K45 Thro Offside Door Dummy		
926	Detail LHD After Test K45 Nearside Door Dummy		
927	Detail LHD After Test K45 Nearside Door Dummy		
928	Avenger LHD After Test K45 Off-side		
929	Avenger LHD After Test K45 Near-side		
930	Avenger LHD Test K45 Nearside	Avenger	

931	Avenger 4 Door Test K45 Offside		
932	Avenger 4 Door Test K45 Nearside People		
933	Avenger 4 Door After Test K45 Nearside Rear Quarter		
934	Avenger Test K45 View thro Rear Window		
935	Typed Text "Rigid Foam Anthropometric Test Device"		Neg Damaged
936	Block Dummy		
937	Block Dummy		
938	Line up of Various Damaged Test Cars K7 plus		
939	Front Damage Test K45 Avenger 4 Door		
940	Text Document Vehicle Primary Control and Stability		
941	Graph		
942	Graphs Examples of Known Car Layout Constant 40mph		
943	Graph/Diagram Test Method		
944	23 Detail Seatbelt Anchor		
944	24 Deatil Seatbelt at Side of Driver Seat		
948	Instrumented Seat and Dummy on Trolley		Run Number 1
949	Instrumented Seat and Dummy on Trolley	01/02/1972	Run Number 2
950	Instrumented Seat and Dummy on Trolley	01/02/1972	Run Number 3
951	Detail of Diff and Spring		
952	Block Dummy in Front Passenger Seat		
953	Detail of Seatbelt Anchor		
954	Detail of Seatbelt across Block Dummy		
955	Block Dummy in Drivers Seat		
956	Block Dummy in Drivers Seat		
957	Seatbelt across Block Dummy in Passengers Seat		
958	Block Dummy		
959	Block Dummy		
960	Avenger 4 Door LHD Test K99		
961	Avenger 4 Door LHD Test K99 Damaged		
962	Avenger 4 Door LHD Test K99 Drivers Position		

963	Avenger Estate Test K99 View of Rear		Avenger Estate
964	Avenger Estate Test K99 View thro Rear Offside Window		
965	Avenger Estate Test K99 Engine Bay		
966	Avenger Estate Test K99 Nearside		
967	Avenger Estate Test K99 Offside		
968	Avenger Estate Test K99 Offside Front Damage		
969	Avenger Estate Test K99 Nearside Front Damage		
970	Avenger Estate Test K99 Nearside Front Damage		
971	1 Dummy in Seat		
971	2 Close up of Dummy in Seat		
971	3 Dummy out of Seat		
971	4 Close up of Dummy out of Seat		
971	5 Test Wiring to Test Seat		
971	6 Detail of Seatbelt		
972	7 Negatives of Seatbelt/Dummy Test		
973	8 Negatives of Seatbelt/Dummy Test		
974	6 Negatives of Seatbelt/Dummy Test		
975	Dummy and Seat on Trolley	22/02/1972	
976	6 Negatives of Seatbelt/Dummy Test		
977	Dummy and Seat on Trolley	22/02/1972	
978	6 Negatives of Seatbelt/Dummy Test		
979	Dummy and Seat on Trolley	22/02/1972	
980	9 Negatives of Seatbelt/Dummy Test		
981	Dummy and Seat on Trolley	22/02/1972	
982	6 Negatives of Seatbelt/Dummy Test		
983	Dummy and Seat on Trolley	22/02/1972	
984	6 Negatives of Seatbelt/Dummy Test		
985	Dummy and Seat on Trolley Test KS184	07/03/1972	
986	6 Negatives of Seatbelt/Dummy Test		
987	Dummy and Seat on Trolley	07/03/1972	
988	6 Negatives of Seatbelt/Dummy Test		

989	Dummy and Seat on Trolley	07/03/1972		
990	Dummy and Seat on Trolley	07/03/1972		
991	6 Negatives of Seatbelt/Dummy Test			
992	6 Negatives of Seatbelt/Dummy Test			
993	Dummy and Seat on Trolley	07/03/1972		
994	6 Negatives of Dummy/Seat Test K202			
995	Avenger 4 Door After Test K202 Nearside Quarter			
996	Avenger 4 Door After Test K202 Nearside Quarter			
997	Damage After Test K202			
998	2 Negatives of Test K109			
999	Avenger Estate After Test K109 Nearside View			
1000	Block Dummy			
1001	Block Dummy			
1002	11 Negatived of Avenger Test K241		Avenger	RKV 345H
1003	4 Negatives Details of Test K241			
1004	Bump Trolley For Rear Shunt Test			
1005	8 Negatives of Avenger Test K229			
1006	10 Negatives of Dummy/Seat Test KS325			
1007	3 Negatives of Dummy/Seat Test Ks325			
1008	15 Negatives of Avenger Test K263			
1009	Avenger LHD Test K263 Nearside			
1010	6 35mm Negatives around Steering Wheel			
1011	Avenger 4 Door Test K319 Nearside			
1012	8 Negatives Of Avenger Test K319			
1013	A-6 35mm Negatives around Car Test G69			
1013	B-12 35mm Negatives around Car Test G69			
1013	C-10 35mm Negatives around Car Test G69			
1014	7A-4 35mm Negatives of Steering Wheel			
1015	8 Negatives of Avenger Test L48			
1016	2 Negatives Detais of Test L48			
1017	Avenger 4 Door L48 Nearside			
1018	6 35mm Negatives around Steering Wheel			
1019	7 35mm Negatives around Steering Wheel			

1021	10 Negatived Avenger Test L153		
1023	4 35mm Negatives Car Interior /Person		
1025	Detail of Steering Rack Suspension		
1026	Detail of Car Front Underside		
1027	Detail of Car Front Underside		
1028	Detail of Car Rear Underside		
1029	Detailof Car Rear Underside		
1030	All Underside of Car Test K319		
1031	All Underside of Car Test K319		
1032	Detail of Car Front Underside		
1033	Car Interior Desired Location Area		
1034	Avenger 4 Door Rear Nearside View	Avenger	REG 725
1035	Avenger 4 Door Nearside View	Avenger	
1036	Avenger 4 Door Front Nearside View	Avenger	REG 725
1037	2 35mm Negatives of Engine Bay		
1038	12 35mm Negatives of Body Details		
1039	Lots of 35m Negatives of Body Details		
1040	7 35mm Negatives of Seat/Belt Details		
1041	10 35mm Negatives of Test Damage Detail		
1051	Imp 468 After Crash Test	Imp	
1051	Imp Nearside Front Damage	Imp	VJU68?
1052	Imp 486 After Crash Test	Imp	
1052	Imp Nearside Front Damage Number Plates	Imp	
1053	Imp 486 After Crash Test	Imp	
1053	Imp Nearside Front Damage Number Plates	Imp	
1054	Imp 486 After Crash Test	Imp	
1054	Imp Nearside Front Damage Number Plates	Imp	
1055	Imp 792 After Crash Test	Imp	
1055	Close up of Damage		
1056	Imp 792 After Crash Test	Imp	
1056	Close up of Ddamage		
1057	Imp 792 After Crash Test	Imp	
1057	Close up of Damage		
1058	Imp 792 After Crash Test	Imp	
1058	Totally Wrecked Imp amide other Cars		
1059	Imp 792 After Crash Test	Imp	
1059	Totally Wrecked Imp amide other Cars		
1060	Imp 792 After Crash Test	Imp	

1060	Close up of Damage		
1061	Imp 542 After Crash Test	Imp	
1061	Close up of Damage		
1062	Imp 542 After Crash Test	Imp	
1062	Close up of Damage		
1063	Imp 542 After Crash Test	Imp	
1063	Wrecked Imp/Chamois Front Damage		
1064	Imp 542 After Crash Test	Imp	
1064	Wrecked Sunbeam/Chamois Twin Headlights Front Damage		
1065	Imp 542 After Crash Test	Imp	
1065	Detail Of Front Damage		
1066	Imp 542 After Crash Test	Imp	
1066	Close up of Damage		
1067	Imp 542 After Crash Test	Imp	
1067	Detail Damage		
1068	Imp 542 After Crash Test	Imp	
1068	Imp Extensive Front Damage	Imp	
1069	Imp 542 After Crash Test	Imp	
1069	Imp Extensive Front Damage along side of Minx	Imp Minx	
1070	Imp 542 After Crash Test	Imp	
1070	Imp Extensive Front Damage Person	Imp Minx	
1071	12 35mm 4A-15A Negatives of Avenger	Avenger	
1071	12 35mm 16A-28A Negatives of Details		
1071	12 35mm 29A-37A Negatives of Details		
1072	8 35mm Negatives of Details mainly Interior		
1073	5 35mm Negatives of Detail		
1074	81-12 35mm Negatives of Details		
1081	86-6 35mm Negatives of "M" Registered Car		GRW 6?7M
1087	5/6/7 6 35mm Negatives of Details		
1088	2 Negatives of Dash/Steering Wheel		
1089	Outline of Wheel and Exhaust Boot Layout?		
1090	Outline of Wheel and Exhaust Boot Layout		
1091	8 35mm Negatives of Details mainly Seat		
1091	6 35mm Negatives of Details		3/4 Front
1091	8 35mm Negatives of Details mainly Seat		

1092	6 35mm Negatives of Details including Seat		
1093	12 35mm Negatives of Details including Interior and Wheels		
1094	2 35mm Negatives of Seat Frame		
1095	Dash		
1096	Detail of Dash End		
1097	6 35mm Negatives Dash/Steering Wheel thro windscreen		
1100	2x Diagramatic of Body and Doors		
1101	2x Consept? Car and Person		
1102	Drg 73166246 Assembly of 6 Speed Gearbox		73166246
1103	Drg 73166247 Assembly of 5 Speed Gearbox		73166247
1104	Drg 73166245 Assembly of 5 Speed Gearbox		73166245
1105	Drg 73166243 Assembly of 5 Speed Gearbox		73166243
1106	Drg 73166240 Assembly of 4 Speed Gearbox		73166240
1107	Drg 73166249 Assembly of 5 Speed Gearbox		73166249
1108	Drg 73166250 Assembly of 6 Speed Gearbox		73166250
1109	Drg 73166248 Assembly of 6 Speed Gearbox		73166248
1110	Drg 73166242 Assembly of 4 Speed Gearbox		73166242
1111	Avenger Estate in Test Chamber	Avenger	
1112	Avenger Estate in Test Chamber	Avenger	
1113	Drivers Seat with Skelton Dummy		
1114	Diagram Avenger Estate LHD Int Mirror 10m		
1115	Diagram Avenger Estate LHD Pass Ext Mirror 4m		
1116	2x Diagram Avenger Estate LHD Drivers Pass Ext Mirror 4m		
1117	C6 Diagram RHD Passenger Ext Mirror 6m		
1118	C6 RHD Diagram Passenger Ext Mirror 4m		
1119	C6 RHD Diagram Passenger Ext Mirror 4m		
1120	C6 RHD Diagram Passenger Ext Mirror 10m		
1121	C6 RHD Diagram Drivers Ext Mirror 10m		

1122	Mirror Diagram		
1123	Mirror Diagram		
1124	Mirror Diagram		
1125	Mirror Diagram		
1126	Mirror Diagram		
1127	Mirror Diagram		
1128	Mirror Diagram		
1129	Mirror Diagram		
1130	Mirror Diagram		
1131	Mirror Diagram		
1132	Lorry Plate in front Test	Lorry	
1134	Mirror Diagram		
1135	Mirror Diagram		
1136	Mirror Diagram		
1137	Mirror Diagram		
1138	Mirror Diagram		
1139	Mirror Diagram		
1140	Mirror Diagram		
1141	Mirror Diagram		
1142	Mirror Diagram		
1143	Mirror Diagram		
1144	Mirror Diagram		
1145	Mirror Diagram		
1146	Mirror Diagram		
1147	Mirror Diagram		
1148	Mirror Diagram		
1149	Car Interior Drivers Position		
1150	Car Body in Test Chamber		
1151	Car Body in Test Chamber		
1152	Mirror Diagram		
1153	Mirror Diagram		
1154	Mirror Diagram		
1155	Mirror Diagram		
1156	Mirror Diagram		
1157	Mirror Diagram		
1158	Mirror Diagram		
1159	Mirror Diagram		
1160	Mirror Diagram		
1161	Mirror Diagram		
1162	Mirror Diagram		
1163	Mirror Diagram		
1164	Damage Empty Package		
1165	Graph Pass Side 7m		
1166	Graph Driver Side 10m		
1167	Graph Driver Side 10m		
1168	4 35mm Negatives of Robin Eyre Maunsell Imp	Imp Comp.	LWK 700F
1169	Graph Pass. Side Ext Mirror 4m		27/02/1979

1170	Graph Pass. Side Ext Mirror 6m			27/02/1979
1171	Graph Driver Side Ext Mirror 7m			27/02/1979
1172	Graph Drivers Side Ext Mirror 6m			27/02/1979
1173	Graph Int Mirror LHD 4m			
1174	Graph Int Mirror LHD 6m			
1175	Graph Int Mirror LHD 4m			
1176	Graph Int Mirror LHD 6m			
1177	Mirror Diagram			
1178	Mirror Diagram			
1179	Mirror Diagram			
1180	8 35mm Negatives Mainly Car Interiors			
1181	/1Mirror Diagram			
1181	/2 Mirror Diagram			
1181	/3 Mirror Diagram			
1181	/4/Mirror Diagram			
1182	7 35mm Negatives Peugeot 309 Saloon			
1183	10 35mm Negatives Peugeot 309 Saloon			
1184	7 35mm Negatives Peugeot 309 Saloon			
100	Californian G37 Crash Test (JHP 492E)		Imp Californian	
	Following have D prefix			
1	6 Arrow Type Cars inside Building		Arrow	
2	Car Dash and Steering Position			
3	Chart "E - Car Master Timing Schedule"			
4	Chart "B - Estate Car Timing"			
5	Diagrams "'B' Load Floor Lengths"			
6	"B Estate Car and Competitors-Tailgate Opening Width"			
7	"B Estate Car and Competitors-Rear Aperature Height"			
8	"B E/C Styling Programme"			
9	"Estate Car Comparative Load Floor Lengths"			
10	Chart "E - Car Master Timing Schedule"			2 Negatives
11	Family Tree Type Diagram			
12	"1800cc Engine Master Timing Schedule" H series			
13	"'B' Estate Car and Competitors Prices			2 Negatives
14	"Rapid TransitExperimental (RTX) Coach"		Coach	

15	Futuristic Lorry	Lorry
16	List/Table	
17	"'C' Premium Features Over Highline"	
18	"'C' Highline V6 Features Over Medium"	
19	"'C' Medium Versus Victor 2000 Features"	
20	"'C' Medium Features Over Lowline"	
21	"Premium Additional Specification-Alternatives"	
22	"'C' Lowline Versus Victor 1600 Features"	
23	"'C' Versus Rover 2000 Features"	
24	"'C' Range Kerb Weights and Drag Factor"	
25	"'C' Car Volume Forecasts"	
26	35mm Slide of "'C' Car Options Domestic"	
27	"Large Car Market Prices"	
28	"C Car Master Timing Plan"	
29	"'C' Derivatives Cost Status"	
30	"'C' Highline V6 Versus Corsair 2000E Features"	
31	'C' Lowline Prime Cost Status	
32	"E Car Volumes Domestic"	
33	"E Car Investment"	
34	"E Car Volumes Domestic"	
35	"Recent Decisions Incurring costs"	
36	"C Car Range Name Alternatives"	
37	"Prime Costs to US Eastern Seaboard"	
38	"E Car (Small) v 'B'"	
39	"E Car Prime Cost v B Car"	
40	"'E Car Volumes Export"	
41	"E Car (Large) Price v 'B' and 'C' Cars"	
42	E Car Volumes Export"	
43	"C Car Project Summary"	
44	"E Powertrain Interchangeability pattern"	
45	"E Car Long Range Plan Assumptions"	
46	"E Car Decisions Required"	
47	"E Car Body Panel Alternatives"	
48	"E Car Parameters v 'B' and 'C'"	
49	"E Car Volumes"	

50	"E Car Cost and Price"		2 Negatives
51	Schematic Car E3		
52	Schematic Car E4		
53	Schematic Car E4a		
54	Schematic Car E4b		
55	Schematic Car E5		
56	Schematic Car Ea and b		
57	"E Car Investment Long Range"		
58	"C CarMaster Timing Plan"		
59	"C Car Project Summary"		
60	"C Highline V6 v Corsair 2000E Features"		
61	C Premium v Rover 2000 Features		
62	Large Car Market Prices		
63	C Medium Features over Lowline		
64	C Highline V6 Features Over-Medium		
65	C Medium v Victor 2000 Features		
66	C Premium Features Over Highline		
67	Decisions and Investigations Adversely Affecting Programme		
68	C Car Options Domestic		
69	C Car Options Export Built-up		
70	C Range Kerb Weights		
71	C Outstanding Styling Programme		2 Negatives
72	C Lowline Car Prime Costs		
73	Press Cutting Renault 12/16 Photo		
74	Press Cutting Renault 12/16 Photo		
75	Press Cutting Renault 12/16 Dash		
76	G Series Model Chart		
77	Press Cutting The Time Share Indices		
78	Press Cutting Market Reports (Rootes)		
79	Rear View Arrow Sunbeam	Arrow	JKV 287E
80	Rear View Arrow Sunbeam	Arrow	JKV 287E
81	Track Photo of Lancia	?	
82	Track Photo of Mini	Mini	
83	Track Photo of Porche	Porche	
84	Track Photo of Mini	Mini	
85	Track Photo of Car	?	
86	Track Photo of Cortina	Cortina	
87	Track Photo of Saab	Saab	
88	Track Photo of Lancia	Lancia	
89	Track Of Lotus Cortina	Cortina	
90	Track Photo of Lancia	Lancia	
91	Track Photo of Car	?	
92	Track Photo of Cortina	Cortina	

93	Track Photo of Lancia	Lancia
94	Forward Project Plan Summary Trucks	Trucks
95	Forward Project Plan Summary Car 69 to 79	Car
96	Rootes Series Model Chart	
97	Arrow Long Range Plan	Arrow
98	Rear Door Dimensions	
99	B Estate Load Floor Length	
100	NAS 1970 Facelift Proposals	
101	NAS 1970 Facelift Proposals	
102	NAS 1970 Facelift Proposals	
103	NAS 1970 Federal Requirements	
104	NAS 1970 Facelift Proposals	
105	NAS 1970 Facelift Proposals	
106	NAS 1970 Facelift Proposals	
107	B E/C Styling Programme	
108	B Estate Car and Competitors Rear Aperature Height	
109	Estate Car Comparitive Load Floor Lengths	
110	B Estate Car and Competitors Tailgate Opening Width	
111	Total Cost Effect of Facelift Proposals	
112	Total Cost Effect of Face Proposals	
113	E Car Preprogramme Timing	
114	3D Barchart?	
115	NAS 1970 Proposals	
116	1800cc Engine Master Timing Plan	
117	NAS 1970 Facelift Proposals	
118	B Estate Car and Competitors Prices	
119	B Estate Car Derivative Lineup	
120	Schematic Tailgate Dimensions	
121	Card Marked No Negatives Slides Only	
122	B Estate Car and Competitors Prices	
123	Market Segmentation Chart (Europe)	
124	Forward Product Plan Summary - Car	
125	Forward Product Plan Summary - Car	
126	Major Unit Commonality Chart	
127	Body Unit Commonality Chart	
128	Decision Alternatives	

129	Decision Alternatives		
130	NAS 1970 Facelift Proposals		
131	Total Cost Effect of Facelift Proposal		
132	NAS 1970 Facelift Proposals		
133	NAS 1970 Timing		
134	NAS Federal Requirements		
135	Estate Car Comparative Capacities		
136	B Estate Car and Competitor Prices		
137	B Estate Car and Competitor Prices		
138	B E/C Model Line Differentials		
139	B E/C (Built Up) Model Mix		
140	B eE/C Volumes J Series 1972/73		
141	B E/C Differential Prime Cost Prices		
142	Estate Comparative Load Volumes		
143	B E/C Styling Programme		
144	Estate Car Comparative Load Floor Lengths		
145	B Estate Car Master Timing Plan		
146	Photo of Central Console		
147	Labels?		
148	Forward Summary Plan Trucks		
149	Proposed European Truck Ride and Drive in Belgium		Europe Map
150	Proposed European Truck Ride and Drive in Belgium		Europe Map
151	Continuation of Europe Map Eastwards		Map
152	Project Plan Summary - Passenger Cars		
153	Project Plan Summary - Trucks		
154	Product Plan Summary - Passenger Cars		
155	Product Plan Summary - Trucks		
156	Advanced Product Influence Diagram		
157	Product Plan Summary - Trucks		
158	Routes and Competition	Feb-69	
159	Forward Product Plan Summary - Car(Alternative)		
160	Product Plan Summary - Truck		
161	Product Plan Summary - Truck		
162	Product Plan Summary - Truck		
163	Product Plan Summary - Truck		
164	Volume and Penetration		
165	Investment Alternative		

166	Market Segmentation Chart (Europe)		
167	Market Segmentation Chart (Europe)		
168	Market Segmentation Chart (Europe)		
169	Market Segmentation Chart (Europe)		
170	Market Segmentation Chart (Europe)		
171	Rootes Long Range Plan Alternatives		
172	Market Segmentation Chart		
173	Rootes Market Coverage		
174	Rootes and Competition E Car		
175	Rootes and Competition 'E' Car	Feb-69	
176	Rootes and Competition 'B' Minus	Feb-69	
177	Rootes and Competition 'B' Car	Feb-69	Avenger
178	Unit Commonality Objectives 'B' Car	Feb-69	Avenger
179	Rootes Competitions 'C' Car	Feb-69	Chrysler 180/2.0Lt
180	Rootes Competitions 'D' Car	Feb-69	
181	Body Unit Commonality	Feb-69	
182	Forward Product Planning	24/01/1969	
183	Volume and Penetration	Feb-69	
184	Forward Product Planning		
185	Volume and Penetration	Feb-69	
186	Forward Product Planning	Feb-69	
187	Volume and Penetration	Feb-69	
188	Forward Product Planning Summary	Feb-69	
189	Volume and Penetration, Domestic and Export	Feb-69	
190	Forward Product Plan	Feb-69	
191	Volume and Penetration	Feb-69	
192	Forward Product Plan	Feb-69	
193	1250cc 'B' Car vs Viva		Avenger
194	B' Range, Mechanical Features up to 1800cc		Salisbury Axle
195	B' car vs Cortina 1600cc		Avenger vs Cortina
197	B' Car Production Objectives	Feb-69	Avenger
198	B' Car and Competitions		
199	B' Car Derivative Line-up		Avenger
200	B Low Line vs Minx Low Line Performance		Avenger (B) 88mph 17 secs

200	B Car Vv Minx/Hunter Performance		Minx 83mph 18.2 secs
201	B Low Line vs Minx Low Line General Data		Avenger vs Minx
202	B Low Line vs Minx Low Line Interior		Avenger vs Minx
203	B Car 1250cc vs 4dr Viva SL		Avenger vs Viva
204	B Car Body and Hardware		Avenger
205	Avenger 1250 Lowline vs Escort 1100		Avenger
206	Forward Product Plan	Up to 1976	
207	Forward Product	Feb-69	
208	Market Generation Chart	1972-1973	
209	Market Segmentation Chart (Europe)		
210	M Series Volume + Market Penetration	April-69 and Feb-69	
211	Schematic Side Elevation of Chassis (Low)		
212	High Volume Saloons. C.C. against year	1969-1972	
213	Literature		
214	Car Tuning Summary		
216	City Centre MP A Car + InterCity Family Car		
217	I.C. Imp. BEA Badge. Drawn by "Steicns", Mini MPV		Imp
218	B Car Timing Summary	Apr-69	Avenger
220	C Car Major Changes in Specifications		Chrysler 180/2.0Lt
221	C Car Range Kerb Weight	Apr-69	Chrysler 180/2.0Lt
222	C Car Timing Summary	Apr-69	Chrysler 180/2.0Lt
223	B Car Prime Cost status	Apr-69	Avenger
224	C Car Volume Forecourt	Apr-69	Chrysler 180/2.0Lt
225	C Car Prime Cost inc. Contingency	1968 and 1969, 2off	Chrysler 180/2.0Lt
226	C Range Kerb	Apr-69	Chrysler 180/2.0Lt
227	B Car Timing Summary Pre Launch	Apr-69	Avenger
228	C Car Timing Summary Pre Launch	Apr-69	Chrysler 180/2.0Lt
229	B Car Prim Cost Status	Apr-69	Avenger
230	B Car Total Volume Charge		Avenger
231	Dodge 500 30 ton Tractor - Volume Forecast Intro	05/01/1970	Dodge 500

232	Dodge 500 30 ton Tractor - Financial Data	Apr-69	Dodge 500	
233	Dodge 500 30 ton Tractor - Competitors	Apr-69	Dodge 500	
234	Dodge 300 30 ton Tractor	c 1970	Dodge 500	
235	C Body in White Critical Items	c 1970	Chrysler 180/2.0Lt	
236	C Lowline Prime Cost Status	Apr-69	Chrysler 180/2.0Lt	
237	B - Car, Volume Change	1969 - 05/69	Avenger	
238	Barreiros and Rootes Long Range Plan 3	up to 1980		
239	Commercial Sales Record	Early 1970 to 1980		
240	Product Decision Planning	c 1970		
241	Product Asumptions Plan 2			
242	Product Asumptions Plan 3			
243	Product Asumptions Plan 1			
244	B Car Timing Summary			
245	C Car Volume Forecasts			
246	Forward Product Plan Summary - Cars Alternative			
247	Forward Product Plan Summary - Trucks Alternative 2			
248	Forward Product Plan Summary - Trucks Alternative 3			
249	Forward Product Plan Summary - Cars			5 Negatives
250	E Car Forward Timing Draft			
251	Product Planning Open Building			
252	Chrysler Europe Timing Schedule			
253	Chrysler Europe Timing Schedule			
254	Chrysler Europe Timing Schedule			
256	Barreiros and Rootes Long Range Plan Alternative 2	May-69		2 Negatives
257	Option Code Index G Series			
258	Programme Timing			2 Negatives
259	Photo Religious Picture?			
260	Photo Religious Picture?			
261	Drawing of Simca 937 (derived from Simca 1000)		Simca 937	
262	Total Volume and Domenistic Penetration Graph			2 Negatives
263	Barreiros and Rootes Long Range Plan Alternative 2			2 Negatives
264	CV Product Decision Pattern			2 Negatives
265	Photo Lorry Cab		Dodge	
266	Forward Project Plan Summary - Truck			2 Negatives

267	Forward Product Plan Summary - Car		2 Negatives
268	Chrysler Europe Car Make and Model List	13-May-69	
269	Ideal World Product Plan		
270	Projection of European Truck Sales Trend		2 Negatives
271	Domestic PenetrationBy Big Ten		2 Negatives
272	Domestic PenetrationBy Big Ten		2 Negatives
273	European Truck Market		2 Negatives
274	European BU and KD Tariff Barriers Map		Map
275	European Source CO Ability Truck Requirements		2 Negatives
276	European Truck Market E Series		
277	Four Major European Truck Source Countries		2 Negatives
278	Chrysler European Trucks Production Requirements		2 Negatives
279	Chrysler Sales Projection in European Truck Market		2 Negatives
280	European Truck Market Chrysler Penetration		2 Negatives
281	Recommendations		2 Negatives
282	Commercial Vehicle Strategy Story		3 Negatives
283	Chart?		2 Negatives
284	Chart?		2 Negatives
285	Chart?		3 Negatives
286	Commercial Vehicle Strategy Story		2 Negatives
287	Rootes Commercial Vehicles		2 Negatives
288	Commercial Vehicle Strategy Story		2 Negatives
289	Commercial Vehicle Strategy Story		2 Negatives
290	Commercial Vehicle strategy Story		2 Negatives
291	Commercial Vehicle strategy Story		2 Negatives
292	Commercial Vehicle strategy Story		2 Negatives
293	Commercial Vehicle strategy Story		2 Negatives
294	Commercial Vehicle strategy Story		2 Negatives
295	Map European Truck Market		
296	Tractor Cross Margin		
297	Heavy ?		
298	Light/Medium Contribution		
299	Heavy Truck Crodd Margin		
300	B Vehicle Saloon Car Range		
301	Price Comparision Hillman Ford Austin		
302	Principle Dimensions Light Van Models		

303	Principle Dimensions ??? Van Models		
304	Forward Product Plan Summary Car		2 Negatives
305	Forward Product Plan Summary Truck		2 Negatives
306	Colour Slides Presentation by G.Kleman		Missing
307	Colour Slides Presentation by G.Kleman		Missing
308	Colour Slides Presentation by G.Kleman		Missing
310	Colour Slides Presentation by G.Kleman		Missing
311	Colour Slides Presentation by G.Kleman		Missing
313	Colour Slides Presentation by G.Kleman		Missing
314	Colour Slides Presentation by G.Kleman		Missing
315	Colour Slides Presentation by G.Kleman		Missing
316	Colour Slides Presentation by G.Kleman		Missing
317	Used for Slide		Missing
318	Used for Slide		Missing
319	Photo Detail Of Engine Area Injectors?		
320	Photo Detail Of Engine Area Pipes?		
321	Chart Working Product Plan Summary Trucks		
322	Forward Product Plan Summary Car		
323	Forward Product Plan Summary Trucks		
324	Marker Segmentation Chart		
325	Price and Var. Profit Comparision		
326	R429 Price Variable Profit and Investment		
327	Implications of V6 Engine in Arrow and Rapier	Arrow/Rapier	
328	Announcement Pattern		
329	R429 Timing	R429	
330	Major Changes to Install 1725cc in JR429	JR429	
331	Key Dates		
332	Price Proposals G Series		
333	Coupe Price Coverage		

334	Major Changes to Install 2500cc in JR429	JR429	
335	Rootes Sales/Target Sheet?		
336	Rootes Sales/Target Sheet?		2 Negatives
337	Rootes Sales/Target Sheet ?		2 Negatives
338	Rootes Sales/Target Sheet ?		2 Negatives
339	??? Link Figures?		3 Negatives
340	Promise and Actual Dates		
341	Ventora Badge Behind Front Wheel Bodywork	Ventora	
342	Detail Bodywork in front of Rear Wheel	?	
343	Detail inc Wheel		Water Damage
344	Ventora Badge Behind Front Wheel Bodywork	Ventora	
345	Sunbeam Alpine Specification Content	Sunbeam Alpine	
346	Hillman Imp Saloon Product Concept	Imp Saloon	
347	Sunbeam Alpine Price Comparisons	Sunbeam Alpine	
348	Hillman Imp Price Comparisons	Imp	
349	Hillman GT Price Comparisons	Hillman GT	
350	Hillman GT Specification Content	Hillman GT	
351	Hillman GT Product Concept	Hillman GT	
352	Hillman GT Performance	Hillman GT	
353	Sunbeam Alpine Performance Comparison	Sunbeam Alpine	
354	Hillman Imp Saloon Lowest Priced 4 Seater British Family Saloon	Imp Saloon	
355	Hillman Imp Saloon Profitabilty	Imp Saloon	
356	Sunbeam Alpine "GT Style and Concept at Low Price"	Sunbeam Alpine	
357	Hillman GT "High Performance Low Cost 4 Door Saloon"	Hillman GT	
358	Ideal World Product Plan		
359	Analysis of Alternatives		
360	Arrow Rootes	Arrow	
361	R429 Rapier Rootes	Rapier	
362	Vehicle Weight Estimates lbs		
363	Major Savings Under Consideration		
364	Prime Cost Movement Base Model		
365	Major Specification Changes April-August 1969		1969
366	Anticipated Additional Cost Penalties not yet Detailed		

367	Prime Cost Movement Derivatives including Engineering Contingency		
368	Cost Savings Since Last Review		
369	Engine Performance		
370	Vehicle Performance		
371	JR541 Timing Summary		JR 541
372	Major Changes to Install 1725 TC in R429		R429
373	Major Changes to Install 1800/1800TC in R429		R429
374	Timing Comparisons		
375	Key Date Timing Rootes C Car Simca 949		Simca 949
376	R541 Rootes		
377	R429 Rapier Rootes		Rapier
378	R429 Rapier Rootes		Rapier
379	Sales Volume Forecasts		
385	Long Range Plans Key Dates		
386	Rootes?		
387	Rootes Arrow		Arrow
388	Rootes C		
389	Straight Line Chart?		
390	R541 Long Range Car v ?????		
391	Feature Comparison ??? V ???		
392	Comparison B and C Gearboxes		
393	Comparison B and C Axles		
394	New Medium Saloon Timing		
395	Arrow 4 Door Saloon Timing		
396	1800 B Derived Engine Timing		
397	1725 in B Unique Coupe Timing	Aug 69-Oct 72	
398	Arrow 2 Door Coupe Timing	Aug 69-Oct 70	
399	B / C riveline Capacity Increase Timing	Aug 69-May72	
400	B543? Long Range Plan v Product Engineering Recommendations		
401	JR541 prices v B and C Cars Timing Summary		
402	Major Changes to Install 1800/1800TC in R429		
403	B541 Product Assumptions		
404	Feature Comparisons 1725AL SC v 1800 SC Engineal sc		
405	Vehicle Weight Comparison LBS		
406	Prime Cost Movement Base Model		
407	Manufacturing Project	Aug-69	
408	Prime Cost Movement Derivatives		
409	Rootes C Car Simca 949 key Date Timing	Dec 69-Mar 71	Simca

410	Timing Comparisons		
411	Anticipated Additional Cost Penalties not yet Detailed		
412	Cost Savings Since Last Review		
413	Long Range Plans Key Dates		
414	Variance Over Strategy Study By Model		
415	Variance Over Strategy Study By Model		
416	How Do We Measure Up?		
417	What Makes a Truck Saleable in this High Volume Market?		
418	What Type of Truck are we Designing?		
419	Who are We Competing with in these Market?		
420	Photo Lorry Cab Tilted	Lorry	2 Negatives
421	Photo Lorry Cab Nearside	Lorry	2 Negatives
422	Photo of Lorry Cab	Lorry	2 Negatives
423	Photo Of Lorry Cab Tilted	Lorry	2 Negatives
424	Photo of Lorry Nearside	Lorry	
424	A Photo of Lorry Nearside	Lorry	
425	Photo of Lorry Cab	Lorry	
426	Photo od Lorry Front	Lorry	
427	Diagramme of Lorry Cab Dimension Codes		VGX 317G
428	Photo Details Panel/Pressing		
429	Photo Details Panel/Pressing		
432	Competitive Wheel Base Lineup		
434	Competitive Action		
435	Competitive Wheel Base Lineup		
436	Major Options		
439	Body Payload Factors as / of GVW		
440	8 HP/Ton Optional Engine (Where Available)		
441	CV Segment Market Size		
443	8HP/Ton Standard Engine		
444	Postioning of Payloads v Competition		
445	Diesel Engine Offered Rootes 100 Series v Competition		
446	G.V.W. Ranges of Rootes v Competition		
447	Timing	Oct 69 - Aug 72	4 Negatives
448	Variable Costs		
449	100 Series Cab v Competition Medium Truck		2 Negatives

450	100 Series Cab v Competition Light Truck			
451	Forward Product Plan Summary			3 Negatives
453	Broad Indication of Rootes Car Sales By Volume			
454	Broad Indication of Rootes Car Sales By Value			
455	Sketch Of 1950s Car Steaming Radiator			
456	Sketch Of 1950s Car Swag in Boot			2 Negatives
457	Outline Sketches of 3 Cars Superimposed			
459	Objectives of AD HOC Group	Sep-69		
460	Presentation of Rootes Models Must Pass	Sep-69		
461	Summary of Product Programme Decision and Development System	Sep-69		
462	Long Range Product Plan Decision	Sep-69		
463	Activity Analysis of Product Alternatives	Sep-69		
464	Product study Decision	Sep-69		
466	Programme Approval Decision	Sep-69		2 Negatives
467	Activity Programme Implementation	Sep-69		
468	Company Timing Plan Index			
469	Recommendation			
470	Photo Lorry Front BMC Cunard Line		BMC Lorry	NVP 462G
471	2 Photos Lorry Front BMC Water Splash		BMC Lorry	
472	Photo Lorry Front Quarter BMC Lorry		BMC Lorry	
473	Photo Lorry BMC "Keep in Low Gear"		BMC Lorry	
474	Photo Lorry BMC		BMC Lorry	SRW 107H
475	Photo BMC Lorry from Front Near-side Quarter		BMC Lorry	SRW 104H
476	Photo BMC Lorry Nearside		BMC Lorry	
477	Photo Lorry Nearside			
478	Photo BMC Lorry Front		BMC Lorry	SRW 104H
479	Photo BMC Lorry Laird		BMC Lorry	SRW 107H
480	Forward Product Plan Summary - Car	1970-1974	Imp and Arrow	
481	B Reskin Model Lineup - Current Prices			
482	R429 Prices versus Competition			
483	Proposed B Reskin Panel Formula Saloons			

484	Key Date Timing B Car Programme			
485	R 429 Programmje Parameters	Oct-69		
486	HR 4 29B Unique Skin Coupe Summary Timing			
487	H 429 Initial Financial Release			
488	Import Registration Growth 62/63 - 68/69			
489	Arrow B and C Dimension and Price H Series			
490	Arrow 2 Door/R429 Prices (US Dollar)		Arrow Alpine	Rapier
491	J Series Market Segmentation Chart Domestic			
501	Why Cummins			
502	Tractors		Tractors	
503	Power/Weight Requirements			
504	Technical Details		Cummins Perkins	-
505	Total Range Profitabilty			
506	Technical Details Cummins Engine		Cummins	
507	An Alternative Engine Supply			
511	100 Series Initial Financial Release			
512	C.V.Market Size Total Market			
513	Rootes cv C.V.Total Export Volume			
514	Commercial Vehicle Strategy Study			
515	Capital Requirements	Oct-69		
517	Forward Product Plan Summary Trucks			
518	100 Series Cab v Competition Light Truck			
519	100 Series Cab v Competition Medium Truck			
521	Rootes C.V. Market Segment Shares 4-12 12+(Commer)		Commer	
522	Positioning of Payload v Competition			Damp Damage
523	Payload Factors			
524	Truck Ranges			
525	Construction and Use Regulations			
526	Financial Comparisions Rperiod 1970/1975	1970/1975		
534	New Model Planning Export Sept 1969	Sep-69		2 Negatives
535	100 Series Profitbility	Oct-69		
536	100 Series Programme Timing for Medium Duty Truck 103			
537	Arrow B and C Dimension and Price H Series			

538	J Series Market Segmentation Chart Domestic			
542	Photo Peugeot 504 Berline		Peugeot 504	
543	Photo Peugeot 304 Berline		Peugeot 304	
544	Photo Peugeot 304 Berline		Peugeot 304	
545	Photo Fiat 124		Fiat 124	
546	Photo Fiat 124 Sport Coupe		Fiat 124	
547	Photo Peugeot 204 Berline Grand Luxe	1970	Peugeot 204	
548	Photo Fiat 125		Fiat 125	
549	100 Series Profitability			
550	An AD HOC Group of Affected Functional Directors	Sep-69		2 Negatives
551	Recommendations That the Rootes Administrative Committee	Sep-69		2 Negatives
552	Company Timing Plan Index	Sep-69		2 Negatives
553	Objectives of AD HOC Group	Sep-69		2 Negatives
554	List of Essential Stages New Model Panning	Sep-69		2 Negatives
555	Chrysler Europe Timing Schedule			2 Negatives
556	Chrysler Europe Timing Schedule			2 Negatives
558	Import Registration Growth 62/63 - 68/69			2 Negatives
559	Proposed B Reskin Panel Formula Saloons			
562	Capital Requirements			
563	100 Series Profitability			
564	Rootes Commercial Vehicles			
565	Total Volume Profitabilty			
566	Commercial Vehicle Stategy Study			
567	100 Series Programme			
568	100 Series Programme Capital Expenditure			2 Negatives
570	Rootes C.V. Market Share Domestic			2 Negatives
571	R 429 Prices v Competition			
572	B Reskin Variable Cost Relationships to B and C			
576	B Reskin Saloons Size and Specification Lineup			
577	U.K.Van Market Growth			
578	European Compact Van Market - 1967	1967		
579	Compact Van Sales 1967	1967		
580	Br H Series Introduction+ Volume Incremental Substitution			
581	B Car H Series Introduction			
582	B Reskin			
583	Arrow 4 Door MID G - H		Arrow	

584	Delay E car to Job One J			
585	Imp H and J		Imp	
586	Expenditure F thru J Codes 1 and 2			
587	ARROW 2 Door H		Arrow	
588	Base Capital Plan f to J eries			2 Negatives
589	Chrysler Europe Rootes Truck Program			2 Negatives
590	Chrysler Europe Rootes Truck Program			2 Negatives
591	Chrysler Europe Passenger Car Product Proposal		K Series	2 Negatives
592	Chrysler Europe Passenger Car Product Proposal		F and J Series	2 Negatives
593	Chrysler Europe Rootes Truck Program Profit Forecast			2 Negatives
594	Chrysler Europe Barreiros Truck Program			
595	Chrysler Eorope Passenger Car Product Proposals		F to J Series	
596	H - Series 910 Extension		H Series	Positive
597	Major Product Developments		G H J K M Series	Positive
598	K Series Investment			Positive
599	Simca Growth Plan			Positive
600	Simca Product Evolution	Oct-69		Positive
601	International Product Planning Committee Proposal	14-Oct-69		Positive
602	K Series Proposals		K - Series	Positive
603	K Series Financial Implications		K - Series	Positive
604	Guidelines and Objectives			Positive
605	Simca Market Growth			Positive
606	Competitive Developments			Positive
607	EEC Market Growth			Positive
608	Simca Product Evolution Novenber 1969	1969-1976		
612	Photo Lorry Offside		Lorry	
613	Car Outline Swag in Boot Universal Outline Specification Losses			2 Negatives
614	Product Specification and Options Vlume and Profit 3 Cars Outlines			2 Negatives
615	Rootes Car Sales F thru l by Volume			2 Negatives
616	UK Specification = Export Flop Car Outline			2 Negative
617	Forward Project Plan Summary Car			
618	Forward Project Plan Summary Car			2 Negatives
619	Rootes Car Sales F thru l by Volume	Sep-69		
620	Graph 100 Series Major Sheet Metal			
621	Graph 100 Series Major Sheet Metal			

622	Graph 103 Range			
623	Graph 103 Range			
624	Graph 103 Range			
625	Graph 103 Range			
626	Graph 103 Range			
627	Graph 103 Range			
628	Graph 103 Range			
629	Graph 103 Range			
630	Graph 103 Range			
631	List of Names and Addresses			
632	C Car Prices UK Basic Retail			
633	Additional Specification Item			
634	Large Car Market Prices UK Basic Retail			
635	Arrow 4 Door Models for F and G Series			F and G Series Arrow
636	Arrow 4 Door Models for F and G Series	Nov-69		F and G Series Arrow
637	Arrow 4 Door Models and Price Lineup for F and G Series	Nov-69		F and G Series Arrow
638	Arrow 2 Door Coupe for G Series	Nov-69		Arrow Coupe
639	Colour Keying Major Items	Nov-69		
640	Exterior Trim Changes Parier Only	Nov-69		Rapier
641	Holbay Performance Package			Hillman GT Alpine Rapier
642	N.A.S Requirements			
643	Arrow 2 Door Coupe for G Series Domestic Timing			
644	Arrow 2 Door Coupe for G Series N.A.S. Timing			
645	Recommended Actions	Nov-69		
646	Timing N.A.S. B Car			
647	Forward Product Plan Summary Truck			
648	Forward Product Plan - Truck			
649	Arrow 2 Door Coupe Sales Forecasts	Nov-69		
650	Photo 2 Door Saloon VIVA HC			Viva HC
651	Grainy Photo of 2 Door Saloon Renault 9?			Renault 9?
652	Forward Product Plan - Truck			
653	3 Photos Of Pickup, Station Wagon, Forward Control Van			
654	List of Names and Addresses			
655	Slide B Lowline v Minx Lowline General Data			Minx
655	to 661 Duplicates of D655 to 661 on one sheet			
656	B Car Body and Hardware Features			Negative

657	B 1250cc Medium Line v 4 Door Viva SL 1150 cc Comparision		Viva	
658	B 1250cc Medium Line v Escort 1300 cc Super Comparision		Escort	
659	B Lowline v Minx Lowline Interior Package		Minx	
660	B Lowline v Minx Lowline General Data		Minx	
661	B Car Product Objectives			
662	Anticipated Additional Cost Penalties not yet Detailed			
663	B Car Domestic Costs			
664	B Car Domestic Costs			
665	B Car Vehicles Weight Estimates LBS			
666	B Car Additional Cost Savings under Consideration			
667	B Car Additional Cost Savings under Consideration			
668	Major Cost Changes ( Prime Cost )			
669	Major Cost Changes ( Prime Cost )			
673	Manufactures Participation By Segment	1973/74		
674	B Plus B Reskin Exterior Dimension Comparison			
676	B Reskin Plus Saloon Size and Specification Lineup			
677	B Reskin B Plus Variable Cost Relationship to B and C			
678	B Reskin B Plus Panel Formula Orginal Plan			
679	B Reskin B Plus Panel Formula (Saloons) Current Status			1500-1250 Engines
680	B Reskin B Plus Panel Formula Saloons Current Status			1725 Engine
683	B Plus B Re-Skin Formula Estates Current Status			
684	B Reskin B Plus Model Limeup Prices			
685	B Plus B Reskin Engine Range Comparision			
686	Planned Weekly Capacities J Series			
687	To Small to Read ?			
688	To Small to Read ?			
689	PPC meeting Structure U.K.Market 1 Color Slide J McDonald	06/01/1970		Note
690	Tradesman 108 Wheelbase Van		Dodge A100	
691	Dodge Job Mated Tradesman Vans		Dodge A100	

692	Dodge Tradesman Vision Van	Dodge A100	
693	Rootes B Vehicle Presentation Utilisation Chart B		
694	Section Drawing Thru B Rear Axle		
695	3 Alternative Dashboard Layouts		
696	Photo of Dash in Lorry Cab	Lorry?	
697	Photo of Drivers position in Lorry Cab	Lorry?	
698	Photo of Dash in Lorry Cab	Lorry?	
699	Photo of Lorry Can Nearside Door Open	Lorry?	
700	Photo of Drivers position in Lorry Cab	Lorry?	
701	Photo of Dodge Van Frint	Vision Van?	
702	Photo of Dodge Vision Van Front Offside Quarter	Vision Van?	
703	Photo Of Dodge Vision Drivers Position	Vision Van?	
704	Structure of the UK Market		Water Damage
705	4 Profile Car Shapes-Saloon Coupe Estate		Water Damage
706	Outline 4 Door Passenger Compartment People Outlines		
707	Many Blue Chrysler Pentagons		
708	Press Cutting of Holden Torana Australias	Torana	
709	Profitability Statementon P.B. Minor Facelift		
710	Timing Schedule for Facelift		
711	Investment Costs for P.B. Minor Facelift		
712	Volume Data P.B. Minor Facelift		
713	Option Prices for Deluxe Cabs on Van Ranges		
714	/8A Photo of (Avenger) Car from another	Avenger?	2 Negatives
714	2x35mm Photo of Avenger? From another Car.		Package Damaged
715	Photo Van Cab Drivers Position	Bedford?	
716	Photo Van Cab Drivers Position	Bedford?	
717	Photo Van Cab Drivers Position	Bedford?	
719	Photo Van Cab Drivers Position	Bedford?	
720	Photo of Van Front side nearside Quarter	Bedford?	
721	Comparision of Design Differences		2 Negatives
722	Comparision of Design Differences		2 Negatives

723	1970 U.K.Domestic Market Light Car Segment Sedan Prices			2 Negatives
724	New Product Programme by Major U.K. Manufactures			2 Negatives
725	!970 U.K.Domestic Market Smal Car Segment Sedan Prices			2 Negatives
726	Comparision of Design Differences		Imp-Arrow-Avenger	2 Negatives
727	Structure of uk Market			4 Negatives
728	Rootes Passenger Car Engines			2 Negatives
729	Site Boundary Map (Linwood Plant)			
730	Site Boundary Map (Linwood Plant) with added Buildings?			
731	UK Market by Segment 1965-1975	1965-1975		2 Negatives
732	Side View Outline with Power Chain B Car			
733	100 Series Abridge Profile Issue 10	27/07/1970		
734	Timing Schdule for Minor Facelift	Jan/Feb 1970		
735	P B Van Range Minor Facelift (Title Slide)			
736	Production Releases			
737	100 Series Timing	Mar-70		
738	Option Prices for Deluxe Cabs on Van Ranges			
739	Investment Costs for P.B. Minor Facelift			
740	Walk Thru Programme Review (Title Slide)			
741	Reason for Keeping the Walk Thru			
742	Accounte Loss Walk-Thru Range	1965-1974		
743	Price Increases Effective from 1 Jan 1970 Walk Thru Range		Model K30	
744	Price Increases Effective from 1 Jan 1970 Walk Thru Range		Model KC 40	
745	Financial Effect of Walk-Thru Deletion			
746	Programme Approval Package April 1968 Notes 1 to 6	Apr-68		
747	Programme Approval Package April 1968 Notes 7 to 13	Apr-68		
748	Present Walk-Thru Improvement Package Notes 1 to 6			
749	Proposed New Items			
750	Indicative Volumes for Walk Thru Range			
751	Top Half Photo of 2 Door Saloon Ford Taunus?		Ford Taunus?	

752	Bottom Half Photo of 4 Door Saloon Avenger?	Avenger?	
753	Photo of 2 Door Saloon	?	BE 96096
754	Market Relationship of UK Competitive Entrants		
755	Diagram Avenger Interior and Exterior Width	Avenger	
756	Section Drawing Thro B Rear Axle		
757	B Car Objectives "More Car Than Competition"		
758	Outline Side view Comparision of Arrow and B Car Gearbox		
759	Outline Of B Car Rear suspension		
760	Side Outline with Drive Chain B Car		
761	Diagram of Cross Section of B Engine		
762	Comparision of B Model v Arrow Seating Package		
763	UK Car Market by Segment Early 1960's		
764	UK Car Market by Segment 11 Months 1969		
765	UK Car Market by Segment Mid 1960's		
766	Photo of Nearside of Hunter (Arrow)	Hunter	
767	Photo of 4 Door Saloon Avenger?	Avenger?	PVC 606H
768	Photo of 4 Door Saloon Rear 2 People	?	
769	"Kingfisher Blue" Photo of Series 5 Hillman Minx	Minx	
770	Photo of People around a Fullsize Car Model Design Workshop	?	
771	Photo of People Building above Model Design Workshop	?	
772	Photo of Ford 105E Anglia	Ford Anglia	
773	Photo of Vauxhall Viva	Vauxhall Viva	
774	Photo of 3 Dash layouts		
775	Photo of 4 Door Saloon 2 People	?	
776	Photo of 4 Door Saloon Grill Change	?	
777	Photo of 4 Door Saloon Avenger?	Avenger?	
778	Photo of Avenger production Line	Avenger	
779	Photo of Front Seating in Automatic Car Avenger?	Avenger ?	
780	Side View Diagram of Car W1 with Engine Block	?	

781	Side View Diagram of Car W3 with Engine Block and Drive		?	
782	Variable Costs Detail (Over)			
783	Kety Model Costs Vendor Tooling			
784	Key Model Cost Variable Cost			
785	100 Series Status Review 24-March 1970 (Title Slide)	24/03/1970		
786	100 Series Timing			
787	Barreiros E.H.D. Tractor		Tractor	
788	Investment Costs for P.B. Minor Facelift			
789	Profitability			
790	Capital Expenditure			
791	500 Series Deluxe Car			
792	Weight Variance 11.2 Ton Key Model 103 Range			
793	Items for Discussion			
794	Volume Loss Detail 104 Range			
795	Volume Loss Detail 103 Range			2 Negatives
796	Volume Loss Detail 102 Range			
797	Volumes 100 Series			
798	Timing 100 Series			
799	Photo of Coupe Front Offside View		?	2 Negatives
800	Photo of Coupe Offside View			2 Negatives
801	Photo Fullsize Model of Coupe Style Car Front			2 Negatives
802	Photo Fullsize Model of Coupe Style Car Rear			2 Negatives
803	Photo Fullsize Model of Coupe Style Car Nearside			2 Negatives
804	Photo Fullsize Model of Coupe Style Car Nearside Rear			3 Negatives
805	Photo Coupe Style Car Gallant		Gallant?	4 Negatives
806	Photo Coupe Style Car Gallant			4 Negatives
807	Major Unit Programme Front Axle Variable Costs			
808	Major Unit Programme Front Axle Reasons for Proposal			
809	Major Unit Programme Proposal			
810	Eaton Axles - Gearbox			
811	Major Unit Programme Current Drive Line Components			
812	Major Unit Programme Design and Development Cost			
813	Major Unit Programme Variable Costs Axles			
814	Variable Cost Assumptions			

815	Major Unit Programme Proposed Units G/Box - Axles	
816	Major Unit Programme Commer and Dodge Trucks	
817	Major Unit Programme Graph Indicative Cost Savings	
818	Major Unit Programme Variable Costs Gearboxes	
819	Major Unit Programme Rear Axle and Gearbox Investment	
820	Major Unit Programme Proposed Major Unit Lineup	
821	To small to read Presentation Slide?	
822	To small to read Presentation Slide?	
823	To small to read Presentation Slide?	
824	To small to read Presentation Slide?	
825	To small to read Presentation Slide?	
826	To small to read Presentation Slide?	
827	Rootes Motors Limitede plus Pentagon	1 Pos/1 Neg
828	Major Unit Programme Proposed D/L Units	
829	Major Unit Programme Proposal	
830	Major Unit Programme Current Drive Line Components	
831	Major Unit Programme Indicative Cost Savings	
832	Major Unit Programme Variable Cost	
833	Major Unit Programme Design and Development Cost	
834	Major Unit Programme Return-Rear Axle/Gearbox Return on Investment	
835	Major Unit Programme Return-Rear Axle/Gearbox Payback	
836	Major Unit Programme Volumes Proposed Unit Lineup	
837	Major UUnit Programme Front Axle Return on Investment	
838	Major Unit Programme Front Axle Payback	
839	Major Unit Programme Front Axle Investment	2 Negatives
840	Epicyclic Drive	
841	Range Change 8 Speed Gearbox Straight 8 Speed G/Box	2 Negatives

842	Advantages of Cummins V504 over V8 470		
843	Cummins V8 504 Investment		
844	Cummins V8 504 190 Volumes		
845	Variable Cost (Over)/Under V8 470		2 Negatives
846	Technical Detail Cummins Engines		2 Negatives
847	Product Study April 1970	Apr-70	
848	Cummins V 8 504 Average Annual Financial Effect		
849	List of Names and Addresses		
850	Block Diagram of Departments and Management		Damaged
851	Walk Thru Improvements Profitability Statement		
852	Walk Thru Improvements Investment Costs		
853	Walk Thru Improvements Timing Schedule		
854	Walk Thru Improvements Price Increases		
855	Walk Thru Improvements Programme Approval May 1970	May-70	2 negatives
856	Volumes Walk Thru Range Domestic		
857	Present Walk Thru Improvement Package		
858	Proposed New Items		
859	Sunbeam Arrow Badge"		Sunbeam Arrow
860	Plymouth Avenger Badge		Plymouth Avenger
861	Sunbeam Arrow Badge"		Sunbeam Arrow
862	Plymouth Badge		Plymouth
863	Photo of 6 Cars/Models Own and Competitors		Various
864	Photo of 6 Cars/Models Own and Competitors		Various
865	Cutting Autocar 7-5-1970 Ford Pinto GM XP887		Ford Pinto
866	Photo Toyota Corona Mark 2		Toyota Corona
867	Ford 15M (Foreign Magazine)		Ford 15M
868	Opel Coupe plus 2		Opel Coupe
869	Mercedes 4.5		Mercedes 4.5
870	VW/NSU K70		VW-NSU K70
871	Ford 12m-15M (Foreign Magazine)		Ford 12M-15M
872	Ford 12m-15M (Foreign Magazine)		Ford 12M-15M
873	Photo of Underside Engine Bay Car?		?

874	Photo of Underside Engine Bay Car?		?	
875	Photo of Underside of Rear Car?		?	
876	Photo of Nearside of Car? Doors Open		?	
877	Photo Boot of Renault 12		Renault 12	
878	Photo Engine Bay Renault 12?		Renault12?	
879	Models for Future Annouement		Various Competi- titors	
880	36 Own and Competitors Cars/Models Prices	May-70	Various	
881	11 Own and Competitors Cars/Models Specs-Dimensions		Various	Sht 1 of 2
882	11 Own and Competitors Cars/Models Specs-Technical		Various	Sht 2 of 2
883	11 Own and Competitors Cars/Models History Sales	1969	Various	
884	Chrysler B Car v Ford Europe			
885	Photo of Differential Area Lorry?		?	
886	Photo of Engine Rear Area Lorry?		?	
887	Photo of Silencer Underside of Lorry?		?	
888	Photo of Engine/Injectors of Lorry?		?	
889	Photo of Engine Top of Lorry?		?	
890	Photo of Gearbox end of Engine Lorry?		?	
891	Photo of Chassis fixing/Mounting Fitting Lorry?		?	
892	Photo of Rear Spring to Chassis fixing		?	
893	Photo of Detail Fitting? Lorry?		?	
894	Photo of Detail Fitting? Lorry?		?	
895	Photo of Hub (Front) Lorry?		?	
896	Photo of Hub (Front) Lorry?		?	
897	Photo of Cable Harness		?	
898	Photo of bare Lorry Chassis		Lorry?	
899	Photo of bare Lorry Chassis with Wheels		Lorry?	
900	Photo of Lorry? Engine			
901	Photo of Lorry Engine and under-slung Radiator		Lorry	
902	Photo Sidelights on Cab/Van			
903	Photo of Van Body Rear			
904	Photo of bare Lorry Chassis		Lorry	
905	Phot Triumph 1300 Saloon		Triumph 1300	GWK 879D
906	South African Spec			
907	Engine Applications			
908	Car Features			

909	Cab Weight and Simplicity 103 and 500 Series			
910	Timing Job No 1			
911	Competitive Weight Summary 100 Series Key Models			
912	Block Diagram of Departments and Management			
913	Action and Risk			
914	Weight Status			
915	Unit Variable Cosr Movement by Key Model			
916	Domestic Retail Price Movement Key Models			
917	Unit Variable Cost Movement Approved Changes			
918	Volume Change Casual Factors 1971	1971		
919	Volume Change by Range 1971	1971		
920	Timing Domestic			
921	Arrow Facelift Key Dates	July 1970- Oct 1971	Arrow	
922	Financial Summary 1971 - 4	1971-1974		
923	100 Series Staus and Financial Report No 2 June 1970	Jun-70		
924	Casual Factors			
925	Cost Variance Causal Factors Summary 1971 - 4	1971-1974		
926	South Africa Spec Commercial Vechicles 10,000-14,000 lb			
927	South Africa Spec Commercial Vechicles 14,000-16,000 lb			
928	South Africa Spec Commercial Vechicles 16,000-19500 lb			
929	South Africa Spec Commercial Vechicles 19,501-26,000 lb			
930	South Africa Spec Commercial Vechicles 26,001-32,500			
931	Chrysler U.K. Proposed Models 26,001-32000lb			
932	Photo of Car Front		?	
933	Photo of Car Rear Houses in Background			
934	Photo thro Edge of Windscreen another Car		?	
935	Photo 2 Cars Parkes Front on Rear		?	
936	Photo on open road Overtaking		?	
937	Photo of Lorry/Car at crossroads		?	
938	Photo of 2 Cars in Driveway		?	
939	Photo of 3 Cars at Roadworks		?	

940	Cutting (Foreign Magazine) 2 Door Saloon Car		?	
941	Cutting (Foreign Magazine) 2 Door Saloon Car		?	
942	Cutting (Foreign Magazine) 2 Door Saloon Car Rear		?	
943	Cutting (Foreign Magazine) 2 Door Saloon Car Side/Rear		?	
944	Cutting (Foreign Magazine) New Fiat 850		Fiat 850	
945	Arrow Facelift 1972 Model Year	1972	Arrow	
946	Iran Arrow Facelift 1971 Model Year	1971		
947	Paint and Trim Colours 1971 Model Year	1971		
948	Ride/Drive Outward Route (A.M.)			
949	Ride/Drive Afternoon Route			
950	Ride/Drive Return Route (A.M.)			
951	Model History Production and Sales 1969 Routes and Competitors	1969		
952	Specifications Sheet 1 of 2 Technical	May-70		
953	Specifications Sheet 2 of 2 Technical	May-70		
954	Motor Road Test or Advertising Material			
955	Pricing Hillman and Competitor Cars			
956	Model for Future Announcement (Competitor Cars)			
957	Destroyed			
958	Triumph 1500	20/08/1970	Triumph 1500	RVC 458H
959	Triumph 1500	20/08/1970	Triumph 1500	RVC 458H
960	Photo of 2 Door Saloon Car		?	RRW 97J
961	Photo of Control Pedals		?	
962	Photo of Car just below Driving Mirror		?	
963	Photo of Car Drivers Position		?	
964	Photo of Car Engine over Wing Bonnet Open		?	
965	Photo of Exhaust under Car?		?	
966	Photo on Underside of Car Towards Front		?	
967	Photo on inside of Wheel		?	
968	Photo on Underside of Car Towards Front		?	
969	Photo showing Sparewheel in Boot		?	
970	Exclusive 2 Photos of Car thro Bars		?	
971	Photo of Small 4 Door Car Rear Nearside Quarter		?	
972	Photo of Perche127?		Perche 127	Damaged

973	Photo of New Citroen GS		Citroen GS	
974	3 Views of Citroen GS		Citroen GS	
975	Tatra "T 613"		Tatra T 613	
975	2nd Cannot get out of Package			Water Damage
976	Exclusive 2 Photos of 2 Door Car		?	
977	5 Photos of Small Cars (2 Models)		?	
978	Photo of Small 2 Door Car		?	
979	2 Photos of Bmw Opel Cars		BMW Opel	
980	3 Photos of Opel and BMW Cars		Opel BMW	
982	Photo of Coupe Style Car behind Barrier		?	
983	Photo of Coupe Style Car behind Barrier mot 8/70	Aug-70	?	
985	Photo of Arrow Car Rear		Arrow	LWK 839F
986	Photo of Arrow Car Fronr		Arrow	LWK 839F
987	Photo of Arrow Car Nearside		Arrow	LWK 839F
988	Photo of Arrow Carb Nearside Rear Quarter		Arrow	
989	Photo of Arrow Car Nearside		Arrow	
990	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
991	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
992	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
993	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
994	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
995	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
996	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
997	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
998	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
999	Imp Vans SKV 144H and SDU 429G, Advertising Shots		Imp Van	
1000	Imp MHP 181F (Has Mk1 Trim)		Imp	
1001	Photo of Imp Offside Front Quarter		Imp	
1002	Imp MHP 181F (Has Mk1 Trim)		Imp	
1003	Imp MHP 181F (Has Mk1 Trim)		Imp	
1004	Imp MHP 181F (Has Mk1 Trim)		Imp	
1005	Photo Nearside of Arrow		Hunter?	
1007	Photo Hillman Hunter Rear Offside Quarter		Hunter	YMV 626H

1008	Photo Hillman Hunter Rear	Hunter	YMV 626H
1009	Photo Hillman Hunter Front	Hunter	YMV 626H
1010	Photo Lorry Short Wheelbase	Lorry	
1011	Photo Lorry Short Wheelbase	Lorry	
1012	Photo of Coach-Barrebos	Coach	
1013	Photo of Rocket Battery Fitted Truck	Military	
1014	Photo of Tilt Covered Lorry	Lorry	
1015	Photo of Tilt Covered Lorry	Military	
1016	Photo of Tilt Covered Lorry Militaires Barreiros	Military	
1017	Articulated Lorry plus Trailer Options	Lorry	
1019	Tractor 7.000	Tractor	
1020	Lorry being loaded bt Forklift	Lorry	
1021	Coach inside plus Engine and Drivers Position	Coach	
1022	Photo of Car 2 Door Saloon	?	1971 AC 78
1023	Photo of Car 4 Door Saloon	?	1971 AS 78
1024	Photo of Yute-Pickup Chrysler Banayi Fargo	Fargo	
1025	Photo of Hillman Hunter DL Rear	Hunter	
1026	Photo of Hillman Hunter DL Offside Front Quarter	Hunter	
1027	Photo of Hillman Hunter DL Offside	Hunter	
1028	Photo of Hillman Hunter DL Rear Offide Quarter	Hunter	
1029	Photo of Hillman Hunter DL Front	Hunter	
1030	Imp MYM 770H Outside Offices	Imp	
1031	Photo Avenger Estate Car People	Avenger	SVC 826J
1032	Photo Avenger Estate Car	Avenger	SVC 826J
1033	Photo Avenger Estate Car Rear	Avenger	SVC 826J
1034	Bar Chart Eoropean b Saloon KR 641		
1035	Photo of Car 2 Door Saloon	?	
1036	Photo/Outline Hatchback Saloon Cars	?	MLG 401H
1037	2 Photos of Car 2 Door Saloon thro bars	?	
1038	Magazine Cutting Of Triumph? 2 Door Saloon	Triumph?	RVC 447H
1039	Photo of Car 2 Door Saloon at speed	?	
1040	Photo of Car LHD 4 Door	?	7122 VZ 75
1041	Photo of Commer Van	Commer Van	
1042	Photo of Larger Van	Van	
1043	Photo of SWB Commer Lorry	Commer Lorry	
1044	Date Barchart Chrysler Product Plan - Passenger Car	Various	

1045	Date Barchart - US 2 Door Coupe H/A 429		H/A 429	
1046	Date Barchart - European B Sa- loon K/R 641		K/R 641	
1047	Barchart Arrow Facelift H/R 541		Arrow	
1048	Date Line Paint and Trim Colours 1972 Model Year	1972		
1049	Barchart Iram Arrow Facelift H/I 541		Arrow	
1050	Date Line B Estate Car H/R 445		H/R 445	
1051	Date Line Chrysler European Prod- uct Plan Passenger Car		Various	
1052	Effects of BHP/Ton Legistration on Current Range			
1053	Current Longe Range Plan Strategy			
1054	U.K. Market Size - Volume			
1055	Phase 1 Proposals			
1056	Recommended Guidelines for 500 Series Replacement			
1057	Possible Alternative Regulations			
1058	Construction and Use Regulations			
1059	Expected Regulation			
1060	Why Replace the 500 Series			
1061	Decisions Required			
1062	500 Series Phase 1			
1063	Alternatives Cabs			
1064	Possible Power Trains with 8 BHP/Ton			
1065	Actions Required 500 Series			
1066	Planning Assumptions			
1067	Current Heavy Truck L.R.P.			
1068	Premium Heavy Truck Market (1969)	1969		
1069	15m Length / Front Overhang	Oct-70		
1070	Possible Power Trains with 8 BHP/Ton			
1071	500 Series Phase 1			
1072	Phase 1 Proposals			
1073	Expected Regulation			
1074	Current Heavy Truck L.R.P.			
1075	Premium Heavy Truck Market (1969)	1969		
1076	15m Length / Front Overhang			
1077	1969 European Heavy Truck Market	1969		
1078	Could not Rear Stuck in Package			
1079	Photo Of 2 Door Coupe Rear		?	Stuck
1080	Photo Of 2 Door Coupe Nearside		?	

1081	Photo Of 2 Door Coupe Nearside Front Quarter	?	HWV 834J
1082	Interior Photo of Front Seating of Car	?	Stuck
1083	Photo of Cortina Estate Car Nearside	Cortina	
1084	Barchart Chrysler European Product Plan Passenger Car	Various	
1085	Barchart Chrysler European Product Plan Passenger Car	Various	
1086	Barchart Chrysler European Product Plan Passenger Car	Various	
1087	Barchart Chrysler European Product Plan Commercial Vehicles	Commercial	
1088	Barchart Chrysler European Product Plan Commercial Vehicles	Commercial	
1089	Photo of Simca 1204 Special	Simca1204	
1090	Photo of Simca 1000 Special	Simca1000	
1091	Photo of Simca 1200 S Coupe	Simca 1200S	
1092	Photo of Simca 1501 Special	Simca 1501S	
1094	Photo of Fiat 125 Special	Fiat 125	
1095	Photo of Fiat 124	Fiat 124	
1096	Interior Photo of Front Seating of Car	?	Stuck
1097	Interior Photo of Fiat 124	Fiat 124	
1098	Interior Photo of Fiat 125 Special	Fiat 125	
1099	General Data Engines		
1100	Exterior Dimensions		
1101	Chrysler 100 Standard Features		
1102	General Data Chassis		
1103	Interior Package		
1104	Barchart Chrysler European Product Plan Passenger Car	Various	
1105	Barchart Chrysler European Product Plan Commercial Vehicles		
1106	Photo in Showroom a line of 9 Cars	Various	
1107	Imp SDU 626 Show Stand Pictures	Imp	
1107	Photo in Showroom a line of 8 Small Cars	Various inc Imp	
1108	Imp SDU 626 Show Stand Pictures	Imp	
1108	Photo in Showroom 2 lines of Cars as 1106-1107a	Various inc Imp	
1109	Photo of Car Wheel Firestone Wide Oval Tyre		
1110	Long Range Plans Key Date Timing Chrysler Europe Cars		
1111	Long Range Plans Key Date Timing Chrysler Europe Cars		

1112	Long Range Plans Key Date Timing Chrysler Europe Cars		
1113	Photo of 4 Door Saloon Car	?	DYF 334
1114	Photo of LHD Fastback Car Audi?	Audi?	
1116	Photo of 4 Door Saloon Car Audi	Audi	
1118	2 Photos of 2 Door Coupe Style Car	?	
1119	Photo of 4 Door Coupe Style Car People Relaxing	?	
1120	Photo of 4 Door Saloon Car		HVW 823J
1121	Photo of 2 Door Car Capri	Capri	KEV 915L
1122	2 Photo of 1971 Vega 2300 Coupe	Vega 2300	
1123	Hillman Hunter Chrysler UK	Hunter	
1124	UK-Simca 3303? Chrysler France	Simca 3303?	
1125	100 Series Truck	Truck	
1126	Renault 12	Renault	
1127	Fiat 126?	Fiat	
1128	Colt Gallant	Colt	
1129	Simca 3300	Simca 3300	
1130	Simca 3301	Simca 3301	
1131	Hillman Avenger	Avenger	
1132	Ford Escort	Ford Escort	2 Negatives
1133	Alpine/Rapier Chrysler U.K.	Alpine/Rapier	
1134	Austin/Morris 1100/1300	BMC 1100/1300	
1135	Vauxhall Viva GM UK	Viva	
1136	Chrysler 160/180 (Chrysler France)	Chrysler 160/180	
1137	Cortina Mk III	Cortina	Stuck
1138	Toledo	Toledo	Stuck
1139	Foreign Magazine Article Test VW 1302/1302S	VW 1302	
1140	Foreign Magazine Article Test VW K70	VW K70	
1141	Foreign Magazine Article Mercedes 250/250CE	Mercedes 250	
1142	Foreign Magazine Article Opel Model?	Opel?	
1143	Cartoon City Fire Tender		
1144	Barchart Chrysler European Prod- uct Plan Passenger Car	Various	
1145	Magazine Article VW Small Car	VW?	Stuck
1146	Outline BMW Coupe	BMW	Stuck
1147	2 Photos of Renault 12	Renault 12	Stuck
1148	Mini Volkswagen	VW	Stuck
1150	Mini Audi	Audi	Stuck
1151	BMW 2000	BMW 2000	Stuck
1152	Mercedes 350SL	Mercedes 350SL	Stuck
1153	Outline of 2 Door Coupe Style Car	?	Stuck
1154	Foreign Magazine Article of Small 2 Door Car	?	Stuck

1155	Photo of 2 Door Car	?	Stuck
1156	Photo of 2 Door Small Car	?	Stuck
1157	Photo of 4 Door Car Volvo?	Volvo?	Stuck
1158	Photo of 4 Door Large Car?	?	Stuck
1160	Automotive Product Group Lorry		HUE 997D
1161	Karrier Bantam Tractor Units 1M Order from British Rail	Karrier Bantam	
1163	7 Photos of Imp and 6 Other makes of small Car	Imp +	KYM 770H
1164	5 Photos of Cars Chrysler European Products	Arrow inc	
1165	6 Photos of Vans-Lorries Chrysler European Products		
1166	3 Photos of Lorries Chrysler Euro- pean Products		
1167	1A Photo of Car thro Window of an- other	?	
1167	2A Photo of Car thro Window of an- other		
1167	3A Photo of Car thro Window of an- other		
1168	4A Photos including Filling Car ar Fuel Pump		
1169	Magazine Article "Rovers Shape of Things to Come"	Rover V	
1170	Car Outline Drawing Iran B Near- side	Iran B	
1171	2 Outline View Drawings of Iran B	Iran B	
1172	Photo of 4 Door Saloon Car	?	
1173	Car Outline Drawing Iran B Rear	Iran B	
1174	18 Negs of Car Details	?	
1175	Photo of 2 Door Coupe Style Car	?	Stuck
1177	Photo of Ford Capri	Ford Capri	
1178	4 Photo of Exterior/Interior of Coupe Style Car	?	Stuck
1179	Photo of 2 Door Coupe Style Car- VW?	VW?	Stuck
1180	Photo of 2 Door Saloon Car	?	Stuck
1181	Chrysler European Product Plan - Commercial Vehicles		
1182	Chrysler Far East and Africa Prod- uct Plan Passenger Car		
1183	Chrysler European Product Plan - Passenger Car		
1184	Chrysler European Product Plan - Passenger Car		
1185	Chrysler European Product Plan - Passenger Car		

1186	Chrysler European Product Plan - Commercial Vehicles		
1187	Chrysler European Product Plan - Commercial Vehicles		
1188	Chrysler European Product Plan - Passenger Car		
1189	Chrysler Latin America Product Plan - Passenger Car		
1190	Photo of 2 Door Coupe Style Car?	?	DXE 143J
1191	Chrysler European Product Plan - Passenger Car		
1192	Chrysler European Product Plan - Passenger Car		
1193	Chrysler European Product Plan - Commercial Vehicles		
1281	Photo of Hillman Hunter Front Off-side Quarter	Hillman Hunter	WRW 259J
1282	Photo of Hillman Hunter Front Off-side Quarter	Hillman Hunter	WRW 259J
1283	Photo of Hillman Hunter Rear Off-side Quarter	Hillman Hunter	WRW 259J
1284	Photo of Hillman Hunter Rear Off-side Quarter	Hillman Hunter	WRW 259J
1285	Chrysler European Product Plan - Passenger Car		
1286	Chrysler European Product Plan - Commercial Vehicles		
1287	Chrysler European Product Plan - Passenger Car		
1288	Chrysler European Product Plan - Passenger Car		
1289	Chrysler European Product Plan - Commercial Vehicles		
1290	Chrysler European Product Plan - Commercial Vehicles		
1291	2-2 Colour Negatives of Lorry? Front	Lorry?	
1291	4-2 Colour Negatives of Lorry? Front Offside Quarter	Lorry?	
1291	6-2 Colour Negatives of Lorry? Side	Lorry?	
1291	7-1 Colour Negatives of Lorry? Inside Cab	Lorry?	
1291	8-1 Colour Negatives of Lorry? Inside Cab	Lorry?	
1291	10-2 Colour Negatives of Lorry? Rear of Tractor Unit	Lorry?	
1292	10 Sheets Expressed Demand for European Size Engines etc		

1293	Engine Cost Penalty U.K. Manufacture	Avenger/Arrow	
1294	Engine Cost Penalty France Manufacture		
1295	15 Color Negs of Lorry? Detail	Lorry?	
1296	Photo of Lorry? Front Nearside Quarter	Lorry?	
1297	Photo of Lorry? Cab Nearside-Dodge?	Dodge?	
1298	Photo of Lorry? Cab Nearside Front Quarter Berliet TR 300	Berliet TR 300	
1299	Photo of Lorry? and Trailer	?	M 887645
1300	Photo of Scania Lorry Tractor Unit Dick Hamptons	Scania	UOT 174H
1301	Photo of Fiat Lorry Cab	Fiat	
1302	Photo of Styer Lorry Cab	Styer	L90 390
1303	Photo of Volvo Lorry Front	Volvo	N5327
1304	Photo of Car Transporter Cab AEC James Car Deliveries	AEC	KPW 425E
1305	Photo of Car Transporter Cab AEC James Car Deliveries	AEC	KPW 425E
1306	Photo of Car Transporter Cab Guy Richmond Rd Garage	Guy	
1307	Photo of Car Transporter Cab Guy Richmond Rd Garage	Guy	
1308	Photo of Henschel Lorry Front Nearside Quarter	Henschel	
1309	Photo of Man Lorry and Trailer	Man	
1310	Photo of Mercedes Lorry and Trailer	Mercedes	
1311	Photo of Daf Articulated Lorry Front	Daf	
1312	Photo of Lorry? Front Nearside Quarter	?	
1313	6 Negatives Roadscene Cars Van	?	
1314	Product Comparision Commercial Vehicles		
1315	A lot of Product Comparision Commercial Vehicles Sheets		
1316	Photo Of Car Rallye 1 Front	Rallye 1	
1317	Photo Of Car Rallye 1 Rear	Rallye 1	
1318	Photo Of Car Rallye 2 Rear	Rallye 2	
1319	Photo Of Car Rallye 2 Front	Rallye 2	
1320	Photo of 4 Door Saloon Car		
1320	Photo of Small Van	Van?	YWK 889K
1321	Photo of Small Van Rear Door Open	Van?	
1351	Photo of the Consul GT	Consul GT	MNO 253K
1352	Photo of the Consul GT? Nearside	Consul GT?	

1353	Photo of a German 4 Door Car Rear Offside Quarter	?	GG-DM 329
1354	Photo of 4 Door Hatchback Car?	?	
1355	Photo of 2 Door LHD Small Car?	?	2807 CB 92
1356	Photo of Opel Ascona SR	Opel Ascona	
1356	2 Photo of 2 Door Small Car	?	
1356	3 Photo of 2 Door Small Car	?	
1356	4 Photo of 2 Door Small Car	?	
1357	Small 2 Door Car	Simca?	
1357	5 Photo of 4 Door Saloon Car	?	
1357	6 Photo of 4 Door Saloon Car	?	
1357	7 Photo of 4 Door Saloon Car	?	
1358	Photo of Consul Fastback Style	Consul	
1358	10 Photo of 4 Door Small Car	?	LGO 961K
1358	11 Photo of 4 Door Small Car	?	
1358	12 Photo of 4 Door Small Car	?	
1359	4 Photo of 4 Door Small Car	?	
1359	5 Photo of 4 Door Small Car	?	
1359	6 Photo of 4 Door Small Car	?	
1359	Photo of Car BMCL 15	BMCL 15	
1360	Photo of Small 4 Door Hatchback Car	?	
1360	1 Photo of 4 Door Saloon Car	?	
1360	2 Photo of 4 Door Saloon Car	?	
1360	3 Photo of 4 Door Saloon Car	?	
1361	5 Photo Of Citroen 4 Door Car	Citroen	
1361	6 Photo Of Citroen 4 Door Car	Citroen	
1361	7 Photo Of Citroen 4 Door Car	Citroen	
1361	11 Photo of 2 Door Small Car	?	
1362	Photo of Saloon Car Auto Union/Audi	Auto Union/Audi	
1362	12-/1/H 3 Photos of Raised Back Van?	Van?	
1363	Photo of Car BMW?	BMW	M-YE 1450
1363	6 Photo of Car Peugeot?	Peugeot	
1363	7 Photo of Car Peugeot?	Peugeot	
1363	8 Photo of Car Peugeot?	Peugeot	
1364	6-Photo of Small 4 Door Car?	?	
1364	11-Photo of Small 4 Door Car?	?	
1364	12-Photo of Small 4 Door Car?	?	
1365	7-Photo of Small 2 Door Car?	?	
1365	8-Photo of Small 2 Door Car?	?	
1365	9-Photo of Small 2 Door Car?	?	
1366	2- Photo of 4 Door Hatchback Type Car Renault?	Renault?	
1366	3- Photo of 4 Door Hatchback Type Car Renault?	Renault?	

1366	4- Photo of 4 Door Hatchback Type Car Renault?	Renault?
1367	Photo of Wheel/Tyre	
1368	3 Colour Negs Rallye 2 Simca 1100. French Reg	Simca Rallye
1369	Chrysler 180 BKV 303K	Chrysler 180
1369	6-Photo of 4 Door Saloon Car?	?
1369	11-Photo of 4 Door Saloon Car?	?
1369	12-Photo of 4 Door Saloon Car?	?
1370	Fiat 127, K Reg	Fiat 127
1370	4-Photo of Small 2 Door Hatchback Car	?
1370	5-Photo of Small 2 Door Hatchback Car	?
1370	6-Photo of Small 2 Door Hatchback Car	?
1371	Mk1 Simca 1100 Van	Simca 100 Van
1371	1- Photo of Small Van?	?
1371	2- Photo of Small Van?	?
1371	3- Photo of Small Van?	?
1372	Avenger Super Estate	z
1372	1-Photo of Estate Car?	?
1372	2-Photo of Estate Car?	?
1372	3-Photo of Estate Car?	?
1372	4-Photo of Estate Car?	?
1373	5-Photo of 2 Door Fastback Car?	?
1373	6-Photo of 2 Door Fastback Car?	?
1373	7-Photo of 2 Door Fastback Car?	?
1374	Ford Granada Mk1	Granada
1374	8- Photo of 4 Door Saloon Car Ford?	Ford?
1374	9- Photo of 4 Door Saloon Car Ford?	Ford?
1374	10- Photo of 4 Door Saloon Car Ford?	Ford?
1375	Ford Granada Mk1 Estate	Granada
1375	H/12-2 Views of of a Car? Interior	?
1376	Maxi	Maxi
1376	6-Photo of 4 Door Car Maxi?	Maxi?
1376	8-Photo of 4 Door Car Maxi?	Maxi?
1377	Capri	Capri
1377	6-Photo of 2 Door Fastback Car Capri?	Capri?
1377	7-Photo of 2 Door Fastback Car Capri?	Capri?
1377	8-Photo of 2 Door Fastback Car Capri?	Capri?
1378	Taunus Coupe	Taunus Coupe
1378	9-Photo of 2 Door Fastback Car?	?
1378	10-Photo of 2 Door Fastback Car?	?

1378	11-Photo of 2 Door Fastback Car?		?
1944	BMC 1100/1300		1100/1300
1945	Maxi		Maxi
1946	NSU RO80		RO80
1947	BMC 1800		1800
1948	Mini		Mini
1949	Datsun Cherry 100A		Datsun Cherry
1950	Alfasud		Alfasud
1951	Ford Taunus Estate		Ford taunus Es- tate
1952	Fiat 132		Fiat 132
1953	Opel Kadett Estate		Opel Kadet Es- tate
1954	German Group Test		
1955	Chrysler Euro Product Plan		
1979	K Reg Audi 100 Coupe		Audi 100
1980	Product Development Competition, with Photos		
1981	Product Development Competition, with Photos		
1982	Toyota		Toyota
1983	Datsun? Vertical Light over Wing Toyota?		Datsun 180B
1985	Datsun 180B		Datsun 180B
1986	Opel Kadett 2 Door		Opel Kadet
1987	Opel Kadett 2 Door		Opel Kadet
1988	Early VW Golf		VW Golf
1989	Opel Kadet	Oct-72	Opel Kadet
1990	Allegro, K Reg Princess (Wedge) with Boot Spoiler		Allegro and Princess
1991	Opel Kadett Impression		Opel Kadett
1992	VW Passat		VW Passat
1993	VW Passat	1973	VW Passat
1994	Renault R23	1973	Renault R23
1995	Sherpa Van, Distant Shots		Sherpa Van
1996	Mk2 Capri GT		Capri
1997	Mk2 Capri GT		Capri
1998	Mk2 Capri GT		Capri
1999	Mk2 Capri GT		Capri
2000	Mk2 Capri GT		Capri
2002	VW Golf Mk1		Golf
2003	Renault 5		Renault 5
2004	Opel like a Metro		Opel
2005	Opel/Innocenti cross?		Opel
2006	VW Polo Mk1		VW Polo
2007	Opel Kadett Impression		Opel Cadet
2008	104/LNA Impression		
2009	Mk1 Fiesta, Artists Impression		Fiest

2010	VW Golf, German Specification	VW Golf
2011	VW Golf Mk1 4 Door	VW Golf
2012	Golf, Fiat 128	Golf / Fiat 128
2013	Escort, Opel	Escort / Opel
2014	Simca, Renault 6, Golf	Simca
2015	VW Golf Mk1 Advert	VW Golf
2016	K M Bedford	Bedford
2017	K M Cab Interior Bedford	Bedford
2018	Simca 1100 Van	Simca 1100 Van
2021	Early Sherpa Van	Sherpa
2022	Chrysler 180 After Crash Test Rear View	Chrysler 180
2023	Chrysler 180 After Crash Test Rear View	Chrysler 180
2024	Chrysler 180 After Crash Test	Chrysler 180
2024	Chrysler 180 After Crash Test	Chrysler 180
2025	No62 Smashed Front 4 Door	Humber?
2026	Chrysler 180 Interior	Chrysler 180
2027	Chrysler 180 Before Crash Test	Chrysler 180
2028	Chrysler 180 Before Crash Test	Chrysler 180
2029	Chrysler 180 Before Crash Test	Chrysler 180
2030	Chrysler 180 Before Crash Test	Chrysler 180
2031	Chrysler 180 Before Crash Test	Chrysler 180
2032	Chrysler 180 RH Side Before	Chrysler 180
2033	Chrysler 180 RH Side Before	Chrysler 180
2034	Chrysler 180 LH Side Before	Chrysler 180
2035	Chrysler 180 Front View (Crashed)	Chrysler 180
2036	Chrysler 180 Rear View - French No plates	Chrysler 180
2037	Chrysler 180 Crash Test Interior	Chrysler 180
2038	Chrysler 180 Crash Test LH Side View	Chrysler 180
2039	Chrysler 180 Crash Test Underside	Chrysler 180
2040	Peugeot/Citroen Product Development	
2041	Ford Product Development	
2042	Fiat Product Development	
2043	Renault Product Development	
2044	VW/Audi Product Development	
2045	BLMC Product Development	
2046	Europe Product Development	
2047	Fuel Consumption vs Competition 840-1100cc	
2048	Fuel Consumption Avenger vs Competition 1100-1600cc	
2049	Fuel Consumption Hunter vs Competition 1600-2000cc	

2050	Chrysler European Trucks Projection		
2051	Dodge Pick Up Interior	Dodge Pick Up	
2052	Dodge Pick Up	Dodge Pick Up	
2053	Dodge Pick Up	Dodge Pick Up	
2054	Dodge Pick Up	Dodge Pick Up	
2055	Dodge (D50) Pick Up	Dodge Pick Up	
2056	Magirus Deutz Lorry		
2057	Opel Ascona	Opel Ascona	
2058	2 door Coupe (Opel Manta Influenced)		
2059	Alpine Prototype and V W Passat	Alpine Prototype	
2060	Ford Escort 4 Door	Escort	
2061	Solar Prototype and Audi	Solra Prototype	
2062	Commer Road Sweeper, Norwich. Commando Type	Commer	
2063	Dodge Commando Tipper	Dodge Commando	
2064	Dodge Commando	Dodge Commando	
2065	PVC 153 N Commer PB Ambulance (Works)	Commer PB	
2066	Lorry Chassis		
2067	M Reg Dodge Commando	Dodge Commando	
2068	Dodge Barreiros Tractor Unit	Dodge	
2069	Dodge Cab Interior	Dodge	
2070	Three Dashboard Commercial	Dodge	
2071	Consept 4 Door GT Car	?	
2072	Consept Utility Badged Commer	Commer	
2073	Consept Pickup	?	
2074	Renault 14, Peugeot 205 Photo	Peugeot 205	
2118	Photo of 4 Door Saloon Car Avenger?	Avenger?	
2119	Photo of 4 Door Saloon Car Avenger?	Avenger?	LRW 163P
2120	Photo of 4 Door Saloon Car Avenger?	Avenger?	LRW 163P
2121	Photo of 4 Door Saloon Car Avenger?	Avenger?	LRW 163P
2122	Photo of 4 Door Saloon Car Avenger?	Avenger?	LRW 163P
2123	Photo of 4 Door Saloon Car Avenger?	Avenger?	LRW 163P
2124	Photo of 4 Door Saloon Car Avenger?	Avenger?	LRW 163P
2125	Photo of 4 Door Saloon Car Avenger?	Avenger?	LRW 163P

2126	9 Photo Of Details of Car Interior		
2127	Photo of 2 Door Car Ascona	Ascona	
2128	Photo of 4 Door Car Ascona	Ascona	
2129	Photo of 2 Door Car Manta	Manta	
2130	Photo of 2 Door Car Manta	Manta	
2131	Photo of 4 Door Car Manta	Manta	
2132	Photo of German 2 Door Small Car	?	K-UT 202
2133	Photo of German 2 Door Small Car	?	K-UT 202
2134	Photo of 4 Door Car Renault	Renault	5228 EK 92
2135	Photo of Fiat 128-3P	Fiat	
2136	Photo of 2 Door Hatchback Car?	?	
2137	Photo of 2 Ford?Door Saloon Car	Ford?	K-AP 996
2138	Photo of 4 Door Estate Car?	Estate?	
2139	Photo of 2 Door Fastback Car?	?	LMJ 243P
2140	Photo of 4 Door Saloon Car?	?	LMJ 242P
2141	Photo of 4 Door Hatchback Car?	?	5232 EK 92
2142	Photo of a Number Plate just		
2143	Photo of 2 Door Hatchback Car?	?	
2144	Photo of 4 Door Renault 20 TL	Renault 20 TL	
2145	Photo of 2 Door LHD Small Car? Tradeplates	?	
2146	Photo Of 4 Door Saloon Car Ford?	Ford	K-LV 526
2147	Photo Of 4 Door Saloon Car Ford?	Ford	K-LV 526
2148	Photo of 2 Door Hatchback Car?	?	
2149	Photo of 2 Door German Hatchback Car?	?	K-UK 993
2150	Magazine Article Tipo 124	Tipo 124	
2151	Magazine Article Coupe Seat 143	Seat 143	
2152	Photo of 2 Door Small Car?	?	
2153	Photo of Hatchback Rear Door	?	
2154	Grainy Photo of Car	?	
2155	Grainy Photo of 4 Door Saloon	?	
2156	Specifications, Timing, Emissions Literature		
2156	Grainy Photo of Audi 120	Audi 120	
2157	Photo of 2 Door Car?	?	
2158	Photo of 2 Door Car?	?	
2159	5 Photos of Car?	?	
2160	12 Photos of Detail of Inter- ior/Exterior Car	?	
2160	15 Photos of Detail of Small Lorry Interior/Exterior	Lorry	
2161	11 Photos of Detail of Interior of Car?		
2161	14 Photos of Detail of People Car- rier Interior/Exterior	People Carrier	
2161	12 Photos of Detail of People Car- rier Interior/Exterior	People Carrier	

2161	Photo of 4 Door Saloon Car Avenger?	Avenger	GVC 185N
2162	Photo of 4 Door Saloon Car Avenger? Offside	Avenger	
2163	Photo of 4 Door Saloon Car Avenger? Nearside	Avenger	GVC 185N
2164	Photo of 2 Door Saloon Hillman	Hillman	OAC 361P
2165	Photo of 2 Door Saloon Hillman	Hillman	OAC 361P
2166	Photo of 2 Door Saloon Hillman	Hillman	OAC 361P
2167	Photo of 4 Door Estate Car Hillman Avenger	Avenger	OAC 362P
2168	Photo of 4 Door Estate Car Hillman Avenger	Avenger	OAC 362P
2169	Photo of 4 Door Estate Car Hillman Avenger	Avenger	OAC 362P
2170	17-Photo of Door Interior		
2170	19-Photo of Front Seats		
2171	20-Photo of Door Interior		
2171	21-Photo of Front Seats		
2172	15-Photo of Door Interior		
2172	16-Photo of Front Seats		
2173	Photo of Front of Car?		
2174	Photo of 4 Door Saloon Car OFF-SIDE Front Quarter		
2175	Photo Of 4 Door Saloon Car?	?	
2176	Photo of the Front of a Small Car Fiat	Fiat	
2177	Photo Of a 2 Door Small Car Fiat	Fiat	
2178	Photo of a 2 Door Fiat Rear	Fiat	
2179	Photo of the Front of Car?	?	
2180	Photo of a Small Hatchback Car?	?	
2181	Photo of an Opel Small Car?	Opel?	
2182	Photo of a Small Fiat Car	Fiat	ORW 976P
2183	Photo of a Small Fiat Car	Fiat	ORW 976P
2184	Photo of a Small Fiat Car Rear	Fiat	ORW 976P
2185	Photo of Front of Car?	?	
2186	Photo of Offside Front of Small Car?	?	
2187	Photo of Nearside Rear of Small Car?	?	
2188	Photo of Front of Car?	?	OHP 488P
2189	Photo of Same Car as 2188	?	OHP 488P
2190	Photo of Same Car as 2188	?	OHP 488P
2191	Photo of Front of VW Small Car?	VW	
2192	Photo of same Car as 2191	VW	
2193	Photo of same Car as 2191	VW	
2194	Photo of Front of VW Small Car	VW	
2195	Photo of same Car as 2194	VW	
2196	Photo of same Car as 2194	VW	

2197	Photo of Front of Vauxhall Car	Vauxhall	MVC 41P
2198	Photo of same Car as 2197	Vauxhall	MVC 41P
2199	Photo of same Car as 2197	Vauxhall	MVC 41P
2200	Photo of Rear of a small Car?	?	
2201	Photo of the same Car as 2200	?	
2202	Photo of same Car as 2200	?	
2203	Photo of an Audi Car Front	Audi	JVB 331P
2204	Photo of same Car as 2203	Audi	JVB 331P
2205	Photo Of same Car as 2203	Audi	JVB 331P
2207	Photo of a Cars Drivers Console		
2208	Photo of a NCL Electric Powered Van	Electric Van	
2209	Photo of Toothed/Vee Belt Drive Engine		
2210	Photo of 3 Round Details?		
2211	7 Photos of Interior/Exterior View of Car?	?	OAC 145P
2211	7 Photos of Detail View of Car?		
2212	4 Photos of 4 Door Saloon Car	?	NMJ 292P
2213	8 Photos of 2 Doror Small Hatchback	?	PLH 665R
2214	11 Photos of Interior/Exterior of 4 Door Car?	?	NOF 700R
2215	5 Photos of Interior/Exterior of 4 Door Car?	?	PKV 472R
2216	9 Photos of Detail View of Car?		
2217	5 Photos of Detail View of Car?		
2218	11 Photos of Interior/Exterior View of 4 Door Car?	?	
2219	3 Photos(same side view) of a 4 Door Saloon Car	?	
2220	2 Side Photos of 4 Door Saloon Car (same as 2219?)		
2221	2 Photos of 4 Door Fastback Car?	?	
2222	Photo of 4 Door Hatchback Type Car?		
2223	Photo of Vauxhall Commodore	Vauxhall	
2224	Photo of Side of Car Vauxhall Commodore?		
2225	Photo of side view of Car with Air-flow Lines		
2226	Photo of Renault 30TS	Renault 30TS	
2227	Photo of Car possibly Ford?	Ford?	PUK 197R
2228	Photo of same car as 2227		PUK 197R
2229	Photo of Front of same Car as 2227		PUK 197R
2230	Photo of same Car as 2227 with Door/Hatch open		
2231	1-2 Photos (same) of a Wheel/Tyre		

2231	2-2 Photos (same) of a Wheel		
2232	Photo part Nearside View of 4 Door Car	?	
2233	Photo part Nearside View of 4 Door Car as 2232	?	RRW 395N?
2234	Photo of Rear Nearide Corner of Car as 2232	?	
2235	Photo of Nearside of Car as 2232	?	
2236	Photo of Offside of Car as 2232	?	
2237	Photo of Simca Car Rear	Simca	237BNZ 75
2238	1-11 Photos of Detail ViewS of Car?		
2238	2-4 Photos of Detail ViewS of Car?		
2239	1-Photo of Prototype Mini?	Mini	ADO 88
2239	2- 2 Photos(same) of Prototype Mini?	Mini	ADO 88
2240	Photo of Side view of Car? Singer?	Singer?	
2241	Photo of Nearside Front Quarter of Car? as 2240		
2242	Photo of Offside Rear Quarter of Car? as 2240		
2243	Photo of Control Console Possibly Car as 2240		
2244	Photo of Control Console		
2245	Outline of Vans 50 Series HCV WheelBases and Volumes	50 Series Vans	
2246	Outline of Trucks 50 Series HCV WheelBases and Bodylengths	50 Series Trucks	
2247	Outline of Walk Thru Van	Walk Thru Van	
2248	50 Series Job 1 Introduction Dates	Oct 78 - Jan 80	50 Series
2249	Outline of Bantam Truck		Bantam Truck
2250	Outline of 50 Series Cab Variations		50 Series
2251	50 Series Models and Weights Chassis/Cab		50 Series
2252	7 Photos of Interior of Cabs possibly Vans/Trucks		
2253	15 Photos of Detail of Interiors of ?/Exterior		
2254	2 Photos (same) of Display on Wall		
2255	Outline of 10-40 Series Van - Beam Axle 127" WB		10-40 Seies Van
2256	Outline of Euro Van - RWD 128" WB		Euro Van
2257	Outline of Euro Van - FWD 128" WB		Euro Van
2258	Outline of 10-40 Series Van - IFS 127" WB		10-40 Seies Van
2259	Outline of 45 Series Van 127" WB		45 Series Van

2260	1-5 Photos of Exterior View of Vans and Lorries	Van/Lorry	
2260	2-12 Photos of Exterior View of Vans and Lorries	Van/Lorry	
2260	3-11 Photos of Exterior View of Vans and Lorries	Van/Lorry	
2260	4-11 Photos of Exterior View of Vans and Lorries	Van/Lorry	
2260	5-15 Photos of Exterior View of Vans and Lorries	Van/Lorry	
2260	6-15 Photos of Exterior View of Vans and Lorries	Van/Lorry	
2261	11 Photos of a Medium Van and Lorry	Van/Lorry	
2262	12 Photo of a Lorry and a Van	Van/Lorry	
2262	11 Photos of Exterior/Interior View of a Pickup	Pickup	
2262	12 Photo of Detail of Pickup	Pickup	
2263	2 Slides of Van-Future Legislation/Compliance		
2264	29 Photos of Interior Detail of Cabs Van/Lorry?	Van/Lorry	
1984	Datsun 180B	Datsun 180B	
	Following have E prefix		
1	Photo of Fiat 125 Car Seat Frame and Springs	Fiat 125	
2	Photo of Fiat 125 Car Seat Covers	Fiat 125	
3	Photo of Rusty Body Work?		
4	Photo Of Ford Escort Radiator Parts	Ford Escort	
5	Photo Closeup of Radiator Detail		
6	Photo of Inside of Luggage Compartment		
7	Photo of empty Engine Compartment		
8	Photo of Driving Position		
9	Photo of Inside of Luggage Compartment		
10	Photo of Bodywork Construction Detail		
11	Photo of Bosch and Lucas Alternator Parts		
12	Photo of Bodywork Construction Detail?		
13	Photo of Bodywork Construction Detail?		
14	Photo of Ford Escort 1100 Silencer Box Detail	Ford Escort	

15	Photo of Ford Escort Pedal Arms-Fulcrum Brkt-Accelerator Arm		Ford Escort
16	Photo of Steering Rack-Wheel-Shaft Detail		
17	Chart too small to see		
18	Competitive Vehicle Analysis and Cost Reduction Dept. Major Function		
19	Vendor Costs		
20	C Car Primary Category Cost Breakdown		
21	Lines of Communication		
22	Chart too small to see		
23	Facelift/New Model Programmes and Control Report 1968/75	1968-75	
24	Organisation and Headcount		
25	Workload and Allocation (Estimating and Clerical)		
26	C Car Comparitor Vehicle		
27	C Car Triangulation Sheet		
28	Corporate Prime Cost		
29	Photo of incomplete Car Body on Jig		
30	Photo of Half a Floor Pan on Jig		
31	Photo of incomplete Car Body Boot		
32	Photo of incomplete Car Body Bulkhead Forward		
33	Photo of incomplete Car Body Rear Passing Area		
34	Photo of incomplete Car Body Front Offside Wing		
35	Photo of Nearside of Ford Capri		Ford Capri
36	Photo of Rear of Ford Capri		Ford Capri
37	Photo of Front of Ford Capri		Ford Capri
38	Photo of Front Offside Quarter of Ford Capri		Ford Capri
39	Photo of Rear Nearside Quarter of Ford Capri		Ford Capri
40	Photo of Drivers Position of Ford Capri?		
41	Photo of View inside of Boot of Ford Capri		Ford Capri
42	Photo of View inside of Engine Bay of Ford Capri		Ford Capri
43	Photo on Underside Rear of Ford Capri?		
44	Photo on Underside of Ford Capri?		

45	Photo on Underside of Engine Ford Capri		
46	Photo of 3 ??? off Cortina-Escort C Model		
47	Photo of Bodywork Construction Car		
48	Photo of One Side of Body Structure Front		
49	Photo of One Side of Body Structure Rear		
50	Photo of One Side of Body Structure		
51	Photo of Body Construction Rear Bulkhead		
52	Photo of Body Construction Front Bulkhead		
53	1-Photo of 2 Body Part Pressing		
53	2-Photo thro Door of Lorry Cab		
54	Photo of Body Construction Upside Down on Jig		
55	1-Photo of Twin Rear Wheel Flatbed Lorry NearSide View	Lorry	
55	2-Photo of 2 Body Part Pressing		
56	Photo of Twin Rear Wheel Flatbed Lorry Rear View	Lorry	
57	Photo of Twin Rear Wheel Flatbed Lorry Front View	Lorry	
58	Photo of Twin Rear Wheel Flatbed Lorry Front Offside View	Lorry	
59	Photo Of Detail Parts?		
60	Photo of Inside Door Structure for Lorry		
61	Photo of Door Mechanism for Lorry		
62	Photo of Front of a Van or Pickup		
63	Photo on Underside of a Chassis		
64	Photo of Driving Position of Van or Pickup		
65	Photo showing Sideview of Pickup		
66	Photo of Driving Position of Van or Pickup		
67	Photo showing a Side view on a People Carrier possibly VW	VW?	
68	Photo Showing Nearside Quarter View Vehicle as 67	VW	UXD 631G
69	Photo Showing Offside Quarter View Vehicle as 67	VW	UXD 631G
70	Photo Showing Front View Vehicle as 67	VW	UXD 631G

71	Photo Showing Rear View Vehicle as 67	VW	UXD 631G
72	Photo Showing Inside Rear of Vehicle as 67	VW	UXD 631G
73	Photo on Underside of a Chassis		
74	Photo on Underside of a Chassis		
75	Photo on Underside of a Chassis		
76	Data Sheet Friden Decimel Equivalents		
77	Photo of Detail possibly Engine Bay		
78	Photo from Front Quarter of Car across Engine Bay?		
79	Photo from Front Quarter of Car across Engine Bay?		
80	Photo Inside a Car? Boot		XWD 766H
81	Photo of Car? Spare Wheel and Cover		
82	Photo of Car? Spare Wheel in Storage		
83	Photo of Car? Spare Storage from Underneath		
84	Photo of Car? Oneside Drive Shaft from Underneath		
85	Photo of Car? Underneath showing Suspension?		
86	Photo of Car? Underneath showing Steering-Drive-Suspension?		
87	Photo of Car? Underneath showing Diff?		
88	Photo of Car? Underneath showing Exhaust-Silencer		
89	Photo of Car? General Underneath View		
90	Photo of Honda 77 Rear View	Honda 77	
91	Photo of Honda 77 View Underneath Rear	Honda 77	
92	Photo of Honda 77 View of Front Bonnet Open	Honda 77	
93	Photo of Honda 77 View Underneath Front	Honda 77	
94	Photo of Honda 77 View Front of Front Wing	Honda 77	
95	Photo of Honda 77 View Rear of Rear Wing	Honda 77	
96	Photo of Honda 77 View of Driving Position Closeup	Honda 77	
97	Photo of Honda 77 View of Driving Position	Honda 77	

98	Photo of Honda 77 View of Driving Position Closeup	Honda 77	
99	Photo of Honda 77 Rear Light Cluster	Honda 77	
100	Photo of Honda 77 Engine Bay	Honda 77	
101	Photo of Honda 77 Boot	Honda 77	
102	Photo of Honda 77 Engine Bay	Honda 77	
103	Photo of Honda 77 Front Bonnet OpenEngine Bay	Honda 77	
104	Photo Underneath Car Engine/Exhaust		
105	Photo Underneath Car Engine/Exhaust		
106	Photo Underneath Car Silencer		
107	Photo of Car Details?		
108	Photo of De Dion and Elbow Assembly		X1251539
109	Photo of De Dion and Elbow Assembly		X1251539
110	2 (same) Photo of Final Drive and Torque Tube Assembly		
111	Photo of Brake Drum		X1239804
112	Photo of Top Link		X1251552?
113	Photo of Bottom Link		X1243541
114	Photo of Panhard Rod		X156610A?
115	Photo of Bottom Link		X1251541
116	Photo of Brake Assembly		X1251528?
117	Photo of Mounting Rubber		X1251553?
118	Photo of Drive Shaft		X1251558?
119	Photo of Mounting Bracket		X1251533
120	Photo of Drive Flange		X1251524
121	Photo of Hub		X1251569
122	Photo of Drive Shaft		X1251512
123	Photo of Lots of Car Parts		
124	Photo of 3 Hill Start Test Clutches Test 1,2,and New DSW8		
	Following have F prefix		
1	Defrosting Test-4 Door Arrow Sedan	Sunbeam	
2	Plots from an Overdrive Test		
3	Defrost Test-Sunbeam Alpine GT (Prototype)	Sunbeam Alpine	
4	Defrosting Test-Sunbeam Alpine Coupe Production Vehicle	Sunbeam Alpine	
5	Defrost Test-Sunbeam Alpine GT (Production)		
6	Defrost Test-Commer VanPB Range LHD (Production)	Commer Van	

7	Demisting Test-Hillman Hunter Saloon (Production Vehicle)		Hillman Hunter	Report10691
8	Demisting Test-B Model Saloon (Prototype Vehicle) Fig1			Report10691
9	Demisting Test-B Model Saloon (Prototype Vehicle) Fig2			Report10961
10	Defrost Test B Model Vehicle B12 LHD Saloon			Report10961
11	Defog Test B Model Vehicle B12 LHD Saloon	29/11/1968		TR No21498
12	Plots from an Overdrive Test			
13	Defog Test Front WindShield C Model	03/12/1968		Report10739
14	Defrost Test C Model			Report10739
15	Photo of Inner Workings of Diff 125lb/Ft Drive			
16	Photo of Inner Workings of Diff 125lb/Ft Drive			
17	Photo of Inner Workings of Diff 250lb/Ft Drive			
18	Photo of Inner Workings of Diff 250lb/Ft Drive			
19	Photo of Inner Workings of Diff 375lb/Ft Drive			
20	Photo of Inner Workings of Diff 375lb/Ft Drive			
21	Photo of Inner Workings of Diff 500lb/Ft Drive			
22	Photo of Inner Workings of Diff 500lb/Ft Drive			
23	3 Photos of person working on ???			
24	2 Photo Underneath Car?			
25	Photo of Inner Workings of Diff 375lb/Ft Drive			
26	Photo of Inner Workings of Diff 250lb/Ft Drive			
27	Photo of Inner Workings of Diff 500lb/Ft Drive			
28	Photo of Inner Workings of Diff 125lb/Ft Drive Overrun			
29	Photo of Inner Workings of Diff 250lb/Ft Drive Overrun			
30	Photo of Inner Workings of Diff 375lb/Ft Drive Overrun			
31	Photo of Inner Workings of Diff 500lb/Ft Drive Overrun			
32	Photo of Inner Workings of Diff 125lb/Ft Drive			

33	Defog Test Front WindShield C Model	0/12/1968	Report10739
34	Defrost Test C Model		
35	Some Rig		
36	As 35		
37	Test Rig around Wheel Disc		
38	Test Rig around Sterring/Front Suspension		
39	Compression Test Machine		
40	Defog or Defrost? Test/ Area Plot to small to read		
41	Defog or Defrost? Test/ Area Plot to small to read		
42	Detail Photo of showing Straps above Diff?		
43	Detail Photo of showing Seats Back?		
44	Detail Photo of showing Straps above Diff?		
45	Detail Photo of showing Straps above Diff?		
46	Detail Photo of showing Seats Back?		
47	Photo of showing Floor Pan Damage/Straps above Diff?		
48	Detail Photo of showing Seats Back?		
49	Photo showing extensive inside of Car Passenger Area		
50	Photo showing Front Edge of Rear seat		
51	Detail Photo showing bolts on Strips?		
52	Detail Photo showing bolts on Strips?		
53	Photo of 4 Door Saloon Car? Fan across Windscreen?		
54	Photo of 4 Door Saloon Car? By brick wall		
55	Photo of Car (same as 53) Front Unfinished		
56	Photo of Car (same as 53) Rear Unfinished		
57	Photo of Engine in Car C92		C 92
58	Photo of underside Front detail Steering/Suspension		
59	Photo showing Steering/Bellhousing/Wiring(Test)		
60	Photo showing Steering Components in Test Machine		

61	Photo showing Detail-Hinge-Bolts-Tube?		
62	Photo of Steering Items in Compression/Vibration Tester		
63	Photo of Imp/Chamois Outside of Building		
64	Photo of 2 Assemblies?		
65	Photo of 2 Assemblies?		
66	Photo of Hexagon Detail?		
67	Photo of Hexagon Detail?		
68	3 View Drawing of Diff.-Deflection Test Fig 1 C Model.		Report12214
69	C Model Defog Performance Windscreen Diagram		
70	C Model Defrost Performance Windscreen Diagram		
71	Defrost Test Dodge Light Bus RHD PB Range Diesel		Report12417
72	Defrost Test Dodge Light Bus RHD PB Range Diesel		
73	Defrost Test Dodge Light Bus RHD PB Range Diesel		
74	B Propshaft Plunge Fig1-2-3-4 Traces		Report8868
75	2 Photos (same) too small to read		
76	2 Photos (same) of Testing Machine?		
77	Photo of Specimen under Tensile Testing		
78	2 Photo of Hinge Component Parts		
79	Outline Drg.- Mode Shape at 12.5c/s Resonance	05/03/1968	H.J.Wyman
80	Three D.O.F.Ride and Shudder Model Diagram		
81	Diagrammatic Representation of Car Degrees of Freedom		
82	Outline Drg.- Mode Shape at 8.8c/s Resonance		
83	Photo of Specimen after Tensile Testing		
84	Photo of Jig/Fixture in Testing Machine Test Area		
85	Photo of Jig/Fixture in Testing Machine Overall View		
86	Photo of Jig/Fixture out of Testing Machine		
87	Photo of Jig/Fixture out of Testing Machine		

88	Photo of Jig/Fixture out of Testing Machine	
89	Photo of Jig/Fixture out of Testing Machine	
90	Photo of Door Latch Items readied fro Testing?	
91	Defrost Test Dodge Light Bus RHD PB Range Diesel	Report12137
92	Defrost Test C Model Prototype (C11) Lo-Line 1724cc	Report12684
93	Defrost Test Hillman Avenger GL (Pre-Production) Cond.2	Report12750
94	Defrost Test Hillman Avenger GL (Pre-Production) Cond.3	Report12750
95	Defrost Test Hillman Avenger GL (Pre-Production) Cond.1	Report12750
96	Defrost Test Hillman Avenger GL (Pre-Production) Cond.4	Report12750
97	Defrost Test N.A.S.B Model (Pre-Production) Cond.1	Report12912
98	Defrost Test N.A.S. B Model (Pre-Production) Condition 2	Report 12912
99	Defrost Test N.A.S. B Model (Pre-Production) Condition 3	Report 12912
100	Defrost Test N.A.S. B Model (Pre-Production) Condition 4	Report 12912
101	Defrost Test N.A.S. B Model (Pre-Production) Condition 11	Report 12912
102	Defrost Test N.A.S. B Model (Pre-Production) Condition 10	Report 12912
103	Defrost Test N.A.S. B Model (Pre-Production) Condition 12	Report 12912
104	Defrost Test N.A.S. B Model (Pre-Production) Condition 9	Report 12912
105	Defrost Test N.A.S. B Model (Pre-Production) Condition 8	Report 12912
106	Defrost Test N.A.S. B Model (Pre-Production) Condition 7	Report 12912
107	Defrost Test N.A.S. B Model (Pre-Production) Condition 6	Report 12912
108	Defrost Test N.A.S.B Model (Pre-Production) Cond.5	Report12912
109	Defrost Test Commer 103 Phase 1 Prototype Test No 1	Report1292
110	Defrost Test Commer 103 Phase 1 Prototype Test No 2	Report1292
111	Defrost Test Commer 103 Phase 1 Prototype Test No 3	Report1292

112	Defrost Test Commer 103 Phase 1 Prototype Test No 4	Report1292
113	Traces Dynamic Pushrod Loads Figures 1,2,3,4.5.6 and 7	Report1277
114	Defrost Test N.A.S. Avenger (L.C.Engine LHD)	Report12943
115	Detail Photo of Hoses and Frame- trap?	
116	Photo of Jig/Fixture in of Testing Machine	
117	Photo of Jig/Fixture in of Testing Machine	
118	Photo of looks like a Vibration Test Rig	
119	Photo of a Complicated Test Rig	
120	Photo of 2 Fans/Impellers	
121	Photo of Control Console of Test Apparatus?	
122	Photo of a Filtered Test Apparatus?	
123	Photo of a Test Table?	
124	Photo of a Test Frame?	
125	Photo of a Pipe Connection on Test Apparatus?	
131	Photo of a Rotating Joint/Bellows?	
132	Photo with Label "Cross Member Fatigue Test"	
133	Photo of Spined End of Shaft "Al- ternating Torque Test"	
134	Photo of Results of a Rotating Bending Test	
135	Photo of Results of a Rotating Bending Test	
136	Photo of Labelled Shaft/Coupling?	
137	Photo of Results of a Rotating Bending Test	
138	Photo of Results of a Rotating Bending Test	
139	Photo of Results of a Rotating Bending Test	
140	Photo of Results of a Rotating Bending Test	
141	Photo of Body Sheet Metal Work Front Grill Area	
142	Photo of Body Sheet Metal Work Front Radiator Area	
143	Photo of Underneath of Floor Pan?	
144	Photo of Assembly on Test Table Floor Pan?	

145	Photo of Assembly on Test Table Floor Pan?		
146	Photo of Assembly on Test Table Floor Pan?		
147	Photo of Assembly on Test Table Floor Pan?		
148	Photo of Broken Strut Test Result?		
149	Photo of Broken Strut Test Result?		
150	Photo of Assembly on Test Table Floor Pan?		
151	Photo of Assembly on Test Table Floor Pan/Chassis Member?		
152	Photo of Assembly on Test Table Floor Pan/Chassis Member?		
153	Photo of Assembly on Test Table Cross Member?		
154	Photo of Car Body Assembly on Test Table Door Upright Joint		
155	Photo of Car Body Assembly on Test Table Door Upright Joint		
156	Photo of Car Body Assembly on Test Table Door Upright Joint		
157	Photo of Car Body Assembly on Test Table Door Upright Joint		
158	2 Photos of Diff. Internals		
159	Defrost Test 1500cc Avenger LHD Toughened Screen Test 1		Report12987
160	Defrost Test 1500cc Avenger LHD Toughened Screen Test 2		
161	Defrost Test N.A.S. Avenger LHD B238 L.C.Engine		
162	Defrost Test N.A.S. Avenger LHD B238 L.C.Engine		Report 13312/C
163	Defrost Test N.A.S. Avenger LHD B238 L.C.Engine		Report 13312/D
164	Windscreen Defrost Test NAS Avenger LHD	Avenger	
164	Defrost Test N.A.S. Avenger LHD B238 L.C.Engine		Report 13312/B
165	12 Windscreen Plots-Defrost Test NAS Twin Carb B Estate		Peport 13751
166	Defrosting Test NAS Twin Carb. B Estate Test No 9		Report 13751
167	Defrosting Test - Plymouth Cricket (Face Vents Closed)Test 1		Report 13758
168	Defrosting Test - Plymouth Cricket RH239185838 Test 1		Report 13747

169	Defrosting Test - Plymouth Cricket (Face Vents Open)Test 3		Report 13758
170	Defrosting Test - Plymouth Cricket RH239185838 Test 2		Report 13747
171	Defrosting Test - Plymouth Cricket (Face Vents 1/2Open)Test 2		Report 13758
172	Photo ofd Car Items in Test Machine		
173	Angle	Avenger?	
174	Imp Sport Cold Weather Equipment	Imp Sport	
174	Photo of Laidout Car Parts Panels-Silencer-Fan and Cowl		
175	Imp Sport Cold Weather Equipment	Imp Sport	
175	Photo of Sport Apex Engine Bay	Sunbeam Stiletto	
176	Defrost Test - Plymouth Cricket Chassis No23920462		Report 14021
177	Defrost Test - Plymouth Cricket Chassis No23920462		Report 14021
178	Defrosting Test - Plymouth Cricket 12 Module 12 GP Heater 71263066		Report14084
179	Defrosting Test - Plymouth Cricket 13 Module 12 GP Heater 71263067		Report 14034
180	Photo of 2 Triangulated Items		
181	Photo of 2 Triangulated Items		
182	Defrost Test Cricket B278 Chassis No238205383		
183	Defrost Test Cricket B278 Chassis No238205383 Delanair Heater		
184	Unrecognizable Photo Strip		
185	Photo of Cylinder Head Casting?		
186	5 Photos of Detail Views of Car?		
187	Photo of Windscreen with Pads		
188	Photo of Test Console/Aparatus alongside 4Door Saloon		
189	Photo of Test Aparatus with Pads		
190	Photo of Aparatus in 189 fitted to Windscreen		
191	Photo of Driving Position Simulator?		
192	Photo of Driving Position Simulator?		
193	2-2 Circuit Diagrams D3112-Yaw Rate Channel 3		D 3112
193	3-Circuit Diagram D3113-Roll Rate Channel 5		D 3113
193	4-Circuit Diagram D3114-Lateral Accel. Channel 7		D 3114

193	5-Circuit Diagram D3115- Handwheel Angle9 Channel 7		D 3115
193	6 Circuit Diagram D3116-5th Wheel Road Speed Channel 11		D 3116
193	7 Circuit Diagram D3117-Clock Generator – Channel 13		D 3117
193	8 Circuit Diagram D3118-????— Channel 15 and 16		D 3118
193	9 Circuit Diagram D3119 Gyro Unit Gyro Block		D 3119
193	10 Circuit Diagram D3120 Gyro Unit Gyro Power Supply		D 3120
193	11 Circuit Diagram D3121 DC-DC Power Unit Handling Equip		D 3121
193	12 2 Circuit Diagrams D3122 5 Volt Regulator Board P/S		D 3122
193	13 Circuit Diagrams D3123 10 Volt Regulator Board P/S		D 3123
193	14 Circuit Diagrams D3124 –??– Power Unit		D 3124
193	15 Circuit Diagrams D3125 –No Ti- tle		D 3125
193	16 Circuit Diagrams D3126		D 3126
193	1-Circuit Diagrams D3111-Pitch Rate Channel 1		D 3111
194	Photo of Test Car? M119 Front Damaged		
195	35mm-8A-Test Car M119 Front Damage Nearside		
196	35mm-9A-Test Car M119 Front Damage Offside	Saloon	
197	35mm-5A-Test Car M119 Driving Position		
198	35mm-6A-Test Car M119 Engine Compartment		
199	35mm-7A-Test Car M119 Wind- screen Area		
200	35mm-1A-Test Car M119 Nearside	Saloon	
201	35mm-2A-Test Car M119 Offside		
202	35mm-3A-Test Car M119 Driving Position		
203	35mm-4A-Test Car M119 Door Openning		
204	35mm-14A-Test Car M119 Corner of Winscreen		
205	35mm-15A-Test Car M119 Roof		
206	35mm-11A-Test Car M119 Across Front		

207	35mm-12A-Test	Car	M119	Wind-screen Corner	
208	35mm-13A-Test	Car	M119	Wind-screen Edge	
209	35mm-25A-Test	Car	M119	Console/Dash	
210	35mm-26A-Test	Car	M119	Wind-screen	
211	35mm-27A-Test	Car	M119	Wind-screen	
212	35mm-21A-Test	Car	M119	Door Corner?	
213	35mm-22A-Test	Car	M119	Door Opening	
214	35mm-23A-Test	Car	M119	Driving Position	
215	35mm-24A-Test	Car	M119	Console/Dash	
216	35mm-17A-Test	Car	M119	Body Joint Detail	
217	35mm-18A-Test	Car	M119	Body Joint Detail	
218	35mm-19A-Test	Car	M119	Roof Corner	
219	35mm-20A-Test	Car	M119	Roof Corner Inside	
220	Photo Test	Car	M106	Front Damage	Estate
221	Photo	Car		Test Area	
222	Photo Test	Car	M106	Before Damage Nearside	Estate
223	Photo Test	Car	M106	Before Damage Offside	Estate
224	Photo Test	Car	M106	After Damage Offside	
225	Photo Test	Car	M106	After Damage Nearside	
226	Photo Test	Car	M106	After Damage Nearside	
227	35mm-4A-Test	Car	M109	Drivers Seat Area	
228	35mm-5A-Test	Car	M109	Drivers Seat Area	
229	35mm-1A-Test	Car	M109	Detail?	
230	35mm-2A-Test	Car	M109	Front Corner	
231	35mm-3A-Test	Car	M109	Drivers Position	

232	Photo Test Car M91 After Damage Offside	Saloon
233	Photo Test Car M91 After Damage Offside	Saloon
234	Photo Test Car M91 After Damage Offside	Saloon
235	Photo Test Car M91 After Damage Nearside	Saloon
236	Photo of Car? Test M91 Front Damaged	
237	35mm-35 Photo of Car Seat Details	
238	1-35mm-36 Photo of Car Seat Details	
238	2-4X35mm-3,4,5and6 Damage to Car after Test 2	
239	35mm-37 Photo of Car Seat Details	
239	6X35mm-19,21,22,23,24and25 Car Body Damage	
240	35mm-32 Photo of Car Drivers Position	
240	35mm 14 Photo of Car Damage	
240	35mm 15 Photo of Car Damage	
240	35mm 16 Photo of Lorry Damage	Lorry
240	35mm 17 Photo of Lorry Damage	Lorry
240	35mm 11 Photo of Lorry Damage	Lorry
240	35mm 12 Photo of Lorry Damage	Lorry
240	35mm 13 Photo of Lorry Damage	Lorry
241	35mm-33 Photo of Car Seat Details	
241	11X35mm 31A to 42A+Photos of Test Car N75	Saloon
242	35mm-34 Photo of Car Drivers Position	
242	2X35mm 11 and 12 Photo of Damage	
243	35mm-28-Test Car M9 Drivers Position	
243	Photo of Test Machine?	
244	35mm-29-Test Car M9 Drivers Position	
244	Photo of Test Machine?	
245	35mm-30-Test Car Engine Bay	
245	9X35mm Various Photos of Test Car P19?H	Saloon
245	Another 11x35mm Photo of After Test P13? Damage	Saloon
246	35mm-31-Test Car Engine Bay	
246	12x35mm Photo of After Test Damage	

246	Another 11x35mm Photo of After Test Damage				
247	11x35mm Photo of Car Test P35? Damage			Saloon	
247	Another 5x35mm Photos OF AFTER Test Car				FHP 507L
248	12x35mm Photos of Details of Car				FDU 147L
248	Another 6x35mm Photos of Detail of Car				FDU 147L
249	8x35mm Photos Test? Damage				
249	Another 12x35mm Photos of Van Test P36			Van	
250	11x35mm Photos of Vehicles Details				
250	Another 3x35mm Photos of Vehicles Details				
251	12x35mm Photos of Test HS 9 Mainly Seats and Bodywork				
252	3x35mm Photos of Damage Vehicle Cab?				
253	10x35mm Photos of Damaged Test Vehicle				
253	Another 12x35mm Photos of Damaged on Test Vehicle				
254	12x35mm Photos of Damaged Vehicle Test P36				
254	Another 8x35mm Photos of Damaged Vehicle Underneath				
255	3x35mm Photos of Behind Rear Seating?				
256	6x35mm Photos of Test Frame or Tower				
257	6x35mm Photos of Vehicle-Battery-Suspension-Steering				
258	3 x35mm Photos Front Seat Frame in Position				
259	11x35mm Photos of Alternators and Test Equipment				
259	Another 11x35mm Photos of Alternator Parts				
260	Windshield Defront Test	05/02/1976		Avenger/Imp	
261	Avenger/Imp Engine				
261	Windshield Defront Test	17/02/1976		Avenger/Imp	
261	Avenger/Imp Engine				
262	Windshield Defront Test	20/02/1976		Avenger/Imp	
262	Avenger/Imp Engine				
263	Windshield Defront Test	24/02/1976		Avenger/Imp	
263	Avenger/Imp Engine				

264	Windshield Defront Test	12/02/1976	Avenger/Imp	
	Avenger/Imp Engine			
265	Windshield Defront Test	19/02/1976	Avenger/Imp	
	Avenger/Imp Engine			
266	Windshield Defront Test	13/02/1976	Avenger/Imp	
	Avenger/Imp Engine			
267	Windshield Defront Test	27/02/1976	Avenger/Imp	
	Avenger/Imp Engine			
268	Windshield Defront Test	25/02/1976	Avenger/Imp	
	Avenger/Imp Engine			
269	Photo under Rear of Car? Showing Fuel Tank			RDU 51M
270	10x35mm Photos of Damaged Test Vehicle-Drivers Position			
270	1 Photo of Car PR 37 Underneath Rear Showing Fuel Tank			RDU 51M
271	Photo of Underneath- Fuel Tank Datum Marks			
272	Photo of 2 Door Hatchback PR 37 Rear RH Quarter			RDU 51M
273	Photo of 2 Door Hatchback PR 37 Rear LH Quarter			RDU 51M
274	Photo of 2 Door Hatchback PR 37 Above Front RH Quarter			
275	Photo of 2 Door Hatchback PR 37 Front LH Quarter			RDU 51M
276	Photo of 2 Door Hatchback PR 37 Offside			
277	Photo of 2 Door Hatchback PR 37 Underneath Tank Hanging			RDU 51M
278	Photo of 2 Door Hatchback PR 37 Underneath Tank Hanging			RDU 51M
279	Photo of 2 Door Hatchback PR 37 Underneath Tank Hanging			RDU 51M
280	Photo of Underneath Fuel Tank Dented Datum Marks			
281	Photo of 2 Door Hatchback PR 37 Dent in RH Rear Panel			RDU 51M
282	Photo of 2 Door Hatchback PR 37 Dent in RH Rear Panel			RDU 51M
283	Photo of 2 Door Hatchback PR 37 Dent in RH Rear Panel			
284	Photo of 2 Door Hatchback PR37 Damaged Rear End			RDU 51M
285	Photo of 2 Door Hatchback PR37 Damaged Rear End Nearside View			
286	Photo of 2 Door Hatchback PR37 Damaged Rear End Nearside View			RDU 51M

288	12x35mm Photos of Car Damaged from Rear			
289	16x35mm Photos of Car Features Dash-Console-Doorhandle			
289	Another 9x35mm Photos of Dash Parts-Test Equipment			
290	12x35mm Photos Silencer- and Test Equipment			
291	3X35MM Photos of Rear/Boot Floor Area			
292	14x35mm Closeup Photos of PR37 Detail-Springs-Wheel			RDU 51M
292	Another 11x35mm Photos Under- neath Car-Body Panel			
293	12x35mm Photo of after Test PR 37 Damage			RDU 51M
293	Another 4x35mm Photos PR37 Rear Inside-Nearside Rear			RDU 51M
294	7x35mm Photo Inside and Out Test Car PR37			RDU 51M
294	Another 12x35mm Photos PR37 Mainly Outside Views			RDU 51M
295	Defrost Test? Avenger SC1 (Ex B301) RHD 930 Engine	04/05/1976	Avenger	
296	Repeat Test 16 Avenger SC1 (Ex B301) RHD 930 Engine	27/04/1976	Avenger	
297	Repeat Test 18A Avenger SC1 (Ex B301) RHD 930 Engine	05/05/1976	Avenger	
298	Repeat Test 14 Avenger SC1 (Ex B301)	13/04/1976	Avenger	
299	Test as 13 Avenger SC1 (Ex B301) RHD 930cc Engine	12/04/1976	Avenger	
300	Test Avenger SC1 (Ex B301) RHD 930cc Engine	15/04/1976	Avenger	
301	Test Avenger SC1 (Ex B301) RHD 930cc Engine	09/04/1976	Avenger	
302	As Test 19 Avenger SC1 (Ex B301) RHD 930cc Engine	06/05/1976	Avenger	
303	Defrost Test Volkswagen Polo LHD Engine 2950 RPM	25/03/1976	Volkswagen Polo	
304	6x Photos Views of 2 Door Hatch- back			
305	2x35mm Photos of Cars Details? with Datum Marks			
306	11x35mm Photos Mainly Fuel tanks Plus Diff			
306	Another 12x35mm Photos of Details Diff-Underneath-Fuel Filler			

307	11x35mm Photos of Test PR37 Underneath-Outside-Interior		RDU 51m
307	Another 8x35mm Photos of Underneath Mainly Sparewheel Area		
308	4x35mm Photo of Test Car R18		
308	Another 4x35mm Photo of Test Car R18		
309	8x35mm Detail views of Test Car R18		
310	14x35mm Detail Steering-Underneath-Details Test Car		
310	Another 11x35mm Photos of Test Car R19 Underneath		
311	14x35mm Photos of Test Car R19		
312	5x35mm Photos of Test Car R19		MRV 709M
313	10x35mm Photos of Test Van RR35	Van	
313	Another 3x35mm Photos of Test Van RR35	Van	
314	6x35mm Photo of Test Van RR35 Underneath		
315	9x35mm Detail Damage on Test Vehicle		
316	Photo of Car Body on Test Rig		
317	Photo of Car Body on Test Rig		
318	Photo of Car Body on Test Rig		
319	Photo of Small 2 Door Hatchback-Side		
320	Photo of Small 2 Door Hatchback-Rear Nearside		RKV 411R
321	Photo of Small 2 Door Hatchback-Rear		RKV 411R
322	Photo of Small 2 Door Hatchback-Rear		RKV 411R
323	Photo of Small 2 Door Hatchback-Front Offside		RKV 411R
324	9x35mm Photo Mainly Door Details		
325	5x35mm Photo Mainly Door Details		
326	6x35mm Photo Mainly Door Details		
327	12X35mm Photos Details of Test Car R60		
327	Another 10x35mm Photo of Detail of Tested Car		
327	Another 8x35mm Photos of Test Car Suspension-Door		
328	11X35mm Photos Details of Test Car R60		
328	Another 6X35mm Photos Details of Test Car R60 Steering Column		RRR 354R

329	11X35mm Photos Details of Test Car	
330	11X35mm Photos Details of Test Car Drivers Position Pedals	
331	12X35mm Photos Details of Test Car Underneath-Suspension	
331	Another 11x35mm Details of Test Car Underneath-Suspension	
332	9x35mm Photos Mainly Body Details	
333	Outline of 2 Door Hatch showing Airflow over Rear	
334	Outline of 2 Door Hatch showing Airflow over Rear	
335	12x35mm Photos Details of Test Car R88 Inside-Underneath	
335	Another 14x35mm Photos of Test Car R88	
335	Another 11x35mm Photos of Test Car R88 General Views	
336	12x35mm Photos of Test Car R88 Damage	
336	Another 10x35mm Photos of Damage mainly underneath	
336	/14 Another 35mm Photo of ??? (Rayner/Reid/Barley)	
337	12x35mm Photos of Test Car R88 Inside-Outside-Engine Bay	
338	9x35mm Photos of Test Car R88 Outside-Pedals-Body Details	
339	12x35mm Photos mainly of Window Framing	
339	Another 10x35mm Photos mainly Window Framing	
339	Another 9x35mm Photos-Car Person with Dog	RKV 411R
340	12x35mm Photos of Car Mainly Body Details	RKV 411R
340	Another 6x35mm Photos-Seating Details	
340	Another 12x35mm Photos mainly of Window Framing	
341	12x35mm Photos of Building Details?	
341	Another 8x35mm Photos of Building Details?	
341	Another 8x35mm Photos of Building Details?	

342	8x35mm Photos of Tested Car R124		
342	Another 9x35mm of Tested Car R124		
343	12x35mm Detail photo of Test Car R124 Damage		
343	Another 12x35mm Detail photo of Test Car R124 Damage		
343	Another 5x35mm Photos of Test Car Damage		
344	8x35mm Photos of Tested Car R124 Damage		
344	Another 12x35mm Photos of Test Car Damage		
344	Another 8x35mm Photos of Test Car R88 Damage		
345	12x35mm Photos of Test Car R124 Damage		
345	Another 13x35mm Photos of Test Car R124 Damage-Labels		
346	8x35mm Photos of Test Car Damage		
346	Another 12x35mm Detail Damage - Internal		
346	Another 12x 35mm Photos of Test Car R88		
347	8x35mm Photos of Damaged Test Car Mainly Engine Bay		
348	7x35mm Photos of Damaged Test Car Mainly Engine		
349	9x35mm Photos of Damaged Test Car-Body-Underneath		
350	15x35mm Photos of Test Car R141	Estate	
351	12x35mm Photos of Damaged Detail Framing-Some Labeled		
351	Another 3x35mm Photos of Damaged Detail some Labelled		
352	13x35mm Photos of Car Detail some Labelled		
352	Another 12x35mm Photo Of Damaged Labelled P76/152		
353	4x35mm Photos of Edge of Broken Glass		
354	3x35mm Photos of Broken Glass		
355	Photo of Rear of Small Hatchback		
356	Photo of Front of Small Hatchback Chrysler	Chrysler	UHP 238R
357	2 Photos (same) of Small Hatchback as 355 Rear Offside		

358	Photo of Front of Small Hatchback Offside		
359	Photo View of Front Offside Quarter Chrysler	Chrysler	UHP 238R
360	Photo of Test Rig		
361	Photo of Test Rig		
362	Photo of Control Console of Test Rig		
363	Photo of Control Console of Test Rig		
364	12x35mm Photos of Test Car SR13 Boot Floor-Wheels		
365	Photo of Small Hatchback Side House in Background		
366	Photo of Chrysler Hatchback Front Quarter Tree Background	Chrysler	RRW 430R
367	Photo of Chrysler Hatchback Front Tree Background	Chrysler	RRW 430R
368	Photo of Chrysler Hatchback Rear Quarter Tree Background	Chrysler	RRW 430R
369	Photo of Chrysler Hatchback Rear Tree Background	Chrysler	RRW 430R
371	7x35mm Photos of Damaged Test Car Fuel Tank Area		
371	Another 12x35mm Photos of Test Car 204R Damage		
372	9x35mm Photos of Test Car 202		
373	12x35mm Photos of Test Car 202 Damage		
373	Another 14x35mm Photos of Test Car Damage-Underneath		
373	Another 4x35mm Photos of Test Car Damage-Engine		
374	8X35Cmm Photos of Detail Damage mainly Underneath		
375	10x35Cmm Photos of Detail Damage		
376	9x35mm Photos of Test Car TR2		
376	Another 12x35mm Photos Wheels-Boot-Driveshaft		
377	12x35mm Photos of Test Car TR2 Damage		
377	Another 12x35mm Photo of Test Car TR2		
378	9x35mm Photos of Car Damage		
379	10x35mm Photos of Car Damage Underneath		
380	19x35mm Photos of Test Car SR105		

381	8 Plots Of Defrost/Demist Tests 50 Series EV 298		
382	6x35mm Photos of 2 Vans Outside		
383	6x35mm Photos of Test Car T103?- Engine-Underneath		
384	21x35mm Photos of Test Car T103		
385	10x35mm Photos of Test Car T103		
386	9x35mm Photo of Electric Motor Powered Test Rig		
387	12x35mm Photos of Seat Test Rig?		
387	Another 5x35mm Photos of Seat Test Rig		
388	8x35mm Photos of "Doorlocks and Hinges"		
389	5x35mm Photos of "Seatbelt Anchorage Points" Pass		
390	9x35mm Photos of "Seatbelt Anchorage Points" Failure		
391	11x35mm Photos of "Seatbelt Anchorage Points"		
392	11x35mm Photos of Dash/Console Mockup?		
393	22x35mm Photos of Test Car TR191 and T102?		
394	7x35mm Photod of Car Body Joints Labelled		
395	3x35mm Photos of Car Body Structure Labelled		
396	5x35mm Photos of Broken Car Structure		
397	10x35mm Photos of Cab of Body Structure?		
398	12x35mm Photos of Damage Details?		
399	6x35mm Photos of Seatbelt Anchorages		
400	Detail Lights Dodge		Dodge
400	10x35mm Photos of Light Units		
401	2x35mm Photos of Internal Structure-Seatbelt Anchorage?		
402	7x35mm Photos of LorryCab/Van Seating 26Nov1979 RHS	26/11/1979	
403	10x35mm Photos of Seat Setup Surface Plate and in Cab		
404	15x35mm Photos of PB Van (Eire)	27/07/1979	
405	7x35mm Photos of PB Van (Eire) Under Test	27/07/1979	

406	7x35mm Photos of Instrument Panels			
406	Another 3x35mm Photos of Instrument Panels			
407	21x35mm Detail Photos of Test Vehicle			
408	11x35mm Photos of Test Car VR96			
409	15x35mm Photos of Test Car VR96			
410	14x35mm Photos of Test Car VR96			
411	18x35mm Photos of Test Car VR 96			
412	2x35mm Photos of Test Rig with Dial Gauge			
413	8x35mm Photos of Body Structure/Spotwelds	08/07/1980		
414	7x35mm Photos of Something Coiled-Round Object			
415	15x35mm Photos of Car Body Doors Test.			
418	6x35mm Photos of Body Structure/Spotwelds	27/08/1980		
419	10x35mm Photos of Interior Passenger Compartment Views			
420	3x35mm Photos of Car on open Road			Loose
	Following have Q prefix			
62	Avenger Tiger Prototype WVC 204J		Avenger Tiger	
63	Avenger Tiger Prototype WVC 204J		Avenger tiger	
	No prefix			
718	Photo Van Cab Drivers Position		Bedford?	

**3 Negatives Drawer 2.****4 Negatives Drawer 3.****5 Negatives Drawer 4.****6 Negatives Drawer 5.****7 Negatives Drawer 6.****7.1 Imp Related Photographic Negatives**

Just to give a taster, these are some things found in the top drawer. These negatives are numbered and kept in numerical order, but there is little other information about them.

**Crash Tests:****Styling Drawings:****European and Latin America Sales:****Performance Comparisons:**

Number	comments
Drawer 1	
C94-107	Californian G37 crash test (JHP 492E)
C135-49	Imp G44 crash test
C150-71	Husky G48 crash test
C788-99	J80 late model Imp crash test (TDU 626J)
C800-7	J86 Stiletto crash test
C1051-4	Imp 468 afterwards
C1055-60	Imp 792 afterwards
C1061-70	Imp 542 afterwards
D990-9	Imp Vans SKV 144H and SDU 429G advertising shots
D1000-4	Imps MHP 181F -do- (has MkI trim)a
D1030	Imp MYM 770H outside offices
D1107-8	Imp SDU 626J show stand pictures
F174-5	some Imp Sport cold weather equipment
Drawer 2	
AC224	Husky parked on runway, Wellesborne test circuit?
AM1-3	MkIII Imp RH end of dashboard
AM17-20	MkIII Imp LH end of dash (stripped) and bonnet
B79	900 deLuxe badge design detail

Many of the rest of these negatives date from around 1970-71 and show the design study (cars A, B, C, D in various states of finish) which lead to the Avenger. There are also many showing tests on early Avengers. Others show the interior of factories and other buildings, on series is of machinery which appears to be for sale, possible at the closure of the T??? plant.

There is a card index of some previous negatives. Some of these feature Imps, e.g. one is a company car which was damaged in an accident and had been repaired. Unfortunately it seems the negatives themselves no longer exist.

Negative No	Description	Date	Model	Notes
224	Husky Parked on Runway, Wellesborne Test Circuit?		Imp Husky	
1	MkIII Imp RH end of dashboard		Imp	
2	MkIII Imp RH end of dashboard		Imp	
3	MkIII Imp RH end of dashboard		Imp	
17	MkIII Imp LH end of dshboard (Stripped) and Bonnet		Imp	
18	MkIII Imp LH end of dshboard (Stripped) and Bonnet		Imp	
19	MkIII Imp LH end of dshboard (Stripped) and Bonnet		Imp	
20	MkIII Imp LH end of dshboard (Stripped) and Bonnet		Imp	
79	900 DeLuxe Badge Design Detail		Imp	
94	Californian G37 Crash Test (JHP 492E)		Imp Californian	
94	Californian G37 Crash Test (JHP 492E)		Imp Californian	
95	Californian G37 Crash Test (JHP 492E)		Imp Californian	
95	Californian G37 Crash Test (JHP 492E)		Imp Californian	
96	Californian G37 Crash Test (JHP 492E)		Imp Californian	
97	Californian G37 Crash Test (JHP 492E)		Imp Californian	
98	Californian G37 Crash Test (JHP 492E)		Imp Californian	
99	Californian G37 Crash Test (JHP 492E)		Imp Californian	
100	Californian G37 Crash Test (JHP 492E)		Imp Californian	
101	Californian G37 Crash Test (JHP 492E)		Imp Californian	
102	Californian G37 Crash Test (JHP 492E)		Imp Californian	
103	Californian G37 Crash Test (JHP 492E)		Imp Californian	

104	Californian G37 Crash Test (JHP 492E)	Imp Californian
105	Californian G37 Crash Test (JHP 492E)	Imp Californian
106	Californian G37 Crash Test (JHP 492E)	Imp Californian
107	Californian G37 Crash Test (JHP 492E)	Imp Californian
135	Imp 44 Crash Test	Imp
136	Imp 44 Crash Test	Imp
137	Imp 44 Crash Test	Imp
138	Imp 44 Crash Test	Imp
139	Imp 44 Crash Test	Imp
140	Imp 44 Crash Test	Imp
141	Imp 44 Crash Test	Imp
142	Imp 44 Crash Test	Imp
143	Imp 44 Crash Test	Imp
144	Imp 44 Crash Test	Imp
145	Imp 44 Crash Test	Imp
146	Imp 44 Crash Test	Imp
147	Imp 44 Crash Test	Imp
148	Imp 44 Crash Test	Imp
149	Imp 44 Crash Test	Imp
150	Imp Husky G48 Crash Test	Imp Husky
151	Imp Husky G48 Crash Test	Imp Husky
152	Imp Husky G48 Crash Test	Imp Husky
153	Imp Husky G48 Crash Test	Imp Husky
154	Imp Husky G48 Crash Test	Imp Husky
155	Imp Husky G48 Crash Test	Imp Husky
156	Imp Husky G48 Crash Test	Imp Husky
157	Imp Husky G48 Crash Test	Imp Husky
158	Imp Husky G48 Crash Test	Imp Husky
159	Imp Husky G48 Crash Test	Imp Husky
160	Imp Husky G48 Crash Test	Imp Husky
161	Imp Husky G48 Crash Test	Imp Husky
162	Imp Husky G48 Crash Test	Imp Husky
163	Imp Husky G48 Crash Test	Imp Husky
164	Imp Husky G48 Crash Test	Imp Husky
165	Imp Husky G48 Crash Test	Imp Husky
166	Imp Husky G48 Crash Test	Imp Husky
167	Imp Husky G48 Crash Test	Imp Husky
168	Imp Husky G48 Crash Test	Imp Husky
169	Imp Husky G48 Crash Test	Imp Husky
170	Imp Husky G48 Crash Test	Imp Husky
171	Imp Husky G48 Crash Test	Imp Husky
788	Late Model Imp J80 Crash Test (TDU 626J)	Imp

789	Late Model Imp J80 Crash Test (TDU 626J)	Imp
790	Late Model Imp J80 Crash Test (TDU 626J)	Imp
791	Late Model Imp J80 Crash Test (TDU 626J)	Imp
792	Late Model Imp J80 Crash Test (TDU 626J)	iImp
793	Late Model Imp J80 Crash Test (TDU 626J)	Imp
794	Late Model Imp J80 Crash Test (TDU 626J)	Imp
795	Late Model Imp J80 Crash Test (TDU 626J)	Imp
796	Late Model Imp J80 Crash Test (TDU 626J)	Imp
797	Late Model Imp J80 Crash Test (TDU 626J)	Imp
798	Late Model Imp J80 Crash Test (TDU 626J)	Imp
799	Late Model Imp J80 Crash Test (TDU 626J)	Imp
800	Stiletto J86 Crash Test	Stiletto
801	Stiletto J86 Crash Test	Stiletto
802	Stiletto J86 Crash Test	Stiletto
803	Stiletto J86 Crash Test	Stiletto
804	Stiletto J86 Crash Test	Stiletto
805	Stiletto J86 Crash Test	Stiletto
806	Stiletto J86 Crash Test	Stiletto
807	Stiletto J86 Crash Test	Stiletto
1051	Imp 468 After Crash Test	Imp
1052	Imp 486 After Crash test	Imp
1053	Imp 486 After Crash test	Imp
1054	Imp 486 After Crash test	Imp
1055	Imp 792 After Crash test	Imp
1056	Imp 792 After Crash test	Imp
1057	Imp 792 After Crash test	Imp
1058	Imp 792 After Crash test	Imp
1059	Imp 792 After Crash test	Imp
1060	Imp 792 After Crash test	Imp
1061	Imp 542 After Crash Test	Imp
1062	Imp 542 After Crash Test	Imp
1063	Imp 542 After Crash Test	Imp
1064	Imp 542 After Crash Test	Imp
1065	Imp 542 After Crash Test	Imp
1066	Imp 542 After Crash Test	Imp
1067	Imp 542 After Crash Test	Imp
1068	Imp 542 After Crash Test	Imp

1069	Imp 542 After Crash Test	Imp
1070	Imp 542 After Crash Test	Imp
217	I.C. Imp. BEA Badge. Drawn by "Steicns", Mini MPV	Imp
990	Imp Vans SKV 144H and SDU 429G, Advertising Shots	Imp Van
991	Imp Vans SKV 144H and SDU 429G, Advertising Shots	Imp Van
992	Imp Vans SKV 144H and SDU 429G, Advertising Shots	Imp Van
993	Imp Vans SKV 144H and SDU 429G, Advertising Shots	Imp Van
994	Imp Vans SKV 144H and SDU 429G, Advertising Shots	Imp Van
995	Imp Vans SKV 144H and SDU 429G, Advertising Shots	Imp Van
996	Imp Vans SKV 144H and SDU 429G, Advertising Shots	Imp Van
997	Imp Vans SKV 144H and SDU 429G, Advertising Shots	Imp Van
998	Imp Vans SKV 144H and SDU 429G, Advertising Shots	Imp Van
999	Imp Vans SKV 144H and SDU 429G, Advertising Shots	Imp Van
1000	Imp MHP 181F (Has Mk1 Trim)	Imp
1002	Imp MHP 181F (Has Mk1 Trim)	Imp
1003	Imp MHP 181F (Has Mk1 Trim)	Imp
1004	Imp MHP 181F (Has Mk1 Trim)	Imp
1030	Imp MYM 770H Outside Offices	Imp
1107	Imp SDU 626 Show Stand Pictures	Imp
1108	Imp SDU 626 Show Stand Pictures	Imp
174	Imp Sport Cold Weather Equipment	Imp Sport
175	Imp Sport Cold Weather Equipment	Imp Sport

## 8 Negatives Dunstable

I've named this the Dunstable Collection, but maybe it should more properly be the Luton Collection as most of the items are pre-1960.

Some highlights of this set include:

**Y2478:** A Karrier BR100 was the first motorised PSV to climb Porlock Hill with a load of 21 passengers. The 50HP Char-a-banc, owned by Staddon & Sons Ltd., Minehead, climbed the hill on 3/6/1914. Note condition of road surface.

: One of the earlier Karrier models, believed to be of 1912 manufacture, and at that time considered

a revolutionary development. Of the forward control A-type this vehicle seated 20 passengers. Forerunner of many Karrier passenger models.

**K19276:** 1928 Karrier trolley buses, introduced in 1928 and dis-continued in 1948 have proved most popular with operators, the “E6” model still giving excellent service with many municipalities. This photograph of an “E6” with BT-H electrical equipment, placed in service by Doncaster Corporation in 1929. Of this operator’s present fleet of 46 trolley buses 40 are Karriers.

**CX1173:** 1908 Karrier B/50 with detachable van body. Net load 2 tons. Roller chain drive. 22HP 4-cylinder engine. ... Steel frame chassis and artillery style wood wheels.

: 1912 catalogue extract: Commer 4 ton with trailing wagon. The best results from a van or lorry required to draw a trailing wagon cannot be obtained with ordinary gearing and gearbox. To meet the requirements of the double duty we have designed a Commer Car 5-speed gearbox that provides the correct gearing for use when the van or lorry is running under its load only, or when loaded and drawing a loaded trailer.

:  
:  
:  
:  
:

An album of photographs taken by Harry Harle, 15 Biscot Rd., Luton. Commer Cars official photographs from 1908-1944.

Page No	Description	Date	Model	Notes
1	Commer Cars		tipper	Billington and Newton Ltd., Longport
2	Commer Cars		lorry	Brown Brothers flour, Luton
3			6-cylinder fire tender	London Fire Brigade
4			brewery drays	fleet Benskins, Watford
5	Commer Cars		lorry	BM9140 Camwall Table Waters
6	Commer Cars		lorry	BM??? Johnnie Walker Whisky
7	Commer Cars		lorry	XB8123 Johnnie Walker Whisky
8			fire tender	L9673? London Fire Brigade
9			lorry fleet	LN9897 and others Hammerton
10	Commercial Cars		lorry	A.E.Kempster fruitier
11			lorry	John A.Hunter and Co.
12	Commer Cars		van	Parke Davis and Co.

13		van	Southampton Gas and Coke Co.
14	Commercial Cars	char-a-bancs	
15	factory	machine shop	
16	factory	shaft machining	
17	Commer Cars	char-a-bancs	fleet XH4914 and others outside works
18	Commer Car	van	Plaistowe and Co. cakes
19	Commer Car	van	James Hunt Ltd. Fulham printers
20	Commer Car	brewery van	J.W.Green Luton
21	Commer Car	laundry van	Steam Laundry Co. Ilford
22	Commer Car	char-a-banc	
23	Commer Car	char-a-banc	with hood up
24	Commer Car	tanker	
25	Commer Car	tanker	
26	Commer Cars	tipper	
27		bare chassis	
28		engine	
29	Commer Cars	tipper	box lowered
30	factory	machine shop	
31		engine	
32		2x chassis	
33	factory	machine shop	
34	factory	machine	Newark gear cutting

Some negatives are on 6-1/2" x8-1/2" glass plates.

Negative No	Description	Date	Model	Notes
K6299	3-wheeler Karrier chassis		Cob Junior	
C2138	Karrier chassis 3/4 front low level		Cob with trailer Commer	
K7136	3/4 front		Commer	CBM900 Luton Electricity Supply tower truck

K6202	coach chassis drawing trolley bus 6 wheel mil- itary chas- sis	23/5/1937 c.Feb'1952		CU3591 Marston Bay, South Shields
-------	--	-------------------------	--	-----------------------------------

Negatives on film.

Negative No	Description	Date	Model	Notes
(a)			Commer	new truck delivery to Whipsnade Zoo, showing elephants and other animals. Prints made.
(b)			Commer	new truck delivery to Whipsnade Zoo, showing elephants and other animals. Prints made.
			Commer	Civic Defense Fire Pumper No.1 Canada
C1203			Commer	JYY12 and 10 more Royal Mail delivery vans
410 or K50	Karrier		Cob?	BVP323 City of Birmingham high wagon with trailer
325	Commer		4-wheel chassis	
C1269	Commer		EDV?	Craven "A" van
170	Commer Car			LH8935 Fred Davis and Sons, London removers
171	Commer		van	BYV191 Fred Davis and Sons, removers London
180	Commer		van	
C1209	Commer			KAR851 Artistes Transport coach
595				empty wallet
351	Commer		covered wagon	BXV456
364	Karrier		4-wheel lorry	
683 or 8532B		23/10/1942	trolley bus	Eastbourne
321	Karrier		Cob?	DLT227 GWR Paddington
128	Commer		coach	MAN83 Moerzone Coaches
166	Karrier		refuse collector	JA6463 City of Stockport
C1465	Commer		fire engine	KAD765 Gloucestershire
C1466	Commer		fire engine	KAD765 side view
13 (223 on print)	Commer		station wagon	
50/52	Commer		fire engine	LWT154 Rawdon West Riding
69/52	Commer		cattle truck	
C1668	Commer		coach	KAB650 Renown Road Cruiser
359	Commer			LN9535 Gas Light and Coke Co., Westminster
303			Cob?	DJ6070 tractor with trailer, Pilkingtons St. Helen's

53/52	Karrier		van	NTV751 Borough of Lambeth
C1452	Commer		4WD truck	
C1220	Commer		25cwt van	
C1059	Commer		EDV?	
C1052	Commer		flat bed truck	
C1384	Commer		EDV?	Burgess Minerals van outside W.H.Cullen
C1675	Commer		EDV?	
356	Karrier		Cob with ARP tanker	
C1207	Commer		ambulance	County of Bolton
677	Karrier		refuse collector	Helmsley RDC
C1354	Karrier		RSC	Karrier-Yorkshire RSC
588	Karrier		RSC	
337	Karrier		Cob tractors	line up with BNK874 etc.
560	Karrier		Cob tractor unit	CNK875 LMS
562	Karrier		Cob tractor	CNK875 LMS
C1637			van	PZ142 Karrier-Transport Loadmas- ter
96	Karrier		Cob with 4 ton trailer	
1067			Walk-thru van	559BM
C1226	Commer		Superpoise 3-4 ton lorry	
64	Commer	1935	ambulance	Red Cross Jubilee Nyasaland
592 (A.12.692 on neg)			6-wheel lorry	mil. spec. ?
389 (K6254)	Karrier		Cob Senior	I.Spencer and Co. Fleetwood salt
150	Commer		van	Luton Co-Operative
172			2-deck 6-wheel trolley bus	BVK811 Newcastle Corporation
783	Karrier		refuse collector	Hayes and Harlington UDC
152	Commer		van	
C1222	Karrier		flat bed lorry	Corona
C1639	Karrier		refuse collector	Greenock Corporation
C1146	Commer		RSC	Glasgow Corporation
C754	Commer		4-wheel lorry	
1091	Commer		4-wheel tractor unit	
570	Karrier		4-wheel chassis	
1085	Commer		Cob tractor	
C1490	Commer	1953	4-wheel short chassis	
1098	Commer		large van	KVP362
C1232	Commer		4-wheel short chassis	
C719			cab drawing	
			empty wallet	

C1430	Commer	4-wheel single deck bus	
168 and 1842/N5 352	Commer Karrier	4-wheel lorry	CKL237 C.Cuckney, Strood, lorry UJ9708
C1061 1022	Commer	EDV? EDV?	outside A.Anscombe and Sons FTM250, R.G.Leaf, Secretary, Humber Ltd.
223 45	Commer Commer Karrier	4-wheel lorry Centaur	artist shot 3x styling drwgs
178 C1244 C1234 C1606 1607	Commer Commer Commer	4-wheel tipper 4-wheel tipper open truck 4WD 4-wheel long chas- sis, no cab	Borough of Ilford  mil. spec.?
147		4-wheel tractor unit	
791	Commer	long lorry	BUH729 Denny, Mott and Dickson timber, Cardiff BM2856 Earl of Lonsdale GR8090
806 796 C1246 1056 C1640 (YCP96) C1514 C1133	Commer Karrier Karrier Karrier Karrier Karrier	drain cleaner 4-wheel chassis refuse collector drain cleaner drain cleaner 4-wheel tractor w- brewery dray	Congleton Highways Dept. Glamorgan CC Borough of Tottenham
191 1231 1622 1014 451 (452 on neg) 65/52 46/52 C1499 1045	Commer Commer Commer Commer Commer Commer Commer	van cabb styling 4-wheel lorry 4-wheel lorry large van fire engine chassis articulated lorry van lorry cab styling van	Howells, Cardiff      de Havilland Aircraft, Hatfield 327NM on Porlock Hill
788 C334	Karrier Commer Cars	lorry with baskets	
C335 C726 1097 C675 583	Karrier  Biscot Rd.? Commer	char-a-banc RSC short chassis factory buildings mil. spec 6-wheel lorry	DM233 City of Aberdeen showing engine behind cab
491			lorries on line

C132	Commer		tractor unit	RAF
106	Commer		covered truck	RAF
118	Commer		chassis	artists view
232			factory	chassis final checking
489			covered truck	mil. spec
C1604	Commer		factory	cab installation
130			truck	mil. spec
136			truck	DMC75 mil. spec side view
520	Luton		truck	DMC75 mil. spec
583			artists aerial view	Corzon Rd. Biscot Rd.
			6-wheel covered	mil. spec
587	Commer		lorry	
			mil. spec 4-wheel	
C598			lorry	
600			covered wagon	military
			armoured gun	
610			carrier	
			4WD chassis en-	mil. spec
C618			gine at rear	
C636	Karrier		armoured car	
			4WD covered	
C635	Commer		lorry	with soldier
644	personnel		covered lorry	in uniform with rifles
C652	personnel		staff photo	Wadking milling machine
c654	personnel		2 operators	building lorry bodies on line
655	personnel		operators	women machinists
657	personnel		gear shafts	woman operator
C658	personnel		gear machining	machinists
C659	personnel		gear shop	shows women machinists
C662	personnel		gear shop	men and women
C667			gear box assy	lorry finishing end of line
C668	personnel		gear box assy	shows 2 men at work bench
C673	personnel		notice board	Commer-Karrier war fund etc.
C674	Commer Cars Ltd		factory	main entrance
C687		1943	Shuff cartoon	
698	personnel		total board	War savings
C671	Karrier		Cob w- strange	BMJ539 Highways Dept.
			trailer and people	
C692	Commer		4-wheel chassis	
C694 1461			armoured car	
C695 1581?			armoured car	
C696			armoured car	
C713			chassis	mil. spec with winch
C792	personnel		Mr.Struller ?	
C1176	personnel		Mr.Cousins	
C1090	personnel		no name	

C1247	personnel	Cumberland	
C1092	personnel	Quinn	
C1079	personnel	Mr.Smith	
C734	personnel	Mr.Ackroyd	
C1167	personnel	Smith	passport
C722	personnel	Mr.Bragg	
C1525	personnel	Mr.Groves	
C1284	personnel	Mr.Lawrence	
C1071	personnel	Sharratt	
C1172	personnel	no name	
C1451	personnel	Mr.Newsome	passport
C1528	personnel	Mr.Terrance	
C1461	personnel	Mr.Faulkner	
C1478	personnel	Mr.Wigginton	
C1230	personnel	Howard	
C1603	personnel	Lewis	
4778	personnel	Cooper	
64/52	personnel	Miss Dyson	
55/52	personnel	Sherwin	
765		FV	
766		FV	
776	Commer	articulated covered lorry	Cunliffe-Owen Aircraft
C1089	Commer	BLSP articulated lorry	
1095	personnel	presentations?	
124/54	Commer	TS3 diesel engine	cut-away drawing
682		trolley bus	GHN322 Eastbourne

Prints.

Print No	Description	Date	Model	Notes
	Karrier char-a-banc	3/6/1914	Karrier	Y2478 outside the Ship Inn prior to journey to Lynmouth Y2478
	Char-a-banc on Porlock Hill	1914	BR110 23-seat	Y2478 descending a hair-pin Lynmouth
	Karrier (2 copies)	3/6/1914	BR110	Y2478 front view

	Karrier	c.1912	Karrier A-type char-a-banc	
K19276 3774	Karrier Commer Karrier	1929 1936	E6 trolley bus WL6 6-wheel 40- seat single deck	DT1146 Doncaster DT1146 trolley bus Doncaster No29 Wigan Corporation Tramways
	Karrier	1908	B/50	CX1173 Mundin Bros., Northamp- ton
	Karrier Commer	1908 1919	B/50 1919	ditto post card NB6992 Char-a-banc used by Messrs. Topping outside Warring- ton Ales in Liverpool
	Karrier	1908	B/50 ??	AJ1869 Brewers lorry outside Cay- ley Arms, Scarboro and Whitby Brewers Ltd.
post card	Karrier	1908	A/60 ??	AJ1869 Brewers lorry outside Cay- ley Arms, Scarboro and Whitby Brewers Ltd.
	Karrier Commer	Mar'1937	CY	CXC420 X7636, Currie and Co., Newcastle upon Tyne
Parrott 14/55 3454/A	Karrier	1915 1910	RSC rail vehicle	book print Commer converted for shunting, Bedfordshire, general view
3454/F		1910 1912	rail vehicle "CC" type 5-ton fixed tilt van	engine and radiator J.Knight soap, Silvertown, from cat- alogue
	2x Karrier Commer	1914-18	Subsidy type RC type?	CXC417 CXC420 military vehicles BM7114 J.W.Green's Luton ales and stout
	Karrier	Apr'1935		L and SWR collection and delivery vans
	Karrier			CX987 Bransbury, Stratton and Co., brewers, Redhill
1045	Karrier Commer Karrier Karrier Karrier			CXC409 Tocia coach 327NM lorry on hill CXC407 lorry on hill with people CXC407 lorry front view
BR60 32	Karrier ?? Karrier Commer Karrier			ASC No131 lorry side view lorry, lined finish, Cape Town view of bare cab w- fuel tank behind Co-Operative
	Karrier Commer Karrier		A/110 military truck B/80 30HP	WD 61194 3-stage tower wagon with revolving top
AR50	Karrier Karrier		B/80 omnibus	CX1013? Abersoch Motors Bolckow, Vaughan and Co. Ltd.

	Karrier	c.1931	E4 single deck trolley bus	City of York fleet of 32
	Commer	1909	MC type 2-ton	Walker and Sons, for Ceylon tea plantations
	Karrier	1908	B/30 22 cwt 16HP	
	Karrier	1910-	B/30 1-1/2 ton 16HP	Great Horton confectioners and caterers
	Karrier			4-wheel chain drive chassis outside offices
	Karrier	1909		C3248 Walshaw-Drake Co. Ltd., yarn dryers, Rastrick
1316	Karrier	card 8/12/1930	Cob ? RAF long trailer	UR7470 cake delivery
AR160	Commer Karrier Karrier Karrier	c.1910  issued May 1945	BC  char-a-banc c.1930	Gleniffer Laundry, Catford, SE, No4 NA1067 Great Central railway CX1212 GN9072 LNEr 5420 mechanical horse
AR50	Karrier Karrier Commer	c.1912	A/80  4 ton with trailing wagon	Rochdale Equitable truck CX1633 Amos and Smith Ltd. Warings Removals, London
7299	Karrier	30/5/1935	A110 ?	Lockwood and Elliott, Wakefield tipper
02497			trolley bus	FTD453 Atherton
7	Karrier Karrier Commer Cars Commer Cars	1908 6/12/1930 1912 catalogue 1912 catalogue	B/30 22cwt Cob CC 5-ton lorry 6-ton	LMS Co-Operative Manchester Lever Bros. Port Sunlight fleet (26) BM1138 etc.
375/64	Commercial Cars		char-a-banc	BM2156 decorated
373/64	Commercial Cars		char-a-banc	
1788TI	Commer Luton	1931 1912	Centaur main erecting shop	first to leave the assembly line
R8019	Luton	1/4/1949	machine shop from East	
601 K6526 K6532	Karrier		KT4 FWD Gun Tractor	Commer-Karrier Club members supplied to Indian Army
148/53	Luton			family open day? armoured cars in factory armoured cars in factory part of factory

?6871?	Commer		Q4 3ton 4x2 general service	Ministry of Supply man and woman opening door factory lathe shop factory machine shop general view of machine shop
R9224 C2835	Luton Commer	1939-45	Superpoise 3 ton carrier	machine shop gearbox Russian military trials 1910
R5935	Commer Cars Luton Stoke- Aldermoor	1912	4 ton carrier  factory Commer assy plant	aerial shot artist enhanced artists proposal?

## 9 Acknowledgements

[TBA]